

3716 - Orig Notes (1860) 77.16 @ 6°30'E (Now should be 1°15'E±) - 40.00
 (checks about 1°30'E±)
 Vaughan (1907) - 3721 -

MAP # LI 278
 DATE FILED DEC 09 1883
 B
 DESCRIPTION FILED
 OREGON CO SURVEYOR'S OFFICE

NOTE - Blue Lines are not correct, but accepted
 due to 1/4 section circuit

Mauve (1936) 40.28 @ 30°E (2°±)
 - 40.00 - Orig (1860) - 81.04 @

3783
 29.84 ← Vaughan (1908) 77.22
 - 33.10 Wincentzen (1954) 77.29

NOTE -
 Vaughn's center is 0.46 ft
 of Wine E-W Random
 and 4.52 E of h 5N-5R
 or - about 1.34 N and
 4.50 E of his center
 (Vaughn BT had 5E 92)
 75 ft OK

72.22
 20.78 @ 6°30'E (Now 3°±) - 40.94
 39.90 - Wincentzen (Jan 1954) 82.64 (1995)

3°50'E (Now 1°20'E±) - 39.39
 (26.00 to RR)
 @ 0°30'E± - 44.10 - (22.05)

39.64 → Vaughan (1908) 77.22
 (55.20 to R.R.)
 → Vaughan 39.64 @ 40°20'E (1°50'±)
 (28.25 to R.R.)
 (2098)

41.50
 39.50 → Vaughan (1908) 77.22
 (24.00) (Now 3°30'±)
 - 40.00 - Or 9 80 32 @

2930 - Orig (1863) 69.00 @ 6°E (Now 0°45'±) - 40.00

2918 ← Vaughan (1907) 69.02 @ 40°14'E (Now 1°20'E±) - 39.84
 9.00 Wincentzen (1949) 69.02 @ 0°± →

NOTE -

I believe Vaughan started from good Gov't SE Corner, but made an error on West by probably mistaking someone's W/4 for Sec Corner. Orig notes also about 9 ch in error on this E-W line. Undoubtedly Vaughan found plenty original evidence and other lines OK as R.R. is plotted accurate. Believe Wincentzen in error by not proportioning SE Cor and 1/4 Cor, but must leave his stand due to setting improved prop. lines Sec 8, etc.

LI 278

7032

6°12'E (Now 1°E±)

Or 9 80 32 @

LI 278