


SEC. 33 T. 39 N., R. 7 W.



① N<sup>1/4</sup> - NE<sup>1/4</sup>, 33 found 2" Iron Pipe  
Bt<sup>s</sup> M.R. 6" S42°E 15.10'  
B.Y. 8" S70°W 18.20'  
(Dist measured To ctr.)

(Comp. Loc. falls S87°31'W 3.10')

(Vissers, 1979)

② N<sup>1/4</sup> 33 found 1 1/2" Iron Pipe P.H. = N89°W 45.2'; O.H. = N58W 77.0' (Comp. Loc. falls S87°31'W 3.10')  
Bt<sup>s</sup> B.W. 14" N88°W 74.80'  
B.W. 10" S49°W 60.65'  
See Corner file

(Vissers, 1979)

③ N<sup>1/4</sup> - NW<sup>1/4</sup> 33 found 1 1/4" Iron Pipe  
Bt<sup>s</sup> OR 18" N58°W 14.05'  
P.N. 10" N80°E 5.70'

RECEIVED & FILED #	1780
Oneida County Surveyor's Office	
Date	APR. 22 1988
By:	S. J. D.
OCS Area #	

(Vissers, 1979)

1,280

- (4) N.W. Cor 33 found 4" Soil pipe and D.N.R. Brass Cap  
 leaning loosely alongside, Soil pipe predicated Brass Cap,  
 and by doubling dist. & bearing from N $\frac{1}{4}$  & N $\frac{1}{4}$ -N $\frac{1}{4}$  Loc.  
 falls inside Soil pipe. - Set Brass Cap inside Soil pipe. -  
 BT<sup>s</sup>. B.W. 16" N $78^{\circ}$ E 57.40'  
 M.R. 8" N $89^{\circ}$ N 8.25' (Now a step)  
 See Corner file OR 16" S $38^{\circ}$ W 48.35' (To ctr)  
 MH 6" N $78^{\circ}$ W 25.55'


(Vissers, 1979)

- (5) W $\frac{1}{4}$  33-39-7 True Location would put cor in NE cor.  
 of Bldg. built into hillside. Err W.C.D. Brass Cap  
 See Corner file

- (6) NMC  
 See Corner file

- (7) W $\frac{1}{4}$  NW $\frac{1}{4}$  found 2" i.p. (4-27-82) Made BT<sup>s</sup> on 9/13/84 OR 16" S $23^{\circ}$ W 27.7'  
 M.R. 5" S $55^{\circ}$ E 15.95'  
 Symon + Freund

SEC. 33 T. 39 N. R. 7 W.



① w<sub>4</sub> 33

wcd err. brass cap on fence line  
made BT<sup>5</sup> BW 14" twin N 56°W 12.70'; BW 14" 59°W 13.30'  
(10-27-80 Seymour, Vissers, Freund)

② MC (orig) WCD Brass cap found, made BT<sup>5</sup> FB 7" N 55°W 19.10', PN 9" N 9°W 12.71'.  
(10-27-80 Seymour, Vissers, Freund)

RECEIVED & FILED #	1780
Oneida County Surveyor's Office	
Date	APR 22 1988
By	S. J.
OCS Area #	