B1173



▲ = ERRONEOUS ANGLE IRON FOUND
✦ = ERRONEOUS IRON PIPE FOUND
● = IRON PIPE FOUND
— — — DASHED LINES REPRESENT CONFIGURATION OF PARCELS AS DESCRIBED BY DEED
o = IRON PIPE SET

Part of the

SE 1/4 of the SE 1/4
SECTION 4, T36N, R9E

Pelican Township
Oneida County, WI

WISCONSIN LAND SURVEYOR
JAMES F KASSON
S 1416
RHINELANDER
WIS

James F Kasson
AUGUST 28, 1980
Revised Aug. 29, 80

I, James F Kasson, hereby certify that I have surveyed the property shown hereon, that this map represents an accurate survey of said property to the best of my knowledge and belief, I have conducted this survey by order of Peter Fronsee Jr; and that I have complied with all applicable requirements of Wisconsin Administrative code S A-E 5 01.

RECEIVED & FILED # B1173
Oneida County Surveyor's Office
Date JAN 30 1986
By M.J.H.
OCS Area #

RECEIVED & FILED # C5354
Oneida County Surveyor's Office
Date 14 Oct '80
By D. M. Wenat
OCS Area # 16-4-3609

Drawn by Jim Kasson