

Mounders Continued

Post	Course	Dist	Post	Course	Dist
21	40 E	11.00	20	72 W	13.50
22	65 E	4.00	19	48 W	6.00
23	83 E	12.00	18	80 W	2.00
24	75 E	9.00	32	20 58 1/2 W	2.91
25	84 E	6.50			
26	63 E	7.00	Lake in Sec 21 & 22		
27	41 E	7.50			
			33	50 1/2 W	11.25
24	21 E	16.00		5 1/2 E	7.25
25	9 E	9.00		20 74 E	6.50
26	11 W	22.50		20 72 E	9.82
27	6 E	13.50			
28	19 W	5.50	34	21 48 E	3.50
29	32 W	7.50		20 2 E	13.50
30	60 W	11.50		20 57 W	9.00
31	73 W	6.50		5 6 1/2 W	11.00
			33	5 16 1/2 E	15.50
32	88 W	9.50			
33	76 W	6.00	Sugar C. Lake Sec. 31		
34	82 W	9.00			
35	15 W	10.00	35	20 35 W	6.00
36	20 W	10.00		5 58 W	3.50
37	25 W	5.50	36	20 78 W	3.41
38	25 W	9.00	Point in Lake Sec 1		
39	27 W	20.50			
40	30 W	11.00	37	5 45 W	6.00
41	17 W	3.50	38	11 27 W	4.7
42	14 W	6.40			
26	15 W	10.50	Total	26.88	92
27	5 E	4.00			
28	25 E	11.50			
29	3 1/2 E	9.00			
30	75 E	5.50			
31	67 E	9.50			
Lake in Sec 21 & 32					
27	88 E	12.00			
28	48 E	6.00			
29	72 W	12.00			
30	75 W	12.16			
28	73 1/2 W	5.50			
29	88 W	11.50			
30	6 W	14.50			
31	33 W	9.00			
32	14 W	6.00			
Lake in Sec 29 & 32					
27	North	3.00			
28	65 W	2.50			
29	89 W	1.50			
30	12 W	11.13			
29	21 W	10.00			
30	67 W	8.50			
31	4 E	11.00			
32	56 E	15.00			
27	20 1/2 E	25.00			
Lake in Sec 25					
31	6 E	24.00			
32	6 E	16.75			
33	32 W	16.50			

at the above  
Mounders

W.C. P. Co.  
Feb 1 '92  
July 29 '92

B. Smith