

Sec 25 T 36 N R 11 E

CHAINS	H. LAWRENCE } Nov. 12 S.P. MARKS } J.P. NEHLIS } 1954	CHAINS	H. LAWRENCE } DEC. 8 S.P. MARKS } A.W. ARBUTT } 1954
<u>SOUTH 1/2</u>	LINE BETWEEN SEC. 25 AND 26. FROM B.F. DORR'S 1/4 COR. BETWEEN SECS. 25 AND 26 WHICH WAS SET BY HIM IN 1899. STAMPS OF DORR'S TAMARACK B.T.S ARE HERE, MARKS O.K. VIZ: TAM. 20" S 57° W 26 IKs AND A TAM. 16" N 40° W 18 IKs. ALSO OLD POST FOUND. I SET NEW 6" CEDAR POST IN OLD POST HOLE AND MADE N.B.T.S VIZ: (CEDAR 8" S 41 1/2° W 30 IKs.) & (CEDAR 14" N 30° E 39 IKs.) I RUN SOUTH 2° 30' W MAG. FROM 1/4 COR.	<u>WEST 1/2</u>	LINE BETWEEN SEC 25 AND 36 FROM CORNER OF SEC. 25-26-35 AND 36 I OBSERVED THE FOLLOWING BEARINGS. VIZ:- 4" Sec Line Road bet 25-36 bears S 86° 00' W. 4" " " " 35+36 " S 2° 30' W. NORTH EDGE OF CLEARING ON NW/4 SEC. 36 BORN N 89° 00' E TO AVOID THE STONES, BRUSH AND OTHER BEDS ALONG THE NORTH BORDER OF CLEARING I RUN N 86° 00' THEREBY KEEPING MY RANDOM LINE ON CONSOLIDATED OWNERSHIP. I am North of and in line with EAST BORDER OF FIELD. I am " " NW COR. of Field Pine Plantation here at which Point The 1/4 Corner between 25-36 is 240 chs SOUTH of R/A. THIS 1/4 COR. WAS SET BY DORR IN 1906. DORR'S DISTANCE THIS 1/2 MILE WAS 4412 CHS DORR MADE B.T.S VIZ: HORWAY PINE STP. 12" S 15° W 24 1/2 IKs AND A NEW PINE 10" N 23° W 15 IKs. ON JUNE 6-1946 I FOUND BOTH OF THESE BURNED & FIRE SCARRED BUT FACING AND B.T. NOTCHES O.K. AT THAT TIME I SET DRY W. PINE POST 6" DIAM. FROM THOSE BEARINGS. AS OF DEC. 8TH 1954 I FOUND MY 1/4 POST ROTTED OFF AT GROUND LEVEL. I DUG OUT OLD POINT AND SET A NEW 4" TAM. POST IN SAME HOLE. THE HORWAY PINE STUMP CAN STILL BE IDENTIFIED BUT THE OTHER IS ROTTED TOO ENTIRELY TO RETAIN ANY IDENTIFYING MARKS. AS THERE ARE ONLY ASPEN TREES AND BURNED AND ROTTED PINE STUMPS SURROUNDING 1/4 COR. I DID NOT MAKE ANY B.T.S. AS THE POST WILL OUTLAST THE ASPEN. AT 20.59 chs. I R/A SOUTH 1.20 CHS AND SET NEW 4" TAM. POST FOR W 1/6 COR. (NO B.T.S. HERE EITHER.)
2.25	I SET LOCATION POST AND PASTER IN LINE WITH HI LINE POLES	8.00	
2.88	4" of U.S. Highway " 8.	21.00	
6.50	Leave Slip Jaw Ridge E. & W.	41.18	
15.00	enter west margin of small circular muskeg marsh.		
17.00	leave " " " " " " " " " " " "		
23.00	enter Spruce Muskeg bottom with adms		
33.50	run East and West fence line & enter open field.		
36.46	Intersect North Shoulder of Sec Line Road between Sec. 26 and 35 FROM WHICH POINT THE CORNER OF 26/35 IS 74 IKs EAST AT R/A. THIS CORNER IS DESCRIBED IN DETAIL AT SW COR. OF PLAT (ALSO see Line bet 26+35.) DORR'S NOTES CALLS FOR 36.36 FOR THIS 1/2 MILE. LOOKED FOR DORR'S S 1/6 COR. AT 18.18 AND 37 LINKS EAST HE CALLS FOR STONE IN PLACE ALSO TAM. 7" S 23 1/2° E 4 1/2 IKs. COULD NOT FIND ANY EVIDENCE OF TAMARACK TREE, OR STUMP, SEVERAL OUT CROP Boulders HERE BUT NO CROSS OR MARKS ON THEM, ALSO NUMEROUS ROTTED & BURNED WHITE PINE STUMPS. (DORR'S STONE MIGHT HAVE BEEN BURIED) I SET A 4" TAM. POST FOR S 1/6 COR. 37 IKs EAST OF 18.23 CHS. AT R/A AND MADE B.T.S VIZ: W. Birch 7" S 86° W 32" W. Pine Sp 18" S 30° E 63 1/2" (.74 - 36.46 = .0202) .0202 = 1° 10' DEFL. Δ S 2° 30' W - 1° 10' = S 1° 20' W. MAG. TRUE LINE.		
<u>NORTH 1/2</u>	FROM 1/4 COR. BETWEEN SEC 25 & 26 I RUN N 1° 20' E. MAG.	<u>EAST 1/2</u>	NOT RUN. 12/8/54
18.20	DORR'S N 1/6 COR. IS 13 IKs. WEST AT R/A DORR'S TAM. 13" S 17° W 17 IKs IS A STANDING STUB MARKS O.K. GRUBBED AROUND FOR DORR'S POST OR POINT OF SAME BUT FOUND NOTHING. I SET NEW 5" CEDAR POST FROM DORR'S TAMARACK B.T. AND MARKED A CEDAR 10" N 54° E 25 IKs B.T. CONTINUED MY RANDOM LINE NO CHANGE IN COURSE.		
29.48	A LOG ROAD IN SLIP COURSE NW & SE		
36.40	AN OLD POST FOR COR. TO 23-24-25 AND 26 IS 33 IKs WEST AT R/A. NO BEARING TREES OBSERVED HERE I SET NEW 5" CEDAR POST IN OLD POST HOLE. NO TREES SUITABLE FOR B.T.S. THIS 1/2 MILE IS ALL THROUGH SWAMP (.33 - 36.40 = .009) .009 = 0° 36' DEFL. Δ N 1° 20' E - 0° 36' = N 0° 50' E TRUE LINE.		