	s 20	1 6 2	S-498 Q-		is corner.	ereon; and tha a new monum nereon to perj	sections 17 p 36 East Fourth	of April 1979, I found evidence of the W 1/16
1	<u> </u>	<u> </u>	N.O.P	₩.	Secretary of the secret	nce ies nal	nge an,	hud

O = Corner monument restored.

Ву.....

(Register of Deeds)

......Deputy

## CERTIFIED LAND CORNER RESTORATION

Index No. N-6

History of original corner establishment:

Corner established by N. Loftus, Ripco Surveyor, in 1958. Ran line east from section corner 17, 18, 21 and 20, 84.93 chains to close out 1.21 chains north of section corner 16, 17, 20, 21. Corrected bearing 8 89 11' E. Set W 1/16 at 21.2325 chains. Marked NBT's -

Hemlock 10" S24°W 26½ links Cedar 8" N12°W 92 links

certify that on the 20th day

Philip T. Hansen , do hereby

County of.....

Oneida

šs.

State of Wisconsin

Description of corner evidence found:

Recovered Ripco's 3/4" iron pipe with 3" square brass cap in good condition. Recovered OBT's - Cedar 8" (10") N12°W 92 links, scribed W 1/16 Sec. 17 BT. Hemlock 10" (11") S24°W 25.5 links (27.0 links)

Monument projects 24", cap stamped:

W  $1/16 \frac{$17}{$20}$ 

RIFCO

Description of monument and accessories I established to perpetuate the original location of this corner.

Monument left in place as recovered.

Marked NBT - Maple 6" N88°E 46.6 links, scribed 1/16 BT.