びと OURN'S AND 18E SURVEY 79 07

O = Corner monument restored.

By.

.Deputy

l

## CERTIFIED LAND CORNER RESTORATION

Index No. G-25

History of original corner establishment:

State of Wisconsin

Original Corner established by H.C. Fellows, Deputy Surveyor, in 1860, from which Red Oak 8" bears S32°E, 8 links and Red Oak 9" bears N 87° W, 14 links. corner at 40.52 chains, 2.15 chains west.
Marked NBTs - Maple 4" NI3°E, 30½ links.
Oak 4" S20°E, 47 links. corner section 12 and at 81.24 closed out 4.23 chains east of Section Corner. Set 1/4 Corner re-established by Ripco surveyors in 1960. Ran a random line NO 30 E from SE

Description of corner evidence found:

Recovered 1-3/4" iron pipe with 3" square brass cap in excellent condition and set firmly

370

Monument projects 24" above ground Recovered OBTs - Maple 4" (5") NI30

in ground.

Cap stamped:  $\mathbb{E} (N18^{\circ}\mathbb{E})$  30.5 links, scribed 1/4 BT.  $(S16^{\circ}\mathbb{E})$  47.0 links.

NBTs - Maple 7" N72°W, 11.5 links, scribed 1/4 BT.
Oak 7" N22°W, 19.5 links, scribed 1/4 BT. As monument was recovered in excellent condition, it was left as found. Description of monument and accessories I established to perpetuate the original location of this corner.

Lone Verage Kuchn
at 20° o'clock M.

₹0°¦25