


MAP # C1195
 DATE FILED DEC. 01 1995
 BY *JB*
 DESCRIPTION FILED
 ONEIDA CO. SURVEYOR'S OFFICE

W.C.D. Brass Cap
 5" Oak
 5 66" W, 26 5'



Meander Corner

12" N Pine
 S 60° E, 4 6'



bearings solar

0" iron pipe

MUSKELLUNGE LAKE

-22-
 10.2 Acres

Muskellunge

Highland

MUSKELLUNGE LAKE HIGHLANDS

Part of

GOV'T. LOT 6
 SECTION 10
 T38N, R8E

Oneida County, Wis.

October 2, 1995


Recovered, verified, and marked monuments at the corners of Lot 6 as follows.

- = Iron monument found in place and marked with flagged lath stake.
- /// = lot lines marked approximately with fluorescent surveyor's flagging ribbon; steel fenceposts set on both side lot lines from town road to lake.

This survey was completed for the purpose of locating existing lot corners and flagging approximate property lines by the order of the Richard Rappi, who has executed a written waiver for all other requirements of Wis. Adm. Code Chap. A-E 7.

This survey does not comply with the following requirements of Wisconsin Administrative Code Chapter A-E 7.

- 1) The surveyor did not acquire or analyze data necessary to retrace record title boundaries to determine the boundaries of the parcel surveyed.
- 2) The surveyor did not make a field survey traversing and connecting monuments necessary for location of the parcel and coordinate the facts of the survey with the analysis, and did not set monuments marking the corners of the parcel where monuments did not already exist.
- 3) The surveyor did not prepare a new legal description or a new map of the parcel surveyed referenced as provided in Section 89.01 of Wis. Statutes.
- 4) The surveyor did not make a new determination of the lengths and bearings of the boundaries of the parcel surveyed. The lengths and bearings shown herein are from previous surveys and recorded documents.
- 5) The minimum accuracy of linear measurements between points is not 1 part in 3000. A closed traverse connecting the monuments was not made. Bearings and angles may not be shown to the nearest 30 seconds, and distances may not be shown to the nearest 0.01 foot. Accuracy of measurements to confirm the monuments recovered and set any approximate corner markings is 1 part in 100 and plus or minus 2 degrees.



Scale 1"=100'

July, 1966

Revised May, 1967

Northwoods Surveyors

Land Surveyor

Revised May, 1974 (Added #22)

Land Surveyor

Meander Corner
 12" Maple
 S 88° E, 1 4'
 11" W Pine
 S 17° E, 5 6'