

L1718

L1718

# ADDENDUM

to existing information for the

South quarter corner of Section 10, T. 35 N., R. 11 E.  
Oneida County, Wisconsin.

A Certified Land Corner Restoration form was prepared by Philip T. Hanson, RLS-498, on November 29, 1976 and was filed in the Oneida County Register of Deeds office on December 7, 1976.

On 11/13/96, I visited the corner and found the corner monument as described on the above mentioned Corner Restoration form. For maintenance to the corner I added aluminum nails to the right side of:


- Existing BT'S:
  - Cedar, 15", N27°W, 35.91 feet
    - Added BT sign to this tree.
  - Cedar, 13", N39°W, 64.05 feet
  - Spruce, 12", S74°W, 36.94 feet
- New BT:
  - Spruce, 4", S47°E, 23.20 feet
    - Placed BT sign on this tree.

Painted all trees blue.


I set a white vinyl sign post, 1.2' north of the corner monument.

I certify that this information is correct to the best of my knowledge and belief.

January 14, 1997



David E. Tlusty, RLS-1390



MAP #	<b>L1718</b>
DATE FILED	<b>MAY 12 2000</b>
BY	.....
DESCRIPTION FILED	.....
ONEIDA CO. SURVEYOR'S OFFICE	

L1718