

Lost Corners Found or Relocated

T 37 N R 8 E

Section 35  
SW & SE  
SEC COR  
& SOUTH ME.

Southeast Section Corner. Falls on the centerline of Township 47 & R. I ran the south line of this section beginning at the southwest corner which is north of Hwy 4 (maybe GLO) Found a GLO M.C. on the West side of Town Line Lake, an iron pipe for M.C. on the East side of the lake, and an iron survey marker in a small swamp for the East 1/2 corner on the south line. Extended this south line Eastward, using available notes and the section corner falls on the centerline of 47 & R. No marker in road; Ivar Asberg survey tied into section corner.

W 1/4 COR

About 1350 feet west of Road Corner. Follow Line Fence. I believe it is marked with an angle iron corner, is East of Four Mile Creek. Carl Walk told me about this corner. His father homesteaded that land about 100 years ago.

NE Sec Corner

It sits in a swamp about 100 yards East of the Town Road. I set that corner about 25 years ago and it checks with Dorrs notes. I think I set a 2 inch iron pipe. No B.T.s. Surveys for Mason Bourcier & Day were tied to it.

NE Sec Corner

From available notes & BT I set a 2 inch iron pipe about 25 years ago. It got washed out with rain. Surveys for Haverly, Zwickley & for Walt Smith were tied into this section corner.

By M. Postis

MAP #	L 1888
DATE FILED	AUG 2 2002
BY	
DESCRIPTION FILED	
ONEIDA CO SURVEYOR'S OFFICE	

North Corners Found or Relocated

T 37 N. R 8 E

Section 33

Northeast section corner set by Cut O. It is just a 2 inch iron pipe. No BT's. Corner set in a hollow Northwest of the junction of Velveth Lake Road and Flannery Lake Road

M.C. on East side of Lake was an iron pipe no BT's. G.L.D. did a quite a bit of work in this area to correct or errors in original survey.

South West  $\frac{1}{4}$  corner

Set by F.W. Wamontsen. Corner is set southwest of the junction of Hwy. K. and Rifle Road

Section 34

I subdivided this section. Found section corners East & West  $\frac{1}{4}$  corners. The original survey of section 34 was fraudulent as it did not even show the lake. The North  $\frac{1}{4}$  corner falls on a bog at the Northwest of the lake. Frosty Wamontsen subdivided this section but he had an error of about 50 feet between the NW section corner and his given distance to the West shore of the lake. Ivan Braden also subdivided this section and our results were quite close.

Section 29

I believe the Northeast section corner of section 29 is the original location. I found Boris M.C. on the south shore Sherry Lake.

Section 27

Northwest corner in place. Southwest mentioned for Section 33 above. Southeast mentioned for section 35. Northeast corner within intersection of town roads by Frosty Wamontsen. Taylor & Dear did not agree on North  $\frac{1}{4}$  corner. West  $\frac{1}{4}$  corner. I erred when I set the first corner. Correct corner is set about 4 feet South (Walter Wamontsen).

Signed by M. Parker

## Govt Corners Found or Relocated.

T. 37 N, R 8 E

Section 27  
Continued

I set a railroad spike <sup>or steel rod</sup> in the town road for the East  $\frac{1}{4}$  corner. Used Dorr's and Hall's notes. Found a post hole East of the road that Dorr used as one B.T. No question about accuracy.

Section 26

West <sup>section and  $\frac{1}{4}$  corner</sup> corner common to sections 27 & 35. The Northeast section, I believe is a good corner and well accepted.

The North  $\frac{1}{4}$  corner is set East of Hwy 47 & I don't question the East  $\frac{1}{4}$  corner.

Section 22

I'd curved the interior of Section 22 like the plough.

Section 21

Southeast section corner, common to sections 28 & <sup>27</sup> ~~26~~. Northeast section corner set by Treaty Meniscation South of Hwy 47 at junction with Upper Dore. <sup>Treaty did considerable work on this area.</sup>

Section 15

North  $\frac{1}{4}$  corner perpetuated by County Surveyor H.C. on North side, East of river marked with  $\frac{1}{2}$  inch iron pipe &  $\frac{1}{2}$  inch rod. Since it is on the river bank near the channel, I believe it is good since it has been there for 30 years or far more. The Northeast section corner could be quite easily relocated from Dorr's Notes and there are existing  $\frac{1}{4}$  corners to the East and West of said section corner. <sup>The South  $\frac{1}{4}$  corner was in</sup> before Hwy 47 was relocated.

Section 9

The Southwest section corner was in place marked with iron pipe and one or both of Dorr's B.T.s existing about 40 years ago. As I recall it was East of Hwy 47 and the B.T.s were Norway Pine.

Sy. M. Poshic

## Good Corners Found or Relocated.

T. 37 N, R. 9 E,

Section 7

I perpetuated the Southeast section corner. The Northwest & Southwest <sup>section</sup> corners are in, as is the West  $\frac{1}{4}$  corner, Good Corners, work by Dorr and Maine. The East  $\frac{1}{4}$  corner is in question but Frosty Minicature corner set about in the early 1950s has been accepted. I intend to try and relocate Frosty's Northeast section corner and possibly Ivan Brankham's N  $\frac{1}{4}$  corner. There is a wood post marking Ivan Brankham's South  $\frac{1}{4}$  corner, which he believes is the location of the original and Dorr's corner.

By M. Poche