


SEC. 10 T. 39 N. R. 1 E.

① N¹/₄ NE¹/₄ at 20.685 set # 1 I.P. ^{L614}

Painted red for 7/8 Cor. New B.T. BW 12"
S19°E - 0.523 ; OR 14" - S53°W - 0.466 ch

(Jly 1972)



② N¹/₄ Sec 10 at 41.364 set D.N.R. pipe. for new 1/4 Cor. New B.T.
PN 10" - S61°E - 0.595 ch. ; BW 9" - S16°E - 0.151 ch. ; OR 10" -
N73°W - 0.190 ch. (Jly 1972)

③ N¹/₄ NW¹/₄ at 20.685 set 3/4" I.P. painted red for 7/8 Cor. New B.T.
BW 10" - S45°W - 0.211 ch. ; OR 16" - N89°E - 0.166 ch

RECEIVED & FILED
Okla County Surveyor's Office
Date 1/5/88
M.R.
Cor Area #.....

④ NW cor. Sec 10 Replaced Vaughns iron pipe with
DNR. pipe. Vaughns B.T. still living, is PW 20" - S58°W - 0.642 ch.
(Chopped open for & found scrubby). Vaughn said this corner was orig. New B.T.
PW 9" - S76°W - 0.253 ch.; MR 8" - N01°W - 0.406 ch. (Pg 6/72)

⑤ W¹/₄ NW¹/₄

SET 1" I.P. OR 10" - N20°E - 20.0', MR 4" - S85°W - 33.5'
(SEYMOUR, OBADAL, FREUND, 1976)

⑥ W¹/₄ Sec 10 Corner by Genesee Co. (Pg 6/72) 1 1/2" Iron pipe (B.T. 17' deep 54ft, 22.9')

⑦ W¹/₄ SW¹/₄

SET 1" IRON PIPE PN 10" - N56°W - 29.2', PN 10" - S58°W - 32.2',
ERRON. IP BY ? - S56°E - 4.1' (SEYMOUR, FREUND, OBADAL 1976)