


L 685

SEC. 4 T 38 N. R. 18 E

conduct
lake



By Montgomery & Co. Surveyors
 (orig. cor.)
 RECEIVED & FILED # 1944
 Oneida County Surveyor's Office
 Date 6 8 54
 Area


① N. 1/4 Cor. set a 1 1/2" I.P. brass cap 1. P. right against Harry Hall's 4 1/2" I.P. corner. 2 orig. B.T. stumps. New B.T. = OR 9" S 2° E 46 1/4 LK. Sharp notch on top of 2 ft. boulder N 82° E - 19 LK.

② N 1/8 of NE 1/4 Sec. 1 1/2" I.P. B.T. 12" PN - N 43° W - 57.2 LK. B.T. 5" BW - S 8° W - 76.4 LK. }
 Hilly here. meas level on at MEASURED CORNERS

L 685

L 685

SEC. 4 T. 38 N. R. 8 W.



① N¹/₄ NE¹/₄ at 19.989 set 1 ^{1.0 0.0 0.0} iron pipe
for 1/8 cor. PN12" - N43°W - 0.572 ch.,
BW5" - S08°W - 0.764 ch. (Cg 64)

Found by Lopp 1976

② N¹/₄ Sec 4 Found OBT. PN18" - N33°W - 11 ch & PN16" - S33°E - 41
in good condition. Set W.C.P. pipe west & next to 4" pipe which
is in covered place. New B.T. OR9" - S2°E - 0.462 ch.; sharp notch on top
of 2' Boulder - N82°E - 19' (Bernolt 10/31/63) found by Lopp 1976

③ MC (east shore Woodcock Lake) Found OBT^s, stp P4 11" N71°E 25.1', stp P4 12" S14°W 8.6',
New BT PN 16" S2°W 12.2', Northwoods BT 22" Pw N65°E, 21.3' Location of MC ^{set from OBT distances} is in water so no
monument set. Instead set Witness Corner (2" W.P. w/ brass caps) 20.0' east of M.C. BT^s to
Wit Cor. are Ow 9" N80°E 9.65' and Ow 11" S20°W 28.5' (Lopp, Keyman, Gehrig 6-76)