

L703

3-7-55

N.J.L.

L703

Random North from  $N 5^{\circ} 15' W$   $\frac{24/19}{25/30}$  Bearing

$NTC = 0226$   
 $\delta = 1^{\circ} 16'$

76.98 ch fell 1.74 ch West of cor  $\frac{13/18}{24/19}$

Correct Bearing  $N 3^{\circ} 57' W$

18.46 ch set  $S \frac{1}{16} E$   $443$  ch E of random.

BTs sb  $3\frac{1}{2}$   $N 5^{\circ} E$  54 lks

sb 6  $N 75^{\circ} W$  92 lks

36.92 set  $W \frac{1}{4}$  .886 ch east of random  
Iron Pipe Brass Cap.

BTs Ms 5  $N 63^{\circ} E$  15 lks

Fb 6  $S 37^{\circ} W$   $22\frac{1}{2}$  lks

56.95 ch set  $N \frac{1}{16}$  on west line 1.29 ch E  
of random

BT sb 3  $N 70^{\circ} E$  31 lks.

sb 2  $S 60^{\circ} W$  24 lks.

Blazed true line to  $N \frac{1}{16}$  corner.

Some one had run a random  
northerly previous to our survey and set  
wooden posts - (no scribing or BTs) at approx  
20 40 & 60 chs.

Had he run the line through to the  
NW section corner he would have found  
his corners were East and North of  
where they are supposed to be. He also  
ran a line west from his North  $\frac{1}{16}$ .  
There has been some trespass of Aspen  
and Pine along the line.

Dorr had 40.06 from the  $W \frac{1}{4}$  south to  
the section corner. I could not find his  $\frac{1}{4}$  corner.

RECEIVED & FILED #14770.3
By
Area #
Date 9-10-1988
File No.
.....
.....
.....
.....
.....
.....
.....
.....

L703