


SEC...6...T.39...N, R.9...E
W.



① N¹/₄NE¹/₄ at 20.60 set ¹/₈ cor. PW 8"-
N 58°W - 13 ch; PW 8"-N 73°E - 25 ch
(Vaughn 4/27/14) at 20.574 set ³/₄" iron
pipe below road surface. Vaughns BT taken out
by road but a fence running north from road is
within 1 1/2 feet of our point. New BT. PW 11"-
S 42°W - 0.473 ch. (Coff & Berra 5/13/59)

Found ³/₄" ip. Seymour 3/9/82 18' S of road

② N¹/₄ Sec 6 at 41.20 west of SE cor. fell 1.23 north of ¹/₄ post. ~~off~~
of both O.B.T. (Vaughn 4/27/14) set a RR spike below road surface, west
edge of N/S road, by projecting Vaughns distance & ogl distance against ours.
From this point there is a pure stp. corner for bearing, distance & diameter
(without marks) for O.B.T. N 67°E - 1.06 ch. Other O.B.T. taken out by road.
There is another bolt in road surface 23± link east of ours but no stps
set out to it for O.B.T. New B.T. PN 10"-N 45°W - 1.509 ch.; PN 15"-
S 59°E - 1.358 ch. (Coff & Berra 5/13/59) set 1" IP below road surface using
BT. which are still O.K. (John Grohn 7/7/1)

See corner file

L756

RECEIVED & FILED **L756**
Onanda County Surveyor's Office
Date **APR 22 1988**
By
OCS Area #

③ N¹/₄ NW¹/₄ at 19.998 west of ¹/₄ Cor. & 18.879 east of
NW Cor. set iron pipe below road surface. PJ 7" - N1°W - 0.459 ch.
(Coffey & Burren 5/13/59) found i-p. & PJ 12" N1°W ^{Reynolds} 3/9/82

④ NW Cor. Sec. 6 at 38.12 west of N¹/₄ Cor. fell 24 ch north of cor. to
post from NW O.B.T., a 7' stb.; NE O.B.T. is OK. (Vaughn 4/27/14)
at 38.077 west found iron pipe below road surface from which two
possible O.B.T. bear N77°W - 1.93 ch. (org N71°W - 1.76); S 64°W - 1.58 ch.
(org S 68°W - 1.54 ch) Other B.T. present are PJ 10" (dead) N73°E -
0.604 ch.; PJ 14" - S15°W - 0.458 ch. New B.T. PJ 12" - N40°E 1.022 ch.
(Coffey & Burren 4/27/59) see corner file

⑤ W¹/₄ 6 see corner file

⑥ W¹/₄ SW¹/₄ found 1¹/₄" i-p., no BT^s, on 9/13/84 made 2 new BT^s PJ 12" S32°W 23-40'
PW 8" N71°E 9-30' ^{Reynolds} _{excuse}