


1 N¹/₄ NE¹/₄ Found 2" i.p. (Inman) is 10' off on distance, left in place as is because of surveys poss. made from it.
 New BT's made PW 14" S 26° E 7.90'
 PN 16" N 77° W 12.85'
 Seymour 4/30/82



2 N¹/₄ See corner file

3 N¹/₄ NW ¹/₄ Reset 1" i.p. as it was taken out by WPS on power line.
 Oak 17" N 30° W 38.9' (ctr) Oak 14" S 30° W 48.8' (ctr)
 Seymour 4/2/82

4 NW cor. WCD cap H 25" S 29° W 20.5'; H 28" N 88° W 35.7'; M 7" N 55° E 79.4' (Eri = m' 82)
 See corner file

RECEIVED & FILED #
Oneida County Surveyor's Office	
Date	APR 22 1988
By
OCS Area #

5 W¹/₄ NW ¹/₄ Set 1" i.p., south of creek, west of snow trail.
 BT's OR 10" S 7° E 26.95', OR 14" S 75° W 21.98'
 Seymour 7/26/84

37787

NO

⑥ W/4 25
See corner file

⑦ NMC (with)
See corner file

⑧ SMC See corner file