


SEC. 34 T. 39 N. R. 7 W



- ① NW Cor 34 W.C.D. Brass Cap
 BT^s (old) B.W. 12" S65°E 18.70'
 (NEW) P.W. 7" S40°E 40.10'
 B.W. 14" S50°W 33.30'
 See Corner file ASP. 12" N30°W 25.75'
 ASP. 10" N52°E 14.95'
 Scribed stp. N48°W 45.40'
 60 P.W. stp. N56°W 44.0 (Fisher 72)

- ② MC
 P.N.P. S11°W 13.1' (Griffin 1966)
 See Corner file

(Visser, 1979)

- ③ N¹/₂ NE¹/₄
 M.P. S73°E 12.7'; 0 12" S34°W 13.9'
 Found 3/4" i.p. south of rd. jct. with both BT^s, Seymour 12/15/82

- 4 N¹/₄ 34 See Corner file

RECEIVED & FILED #	1781
Florida County Surveyors' Office	
Date	APR 22 1988
By	S. J.
OCS Area #	

- 5 N¹/₄ NW¹/₄ Set 1" i.p. (north of rd.) BT^s BW 8" N 78°W 11.95', BW 10" N42°E 17.70'
 Seymour 6/21/84

1981

W - SW -

Found 1/2" WCO pipe 24.7' N 116° E 15.4' (24.7-73)

found 1/2" red New BT³ BW 10" N 65° W 24.87, MH 12" N 12° E 12.13'
Seymour 9/8/82

② 1/2" WCO pipe


0.6" N 20° E 13.1'; Chasing 7" S 50° W 9.0'; Nail in Post S 33° 26' W 153.5'

See Corner file

⑧ W 1/4 SW 1/4 Sound T-p. for pass cor. Seymour 9-8-82

SEC. 34 T. 39 N. R. 7 W

L781



- ① NW Cor 34 W.C.D. Brass Cap
 BT^s (old) B.W. 12" S65°E 18.70'
 (NEW) P.W. 7" S40°E 40.10'
 B.W. 14" S50°W 33.30'
 Asp. 12" N30°W 25.75'
 Asp. 10" N52°E 14.95'
 Scribed stp. N48°W 45.40'
 60' P.W. stp. N52°W 44.0 (Fish 672)

- ② MC
 PN 8" S11W 13.1' (Griffin 1966)
 See Corner file

(Visser, 1979)

- ③ N¹/₄ NE¹/₄
 ME 8" S73°E 12.7'; 0 12" S34W 13.9'
 found 3/4" i.p. south of rd jct. with both BT^s, Seymour 12/15/82

- 4 N¹/₄ 34 See Corner file

- 5 N¹/₄ NW¹/₄ Set 1" i.p. (north of rd.) BT^s BW 8" N 78°W 11.95'; BW 10" N42°E 17.70'
 Seymour 6/21/84

⑥ W 1/4 NW 1/4
found 2 red New BT's BW 10" NOS 24.87, MH. 12" N 12° E 12.13'
Seymour 9/8/82

⑦ NW 1/4 NW 1/4
found 2 red New BT's BW 10" NOS 24.87, MH. 12" N 12° E 12.13'
Seymour 9/8/82

⑧ W 1/4 SW 1/4 found 2 red New BT's BW 10" NOS 24.87, MH. 12" N 12° E 12.13'
Seymour 9-8-82