

January 15, 1979

Sec. 29 T36N, R7E

Meander corner on west line of Section 29 on south shore of Virgin Lake,
2" brass capped iron pipe found in place
No bearing trees.

Sec. 5, T36N, R10E

West 1/4

1-1/4" iron pipe found in place
17" Maple N84°E, 2.5 feet
White Birch Stump S31°W, 14.4 feet
22" White Pine N19°E, 33.6 feet

Meander corner

1470 feet ± on west line Section 5
(near southerly bank of the North Branch Pelican River)
2" iron pipe found in place
4" White Pine S21°E, 21.7 feet
5" Tamarack S5°W, 32.3 feet

Sec. 27, T37N, R6E

NE Section Corner

Set R.R. by crossing bearing trees

Nail in 15" White Pine N77°E, 40.9 feet
Nail in 9" Norway Pine S30°E, 62.0 feet
E 1/4

Set

R.R. spike

8" Norway Pine S60°E, 43.8 feet
8" Norway Pine N68°E, 47.7 feet

SE Section corner

Found old post hole & C.I. tag on corner fence post - blazed line west

Set 2" Iron pipe and wooden post.

10" White Birch N58°E, 8.3 feet
14" Norway Pine N84°E, 16.0 feet

Sec. 16, T37N, R7E

SW Section corner

2" iron pipe with brass cap found in place
No bearing trees

Sec. 19, T37N, R7E

NW Section Corner

1-1/2" iron pipe found in place
no bearing trees

Sec. 19, T37N, R7E

West 1/4 corner

2" iron pipe set
6" White Birch N54°E, 6.60 feet
5" White Birch N13°E, 29.40 feet

Sec. 25, T37N, R8E

South 1/4 corner

1-1/4" iron pipe found in place
10" Norway Pine S52°W, 37.5 feet
6" Norway Pine N34°W, 40.6 feet

Sec. 25, T37N, R8E

NE Section Corner

1-1/2" iron pipe found in place
Old Pine stump S24°E, 36.4 feet
New: 12" Norway Pine S84°W, 20.00 feet
6" Oak S60°W, 38.2 feet
Tamarack post

Sec. 25, T37N, R8E

L8374

Jeff Austin sent these to me. He did not know who did these. mgr.

RECEIVED & FILED #	18871
Oneida County Surveyor's Office	
Date	MAY 27 1988
By	M. Q. S.
OCS Area #	

L8371

Meander corner on east line of Section 25 on North shore of Boom Lake.

1-1/4" iron pipe found in place
20" Norway Pine S80°E, 12.9 feet
5" Oak S72°W, 4.0 feet

Sec. 25, T37N, R8E

West 1/4 corner

1" iron pipe and scribed Oak Post found in place
14" White Pine S45°W, 36.2 feet

Sec. 25, T37N, R8E

North 1/4 corner

2" iron pipe found in place
Nail in a 12" Jack Pine S21°34'E, 166.70 feet

Sec. 36, T37N, R8E

East 1/4 corner

1-1/2" iron pipe 6" from north edge of Black top, found in place

Sec. 27, T38N, R5E

North 1/4 corner

W.C.D. Brass cap found in place
8" White Birch S76°W, 31.3 feet
8" White Birch S24°E, 38.1 feet

Sec. 27, T38N, R5E

East 1/4 corner

1" iron pipe and scribed post found in place
4" Spruce W/Metal tag S32°W, 41.0 feet
10" White Pine N82°E, 53.40 feet

Sec. 27 T38N, R5E

South 1/4 corner

2" iron pipe and scribed post found in place
32" White Pine (orig.) S72°E, 9.4 feet
6 6" Balsam (dead) S12°W, 18.9 feet
10" White Pine N66°W, 20.00 feet
18" Norway Pine N78°E, 21.8 feet

Sec. 27, T38N, R5E

West 1/4 corner

Found hole from previous corner reset 2" iron pipe
O-I scribed post
P.K. in large rock S1°W, 7.43 feet

Sec. 1, T38N, R6E

Southwest corner

1" iron pipe and post by Kowalke
8" Oak N78°E, 16.9 feet
10" Oak S75°E, 26.3 feet
9" Oak S8°W, 30.1 feet

SE Section corner

2" iron pipe found in place
8" Oak N42°W, 19.2 feet
14" Poplar S38°W, 22.4 feet
13" White Pine S25°W, 27.6 feet

Meander corner - east line section 1, southerly shore Tomahawk

1" iron pipe & post found in place
6" Oak S75°E, 26.2 feet
6" Oak S12°E, 20.0 feet

Meander corner - west line section 1, sly shore Tomahawk Lake
old post baddly rotted

####*1*

Sec. 12 T33N, R6E

West 1/4 corner

Crimped 1" iron pipe and scribed post found in place
 12" Norway Pine S74°W, 32.0 feet
 14" Norway Pine N38°, 40.3 feet
 Meander corner on west line of section 12 on the south shore of
 Miller Lake
 1" iron pipe found in place
 no bearing trees

Sec. 28, T38N, R6E

South 1/4 corner
 1" iron pipe and Cedar post found in place
 10" Tamarack N40°E, 8.5 feet
 11" Tamarack S38°E, 11.3 feet

Sec. 3, T38N, R7E

Southeast section corner
 Oneida Co. brass cap on 2" iron pipe found in place
 8" Maple (dead) S30°W, 8.1 feet
 8" White Birch S86°E, 10.5 feet
 16" Pine stump N42°E, 18.0 feet

Sec. 9 T38N, R7E

South 1/4
 1-1/2" G.L.O. cap found in place
 18" Norway Pine S3°E, 20.7 feet
 16" Norway Pine N64°E, 23.7 feet
 East 1/4
 R.R. spike found in place
 no bearing trees
 Southeast Section corner
 Tied to tack 0.95 south of corner per DNR information

Sec. 14, T38N, R7E

Northeast corner
 1-3/4" iron pipe and wood post found in place
 22" Norway Pine N78°W, 10.4 feet
 20" Norway Pine N82°E, 14.5 feet

Sec. 18, T38N, R8E

Southeast Section Corner
 3" iron pipe and post found in place
 14" Oak N58°W, 43.0 feet

East 1/4 corner
 2" iron pipe found in place
 12" Norway Pine N65°W, 21.8 feet
 16" Pine stump N68°W, 12.5 feet

Northeast Section corner
 1-1/2" iron pipe and cedar post found in place
 7" double Maple S48°W, 29.1 feet
 26" White Pine N68°W, 67.7 feet
 North 1/4 corner
 2" iron pipe found in place
 8" Oak N78°W, 52.7 feet
 6" Jack Pine S55°E, 25.7 feet

Northwest section corner
 W.C.D. brass cap on 2" iron pipe found in place
 7" Oak N27°W, 34.5 feet
 7" Oak S71°W, 11.3 feet

Sec. 8, T39N, R4E

East 1/4
 1" iron pipe found in place
 20" Yellow Birch N86°E, 56.3 feet
 Meander corner (south of E-1/4 on section line nwly shore
 Squaw Lake)
 2" iron pipe found in place
 White Birch stump, S85°W, 3.7 feet

Section 9, T39N, R5E

Meander corner (nly shore Squirrel Lake on section line common to sections 8 and 9)

1-1/4" iron pipe found in place

no bearing trees

Sec. 24, T39N, R5E

Northeast section corner

1-1/2" iron pipe found in place

12" Oak S58°E, 52.2

8" Oak N32°E, 59.4 feet

North 1/4

1" axle and scribed post found in place

20" White Pine N40°E, 11.3 feet

20" Norway Pine N6°E, 38.0 feet

East 1/4

1-1/2" iron pipe and post by Northwoods Surveyors

Set new Spruce post

4" Spruce S21°E, 18.5 feet

5" White Pine, N34°E, 14.5 feet

Southeast Section corner

6" X 6" concrete monument found in place

13" White Pine N34°W, 7.8 feet

nail in 16" White Pine S34°W, 23.1 feet

South 1/4

6"X6" concrete monument found in place

24" Norway Pine S10°E, 98.2 feet

17" Norway Pine N56°E, 48.3 feet

West 1/4

1-1/2" iron pipe found in place

R.R. spike in 14" Norway Pine N55°W, 118.93 feet

22" Norway Pine (cut open and painted balck) S35°W, 140.98

Northwest Section corner

1-1/2" iron pipe found in place

12" Oak S58°E, 52.2 feet

8" Oak N32°E, 59.4 feet

Sec. 2, T39N, R6E

South 1/4

2" iron pipe found in place

no bearing trees

Sec. 10, T39N, R6E

West 1/4

nail in 2" iron pipe found in place

PK nail in telephone pole S36°W, 22.3 feet

PK in 5" Jack Pine S16°W, 30.97 feet

Sec. 11, T39N, R6E

North 1/4

2" iron pipe found in place

16" White Pine N83°W, 9.8 feet

5" Maple S52°W, 31.7 feet

Sec. 11, T39N, R6E

South 1/4

1-1/2" iron pipe and 6" X 6" wooden post found in place

no bearing trees

Meander corner on south line section 11 near wly shore Minocqua Lake

1-1/2" iron pipe found in place

4" Oak N60°W, 19.2 feet

14" Oak S35°W, 37.5 feet

Sec. 12, T39N, R6E

Northeast Section corner
 1/2" iron rod found in place
 14" Jack Pine N21°W, 37.8 feet
 10" Jack Pine N11°W, 32.8 feet
 14" Jack Pine, N42°E, 47.8 feet

Sec. 21, T39N, R6E

Southeast Section corner
 2" iron pipe
 no bearing trees

Sec. 22, T39N, R6E

East 1/4
 2" iron pipe w/bronze cap found in place
 nail in 36" White Pine N68°38'E, 69.8 feet

Sec. 24, T39N, R6E

West 1/4
 6" round concrete monument found in place
 16" Norway Pine, S4°E, 38.1 feet

Sec. 25, T39N, R6E

West 1/4
 1-1/4" iron pipe and post found

Sec. 25, T39N, R6E

Meander corner on northerly line Section 25, near westerly shore
 of Tomahawl Lake.
 1" iron pipe found in place
 no bearing trees

Sec. 27, T39N, R6E

West 1/4
 2" iron pipe found on place
 9" White Pine S88°W, 10.0 feet
 12" White Pine N42°E, 3.1 feet

Northeast Section Corner
 2" iron pipe found in place
 no bearing trees

North 1/4
 Axle shaft found in place
 12" Oak S45°W, 96.8 feet

Sec. 34, T39N, R6E

Northeast Section corner
 R. R. spike ~~Set~~ over iron shaft
 PK nail in ~~power~~ pole N41°W, 31.45 feet
 1-1/2" iron pipe S57°W, 33.0 feet
 Concrete monument south 33.0 feet

Sec. 6, T39N, R7E

Northwest Section corner
 1" iron rod found in place
 14" Jack Pine N43°E, 67.4 feet
 16" Jack Pine S16°E, 30.6 feet
 W.C.D. post and metal tag north 18.5 feet

West 1/4 corner
 2" iron pipe and post found in place
 nail in 20" Norway Pine S84°W, 111.7 feet

North 1/4 corner
 1" iron pipe found in place
 14" Norway Pine N32°W, 99.5 feet
 18" Norway Pine N63°E, 89.5 feet

South 1/4 corner

R.R. spike in intersection found in place
18" Oak N50°E, 67.8 feet
10" Norway Pine N30°W, 76.1 feet

Northeast Section corner

W.C.D. brass cap found in place
26" White Pine N89°E, 9.5 feet
14" White Pine S49°E, 46.4 feet
12" Norway Pine S22°W, 32.7 feet
20" White Pine N45°E, 18.3 feet

East 1/4 corner

1-1/4" iron pipe and square post found in place
10" White Pine N48°W, 6.8 feet
12" Norway Pine stump N68°E, 6.7 feet

Southeast corner

2" iron pipe w/brass cap found in place
12" Norway Pine S82°W, 4.9 feet
8" Norway Pine N16°E, 34.1 feet

Sec. 13, T39N, R7E

Meander corner on east line of Section 13 on the south shore of Buffalo Lake.

W.C.D. brass cap on 2" iron pipe found in place
8" Norway Pine S80°W, 11.8 feet
18" Norway Pine S51°E, 12.6 feet

Sec. 29, T39N, R7E

North 1/4 corner

2" iron pipe w/scribed post found in place
no bearing trees

Sec. 33, T39N, R7E

North 1/4 corner

1-1/4" iron pipe found in place
11" White Birch N86°W, 74.7 feet
7" White Birch S54°W, 60.6 feet