

No 1

D.H. VAUGHAN #1



NOV. 7. 1895

Subdivisions of Sec 21-39-6  
commencing at SW. corner  
thence East Var 4° E. 1/4 Post  
4045 FELLE 1/4 N. of 1/4 Post  
E 1/4 Post West correctd Va 3 1/2  
East 20 22 1/4 Set 18 Post

North from 1/4 Post var 4° East  
20 Chans. Set Post That was all  
he wanted done  
O. Dawson Pass  
copied on Page 71 county Record

S  
9  
A  
A  
10  
4  
to  
2  
0  
23  
46  
at

SEC 10 37-6  
 beginning at 44 Past Bet 10+11  
 left hand by measurement from  
 right on N 5 rods of Oxlee found it  
 at 65 links  
 at 1/4 Past  
 Run west var 330 E  
 55 1/2 interest west boundary  
 27 " North of 44 Past  
 corrected var 55 E  
 E Boundary at 1/4 Past  
 Copied on Page 64 County record  
 with from 44 Past 3+10 var 330 E  
 23 interest S. boundary 264 lks  
 which is in lake  
 of 44 Past p-found meander 9 ch  
 of 44 Past Run west var 330  
 chains distance given in F N + etc  
 path corrected var 137  
 23 Interest N Boundary at Post  
 beginning at center Run south  
 53 lks 1/2 of distance to S 1/4 Past  
 bet 1/8 Past by Pine Stump 24 1/2 52 1/2 W 5 1/2  
 22 1/2 30 E 102  
 var 330 E - 40 57 interest E Boundary  
 1/2 N of 1/8 Past  
 local said Post & measured the  
 lines between meanders & found  
 a surplus of 400 lks which I passed on  
 and set 1/8 Past 53.2 lks N of South  
 meander Bet 8 10+11  
 corrected var 2 30

commencing at Meander and  
 section between 10+15-900 lks E  
 of 44 Past thence East to Meander  
 found a shortage of 18 lks + set 1/8  
 Post 1095 East a South meander  
 from 1/8 Past run North var 3030  
 46 41 lks interest E+W 1/4 line  
 149 " West of 1/8 Past  
 which had been located Equidistance  
 between E 1/4 Past + center of  
 Sec in two lines  
 connected going south var 153 E  
 2320 1/2 lks set 1/16 Post  
 46 41 intersected South boundary  
 at 1/8 Past Wednesday Dec 11/95  
 Copied on Page 64 County record

Dec 27 1895

South Between 28<sup>th</sup> & 29 - 36 - 8 - 8  
Var 5 East

7950 Intersect South Boundary 302

Links East of Post

North corner Var 347<sup>1</sup>/<sub>2</sub> East

3975 lat 1/4 Post Bench 5 S 24 W 40 lks  
Tunnel at 14 N 85 W 76 1/2

7950 See corner

West bet. 20 + 29 Var 40 E  
Dec 28 - 1895

3960. Intersect 1/4 line 15 lks North of  
Corner on Page 128 Co Range  
1/4 Post. East corner Var 40 13'

1980 lat 1/8 Post 3960 SEE corner  
South through 29 from 1/4 Post Var 40

7957 Intersect S Boundary 505 lks  
East of 1/4 Post. To locate this Post  
I found Davis Survey commencing at  
1/4 Post between 27 + 34 and found  
his established SEE corner to SSec  
28 + 29. 32 + 33 also found his  
1 1/2 mile Post 2 chains East of said  
corner and his R line 74 lks South

of said car showing a departure  
of 49 4/3 lks to 1<sup>st</sup> mile Then found his  
2 mile Post amid Set 44 Post between  
29+30 26 2/3 lks west and 98 2/3 lks  
North of said 2 mile Post  
North corrected Var 22'

1986 3/4 Set 44 Post NO bearings  
39 72 1/2 " 44 " " "  
59 60 1/4 " 44 " " "  
79 47 " 44 Post between 20<sup>th</sup> and 29  
West 20<sup>th</sup> and 29 from 44 Post Var 31° 36'

39 40 intersect West boundary 16 lks N  
of sec corner which had been located  
by Dora East corrected Var 3° 59'

1970 Set 48 Post

39 40 intersect 44 line at 44 Post  
South from sec cor to 19+20-29+30

Var 3° 45' East <sup>74.05</sup> intersect South  
Boundary 41 lks W of cor to 29+30-31+32  
There being no bearings to this corner  
and being 2 miles South to the nearest

and Maloney not being willing to  
bear the Expense Running further South  
& located Temporary corner, By connecting  
N + S with Dora E + W Random

Setting corner 123 1/3 lks north of his  
Random, and E + W By his 2 1/2 mile  
Post Setting corner west from his 2 1/2  
mile Post 332 lks + 41 East of Point  
copied on Page 128 county record  
where my Random intersected his  
North corrected Var 3° 53'

1976 1/4 lks bet 44 Post - no bearings no trees  
39 52 1/2 " " 44 " } when 5881 & 29  
" " 48 " } " 4 N 71 1/2 W 16 1/2  
39 52 1/2 " " 48 " }

East from 44 Post between 29+30  
Var 40° E

7750 intersect N + S line 188 lks N of  
44 Post. 40° should have is the  
correct Var but local attractions in  
the hills at west 44 Post caused  
the needle to change 10° 20' North

Distance from N + S 1/4 line to  
East 1/4 Post 4055 Distance from  
N + S 1/4 line to West 1/4 Post 3788  
West corrected Var  $3^{\circ}45'8$  1894

2027 1/2 Set 1/8 Post  
4055 " 1/4 " center of S.E.C.

N Pine 16 S 48 1/2 E 15  
" " 16 N 69 W 40

5948 Set 1/8 Post W Pine S E 4  
Capped on Pine 128 ca record  
7750 1/4 Post

South from West 1/8 Post on E + W  
1/4 line 3965 Intersect South boundary  
at 1/8 Post West corrected

1988 Set 1/8 Post no bearings  
West from South 1/8 Post on N + S 1/4  
line Var  $3^{\circ}45'$   
3927 intersect N + S Sec line  
20 1/2 N of 1/8 Post

East corrected Var  $3^{\circ}55'$

1963 1/2 Set 1/8 Post  
3927 1/8 Post on N + S 1/4 line

North from West 1/8 Post on E + W  
1/4 line Var  $3^{\circ}45'$   
3978 Intersect N boundary 138 1/2 W  
of 1/8 Post

South corrected Var  $1^{\circ}45'$   
1989 Set 1/8 Post 3978 1/8 Post on  
E + W 1/4 line

West from N 1/8 Post on N + S 1/4  
line <sup>Center</sup> 3879 Intersect Sec line but  
29 + 30 7 1/2 N of 1/8 Post

1942 Set 1/16 Post at the junction  
of N + S 1/8 3 1/2 1/2 N of E + W  
1/8 line { Fin 9 N 13 W 15 1/2  
Fin 9 N 15 E 13 "

East from S 1/8 Post on N + S 1/4  
line Var 3.30 E

4063 intersect Sec line set 28 + 29  
40 1/2 N of 1/8 Post

West corrected Var  $3^{\circ}38'$

2026 1/2 1/8 Post 3084 N 31 E 9  
The west 3/4 of this Sec has 4 corners

high hills and the local attractions  
affected the middle materially, and  
the a line running E from west  
side would deviate from 2° to 3°  
to the North

South from 48 Post on Sec line  
Bet 20 + 29 East of 44 Post Var 3,30  
2975 intersect E + W 44 line  
Carried on Papp 128 Co record  
16 1/2 kts East of 48 Post

West carried Var 3:27  
1987 1/2 bet 48 Post no bearings  
3975 48 Post finished work in  
This Sec January 2<sup>nd</sup> 1896

East from N 1/8 Post on Sec line  
between 28 + 29 Var 40 E  
1890 intersect Sec line bet 27 + 28  
48 kts N of N 1/8 Post  
January 2 1894

South from 44 Post Bet Sec  
33 + 34 T 36 R 8 E Var 50 E  
40 chains intersect Town line  
No corner. Still South 3100 wis  
River. No meander. Parties would  
not pay to go farther

East from same 44 Post Var 40 E  
8000 No line on 44 Post or meander.  
Carried on Papp 128 Co record  
Past N or S. 438 blue E + W River

South from 44 Post Bet 27 + 34  
Var 40 E

7970 intersect Town line 30 kts  
West of 44 Post which is Wis River  
5.50 kts West of Meander on left  
Bank of Wis River

North carried Var 3:47  
1992 1/2 bet 1/8 Post NO Bearings  
3975 " 1/4 " " " "  
5977 1/2 " 1/8 " " " "  
7970 " 1/4 Post

Carried on Town line from 44 Post on this  
" 4000 kts to Temp cor E. Var 5/8 on  
Sec line bet 33 + 34 3890 intersect 44 20 kts  
S of 1/8 Post

on S side of 33

January 12 1896

North from North meander  
Between 17+18. 39.5. E Var  $4^{\circ} E$

2031 Intersect North Boundary

31 Hks East of SEC cor Post  
corrected Var  $3^{\circ} 6'$

West from cor to Sec 7+8-17+18  
Var  $12^{\circ} E$

3.80 Meander Post

43.51 over lake found meander Post

49 Hks North of Random line

East corrected Var  $13'$  West

Distance between meander as  
given in field notes 4295  
actual distance 4346.

Proved over plus and set 114

SEC Post 5.41  $\frac{1}{13}$  Hks East of  
west meander

2092 Hks East of 114 Post set

118 Post (all in lake) which is  
Equidistant between 114 Post and

SEC corner

Whole distance between 114 Post  
and SEC 4184  $\frac{2}{3}$  Hks

BET 118 Post 2092  $\frac{1}{13}$  Hks from  
each point

South from 114 Post (in Lake)  
Between 7+18 Var  $3^{\circ} 45' E$

71.62 Intersect South boundary

23 Hks East of 114 Post

North corrected Var  $3^{\circ} 31'$  East

3581 Set Temporary Center Post

West from meander bet 18-19 -  
an Squirrel Lake Var  $2^{\circ} E$

8.63 intersect 114 line 5 Hks S of 114 Post  
corrected Var  $1^{\circ} 33'$

East from corner of 18-19-13-24  
Var  $6^{\circ} E$

This corner is in Pond. Witness  
corner 3 chains South. Run



1896

North 3 chains Van 40° E + set Post  
4296 entered 1/4 line 350° E South  
of 1/4 Post - corrected Van 630'

East from 1/4 Post on Range  
Line Bet 13 + 18 Van 232° E  
No chaining done about  
7800 chain ~~intersect~~ Squimel  
Lake + Squard on aster & in  
in dia for ~~meander~~ Post

South from <sup>(in Lake)</sup> 1/8 Post on S 1/2 line  
Bet Sec 7 + 18 and East of 1/4 Post  
Van 318' E

3375 entered 1/4 line 2188' East  
of corrected N + S 1/4 line

January 15<sup>th</sup> 1896

January 16 1895

commencing at center Sec 15

Bearing for Post on 5° E

Jack Pin N 35 1/2° E 4 1/2'

" " S 7 1/2° W 27'

Run west Van 540' E

Entered 1/4 line 7 lks N of 1/4 Post

East corrected Van 551' E

1672 set 1/8 Post " " 8 S E 1342  
" " 9 N E 1744 line

North from same 1/8 Post

Van 230'

4160 entered N Boundary

290 lks East of 1/8 Post

South corrected Van 639' E

2080 set 1/16 Post No bearings

East from center Post Van 556' E

Entered E Band 3 lks N of 1/4 Post

commencing at S 1/8 Post on N + S

1/4 line Run East Van

2043 1/2 entered 1/8 5 lks N of 1/16 Post

January 16<sup>th</sup> 1896

copied on page 14  
county record

January 21<sup>st</sup> 1896

menacing at cor of 8-9-16-17

with Var 3°30' E

9 interest 1/4 line 58 lbs E of Post

with corrected Var 2°40' E

904 1/2 lbs set 1/8 Post

W Pin 14 W 45 N 31  
W Do 12 W 63 S 41

933 fence west Var 4° E

933 fence at West Boundary

41 lbs North of 1/8 Post

East corrected U 540

933 interest East Boundary at Post

North from 1/4 Post Bet 17 + 18  
Var 2°45' E

4023 interest N Bound 76 lbs

of SEC cor of 7-8-17-18

S, corrected Var 3°53' E

2011 1/2 set 1/8 Post W Pin 8 N 31 1/2 E  
W Do 8 S 6 1/2 W 15 1/2

4023 1/4 Post

page 70 county record

January 23 - 1896

Cornering at cor to SEC cor

11-12-13-14 North Var 2°45' E

4022 interest 1/4 line 45 lbs East of

1/4 Post Copied on Page 59  
county record

South corrected U 3°53' E

4022 interest SEC corner of Post

January 25 1896

South from 1/4 Post on Range line

Bet 6+7 Bet SECs 1 + G.T. 38-6

Copied on Page 59 Var 4°15' E

4015 interest South Boundary

81 lbs East of SEC cor to 6-7-1-12

North corrected U 3°05' E

2007 1/2 set 1/8 Post W Pin 16 N 27 E 5

county record Do Do 6 S 16 W 39

West from same 1/8 Post Var 3°30' E

4013 interest Dams corrected

1/4 line 21 lbs North of 1/8 Post

East corrected Var 3°48' E

2000 1/2 set 1/16 Post W Pin 12 N 66 E 15 1/2

S Angle 8 S 66 W 10 1/2

4013 intersect E Boundary at Post  
South from E. 1/16 Post on same  
1/8 line Var  $3^{\circ}45'$  E

2011 intersect S<sup>th</sup> Boundary of  
Sec. 20 1/2 E of Post

North corrected Var  $9^{\circ}11'$  E  
2011 intersect E & W 1/8 line  
at 1/16 Post

January 26 AD 1896  
~~Posted on Page 55 County record~~

February 17 1896  
North from east of 8-9-16+17-39-6-  
Var  $3^{\circ}45'$  E

4865 intersect Lake 35 1/2 E of  
of meander

5778 over same 62 East of Meander

7995 intersect North Boundary

79 1/2 E of Sec. Cor

South corrected Var  $4^{\circ}18'$

3997 1/2 1/2 E of Post Bet sec 8+9

FEB. 18-1896

West. from 1/4 Post Bet 8-9-39-6  
Var  $3^{\circ}45'$  E.

7948 intersect West Boundary

96 1/2 N of of 1/4 Post-

East corrected Var  $4^{\circ}26'$  E

7948 intersect E Boundary at Post

corrected on Page 62  
County Record

Feb 19 - 1896

North from Sec con to 7-8-17-18

Town 33 - R. 6, E. 1/4 N. 40 E

3960 Southwest 1/4 line 1772 lks West  
of 1/4 Post copied

South corrected N. 40 E

3960 Intersect South Boundary  
at Post

May 18 - 1896

South from corner of  
Townships 36 + 37 on R line bet

8 + 9 bet Sec 1 + 6 N. 40 E

40,000 1/4 line 10 lks South of 1/4 Post

5 lks South 20 chains

Thence west - 40 chains

Thence North 18.20 to 10 1/4 line

Run by born Intersect same  
10 lks South of 1/4 Post

Subdivision of the

Found 1/4 line Run by box and  
 N + S 1/4 line north of center also  
 South from center was 10° W  
 north connected 2190 set 1/8 Post  
 north from cor of 41 + 5 - 32 + 33  
 53 1/2 lks West of 1/4 Post. South  
 copied on Page 268

West from South 1/8 Post on  
 4078 entered West Sec line 26 lks  
 4078 " 1/4 line at Post

South from 1/4 Post between 33 & 34  
 north connected 2214 1/2 set 1/8 Post.

west from this 1/8 Post was 345 4065  
 East connected 2032 1/2 set 1/16 Post  
 East from center was 3:45' E 4044

North from East 1/4 Post 2214 1/2 to 1/8 Post  
 1/4 line 23 lks North of Post

East connected 2036 set 1/16 Post  
 2214 entered E + W 1/4 line 52 lks  
 South from cor of 1/8 Post on E + W 1/4

33 T 38 - R 9 E May 20 1896

Post all set also 1/8 Post on  
 1/8 Post on West Sec line N of 1/4 Post

4380 Sec line 4 lks west of 1/4 Post  
 SW Pine 9 N 38 E 6 lks  
 50000 7 S 62 W 29 do

was 10 W 4328 intersect 1/4 line  
 connected 2164 set 1/8 Post  
 W Pine 8 S 30 E 18 lks  
 50000 8 N 58 W 11 1/2 do

north + South 1/4 line was 330'

South of 1/8 Post. East connected was 3:2'  
 copied on Page 268

4429 entered Town on line 52 lks E of cor  
 intersect 1/4 line 26 lks North of 1/8 Post

Entered East boundary at 1/4 Post  
 thence west was 3:45' 4072 intersect N + S

thence South was 10° W  
 East of 1/8 Post North connected  
 line was 900' <sup>2214</sup> intersect 1/8 line 1/2 lks W

Sec 33 cont'd

of 1/16 Post north connected on 10-16  
 West N 48 Post on N + S 1/4 line  
 Thence East 2060 to set 1/16 Post  
 Thence South on 9.30 W 2186 intersect  
 north connected on 10°30' 2186 intersect  
 South from W 48 Post on E + W 1/4 line  
 West of 1/8 Post the bearings to which are  
 North connected on 110 W 2171 1/16  
 are copied on Page 268

May 23 1896

2214 Intersect 1/8 line Post  
 on 40 E 4120 on 4 E Intersect N line at Post  
 W Pine 12 N 70 1/2 W 4 1/2  
 do do 14 S 70 E 22 do  
 E + W 44 36 1/2 west of 1/8 Post The bearings  
 are } W Pine 16 N 72 1/2 W 25  
 Sample 5 S 57 1/2 E 21  
 1/8 line at 1/16 Post  
 on 10 W 2171 Intersect 1/8 line 35 1/2  
 W Pine 22 N 61 W 13 1/2  
 do do 20 S 39 E 14 "  
 Post on north 1/8 line  
 County record

January 9 1899 - 56<sup>E</sup>/1-26-9

East from East meander on Sec line Bet  
Sec 2 + 11. Var 37<sup>5</sup> East  
600 fenced Range line 283 South of corner  
found the distance given by US Field notes  
1277 short. corrected West and set temp  
corner 2921 East of starting point at meander  
and 71.34/100 N of Random

Copied on Page 191  
North from east to 11-12-13-14 Var 4<sup>0</sup> E - 115

567 fell 374 W of Temple corner Dec 481  
course of line to 295<sup>5</sup> E corner line  
continued on this course N to Lake  
and set meander map 9.6.67 W 283/4  
21 links of line equal distance to 6.8.45 E 10  
found distance from east to 11-12-13 + 14  
to lake on corrected line to 9192  
distance of 9.60 Proportioned  
Distance and set ear to 826<sup>0</sup>  
1-2-11-12-2199 S of Lake and  
6913 N from ear to 11-12-13-14  
compass set on 4<sup>0</sup> Birch 12 N 72 1/2 W 8 1/2  
W 22 53 8 20

am sure the govt surveyors did not  
run E from ear to 1-2-11-12 as the  
distance was 1277 short. and the govt  
Field Notes call for 2 Birches and where  
it should be was a large Tam + some  
swamp NO, Birches near and no govt  
marks of any kind. The entire part  
finished Jan 11 1899

County Record

Work done for Geo Chase 12<sup>00</sup> Paid

sampled set for

January 12 1899 - 30 + 31 - 37 - 8 - 8

South from NE corner 30 Var 3<sup>30</sup> original bearing  
4104 fell 117 1/2 E of 1/4 Post O. Bearing when N 55 E is a  
white pine but to OK as 5/12 angle + distance 568283  
corrected N and set 1/8 Post on line Var 152  
Line Equi distant Bet ear + 1/4 Post  
compass attached ear WP 99 S 62 1/2 E 15  
compass on 4<sup>0</sup> E 206 N 11 1/2 W 20  
South from 1/4 Post Bet 29 + 30 Var 152 E  
4230 fell 169 W of ear looked for it 3 days  
N corrected Var 4<sup>00</sup> DEC 4 Links  
2115 set 1/8 Post WP 9 S 7 1/2 W 11  
DO 11 N 11 W 27 1/2

North from SE corner of 31 Var 10<sup>0</sup> E  
2000 windfall this Page all copied on  
9800 beam " Page 155

11719 fell 19 Links E of 1/4 Post  
corrected South and at 7593 found corner  
400 chains W of Random 30 + 31  
Went south from corner set 13<sup>0</sup> or  
3766 1/2 set 1/4 Post (as per set 16 S 76 W 14 1/2  
compass on 4<sup>0</sup> Birch 8 S 79 1/2 E 14  
East from ear to 30 + 31 on Random  
Bet Range 7 + 8 Var 330 E

1400 Lake  
2500 over Lake County Record  
5200 N + S Random 18 links N of 1/4 Post  
5930 set temp corner could find no other  
Star East on same course

108.00 Lake  
13013 58<sup>0</sup> ear to 28-29-31 + 32 644 N of Post  
one O Bearing Birch gone  
Went West on Random to 2964  
and found 1/4 Post 754 South one  
old Bearing S S when gone  
Went West on Random to 4827 and found  
corner 438 South after Standing  
Birch down + green DEC 8 1899  
corrected Random west page 21326

ALL WIND

30 + 31 cont

corrected Var 213°W - bearing 9074 to Chemin  
 598 1/4 East from Range line bet 1/4 Post  
 145° South of Random  
 Compass on 40° E N Pmo 6 N 61 W 265  
 Part in Lake No other areas  
 3228 East from Range line bet 1/8 Post  
 273 South of Random line  
 B. oak 6 N 67 W 227  
 no other near

155 County Road  
 on Pave

West from NE cor 30 Var 330° E  
 572 1/2 Range line 122 South of Post  
 Proportioned distance - bet 1/4 Post  
 3401-06/04 West from corner and  
 1723-97/100 East from corner of  
 Range line corrected Var 207° E  
 compass on 40° E N P. Summit 30 N 13 E 26  
 Dead Birch 18 1/2 B W 33  
 3825 1/2 bet 1/8 Post Equidistant bet 1/4 Post and  
 NE corner

West from 1/4 Post bet 31 + 32 Var 00  
 2850 Lake  
 3650 over Lake  
 5714 Range line 96 N of 1/4 Post  
 corrected East Var 10° E = DSE 177  
 North from S 1/4 Post on Town line  
 Var 730° E

2300 interest Lake  
 2700 over " to Island  
 3375 " Lake  
 4950 over Lake  
 7125 interest Lake  
 7913 full 132 W of 1/4 Post which is in Lake  
 corrected South Var 631 DSE 167  
 bet Post for center at junction  
 of corrected 1/4 lines

30 + 31 cont

Distance to N 1/4 Post 3987 1/2  
 do " S " " 3926 1/2  
 do " E " " 3749  
 do " W " " 1665  
 E W Pmo 10 N 85 E 760  
 no other areas  
 center in Lake

county road

Set 1/8 Post on E + W 1/4 line 1874 1/2  
 West from 1/4 Post bet 31 + 32  
 compass on 40° B. oak 6 N 193 1/4 W 56  
 do 6 South 18'  
 north from this 1/8 Post Var 945° E  
 600 Lake  
 3830 over Lake  
 4004 see line 120 W of 1/8 Post corrected  
 South corrected Var 192° E 560 3.00

North from 1/4 bet 30 + 31 Var 30° E  
 450 over Lake  
 8093 full 144 E of 1/4 Post  
 corrected South Var 40° 02' DSE 177 5.00

155

West from 1/4 Post 29230 Var 10° E  
 4858 full 21 Links N of Post  
 corrected East Var 9 1/2° DSE 285  
 bet Post for center at junction of  
 corrected 1/4 lines  
 Tam 55° 50' W 34  
 do 12 S 13 E 80

copied on Pave

Distance to N 1/4 Post 4047  
 " " S 1/4 " 4046  
 " " E 1/4 " 3258  
 " " W 1/4 " 1600  
 corrected East and bet 1/8 Post Equi-  
 distant bet center + 1/4 Post  
 W Pmo 8 N 61 W 23  
 do 17 S 85 E 10



SEC 30 37-8 continued

South from 1/8 Post on E & W 1/4

Lin Var 40° E  
4068 feet 42 West of 1/8 Post, an sec line  
converted North Var 40° 34' DEC 100

January 22 1898

bet South 1/8 Post on N + S 1/4 line  
E open 10 N 38 E 4 1/2  
W Pine 7 N 63 W 5

East from this 1/8 Post Var 10° E

3202 feet 18 S of 1/8 " an East sec line  
converted W. Var 41' west DEC 052  
and set 1/16 Post W Pine 10 N 68 W 6 1/2

North from E 1/8 Post on E + W 1/4 line  
Var 3° E

4065 feet 92 W of 1/8 Post which is  
W Pine 4 S 78 1/2 E 12 1/2  
W Pine 5 N 12 1/2 E 13  
converted South Var 150 DEC 227

West from N 1/8 Post on E sec line  
Var 145 E

326 feet 60 N of 1/8 Post which is  
W Pine 4 S 45 W 22  
30 6 N 3 1/2 E 14  
converted East Var 247 DEC 192

Set 1/16 Post W Pine 4 S 49 E 8  
30 12 N 76 W 22

WINDFALL extends from near town line  
North to 1/4 line through sec 30  
+ E & W I do not know how far. I have  
had a very poor crew for lines as  
all out of whack. I am tired + mad  
all the time finished Jan 23 1898  
Worked 12 1/2 days D.K. Vaughn

reel

country

155

pan

on

around

SEC 3-36-7 - E January 30 1899

North from SE cor Var 30° E. O'Brien's  
200 Lake and meander O'Brien's  
4702. over Lake and 24° E Var

Proportioned distance across  
Lake and set 1/4 Post 160 South  
from meander (O.B.) both down  
Var from meander to 1/4 Post 24° E

Posted on Pa 46 192

West from 1/4 Post between 2 + 3  
Var 33° E

2000 set Talley and line stakes + quit  
for want of help. Work was done for  
John Maen + Ross Bras. Ross  
agreed to pay 1/2 the expense but  
failed to do so. quit Jan 31-1899 at  
11:30 AM. Worked one day, and  
Lynn was the only help  
D.K. Vaughn

country 402 Reel

7910	4502
3970	3940
<hr/>	<hr/>
3940	562

FEB 9 1899 / old Bearing  
 East from 1/4 Past BET 23 + 24 Var 330 E  
 3991 well 46 links S of car org BT  
 connected west Var  
 1995 1/2 Set 1/8 Past 23 links N of Random  
 campfire an 40 E Norway Stump 24 N 10 E 46 1/2

West from 1/4 Past BET 35 + 36 var 4 E  
 3992 To 1/4 line  
 connected E + set Term 1/8 Past  
 at 1996 East of 1/4 line and 1/4 P

131 north from this Term 1/4 Var 4 E  
 3964 well 40 links W of 1/8 Past  
 connected South Var 324

West from SE car 35 Var 40 E  
 3952 well 37 South of 1/4 Past  
 connected East and set 1/8 Past var 328

South from E 1/8 Past on E + W  
 1/4 line var 330 E  
 3974 well 36 E of 1/8 Past  
 connected North var 259  
 finished survey 18. 1899

work done for Charles Regal  
 West from 1/4 Past BET 1 + 2 35-8-E var 90 E  
 8274 well 138 N of 1/4 Past  
 1/4 Past on E side was set from  
 one O Bearing maple gone and  
 Birch nearly gone made New  
 Bearing stump 19 S  
 work done for Rertze Seald  
 trespass 3 trees 2860 feet  
 March 1st 1899

South from North 1/4 Past line  
 Var 330 E  
 4629 well 34 links west of 1/4 Past  
 connected west Var 355  
 Bearing far Bath 1/4 Past are OK

South from NW car Var 230 E  
 375 1/4 Past remain gone x Riv Stump  
 OK but requires nearly burned out

East from W 1/4 Past var 30 E  
 7926 well 148 N of 1/4 Past, org BT  
 connected W var 156 and  
 set center of line  
 W Riv S 15 1/2 W 19 1/2 links  
 DO N 3 W 14

Distance to W 1/4 Past 3873  
 " " E 1/4 " 4033  
 N 1/4 " 482  
 S 1/4 " 4147

2026 1/2 East of center Set 1/8 Past  
 connected 1/4 line  
 N Riv 10 S 21 E 9  
 W Riv 14 N 60 W 20  
 2073 1/2 South of center Set 1/8 Past  
 W P Stump 28 N 51 1/2 E 23 1/2

as there was no timber along 1/8  
 lines in SE 1/4 did not run them  
 brushed march 6 1899  
 work done for steam boiler co  
 4 1/2 days 2250

Parted on Farm 181 county Record

SEC 2 36-10-E March 7<sup>th</sup> 1899

North from S.E. cor Var Var 8<sup>10</sup> 10<sup>10</sup> Don  
 1858 feet 1 link W of Doras 1/8 Past  
 7405 " 28 " W. " corner, O.B.  
 . connected S Var 4.58' E Sec 038  
 3704 N of S.E. corner 1/4 Past  
 (N Pin 18 N 49. E 22 1/4  
 Pin 10 S 61 W 15)

copied on

Page 308

East from W 1/4 Past Var 4.5 W 1/4 by Don.

7692 feet 102 S of 1/4 Past  
 connected W Var more Sec 185

North from S 1/4 Past Var 1130 E - Vaughn  
 7537 feet 33 W of 1/4 " O.B.

connected S. Var 11.5' E Sec 043  
 Set center at junction of connected 1/4  
 lines (N Pin 14 N 23 W 14 3/4  
 W Pin 10 S 6 1/2 E 15 3/4)

Distance to N 1/4 Past is 3801

" " S " " 3736

" " E " " 3824

" " W " " 3868

1900 1/2 N of center 1/8 Past

1868 S of center 1/8 Past  
 } Term. 24 S 24 1/2 E 5 (compare  
 } thine 9 N 56 W 25 (same 4' E)

1912 E " center 1/8 Past

1934 W " center 1/8 "  
 } Term 16 N 57 1/2 W 21 1/4  
 } do 15 S 47 1/2 E 22

County record

East from NW cor Var 3<sup>0</sup> E  
 4052 feet 151 N of 1/4 Past O.B.  
 connected W Var 52' E Sec 372  
 2026 feet 1/8 Past  
 (cedar 6 N 75 E 3  
 Birch 8 S 35 W 16)

N from W 1/8 Past Var 1252 S  
 3839 feet 65 W of 1/8 Past  
 connected S Var 1153 E Sec 169

finished March 12-1899

work done for W.D. Harrison + Heber

copied on Page 308

May 6 1899

SEC 2 36-10-E

East Trough S W 1/4 Var 21' W  
 3718 feet 14 links N of 1/8 Past

connected same Var Sec 043

County record

Sec 33-37-10-8 March 19-1899

West from E. meander on town line

3374 full 24 links S of west meander  
 Distance given in govt field notes is 4133 links a shortage of 759. Proved same + set 1/4 P on it 14 1/2 W of E meander and 1959 E of west meander on corner line  
 Var 24' W Dec 071

North from S 1/4 P Var 530 E

1175 beam Lake

4080 Old S+W Ransom *checked on Page 335*8206 full 626 E of N 1/4 Post O.B.  
 corrected South Var 752 E Dec 763

1170 N of S 1/4 Post set meander

East from NW cor Var 15' W

3024 full 4 links 1/4 Post O.B. correct set

1512 set 1/16 Post N Pin 48 S 20 E 20 1/2

+ East from W 1/4 Post Var 1' E 10 E.

Fin Back off at 1/4 S mark

Spur gone

6850 new line Blazed N+S could not find 1/4 Post set stakes at 7000 chain and run N+S see line on E side + set new 1/4 Post

7370 full 104 S of 1/4 Post

Corrected same West Var 148 E  
 Dec 141*counts read*

East from E meander on town line

Var 00

2345 full 10 links N of corner O.B. but

Broken down

Corrected W Var 14' W Dec 043

Distance between S E corner and S 1/4 Post is 3760

1880 set 1/8 Post N Pin 14 N 79 E 6

No others seen

Sec 33-37-10-8 continued

North from SE corner Var 330 E

8119 full 112 E of corner which I set from old bearing N 83 E 14 1/2

corrected South Var 417 Dec 137

4059 1/2 set 1/4 S E N Pin 18 N 68 E 47 1/2

Tamarac 14 S 33 W 40

*checked on Page 335*

set center of Sec at junction of its corrected 1/4 lines

compass on Tam 12 S 81 1/2 E 33  
 10 E do 19 S 72 1/2 W 15 1/2

Distance to N 1/4 Post is 4161

" S 1/4 " " 4045

" E 1/4 " " 4030

" W 1/4 " " 3340

at 2015 E of center set 1/8 Post

compass on W Pin 18 S 55 E 5

10 E do 16 N 78 W 8

" 1670 W " set 1/8 Post

compass on W Pin 12 S 23 W 20 1/2

10 E do 15 N 56 1/2 E 6

" 2080 1/2 N " set 1/8 "

Spur 8 S 60 E

Tam 7 N 39 W 8 1/2

" 2022 1/2 S " set 1/8 " 19

compass on Fin 7 N 43 E 9

10 E Tam 9 S 60 W 2

*counts read*

South from S 1/4 Var 605

4050 full 75 W of 1/8 Post in turning off

a right angle at S 1/8 Post on

Town line. Compass showed 595

local attractions at S 1/8 Post on

E+W 1/4 line were gone off 20

Hence the departure of 75 links

corrected N on set 1/16 Post B. on 7 N 61 W 14 1/2

compass on 4 E Spur 8 N 80 E 35 1/2

4133  
3374  
759

See 33-37-10-E continued

West from W meander on Town  
line Van 14<sup>th</sup> W

1640 full 1 link S of corner  
corrected E and set  
1/8 Post at 160<sup>th</sup> W meander  
distance between 1/4 Post on  
S W cor is 3599

1799 1/2 1/8 Post on 1<sup>st</sup>

copied on Page 335

N from W 1/8 P on town line  
Van 6<sup>th</sup> 10<sup>th</sup> E

4044 full 17 E of 1/8 Post  
corrected S Van 6<sup>th</sup> 26<sup>th</sup> Dec 43

3758 S of meander 286 N of 1/8 Post  
on town line

fast map 18 N 82 W 10 1/2

East from South 1/8 Post on  
N + S 1/4 line Van 13<sup>th</sup> E

3895 intersect East 1/8 line at Post

Finished march 31 1899

snow deep and out

little help county record

415

573

90

3167 / 51570

2167 / 51570 (24)

4834  
282830

170  
17  
53

See 33 37-10 E April 22-1899

South from W 1/8 Post on see line

Set 28 + 33 Van 6<sup>th</sup>

4085 full 5 links W of 1/8 Post

corrected N Van 6<sup>th</sup> 4<sup>th</sup> Dec 120

copied on Page 335

East from N 1/8 Post on west see line

Set 32 + 33 Van 14<sup>th</sup> E set

Set Reberne stake April 23 99 + went to 17-38-7-8 to  
meet W Allen + do some work for gateway  
May 1<sup>st</sup> 1899 Took up work again at 3:PM

May 2 1899

continued East

3167 full 90 links N of 1/8 Post

corrected W Van 32<sup>nd</sup> E Dec 284

1555 East of 1/8 Post on see line Set 1116 Post

same 49 12 E 12

DO 10 N 73 E 17

East through SW 1/4 Van 10<sup>th</sup> E

3466 full 76 links S of 1/8 Post

West corrected Van 21<sup>st</sup> Dec 219

finished May 4<sup>th</sup> 1899

Part of work done for Hanger and  
Gilkey Anson co, and same for  
one washer WW co and same for  
Gilkey Anson co

county

Record

3758  
286

3167 / 9600 (284)

6334  
24660  
25336  
13240

150

Survey for Road  
S.E.C. 20-36-10-E May 30, 1899

Set 30 x 2 1/4

North from 1/4 cor Var 5° E Set Post from one A.B. which had been grubbed out but found the body of tree + logs cut from same measured them found roots of both trees made new bearing Sugar 123 5/8 W 28 750 corduroy all hand land S of corduroy 1200 over corduroy to hand land then a slight raise of ground for 30 rods then gradual descent to 4000 corduroy copied on page 305 4400 over corduroy then gradual raise to 5300 gradual descent (all open ground) to 6200 6450 corduroy county record 7100 Tamn Swamp 8450 over corduroy 8158 fell 191 W of 1/4 Post Old Bearings converted south for road Var 340° E Dec to chain 2324

North from 1/4 Post Bet 17+20 Var 3° E 7847 fell 61 links East of Post - converted it south for County Road Var 3° 27 Dec 00077

Memorandum for profile

gradual decline to 750 creek bottom along Sec 1450 over creek bottom to hand ground slight raise to 1600 then slope to creek bottom at 1750. 1600 Right bank of Hog creek runs S 15° E 1750 over creek to left bank, rise 12 links wide 2000 New Hay meadow (Plenty of timber for bridges to over ground) corduroy 2600 then gradual raise 3000 Summit of High ground then level ground to 4400 then gradual decline 5000-8 ft fall in 60 links 5775 Tamn + Spine Swamp 6200 over swamp then gradual raise 6350 left river in 50 links 3 feet decline in 75 links then 8 feet raise in 60 links then four feet fall to 6800 links, then gradual rise to 7000, then 4 feet fall to 7060. Then level ground to 7800. Then gradual fall of 20 feet to 7600 enters Tamn Swamp 7847 1/4 Post Bet 8+17 in Swamp plenty of timber for corduroy in Swamp to H W on Highland

copied on page

June 1st 1899

Old Bearings

North from 1/4 Post Bet 8+17 Took Donor Random which came to decl line Bet 8+17 104 links E of 1/4 Post Var 3° E 3956 fell 52 links East of center Set by Don converted South for county Road and set 1/4 Post Equidistant Between Post and 1/4 Post ran true line Hemlock 22 N 32 1/2 E 47 1/2 Sugar 16 S 57 W 60

North from 1/4 Post Bet 8+17 450 leave Swamp - 825 Summit of Hog Back 20 feet high 600 over Hog back to Tamn Swamp 1200 foot of Hill 1300 Top of Hill a raise of 16 feet then a gradual fall to 1625 then gradual raise of 5 feet to 1700 then gently sloping 1/8 Post at 8456

This page is copied on page 299 County record

June 2nd 1899

Started west from S 1/8 Post on N + S 1/2 line in S.E.C. 8 35-10-E - Var 3° 30 3880 fell 50 S of 1/4 Post set by Don converted S for Co Road Var 246 150 130 Topography of line Slightly rolling to 700 wet marsh as part to 775 then slightly rolling 1000 then a gradual incline to 1375 then a decline to 1750 then wet ground to 1900 then a 4 feet raise and then level ground or slightly rolling to 2125 to Tamn Swamp 2700 over " then level ground to 3880 1/8 Post Bet 7+8 and S of 1/4 Post

June 27 3 1899 SEC 7 35-10-E

North from S 1/4 Past set from O. B Van, 40°  
 7718 full W of 1/4 " Bet 6+7 O Beans  
 South corrected for Co Road Van 336° E & Coords  
 to South 1/4 Past  
 at 4269 found Dams E + West corrected  
 1/4 line and Post set on Beans and  
 read 40 chains N from S 1/4 Past and  
 corrected E W 1/4 line, I used this Post  
 + set center Hemlock 12 S 56 W 31  
 compass on 40° S

Distance to N 1/4 Past 4269  
 " " " " " " 34149

Set 1/4 Past Equidistant Between centers  
 and South 1/4 Past by Birch 14 N 44 E 33 1/2  
 Hemlock 9 N 67 W 23

The following is the Topography of line  
 N from S 1/4 Past on N 1/4 line  
 full of 8 1/2 chains to Tam Swamp

850 over swamp to gradual rise of 4 feet in  
 one chain then level ground to 1300 then  
 gradual slope + level ground to Tam and  
 alder Swamp at 1600  
 1950 slight Rise + Hard ground to 2150 then  
 Tam + alder Swamp  
 2750 over Swamp to slight rise then slopes to  
 2950 to Black Ash Swamp  
 3750 over Swamp - rise of three feet for 1 Chain  
 then level ground + gradual slope to  
 4100 alder Swamp  
 4600 over " then 14 feet rise in 2 1/2 chains  
 then 14 ft fall in 2 chains to swamp  
 5150 over Swamp to foot of 8 foot Rise in 1 1/2  
 chains then gentle slope to  
 5943 1/2 1/4 Past Bet 6+7 35-10-E

all copied on this page at reced  
 Tobogaphay

SEC 7 June 3 1899

Co Pleyan Page 299

West from S 1/4 Past on SEC line

Bet 7+8 Van 380°  
 3968 N + S 1/4 line at 256 S of Post  
 corrected from county road  
 Van 12' W SEC 00645  
 corrected East for county Road  
 level + gently rolling ground to  
 2800 then Tam Swamp  
 18200 over Swamp then gradual slope to  
 3500 then level + gradual slope to  
 3968 to S 1/4 Past on N + S 1/4 line through  
 SEC 7-35-10

county road

Town 35-36 R 940  
 on SEC line

West from 1/4 Past Bet 6+7 Van 945° W  
 4481 full 13 links N of center line  
 corrected E Van Van 00029 Ed Road  
 West from this 1/4 Past  
 100 to Swamp  
 1100 over " to Hard ground 8 feet rise to  
 1500 then gradual slope 1/8 Past in edge of Swamp  
 bet 1/8 Past on Tam line + Proportional Distances  
 Bet cor + 1/4 Past Tam N 15 1/2 E 28  
 Hem 8 45 E 3134

Range line bet 9+10 Towns 35+ Bet cor of 1-6-7-12

North from corner to 1-6-7 end 12' Var 4 200 E  
3998 1/2 fell 1/2 mile E of 1/4 Post which is identified by  
Both old bearings. Both on down. fell N + NE  
Marks on Plains on worn stone Post at  
Stands in water 1 foot deep Both B.T. trees fell  
in water top reaches across hole

7672 fell 304 E of Town cor identified by three stumps  
The N.W. tree is there but does not hook up with goat  
field notes converted South to 1/4 Post for Co. Road  
Var 738 E S 82 E

Copied on  
Page 298  
Done ward

Set 1/8 Post at proportioned dist bet

cor & 1/4 Post Bich 12 S 67 1/2 W 45 1/2

Hem 12 N 32 E 52

connected South to 1/8 Post for Co Road

+ Set 8 1/8 Post

W Pm 18 N 66 W 27 1/4

Bich 14 N 62 E 37

Description of ground along Range line  
N from S 1/8 Post  
generally rolling from 1/8 Post to

- 600 swamp
- 850 over swamp to a gain of 8 feet at
- 1050. Then level + slightly rolling to
- 1998 1/2 1/4 Post then Pond 18 inches deep to
- 2075 Then gradual rise to
- 2250 " level ground on gentle slope to
- 2600 swamp
- 2750 over swamp
- 2850 swamp
- 3500 over swamp to 2 feet rise of then
- level ground to
- 3700 Then 1 foot rise + fell to 1/8 Post at
- 3835

copied on Page 306  
Done book of field notes

June 5 1899 NW from N 1/8 Post 1+7 35+10 45

Run E from S 1/8 Post on Range line bet 14635-103  
With compass adjusted on 330 turned of 23° on S E.

3390' fell 131 N E of 1/8 Post on base line bet 6+7  
converted same NW for county Road  
Var 118 E + 45 E S  
D 384

- NW from W 1/8 Post bet 6+7
- Post stands on edge of swamp
- 900 over swamp. to slight rise to
- 975 Then level ground and slopes to
- 1400 Bash swamp
- 1900 over " then gradual rise to
- 3325 Then slopes to 1/8 Post at
- 3390

West from Town corner to Town 35+36  
bet Range 9+10 E Var 40 E

4145 fell 53 N of 1/4 Post. Identified by Bats OB  
trees gone part of old marks are slight  
of New Post + new bearings  
Tann 20 S 20 E 27

This bearing was set with pocket compass  
w/ 1/4 Post is on large Rock  
connected East + set 1/8 Post at  
2072 1/2 Var 445 E P. S 82 E 100 1/2 E  
W 16 S 86 E 30  
Bich 12 N 72 W 36

finished this line June 6. 1899  
+ went to Rhineland, the Co Road  
does not run on this line but crosses  
at 1/8 Post



June 7 1899 - June 9-9 99

N W from N 1/8 Past an Range line Bet 9+10 T 35  
and Belmer + 6. Compass adjusted on  
40° N 45° W)

2777 full 10 S of 1/4 Past an town line  
connected same for road  
" Van 4957 See 00036

N W this 1/8 which stands in edge of Swamp  
2200 over Swamp to gradual rise to 1/4 P. at  
2777 This line was run by Tom Collins  
June 7 11 1899

W from 1/4 Past Bet 31+36 an Range Bet 9+10  
Town 36-N Van 40°

West from Cor to 25+36-30+31 <sup>old Range</sup> line  
9+10 Town 36-N. Used Dons Random  
which came to Range line 102 South of camp  
& turned Van 30° of

8409 full 1/2 S of cor set by Don  
connected to star 575 See 00892 at

4204 1/2 set 1/4 Past 264.8/100 N of Bender  
102 1/4 " " 182.8/100 " " "  
Compass on 40°. 1/4 Past cedar stump 148 53 E 50

" 1/8 Past " " 14N 57 E 42  
" " " " 104 S 49 W 52

Set Road Stake N from 1/8 Past to 1/4 Past  
Every 500 links Topography = all cedar and  
Tamarac and small spruce Swamp  
1300 then bend to 1900 then Swamp to

2102 1/4 1/4 Past  
Van from 1/4 Past Bet 36+31 an Range  
line Bet 9+10 Town 36-8  
Van 40°

Stopped at 2087 3/8 Proportional distance  
for 1/8 Past distance an town line 2072 1/2  
Distances on Bee line same N 2102 1/4  
1/8 Past will come 43 1/2 links E of 2117 43 4  
Straight line Bet 1/8 Cor 2087 1/8  
Road Road straight

June 8+9 1899

North from E 1/8 Past an town line Bet  
Town 3573 C and 2072 1/2 W of town cor  
Van 40°

8418 full 2 1/8 E of 1/8 Past  
connected South for road  
connected U 557 See 00341  
Topography of line  
June 10 1899

West from 1/4 Past Bet 25+36-36-9-8  
Van 5°

4204 1/2 full 374 S. of cor to 25-26-35-36  
connected E for road Van 6° N, See 881  
Set Road stake very 500 and spotted line  
Between them

Topography of E 1/8 line through 36-36-9  
200 Swamp  
300 over Swamp to last rain to 450 Slope  
500 Swamp  
900 over in gradual rain to  
1100 slight hilly to  
1400 wet marsh  
1500 over " "  
1600 wet ground  
2600 over " to gradual rain  
2800 top of " "  
4000 gradual slope " "  
4600 wet sand to  
4750 over " level ground  
5000 level ground  
5200 lagging Road  
6000 fall of 10 feet to  
6150 level to  
6300 fall of 8 feet to  
6400 Swamp cedar tamarac + spruce  
7600 Spruce all cut to  
8418 1/4 Past

June 11<sup>th</sup> 1899

Totography of line Past 25+36-36-9-8  
from 1/4 W to Sec corner  
Past in Swamp

250 hard ground

600 cedar &amp; tamarac Swamp

800 over " "

1650 Tamarac Swamp

2500 creek 5 links x 1/2 m. N<sup>30</sup>

2600 over creek &amp; Swamp to about rain

2750 Top of 10 feet

2900 down to " "

Tamarac Swamp

3600 over 1/2 m. to gradual rain

3700 Top of 8 feet rain

4000 slope to Swamp

412 1/4 Sec corner to 25-26-35+36-36-9-8

Met from east of 25-26-35-36-36-9-8  
Took some old Rantam & from SW corner

of 26 found distance of line between ear  
of 26. Distances 432 S of Sec 26.

Set 1/4 Past 2166 W of cor to 25-26-35+36  
on true line Birch 11 S 83 W 30

and 324 N of Rantam 1 N 10 N 27 2/3 41

West from corner to 25-26-35+36-36-9-8  
Var 339 E

2166 full 93 S of 1/8 Past

cancelled East for county Road

" Var 537 Sec H 25

Totography of line

550 leaves Swamp

650 top of 12 feet Rain. gradual Rain to

850 gently rolling to

2166 1/8 Past

June 11<sup>th</sup> 1899

North from East 1/8 Past Bet 26+35-36-9-8

Var 30 E

2308 full 47 East of 1/8 Past Met By B F Don

cancelled S for county Road

" Var 45 1/2 E Sec 30204

Totography of line

gradual Rain to

500 Then slopes to

700 Swamp Tamarac

1000 over Swamp then gradual Rain to

1500 Then gradual slope to

1900 alder swall

2000 over "

2303 1/8 Past

Did not Run W an 1/8 line as

I was informed Road was damaged

By B F Don. Distance to W 1/8 Past in

South 1/8 line (Russell's House to)

4333

June 11<sup>th</sup> 1899

573	4011
2292	1117
2652	1021
2303	
3501	
3203	
15990	

Copied on Page 000 next to index

Survey county record Concord

Commenced June 16<sup>th</sup> 1899  
finished June 19<sup>th</sup> 1899Commenced at 1/4 Post on Town  
line Rte. to town 37<sup>+</sup> 38 and Bet. Secs.  
6+31 Range 8. East Thence west Var 30°30'

1716 1/4 Post at Troy Mansel

1775 R.R. track

3170 center of new Rte track

Runs S. 46 1/2° W.

3720 Town corner at Post  
Started in Swamp Town, runs  
in Swamp T.W. 1/2 of this line  
has plenty of timber for Carderay

West from town corner

4014 feet 1/2 links N. of 1/4 Post (on old)  
6027 " 1/2 " " " " (Beaver)  
8037 " 1/2 " " " "

conducted East for County Road

Var 32 1/2° N.E. 00016

Topography

700 large Tamarac Swamp

1750 Top of gradual Rise of 20 feet

1850 wet open marsh

2050 Low

2600 top of a small rise, a large part

3100 foot of slope very slight

Rolling to

4300 then level to road center

Rolling to see car at

8037.

Copied on Page 000. next to index

county record

Survey of Road continued

North from corner 10-1-2-35-36

Copied on Page 000

3959 feet 6 links E of 1/4 Post  
8000 " 27 " " " " " " " " "conducted S for county Road  
old bearings at 1/4 Post are in  
Road limit made new bearings  
& marked same thus. X with  
jack knife 4 1/2 feet from ground  
bearing Post

county record

Tamarac 10-1-2-35-36

Sec 3-35-9-E

South from NW corner Var 30° E

3941 feet 205 W of 1/4 Post

conducted North Var 80° E

1970 1/2 feet 1/8 Post

W Birch 10N21 E 33

Copied on

Page 183

Co: Record

# Survey of Road for Town

Commenced aug<sup>1</sup>  
 commencing at a stake which  
 stands on S&E line bet S&E 26 + 35 in  
 Township NO 38 - Range 9 - E 2181 East of  
 comes to S&E 26-27-34-35-

Thence South  $57^{\circ}$  W 2892 1/2 to a stake  
 which stands on S&E line bet 34 + 35  
 and 1551 South of comes to 26-27-34-35  
 and 745 North of 1/4 Part bet 34 + 35

Being for said Part is W Pin Stump S 83 W 35  
 Thence South on said S&E line S.  $7^{\circ}$  W  
 to cor on Township line bet Towns 37 + 8  
 #  
 N Range 9 - E - 5333 By offset 100 East of  
 5030 to Miss Pond Dist over pond 167

original bearings at each end of this line  
 1/8 + 1/4 Part bet by BE down

South on S&E line bet 243-37-9-E Van 5.31  
 3529 1/4 Part Posted on Page 211

7387 full 3/4 of a link W of Part onto 2-3-10-11  
 County record

# of Sugar camp

28-1899 Parted on Page 215

county record  
 South bet 10 + 11 - 37 - 9 E U 130

7651 full 122 E of carto 10-11-14 + 15  
 corrected same for Town Road

South on S&E line bet 14 + 15 37-9-E Van 5.45

278 to angle bet Part { WP. S. 14 1/4 33  
 Posted on Page 217

South  $47^{\circ} 25'$  W Through 15-37-9-E

12322 full 372 NW of Part carto 15-16-21-22

corrected same N.E. for Road  
 county record

South  $83^{\circ}$  W Through 21-37-9-E

5400 Brown + Robbins P.R. 5825 only B + Robbins P.R.

7200 " " " " P.R. 7230 intersect Road line

10340 S line S&E 21-1818 East of carto 20-21-28-29

bet Part at crossing  
 of S&E line { W Pin 125 75 E 39 221

10742 bet Part at angle { W Pin 208 40 1/2 E 32 1/2

Thence South  $49^{\circ} 10'$  W

11252 to angle bet Part { W.P.S.  $84^{\circ}$  E 28

Thence South  $82^{\circ}$  W

11819 to center of Eagle River Road + bet

from Pin 33 links N of Small creek  
 scratched cedar stump 145 63 1/2 E 42 1/2

Whole distance is 494 1/4 = 6 Miles 57 Rods

Entered on Page  
 County record

## Survey of Road for town of Susan

Commencing again at angle of  $82^{\circ}$  W

Thence S  $76^{\circ}30'$  W

6664 Sec. line Bet 24-29

1927 center of Eagle River Road set Post

WP Stump 1/2 S  $47^{\circ}5'$  E 48

Made New bearing to cor of

15-16-21 & 22-187-9-E

WP in 1/2 N  $57^{\circ}1/2$  W 94

New bearing to 20-21-28-29-37-9

WP Stump 1/2 N  $85^{\circ}1/2$  E 43

C. H. Hill

## Survey of Road for town of Reliance

October 13 & 14 1895

East from 1/4 Post (set by D. W. from O. B.)

Bet 4 & 9 - 36-9-E N on 30<sup>th</sup>

5128 interval Stake

5650 over

5650 full 172 N of 188<sup>th</sup> cor on one O. B. left

Carried N for Road

East from cor to 3-4-9-10-W on 30<sup>th</sup>

4204 full 41 N of 1/4 Post Bet 3 & 10

old bearing nearly gone set new

Bearing (y. P. 18)  $84^{\circ}$  N  $17^{\circ}$  E 27

carried Van 159

assisted by E. Brown & C. B. Damp

copied on Page 192 County Record

See 22-37-8-8

West from cor to 22-23-26-27 Var 230° E.

4229 1/4 Post copied on Page 146

East from cor to 21-22-27-28 Var 100° E

4726 full 231 South Vermont Road 130° 10'

connected west Var 150°

2363 Set 1/8 Post { B Pin 7 W 40 W 46  
" " 9 S 59 S 59

4726 See same county record

Oct 20 1899

See 16 42-5-E Oct 20 1899

South from cor of 8-9-16-17 Var 230° E

Set Post from original Bearings  
8062 full 13 links East of cor to 16-17-20-21  
old Bearings + old 900 Post well preserved  
could not find 1/4 Post  
connected North Var See 0006

at Talley 6046 1/2 Set 1/8 Post 9.67/100 W of Band line

N Bearings

at Talley 4031 Set 1/4 Post 6.49/100 W of Band line

W Pin 14 N 26 1/4 W 22 1/4

at Talley 2015 1/2 Set 1/8 Post 9.22/100 W of Band line

W Pin 10 S 65 W 11  
do 6 S 24 1/2 S 16

East from cor to 16-17-20-21. Var 350° E

4048 full 361 S of 1/4 Post Set from 10 B

and made new Bearing

connected West W Pin N 48 S 26

Var 946 See 887

East from 1/4 Post Bet 16 + 17 Var 40° E

8128 full 339 S of 1/4 Post Bet 15-16

connected West Var 6.23 } one 0 B at East  
1/4 Post

Oct 22 1899

Oct 23 1899 - 16-42-5

North from S. 1/4 Past - Var 3.30  
 In going found Needle changed  
 to 2° W then back to 4° E with compass  
 adjusted an 3.30° E after going 4000 chs  
 It held an 7° W to north line  
 8254 feet 430 west of Past found.

Both O.R. set new Past  
 connected line South Var 330.8 <sup>DEC</sup> 55  
 Set center of S.E. at junction  
 of corrected 1/4 lines

Monway line N 81 W 38  
 W line 9 N 5 E 58

Distance to N. 1/4 - P 4289

" " S. 1/4 " 3965

" " E. 1/4 " 4155

" " W. 1/4 " 4022

at 2144 1/2 N of center set 1/8 Past

W line 18 S 66 W 22

by " 16 N 28 E 14

Oct 23 1899 16-42-5

at 1982 1/2 S. of center set 1/8 Past  
 W line 10 N 87 E 18  
 do 9 S 83 W 24

at 2050 1/2 E of center set 1/8 Past

W line 11 N 88 E 7

W do 13 S 2 W 7

at 2013 1/2 W of center set 1/8 Past

W line 12 N 44 E 34  
 do 11 S 36 E 25 1/2

Run N from E. 1/8 Past on S. W. 1/4 line  
 Var 33.0 E. Stopped at 2205  
 do not know this line in correct  
 Started west from N. 1/8 on N. S. 1/4 line  
 Var 6° E = Oct 23 1899.

4010 feet 214 N of 1/8 Past - W line

Read at west end of this line 4° 45' E

Corrected S. Var DEC 34

at 2005 set 1/16 Past -

W line 12 S 54 W 18

do 9 N 49 E 10 1/2

as I did not run E from NW cor to N  
 1/4 Past - I had no N. 1/8 Past to run to S.  
 I did not set the trees Past may not be right

SEC 16-42-5 Oct 23 1899

Run South from 1/16 Post in NW 1/4  
Var 330 E

2058 feet 42 E of 1/8 Post

Carried N. Var DEC 204

South from W 1/8 Post on E + W 1/4 line

Var 225 E

4005 feet 23 E of 1/8 Post

which I set Equidistant  
Bet SW cor + S 1/4 Post

W line 1763 E 23

North carried Var DEC 057

West from S 1/8 Post on N + S 1/4

line var 330

2017 feet 15 N of 1/16 Post

which I set By taking 1/2  
the distance on N + S 1/8 line

as I did not <sup>know</sup> the Post was right

I did not use scribbles Run

{ W Pin 10 S 86 W 6 3/4

{ Do 18 N 348 21

Carried 1/8 line East S 1/8 P

SEC 13-41-1 Nov 20 1899

East from SW cor - O.B. Var 30' west  
3946 feet 321 S. of 1/4 Post O.B.

Carried West to set 1/8 Post Var 406 E <sup>Dec 308</sup>  
 { FN 4 N 10 W 5  
 { W Pin 14 S 5 E 33 1/2 West

East from South 1/4 Post Var 30' W

4224 feet 12 links South of 1/4 Post

Carried west Var 40' W

{ W Pin 15 N 2 1/2 E 17  
 21+2 set 1/8 Post Pin 24 S 16 W 13

Run north from this 1/8 Post + and  
intersected line Run by Guaman

North from west 1/8 Post. Bet 13 + 24  
Var 257 E

1996 feet 14 W of 1/16 Post set by Guaman  
found trespass on SW 8 E 13, 41-8

WD Guaman had done same  
work in this sec + I finished it  
using his 1/16 Post in SW 1/4



See 24-41-8 Nov 22 1899

South from NW cor. Var 730 W  
I started on this Var as timber was  
cut in 23 as Guamae had run the  
line, but found it was way off

3961 feet 7.49 west of 1/4 Post found  
Timber left in 23

Corrected North Var 320 E  
Dec 1890  
1980 1/2 set 1/8 Post Sugar 8 S 76 E 27  
W Bish 10 S 73 W 24

corrected line north from 1/8 Post to  
corner found timber left on 23.

East from 1/4 Post Bet 23+24 Var 330 E

1100 Swamp

2300 oak "

2700 pine "

32 Slaw " creek 150 S

6350 creek 400 lbs wide

7600 Slough "

7826 oak "

8174 full 252 North of 1/4 Post

Corrected west Var 144 E Dec 308

See 24 continued

N from East 1/4 Post Var 508

4000 full 92 1/2 W of corner

corrected line South Var 341 Dec 231  
2000 set 1/8 Post { N Pine 17 N 84 E 17  
W DO 7 N 88 W 8

as W.D. Guamae had run N + S

1/4 line I used it to set center

Fin 12 S 8 W 5  
Do 8 N 26 E 18

Distance to N 1/4 Post 4206

" " S " " 4149

" " E " " 4025

set N 1/8 Post 2103 N of center

Sugar 10 N 6 E 37  
DO 12 S 59 W 3

" S " " S " "

" E " " " "

" E " " 2074 1/2 E " "

" E " " Fin 10 S 81 W 18  
No other near

" W " " 2012 1/2 W " "

" W " " Tamarae 14 N 35 1/2 W 4  
DO 14 S 20 W 26 1/2

East from N 1/8 Post on west side line Var 255 E  
4010 1/2 full 4 1/2 links S of 1/8 Post

East from N 1/8 Post on N + S 1/4 line Var 137  
4186 full 1/4 link S of 1/8 Post

See 24-41-4-E Post on

N from East of Post on E & W 1/4 line Van 337 E

4108 feet 12 links W of 1/8 Post

connected line South to East 1/16 Post

W Birch 10 S 41 W 14

South from W 1/8 Post on North line

Van 245 E

4123 feet 119 links West of 1/8 Post

connected N to East 1/16 Post

W Birch 12 N 16 W 14  
do do 10 S 55 W 39

finished Nov 26 1899

See 18-41-9-E NOV 26 1899

North from E 1/8 Post on South line

Van 250  
5996 feet 9 1/2 links E of 1/8 Post

connected line South

I used these 1/8 Posts as I was instructed  
to do so they were set by W.D. Gunn.  
Cannot say how correct they are

finished Sunday Nov 26 1899

See 32-41-9 S See 2 1899

South from 1/4 Post Bet 32+33

Van 2:30 S 1 Old Bearing

3985 feet 115 W of corner on

connection line set for See 32

32+33 I set this corner

from 2 Pine Stumps one of  
which showed some faint

Marks of govt Surveyors  
and they both hooked up with

MS field notes

connected line North 1992 1/2

found set 1/8 Post in Swamp

W Pine 18 S 80 W 158 links

connected Van 4:05

See 288

See 10

See 33 41-9 Dec 3 1899

East from S.W. cor on cawchion

Lin var  $3^{\circ}15' E$ 3961 full 12 links N of  $1/4$  Post which I

Set from 1 old bearing the map is gone. the Norway is down

and gov't marks are nearly all defaced by fire and ravages of time

Put in new Post = and made new

bearings <sup>Dead</sup> W Pin 28 N 47 W 59

cancelled lin west to corner

west an See lin Set 28 + 33

from West side of land

2650 found Stumps of both original

Bearings + Set new Post and

made new bearings

W Pin 24 S 67 E 73

See 33 west from S  $1/8$  Post an See lineSet 32 + 33 Var  $3^{\circ} E$ 4032 full 98 N of  $1/16$  Post set by D Grahamcancelled East to  $1/8$  Post Var  $5^{\circ}45'$ 

See 33 41-9 Dec 3 1899

North from East  $1/8$  Post on E + W  $1/4$  lin

Set by D Graham

Run 4000 North could not find

anything I must run this See line

clear through as  $1/4$  cannot be

found and as there is a deep

sluggish stream to cross will

have to wait until it freezes

over = Dec 3 1899

88c 32-37-8 Dec 4<sup>th</sup> 1899

North from S.E. cor Var 40° E  
 I am on this course as old  
 line indicated this was right  
 two old bearings left at corner

4515

full bearing of 1/4 Post Tamarac is  
 then skew gone

associated South & set 1/8 Post used

old Bearings made by someone  
 some 6 years ago

N Pin 22 N 24 E 32  
 W "Stub 18 S 3 W 7

Run west from this 1/8 Post on 5° E as  
 I have subdivided 31 & know the course  
 to run on providing there is no local  
 attraction also there is very little  
 timber on this line & only run 20 chs  
 I also run west from E 1/4 Post  
 as I had set west 1/4 Post and  
 also knew the course of N & S 88c  
 lines my course is 247  
 Rained until noon and is raining  
 now at 6 P.M Dec 9 1899

Posted on Page 156

county  
Record

88c 33-37-8 & Dec 9<sup>th</sup> 99

East from W 1/4 Post Var 00.00

7749 fell 280 S of 1/4 Post Q.B.

associated line West Var 130 E

Page 157

33928 of W 1/4 Post Small lake

4017 " " " " over " "

44 " " " " Lake

52 " " " " over " "

7749 " " " " East 1/4 Post  
 center of Sec is 142 1/2 W of E side of  
 Lake and 378 N of S side of Lake  
 measuring from offset line

Record

Copied on

county

I have set center of this Sec. by lake  
 knowing course of E & W 88c  
 lines and found the S 1/4 Post in center  
 between corners so I did not run  
 the N & S 1/4 line as the N 1/4 Post is in  
 Lake. I set W 1/8 Post on E & W 1/4 line  
 and run South <sup>Var 145</sup> and at 440.3 feet  
 44 E of 1/8 Post set by Dan  
 I intended to run an 115' but made  
 mistake in adjusted Vernier  
 associated this 1/8 line north  
 Dec 11 AD 1899 Snowing hard

See 6-37-10-E Dec 20, 1899

East from  $\frac{1}{4}$  Post Bet 1+6 an Range  
line Bet Ranges 9+10 in town 37

2136 feet 62 South of  $\frac{1}{8}$  Post set by  
Var  $4^{\circ} 0' W$

Done  $\frac{1}{4}$  Post also set by him  
corrected line west

Dec 21" 1899  
copied on Page 324

See 25-37-9-E Dec 22 1899

North from  $\frac{1}{4}$  Post Bet 25+26 Var  $4^{\circ} E$

4212 feet 6 W of  $\frac{1}{4}$  Post

Set Post at  $\frac{1}{4}$  Post and

See corner from original bearings

corrected South & set  $\frac{1}{8}$  Post

East from ear to 23-24-25-26  
corners remain

4115 feet 156 N of  $\frac{1}{4}$  Post set from one  
Var  $5^{\circ} 0' E$   
of the old bearings the stump was

there it stands W of Pig Run about 15 rods

corrected west & set  $\frac{1}{8}$  Post.

corrected Var  $2^{\circ} 50'$

Road for town of Pelican on See"

Line Bet See" 27+34-36-8-E

West from corner to 26-27-34+35-36-8

Var  $3^{\circ} 30' E$

39574 feet 85 N of  $\frac{1}{4}$  Post Both OB

corrected East Var  $4^{\circ} 4'$

1977 set  $\frac{1}{8}$  Post W.P. Stamp 24 N 84 W 58

finished Dec 26" 1899  
Posted on Page 126 Co. Record

72 BEE 4-35-10-E Dec 27-1899

North from South 1/4 Post on Sec line Bet  
3+4 Set By BF Don Var 30E  
1981 fell 30 W of 1/4 Post O.B.  
corrected South Var 230'

Page 299

North from 1/4 Post Bet 3+4 Var 30E

3690 fell 26 East of center 3-4-33-34  
corrected South Var 324 Dec 70/100

1962 1/2 N of 1/4 Post Set 1/8 Post NP 8 N 5E 49

North from center of BEE Set  
By BF Don used his N+6 Random

which run on 40E and was 8 1/2 links  
west of center center read

3728 Town line at 1/4 Post Set by Don

Proportioned Dist and Set 1/8 Post  
1956 North of center

corrected line South to center  
Twp 12 N 65 E 30 1/2

West from N 1/4 Post on Sec line Bet 3+4  
Var 30E

This 1/8 Post sets on Haymeadow near  
N Bank of creek Bottoms and after going  
500 West found I was running on 230  
W Var

4038 fell 45 N of 1/8 Post corrected line  
East should have run on 330 Dec 11/24

73 BEE 9-35-10-E Dec 30-1899

South from 1/4 Bet 4+9 on Dons Random  
Bet Talley Stakes + connect to center  
West from center on Dons Random 40E  
4000 found 1/8 Post Set By Don

corrected East to center  
East from center on Dons Random  
which varied 2 links to chain from  
true line. 4000 1/4 Post Bet  
9+10 Set 1/4 Post from O.B

The Birch I did not use as I  
could not make it hook up  
with field notes.  
East from 1/4 Post Bet 9+10 Var 330'8  
8049 fell 48 links S of 1/4 Post  
which I set from Old Bearings  
the distance to west bearing is  
10 links less than field notes  
call for, but course to both is  
correct also distance to East one  
corrected Var 350 Dec 00059

copied

copied on page 300

SEE 10-35-10-E cont'd DEC 31-10

North from 1/4 Post Bet-10-15. Var 4° E

& set this post from Bath O-B

7941 fell 65 Links W of 1/4 Post. could not find old Bearings looked a long time with 5 men found Post set by same ones who had also made diligent search but could not find it. The govt's line was plain & as the location of this Post agreed with govt notes I used it whenever set did so by running a Random from corner to corner. connected 1/4 line South 20 chains also set center of Sec at junction connected 1/4 lines

	Tamarac	14	N	26 1/2	W	17
	Fin	8	S	38	E	27
Distance to	N 1/4 Post					3989
"	"					3952
"	"					4048
"	"					4000

SEE 10-35-10-E continued Jan 1. 1900<sup>75</sup>

at 199 1/2 N of center Set 1/8 Post

Tam 10 N 19 W 36  
50 9 S 65 E 23 1/2

" 1974 S " "

Set 1/8 Post

Tamarac 5 N 10 W

" 2024 S " "

Set 1/8 Post 293

January 1st 1898

" 2000 W " "

Set 1/8 Post Tam 8 N 70 W 10 1/2  
100 9 S 7 E 27 1/2

West from S 1/4 Post Var 230 E

I started on this course as govt line showed this angle

3956 fell 175 N of corner set by someone who had set it from proportions measurement old corner could not be found this corner is at junction of section lines and has been used by others & I used it <sup>500</sup> at equidistance Bet corner & 1/4 Post  
Set 1/8 Post Tam 11 N 40 E 10  
Nemio S 69 W 20 1/2

North from this 1/8 Post Var 330 E

3973 fell 28 W of 1/8 Post

copied on Page 300 county record

copied on Page 300 county record

SEE 10-35-10-E cont Jan 2<sup>nd</sup> 1900

North from W/4 Post Var 4<sup>06</sup>  
4017 feet 36 E of Sec cor set new  
Post from 2 Original B

S&E 1/8 Post Equidistant Bet 1/4 P. & Cor  
N Pine 18 N 89 1/2 E 686

East from this 1/8 Post Var 3<sup>58</sup> E

4033 feet 19 links N of 1/8 Post  
connected line west to 1/8 Post  
Var 337 D&C 00049

North from E/4 Post Var 4<sup>06</sup> Jan 3<sup>rd</sup> 1900

3914 feet 13 W of cor which I set from the  
Birch which is broke off & down  
Marks are on down Post found  
Some ones cor 44 links to far N  
connected S. Var 3<sup>57</sup>. D&C 00035

1959 set 1/8 Post W Pine 12 N 40 E 6  
20 12 N 1 W 1

West from this 1/8 Post Var 3<sup>20</sup>

4047 feet 4 links N of 1/8 Post connected  
line back to place of beginning  
Var 329

Record  
county  
Pays 300  
an  
copies

SEE 10.35-10-E Jan 3<sup>rd</sup> 1900.<sup>44</sup>

N from E 1/8 P. on SEE line Bet 10+150 Var 3<sup>50</sup>  
3964 feet 24 E of 1/8  
connected South from  
1/16 Post Var 3<sup>57</sup>. D&C 00065

SEE 11-35-10-E January 4<sup>th</sup> 1900

South from W/4 Post Var 4<sup>06</sup> O.B.

3853 feet 80 links East of SW corner  
one old Bearing is ok except the  
Marks are nearly defaced by time

The Birch called for in govt notes  
is a W Pine & had been moved  
and set up beside the W Pine NW  
from cor. I placed it in its  
proper position & braced it up.

Set New Post  
connected back & set 1/8 Post  
W Pine 20 N 79 E 69  
20 18 N 38 W 41

connected Var 249 D&C 208

county  
Pays 301  
an  
copies

copies an Pays 300  
county



SEC 11-35-10-8 Jan 4 1900  
East from SW corner Var 330-8

3600 Pelican Lake

6285 over "

7840 full 49 S of corner Set from

Both O.B could not make the  
corner agree with govt notes  
used distance to set new Post  
west corrected var 351 SEC. 00062

1960 Set 1/8 Post { WP line 26 N 76 E 210

3920 " 1/4 " on No trees near

5880 " 1/8 " { Spence 6 N 79 E 14

7840 SW corner corrected line W  
from W 1/8 Post to SW cor

could not find meander on  
either side of Lake, all burned  
off on W side + blown down  
on East side and rotted

Copied on Page  
301

Records

SEC 11-35-10-8 continued Jan 5 1900  
East from W 1/4 Post Var 330 E

400 leave creek Bottom

2400 Tote Road to Monies

2800 Left Bank Pelican River Runs NW

3000 Right " " " " W

3925 Pelican River 40 links wide " S

6260 " " 25 " " " N

7840 full 121 S of 1/4 Post. Set New Post  
from SW Beams, the Sugar is  
rotted down but is there & only  
used the Birch

corrected Var 423 SEC 00154  
corrected line west to W 1/8 Post

South from E 1/4 Post Var 330

3930 full 59 E of S.E. Corner

corrected N Var 239 SEC 00150

1965 Set 1/8 Post

{ Fin 8 68 1/2 W 37  
Spence 10 59 E 10

Records

County

North corner 1/4 East in Rowan Co. 1345  
7797 feet from center of Post

connected to corner of Post at center  
of corner connected to corner

Var 311

Doc 60097 N Pin 32 N 44 W 92  
no other near

Post 8901

" S " " 3896

" E " " 3944

" W " " 3897

at 1950 1/2 N of center Set 1/8 Post

{ N Pin 24 S 14 E 11 1/2

W DO 10 N 3 W 16 1/2

" 1948 S " "

{ Tam 12 N 82 E 31

DO 12 S 81 1/2 E 28 1/2

" 1972 E " "

{ Tam 7 N 36 E 14 1/2

DO 7 S 14 1/2 E 12

" 1948 1/2 W " "

{ N Pin 15 N 61 W 12

DO 16 S 39 1/2 W 53

copied on Page 301

country read

□ □ □

11-35-10-6 case Jan 7 1859

connected to Post corner of Rowan Co. 2506

3811 feet from center of Post

connected to corner of Post at center

of corner connected to corner

3928 1/2 feet 3 1/2 South of 1/8 Post

connected N. E. corner at

junction of connected lines

1 N Pin 7 N 1 W 14 1/2

1 W Pin 12 S 3 W 56

connected all the lines over that

bounded Gilkey Anson's land

finished Sunday night

January 7 1900

this Page as copied

on Page 301

country read

+++

See 32. 41-9-January 11-1900

West from N.E. corner set by me Var  $330^{\circ} 8'$   
 3994 1/2 full 11 links N of 1/4 Post which  
 I set from N origin bearing  
 which down made on new bearing

IN Pin 12 N  $68^{\circ} 190'$

west from N 1/4 Post Var  $330^{\circ} E$

4028. full 74 N of corner which I  
 set from the aspen stump. could  
 not find. there are two goat teams  
 at this post. but are not mentioned  
 in goat notes. they have one  
 BT mark. I took their bearings

W Pin 12 S  $54^{\circ} W 40'$   
 N 50 12 N  $27^{\circ} E 42'$

there is a Post at this corner set  
 by Briggs but I think it wrong  
 connected east & found middle  
 did not work right in swamp  
 at 1/4 Post & threw me to far  
 North connected var west from  
 1/4 Post is  $4^{\circ} 30' E$

See 32 continued Jan 11-1900

2014 set 1/8 Post

Spencer 4 N 3 W  $27 1/2'$

Do 4 S  $21^{\circ} E 10'$

connected E from 1/4 Post

Var  $340'$

1997 1/4 set 1/8 Post

W Pin Stud 20 S  $38^{\circ} 8' 142'$   
 Dead W Pin 20 S  $58^{\circ} W 143'$

connected E 1/8 line from 1/4 line  
 N to 1/8 Post. I had run this 1/8 line  
 about a month ago & set reference  
 Stake which was 7 links to  
 to far E + + 8 links to far South

Sec 33-41-9-E Jan 20-1894

South from N 1/4 Post which  
I set from North O. B. which  
is down made new bearing

N Pin 15 S 88° 87

Var 3° 30' E

7863 fell 11 links W of S 1/4 Post. which I  
had set in Nov 1899. corrected N  
East from S 1/4 Post Var 3° 15' E

1939 fell 10 links South Meander

original Post is standing with  
North original bearing is there.

But nearly buried down  
set new Post at this bearing  
corrected West to 1/4 Post

Sec 4+5 40-9 Jan 12-1900

North from corner to 4+5-8+9  
Var 128° E

3944 fell fell 3 links West of 1/4 Post set from  
N 1/2 Bearing "W Pin"

continued north on same line & course

could not find the meanders on either  
side Lake, but found the distance to  
the Lake 5300 as returned in govt notes

also the distance across was nearly  
correct being 6015

7604 4th correction line 10 chains East  
of corner of 32+33. could not find  
original bearings everything is burned  
set corner to 4+5 53/4 links E  
of intersection with correction line

W Pin stub S 35° W 50  
do " S 83° W 76

The stub standing 83° W had bearings  
and facing E made by Samson  
unknown to me I did not

correct this line S as I only wanted to  
get the corner to 4+5

Sec. 4+5 continued Jan 13-1900  
 West on Concession from ear to 4+5  
 Var 3-15 East

9019 feet 76 links N of corner to 31+32  
 connected West Var 3+4 25000 95

1999 East of corner to 31+32 found corner  
 to 5+6 said to have been set by

William Allen  
 I could not find original bearings  
 nearly all the timber is down

The line running South crosses  
 creek at the proper distance given  
 in govt notes & used this  
 corner. the distance between the  
 corner to 4+5 & 5+6 is 7020

1/4 Past Equidistant between  
 these corners

}	N	Pine	18 S	51 E	43 1/2
			20	15 S	75 W

Set 1/8 Past Equidistant between

1/4 Past and ear to 4+5. 1755 W  
 of corner to 4+5

}	N	20	17 S	45 W	1
			17 S	9 W	44

connected line East to corner

Sec 4-40-9 Jan 14-1900

South from 1/8 Past on concession line  
 1755 W of ear to 4+5 Var 1.15

Which is an intermediate course  
 1450 intersect Pickens Lake

This work was done for  
 Balsick & Wilson was cutting out  
 Lots 5 in Sec 4 and Lot 1 in Sec 5

Lot 4 is 245 chains Short S+W  
 " 5 is Very large

finished Sunday Jan 14-1900

B&C 13+24 - 36-108 Jan 17-1900

north from corner to 23-24-25+26

(Set Post from Stumps of OR)

copied on page 312  
Jan 7<sup>th</sup>

- 2000 bet stake - Fir 8 - S - 3. links
- 4000 " " HEM 9 S 19 W 18 1/2 "
- 6000 " " Cedar 16 S 5 W 15 "
- 8000 " " Birch N 75 W 9 "
- 14946 full 1020 East of corner to 11-12-13-14

Set By Don - connected South  
 7473 Set Temporary corner  
 connected 510 west of Random 002, 12.5  
 Var 1057.5  
 west from corner on Range line  
 corner to Sec 13-24-18-19 Var 10 W

January 19-1900

Set Post from 20B

all an down Tam + Spruce  
as the others are gone

223.59 full 118 South of cor to  
 15+16 - 21+22 Set Post  
 from NE C.B. connect Var 1.25 W

Proportioned Distance and  
 Set Temp ear to 14+15-22+23  
 county road

at 14911 W of Range Line

copied on page 312

Temp corner Tam 12 N 25 W 3  
 80 15 S 7 E 32 1/2  
 marked bearings with three notches  
 cut with at This Post Stand 79  
 links N of Random - there is a Tam  
 tree on Random 2 chains E. Marked  
 the same as bearings on 2 sides

7450 W of Range line + 39 1/2 West

N of Random Set Temp ear  
 connected Var of this line to Temp  
 corner in 118 W = Dec 53

Run N on connected Var of  
 E + W line 451 chains

Run West on connected Var  
 of N + S line 457 chains  
 which springs E + W line  
 N. 451 chains + N + S line  
 W. 457 chains + Set corner

to 13+14-23+24  
 cedar 12 N 71 E 20  
 No 10 S 40 W 28  
 county road

SEC 13+24-36-10 cont.

1866<sup>3</sup>/<sub>4</sub> North of corner to 13-14-23-24

Set 1/8 Past } <sup>Plugs</sup> 128 29 W 32  
                  }    78 37 28 23 1/2

1851<sup>3</sup>/<sub>4</sub> South of same corner set

1/8 Past } <sup>Tam</sup> 20 N 78 32  
           } <sup>Fin</sup> 12 S 42 W 6

1863 East of same corner set

1/8 Past } <sup>Fin</sup> 75 65 N 10 set with pocket  
           } <sup>compass</sup>

Tramp corner was set  
with Pocket compass

corner to 23+24-13-14 Stands

450 1/2 N of E+W Random at 7450 W of  
Rams line and

967 W of N+S Random at 7399 N of cor

to 23-24-25-26

corner of Var for N+S sec line

bet 13+14 is 7.17 E x

corner of <sup>E+W</sup> sec line bet 13+24 x

is 5-19 W x

corner of N+S line bet 23+24

is 14.24 E

all copied on Page 312

county  
Record

SEC 5-27-10-8 Feb 5-6 1900<sup>91</sup>

South from N 1/4 Past original Beans

used Doug Random which was 29  
links W of Past and south on even

copied on Page 323

needle

1846 to 1/8 Past and found Random

was 20 links west of Past

cornered line north to 1/4 Past

East from North 1/4 Past Var 508

897 1/2 bell 283 N of ear old Beans

cornered west of set 1/8 Past

Equidistant bet 1/4 Past & corner

{ Tamarae 9 S 1/2 E 11 links  
Kenee 9 N 69 E 12 do

cornered Var 1.38

county record

Work Done for M.W.V. Co

at Request of F Robbins

8E@99-36-8-E <sup>++</sup> Apr 20 1900

West from S. 1/4 Part set by Barr

1974 Dows 1/8 line corner <sup>Day 345.5</sup>

3950 <sup>Road</sup> center of line in Road

7900 feet 3 1/2 links N of 1/4 Part set by Barr

connected East and set 1/8

2 1/2 links north of Random and Equidistant between

center & W 1/4 Part

W line stump 20 1/2 E 28 1/2

20 16 S. 9 1/2 W 44

measured from center of

Cash Stump & tree does

not face toward Part

copied on Page 128 ~~county record~~

copied on Page 128 County record

7900	77
3950	3950
3980	3950
3950	3950

SEE 6-36-9-E

copied on Page 194

Survey of Dumping ground for city  
I first commenced at 1/16 Part in

center of NW 1/4 Rpm west Var 41° E  
found an error 100 ch Stake to 2180  
2482 feet 45 1/2 S of 1/8 Part on Range line

commenced 210° E at W 1/8 Part  
connected line East to Starting Point

chains went west on connected line

700 chains to set Part for SE corner of  
Dumping grounds Hemlock 8879 E 21

Thence west on connected 1/8 line

1000 + set Part for SW corner of  
dumping ground 17 chains from SE corner  
of NW NW 6-36-9-E } Dead Birch  
8 N 56 W 4 links

Thence North at Right angles with  
1/8 line 750 chains to set Stake for

NW corner of Dumping ground  
W P Stump 16 S 31 1/2 E 29 1/2

Thence east at Right angles 3.30 chains  
to set mark & set meander

W line 10 S 75 E 43.



Dumping ground continued  
North from stake at SE cor of  
Dump ground at Right angle  
with  $\frac{1}{8}$  line 6.25 chains to west  
marsh & set Post No bearings

Placed Rock around all  
monuments

Commenced April 23 1900  
finished " 24 1900

Copied on Page 194

County Record

May 2 1900

SEE 5-42-8-8

East from center set by manseep  
1701 feet 3 links N of  $\frac{1}{8}$  Post set by manseep  
3400  $\frac{1}{4}$  Post

North from center Van 00  
3635 hill 219 W of  $\frac{1}{4}$  Post  
connected South Van  $30^{\circ} 12' W$ . SEE 6.03  
185  $\frac{1}{2}$  North of center set  $\frac{1}{8}$  Post  
Sugar 14 N  $49^{\circ} 8' 42''$

East from N  $\frac{1}{4}$  Post Van  $145^{\circ} W$   
2890 hill 238 S of meander govt  
measurement calls for 1896

corrected west and set  $\frac{1}{8}$  Post  
1997 East of  $\frac{1}{4}$  Post and  
164.80/100 N of Boardman  
SEE 8.24  
Van 50% Spence 58  $19^{\circ} 12' E$  67  
May 4 - 1900

North from  $\frac{3}{8}$  Post on Ex W  $\frac{1}{4}$  line  
3700 hill 167 W of  $\frac{1}{8}$  Post on Town line  
Van  $60^{\circ} W$

connected South Van  $82^{\circ} 27' W$  SEE 4.51  
set Temp  $\frac{1}{8}$  Post  $87^{\circ} 1/2'$  N of  $\frac{1}{8}$  Post  
on  $\frac{1}{8}$  line

S&C 1-42-8 E May 7<sup>th</sup> 1900North from S.  $\frac{1}{4}$  Post var  $4^{\circ}$  E

7930 feet 2.43 chains W of  $\frac{1}{4}$  Post orig B  
 connected South to center  
 connected var  $2^{\circ} 15'$  E S&C 306 +

East from W  $\frac{1}{4}$  Post var  $1^{\circ} 33'$  E

8470 feet  $30\frac{1}{2}$  links S of  $\frac{1}{4}$  Post orig B  
 connected W of center

" Var 14 $^{\circ}$  S&C 00032

Set stake for center at intersection  
 of connected  $\frac{1}{4}$  lines

Distance to N $\frac{1}{4}$ Post	3939 chains
" " S " "	3991
" " E " "	4207
" " W " "	4263

1969 N of center set  $\frac{1}{8}$  Post  
 { Maple 108  
 Birch 88

1995 $\frac{1}{2}$  " " set  $\frac{1}{8}$  Post

2103 $\frac{1}{2}$  E of center  $\frac{1}{8}$  Post

2131 $\frac{1}{2}$  W " center  $\frac{1}{8}$  Post

S&amp;C 1-42-8 E cont May 9-1900

North from E  $\frac{1}{4}$  Post var  $4^{\circ}$  E

4032 feet 27 W of corner orig Bearing  
 Repartitioned distance & set  $\frac{1}{8}$  Post  
 1991 N of  $\frac{1}{4}$  Post

{ Birds 9 S 68 E  $8\frac{1}{2}$   
 50 11 N 41 W 26  $\frac{1}{4}$

West from N  $\frac{1}{8}$  Post on Range line  
 var  $3^{\circ} 30'$  E

4042 feet  $1\frac{1}{2}$  links N of  $\frac{1}{8}$  Post  
 connected S to  $\frac{1}{8}$  Post var  $22^{\circ}$  S&C

South from E  $\frac{1}{4}$  Post var 856

2984 feet 37 links S of corner var 1000

Read  $4^{\circ}$  E at corner  
 connected N to  $\frac{1}{4}$  Post

connected var  $32^{\circ}$  S&C 98

finished May 11 1900

Lot 6 - 8806 - 34-11-8

Survey made to bind

that part of this lot (which has  
 copied on Page 374  
 been vacated by judgement of  
 court) from the part which  
 remains pattd.

I commenced S.W. corner  
 of said lot then run East on  
 section line between sections  
 6 + 7 - 725 feet & set stake

and placed stone around it  
 thence N at right angles  
 with Sec. line 420 feet and  
 set stake and placed rock

around it - thence east parallel  
 to Sec line 663 feet to west  
 side of Michigan Street and  
 set stake and placed rock

around it thence north at  
 right angles with section line  
 County record  
 set stake and set

stake and placed rock around  
 it & made bearings to same

which are { Item 15 N 41 W 14  
 50 7 S 81 1/2 E 7 1/4

Survey commenced  
 May 19 - 1900 & finished May  
 21 - 1900 work done for

Order so Wis  
 County record

1885  
 37.70  
 39.70

See 33-379-8 May 28" 1900

South from N 1/8 Part (Set by Dan)  
 copied on page 233  
 an section at 32+33 - Van 356 E

2094 feet 89 links W of 1/4 Part org B

connected N Van 5, 80 Dec 425

East from W 1/4 Part Van 208

6918 feet 735 N of 1/4 Part org B

W connected Van going E 400 W Dec 1062

South from N 1/4 Part org B Van 408

7201 feet 653 - E of 1/4 Part org B

connected Van going S 112 W Dec 864

East from NW cor org Remainder 40 W

2165 1/8 Part Set by Dan

4330 1/4 Part county record of field notes

connected 1/4 lines + set centers

{ Town 3 78 1/2 W 24  
 Spruce 3 10 1/2 E 20 1/2

Distance to N 1/4 Part 3963 1/4

" " " " 3237 3/4

" " " " 3046

" " " " 3872

at 1936 W of center set 1/8 Part +

{ W.P. Stump 16 N 71 W 12

" " " 16 N 71 E 32

continued □ □

at 19813/4 N of center set 1/8 Part

{ Spruce 3 N 3 E 21  
 DO 3 N 64 1/2 W 15

East from N 1/8 Part on W section Van 40 W

4133 1/2 feet 101 S of 1/8 Part

connected Van Dec 244

South from W 1/8 Part on W section Van 1 W

4080 feet 218 1/2 W of 1/8 Part

connected these 1/8 lines and set

centers of N W 1/4 at their  
 intersection

{ W.P. Stump 12 N 5 W 27 1/2  
 DO 20 16 N 65 E 26

Work done for Corvide co

finished May 31 - 1900

□ □

all copied on page 233

County Record of field notes

Survey of Road for Town Sugar Camp  
 June 1st to 3-1900  
 beginning at 1/4 Post Between  
 sections 21+22-39-9-E set by  
 Copied B F Don on Page 295  
 thence East Var 1108 on old Random  
 2319 feet 8 links Nob. 1/8 Post  
 4638 " 16 " " " center  
 8283 " 32 " " " 1/4 Post No Bearings  
 East from 1/4 Post Bet 22+23  
 Var 408  
 8180 feet 113 South of 1/4 Post No Bearings  
 connected this line west from  
 Eagle River Road which crosses 1/4  
 line 60.58 chains East of 1/4 Post  
 Bet 22+23  
 county record of field notes  
 also cancelled E & W 1/4 line W  
 from 1/4 Post Bet 22+23 to  
 center of sec 22  
 all in 39-9-E  
 commenced June 1st  
 and finished June 3 1900  
 for Oneida county □□

Bearings for B F Don  
 Road 60.58  
 on E & W  
 1/4 line W  
 sec 22  
 W.P. head 10860824

SEE 25-42-8-E June 4-1900  
 South from East 1/4 Post O. Beans  
 Var 545' E  
 4000 feet 172 E of corner old  
 Bearings all rotten New bearing  
 made { W PINE 7 N 2 1/2 W 8  
 1158 { W Birch 10 S 36 E 54.  
 connected North and set 1/8 Post  
 { N PINE 8 S 59 W 13  
 5020 10 N 2 1/2 W 12  
 connected line North to 1/4 Post  
 Var 317. E SEE 00043  
 East from S 1/8 Post on N + S  
 1/4 line set by W D Guzman  
 Var 358  
 4009 feet 5 links S of 1/8 Post on Range line  
 connected west from center of  
 S E 1/4  
 East from S 1/4 Post org Beans  
 Var 108  
 4010 feet 152 N of sec corner  
 connected west from 1/8  
 Post over

Sec 25-42-8 June 4-1900

Set 1/8 Post 2005

{ Spence	9	68 1/2	W	14 1/2
{ Fin	6	34	E	6

connected Sec line from 1/8 P

to Sec corner

connected Var 115 W Dec 380

= June 6 =

North from E 1/4 Post on S Sec

line Var 315 E

3881 feet 25 links East of Post on E &amp; W 1/4 line

West from E 1/4 Post Var 210 W

(I am on this Var as I was told  
that was the true course)

4012 feet 254 chains N of center Set by

W.D. Guarnan

connected East + set Post no

" Var 127 Dec 60 32

bearings

connected 1/8 line South and

Set 1/16 Post in center of

2 E 1/4 { connected Var for E + W 1/4 line

" " " " " " " " " " " "

" " " " " " " " " " " "

" " " " " " " " " " " "

Impaled on 25-42-8  
cut out S W 5 E  
measuring over  
to fallen S E 1/4

Sec 36-42-8 June 7-1900

South from NE corner Var 315 E

3984 feet 19 links W of 1/4 Post orig. Bears

connected Var 331 Dec 42 at

1992 Set 1/8 Post

N. Pine 24 N 55 W 15

W. Birch 7 S 57 E 18

West from E 1/4 Post Var 20 E

7965 feet 21 links S of 1/4 Post only one

old bearing left + that is down

Set new Post connected Var 153 Dec 27

North from S 1/4 Post Var 330 E

4090 intersect E &amp; W connected 1/4 line

8287 feet 32 East of 1/4 Post

connected East to 1/8 Post

" Var 343 Dec 38

Set center at intersection of connected

1/4 lines. Sugar 5 N 61 W 11

W Pine 10 S 71 E 17

Distance to N 1/4 Post 4197

" " S " " 4090

" " E " " 4012

" " W " " 3963

over

SEC 36-42-8 cont June 8-1900

at 2098 N of center set  $1/8$  Post  
 Birch 8 N 68 E 23 1/2  
 do 9 S 41 E 14

East from N  $1/8$  Post on N+S  $1/4$  line U 35° E

4013 full 13 N of  $1/8$  Post on Range line

finished 36-42-8 cut out

N  $1/2$  NE - June 8-1900

June 10  
 May 26 18  
 May 32

SEC 30-42-9-E

June 9-1900

East from SW corner Var 3° 15' E

1625 Pond

2070 over Pond by offset South 2,40 chains

4221 full 4 links South of  $1/4$  Post org B

Set Post + made New Bearings

B oak 10 S 49 1/2 E 29

W Birch 8 N 39 W 25

connected West + set  $1/8$  Post at

1986 1/3 West of  $1/4$  Post

W Pine 10 S 10 W 5  
 N 50 7 N 14 W 11

D

connected Var  
 3° 24' E  
 Dec 19

SEC 30 Contn June 9-1900

North from S  $1/4$  Post var 3° 30' E

1980

1980 was 40 links W of "Belley's"  $1/8$  Post

3970 "  $1/4$  " E " " center

7988 full 48 " E "  $1/4$  Post any Bearing

connected Var from S 350 DEC 60

" " N 250

June 10-1900

West from N  $1/4$  Post var 3° 20' E

4204 full 6 links North of corner org B

connected East and set  $1/8$  Post

1987 2/3 West of  $1/4$  Post

W Birch 8 N 10 E 26

do do 9 N 58 E 26 1/3

connected Var 3° 25' DEC 14

East from W  $1/4$  Post var 3° 25' E

4212 crossed N+S connected  $1/4$  line

8209 full 29 links S of  $1/4$  Post org Bearing

connected West var 3° 37' DEC 00 35

Set center of SEC at the intersection  
 of the connected  $1/4$  lines

W Birch 7 S 74 E 15

W do 6 N 13 E 14 cont

See 30 42-9 cont June 11-1900

Distance to N  $\frac{1}{4}$  Post from center 3992  
 " " S " " " " 3996  
 " " E " " " " 3998  
 " " W " " " " 4211

at 1998 S. of center set  $\frac{1}{8}$  Post

{ W Birch 6 S  $38\frac{1}{2}$  E 4  
 " Pine 10 N 5 E 32

at 1999 East of center set  $\frac{1}{8}$  Post

{ W Pine 16 S 85 W  $3\frac{1}{2}$   
 " " 18 S 77 E 6

East from S  $\frac{1}{4}$  Post Var  $3^{\circ}30'$  E3860 full 29 links S of corner org<sup>n</sup> beamscorrected Var  $356^{\circ}$  DEC 00079SE  $\frac{1}{8}$  Post Equidistant bet<sup>n</sup>  $\frac{1}{4}$  P. & cor

{ W Birch 7 S 78 W 11  
 " " 4 N 16 E  $17\frac{1}{2}$

North from S.E. corner Var  $130^{\circ}$  E4001 full 112 East of  $\frac{1}{4}$  Post

My line followed govt line

to 2000 chains. there is some local

attraction at that point

corrected Var  $306^{\circ}$  DEC

See 30 42-9 cont June 12-1900

Set  $\frac{1}{8}$  Post at  $2002\frac{3}{4}$  chains

{ W Birch 9 N  $5\frac{1}{2}$  E  $4\frac{1}{2}$   
 Red oak 11 S 50 W 6

West from S  $\frac{1}{8}$  Post on E S&E line

Var  $3^{\circ}40'$   
 3979 full 10 links N of  $\frac{1}{8}$  Post

corrected Var  $349^{\circ}$  DEC 00025

June 13

West from S  $\frac{1}{8}$  Post on N+S  $\frac{1}{2}$  lineVar  $345^{\circ}$  June 13-19004220 full 5 links N of  $\frac{1}{8}$  Post on R. linecorrected Var  $355^{\circ}$  DEC 00012South from E  $\frac{1}{8}$  Post on E+W  $\frac{1}{4}$  lineVar  $3^{\circ}30'$ 3972  $\frac{1}{2}$  full 27 links W of  $\frac{1}{8}$  Postcorrected Var  $420^{\circ}$  DEC 00048corrected line + set  $\frac{1}{16}$  Postat center of SE  $\frac{1}{4}$ 

{ N Pine 24 S  $54\frac{1}{2}$  W  $19\frac{1}{2}$   
 " " 26 S 23 E  $25\frac{1}{2}$

finished see 30 42-9 at 5 P.M.

June 13 1900



110 Sec 31-42-9 June 14 1900

East from West 1/4 Post was 330' E  
8157 full 3 links North of Post orig Bear

South from North 1/4 Post was 330' E

7950 found Town line + 1 Bearing a W. Pin  
Stub and Stands almost S from  
Town line, as I did not have field  
notes and Post was gone I set Temp  
Post as near as possible, the bearings  
being only 20 links from Town line  
and facing directly North  
corner E+W+N+S 1/4 line + set Temp  
center at intersection

Distance to N 1/4 Post	3990 1/2
" " S " "	3959 1/2
" " E " "	3949
" " W " "	4208

East from N 1/8 Post on Range line

Was 330  
4263 full 30 South of Post, very rough  
ground chaining should have  
been 4189

111 Sec 31 42-9 cont June 15-1900

North from W 1/8 Post on E+W 1/4 line  
3974 full 43 1/2 <sup>was 240's</sup> E of Post  
corrected South of set Temp  
1/16 Post.

as I could not positively identify  
South 1/4 Post - I set Temp on center  
and all other Posts which is  
regulated by S 1/4 Post

my opinion is the S 1/4 Post  
is just where I have set Temp  
Post.

This finishes my work for  
Masterson Lbr Co at present  
I go home tomorrow



June 27-1900

Survey of Road for Town of Sugar Camp

Beginning at an Iron Pin which stands in the Barnyard at Robbins farm and said to be the corner to see 3-4-9+10

Posted on Page 212  
To see 3-4-9+10

Thence East by offset of 20 links  
50 feet north to line  
around Barn 150 links to line  
county record

Var 4°45' E

350 Brown Robbins R.R.

375 creek bottom

500 " 150 links wide that includes island

550 over creek to bottom of Hill

600 on Top of Hill 12 feet Rais

115 1/8 Post set by Don

661 Hill 4 links South of see corner  
connected west Var 4°47' E

830. Set 1/4 Post a gas pipe 3 feet long  
Lower end turned east so it cannot  
be pulled up - Placed same kind  
of pipe at 1/8 Post set by Don

Run South to 1/16 Post Var 10' West

899

1955 " North 1/16 " Var 7°06'  
only - The Road is an E & W line  
marked June 29 " 1900

July 11-1900 - 36-11 + 36-10

Survey of Road for Amos Co  
Caption on Page 163

Beginning at 1/4 Post Between  
Sections 19+20 - 36-11 - E.O.B  
Some some one had made survey  
& thence north on section line

Var 10°40' E

3800 intersect Tamarac + Alder Swamp

3350 over " " " " "

3600 intersect " " " " "

4249 Hill 6 links E of Post O.B

connected S for Road

" Var 10°45' D 14/100

West from cor to 17-18-19-20

Var 3°38' E

850 over Tamarac + Alder Swamp

2400 Tamarac Spruce Cedar + Alder Swamp

4146 Hill 44 links South of 1/4 Post O.B

about 1/2 of Swamp is low ground  
and cannot be called Swamp  
county record over

new bearings  
for corner  
Jan 28 12 2 W 43  
150

Road for county continued  
 West from 1/4 Post Betw 18+19-36-1  
 Van 30<sup>E</sup>  
 400 high ground  
 1050 Tam + Spruce alder + cedar Swamp  
 3500 Hardland  
 4916 bell 107 chains South of corner  
 connected East for Road  
 " Van 147<sup>E</sup> Dec 2, 18

East from car to 13-14-23=24 Van 420<sup>W</sup>  
 3000 chains low ground  
 4200 " Tam + alder Swamp  
 4600 " over " "  
 5000 " Swamp  
 5100 " over " "  
 6500 " Tam + alder Swamp  
 6700 " over " "  
 7000 " Tam cedar + alder Swamp  
 7450 " full 124<sup>S</sup> of corner  
 connected East for Road  
 " Van 579<sup>E</sup> Dec 1

exhibit on Page 363  
 county record

~~192~~  
~~179~~  
~~47452~~  
~~1864~~

West from car to 13+14-23+24-36-10-E  
 700 over cedar + spruce swamp  
 5700 Intersect " " " "  
 6600 over " " " "  
 6800 Intersect " " alder "  
 7700 over " " " "  
 8000 Intersect " " " "  
 8200 over " " " "  
 8800 Intersect " " " "  
 8950 over " " " " lowland  
 10700 Tam third alder Swamp  
 14969 bell 196<sup>S</sup> of corner 15-16-21-22  
 connected East Van 16<sup>W</sup> SE-131  
 7871 Set 1/8 Post  
 Tam 14<sup>N</sup> 17<sup>W</sup> 69  
 50 10<sup>S</sup> 30 1/2<sup>E</sup> 38 1/2

3742 1/2 Set 1/4 Post

Tam 8<sup>N</sup> 12<sup>W</sup> 28 1/2  
 50 9<sup>S</sup> 16<sup>W</sup> 38

7485 Set Post car to 14-15-22-23  
 See Page 144 for X  
 corner corner X Tam 24<sup>S</sup> 4 1/2<sup>W</sup> 71  
 after setting this  
 Post. I found I had  
 made a mistake of 5 links and  
 moved Post 5 links West so  
 the bearings show the Post to  
 be 5 links further East than it  
 is connected this line to car of  
 13-14-23-24 to be used as a Road  
 West from the corner Point Jul 18<sup>th</sup> 1860

Sec 29-42-7 July 21-1900

South from NW cor Var 3° E

I set Post from O.B. the south one is down

3218 feet 12 1/2 links South of Meander which

I set from East O.B. west one is gone

and the east one is nearly gone

connected this line North and set 1/8

Post 2087 South of corner  
 connected Var 3° 13' E  
 Sec-39 } WP in stump 22 N 37° E. 34

East from NW cor Var 33° E

2025 feet 3 links S of Sawtooth 1/8 Post

No bearings made

4044 feet 96 links South of 1/4 Post Org. B.

connected west Var 2.10 DEC 235

2022 set 1/8 Post { N Pine 8 N 30 1/2 E 7  
 { W 7 S 36 1/2 W 23

South from N 1/4 Post Var 3° 30' E

8082 feet 275 East of 1/2 corner

Set Post from Tamarac-Spruce is  
 gone + Tamarac is broken off 3 1/2 feet  
 above the ground

32-427 cont July 21<sup>st</sup>-22-1900

I found the bottom of old Post under the

mass - did not connect this line as

I only cared to get the corner

connected Var  
N 133° E

South from W 1/8 Post an N Sec line

To ascertain the course on which to

run this line, I took the course

of west Sec line + N + S 1/4 line and

run on an intermediate course

between them which is 2° 23' E Var

5168 Intersect Trout Lake and squared

up W Pine 7 inches in dia for post

Meander Post from which a white

Pine 18 - bears N 3 W 5 links

quit work at 4 PM it is Sunday

Sec 29-42-7

East from South 1/4 Post Var 3° E

4074 feet 32 links South of corner set

Post <sup>from</sup> Original Bearings. Maple is down

connected west Var 32° E Dec 78/100

Sec 29 - 42-7 cont July 23<sup>24</sup>/1900

North from S.E. corner Van 3°45' E

3907 feet 177 East of 1/4 Post ang. B. New Post

connected South Van 62 1/2° E Sec 4.53

North from East 1/4 Post Van 3° E

4013 feet 228 East of corner ang. B.

connected East Van 61 1/2° E <sup>82508</sup>

West from N.E. corner Van 115° East

4082 feet 6 links S of 1/4 Post ang. B.

connected E Van 114 1/2° S E 15/100

West from N 1/4 Post - Van 93° E

500 loose timber & some Burned Baren

4500 NO corner anything Burned

Run South with Pocket compass

could not find 1/4 Post, but did

find 3/8 Post set by ang. B. McDonald

in 1892 no bearings. No govt line

as there is no timber in 29

along West line and a little

Near N 1/4 Post the paraman seems

not to try to locate NW cor

Sec 9 36-9-E July 31<sup>st</sup> 1900

commencing at a Stake which stands <sup>on the line</sup>  
460 1/3 Chains South of 1/4 Post Bet 8 & 9 in

Town 39-6-E

Thence S E	3.00	Chains + Parallel	with Road
" N	33 1/3	" " "	with Sec line
" NW	3.00	" " "	Road
" S.	33 1/2	" " "	Sec line

to place of beginning

See 27-39-7 August 2 1900

North from E 1/8 Post on S. Sec line  
Set By BF Don Var 4° E

2059 full 37 1/2 W of 1/16 Post Set by Don  
connected S Var 2° E Dec 00182

See 34-39-7-E

South from E 1/8 Post on N Sec line  
Set By Don Var 3° 30' E

4016 full 70 E of 1/8 Post connected N  
and set meander  
9.48 S of 1/8 Post } N Pms 14 N 79-87 1/2

East from center of Sec Set By DNU  
copied on Page 111 Var 3° 30' E

3938 full 12 links N of 1/4 Post org B.  
connected West Var 3° 17' E

1969 Set 1/8 Post MAPLE 7 S 79 W 16  
ROCK 9 N 48 W 26

North from E 1/4 Post Var 3° 20'

3602 full 41 links W of meander  
connected S Var 2° 40' Dec 114

1939 North of 1/4 Post Set 1/8 Post

W Pms 26 N 2 E 24  
DO 20 S 51 3/4 W 48.58

See 34-39-7 east 2 August 3 1900

North from center (the bearings are

W Pms 30 S 49 1/2 E 19  
N " 26 S 20 1/2 W 20

Var 3° 15' E

4055 full 127 W of 1/4 Post org Bearing  
connected S Var 1.27' E Dec 3.13

2022 1/2 Set 1/8 Post

N Pms 20 S 12 E 46

W DO 24 N 39 W

East from N 1/8 Post on N 1/4 line

copied on Page 111 Var 2° 15' E

225 intersect Lake county road

1340 over lake by offset South 3 1/2 chains

3935 full 1.73 1/2 chains S. of 1/8 Post

connected West. Var changed 1945

Set 1/8 Post at intersection of  
connected 1/8 lines

W. Pms 8 S 25 E 15  
W DO 22 S 26 1/2 W 14

Sec 34-39-7 cont Aug 4-1900

South from  $8\frac{1}{4}$  P. Var  $130^{\circ} E$ 3995  $\frac{1}{2}$  full  $139\frac{1}{4}$  W of cor arg B

I also found an Iron at cor

Placed there by Billy Gallus

and myself 3 years ago

went west on Towns Line

found  $\frac{1}{8}$  Post set by Dan

Put in new post &amp; made

new bearings

 $\left\{ \begin{array}{l} WP 11 N - 15 \text{ links} \end{array} \right.$ went west and set  $\frac{1}{4}$  Post

from arg B. and placed

Rock around same.

North from S  $\frac{1}{4}$  Post Var  $3^{\circ} E$ 

3939 full 82 links west of center

connected S Var  $140^{\circ} E$ 1969  $\frac{1}{2}$  set  $\frac{1}{8}$  Post $\left\{ \begin{array}{l} Sugar 12 N 25\frac{1}{2} 824 \end{array} \right.$  $\left\{ \begin{array}{l} W line 16 S 12 N 3 \end{array} \right.$ 

48658

copied on page 111  
County record

Sec 34-39-7 cont Aug 5-1900

East from S  $\frac{1}{8}$  Post on N+S  $\frac{1}{4}$  line Var  $3^{\circ} E$ 3982 full 30 links S of  $\frac{1}{8}$  Post on S side lineNorth from  $8\frac{1}{8}$  Post on town lineVar  $240^{\circ} E$ 3945 full 17 links west  $\frac{1}{8}$  Post on  $\frac{1}{4}$  lineSet a  $\frac{1}{16}$  Post at intersection  
of connected  $\frac{1}{8}$  line $\left. \begin{array}{l} NP 20 N 11 87 \\ WP 16 N 55\frac{1}{2} W 27 \end{array} \right\}$ 

finished in 34-39-7

August 7 1900

copied on page 111

County record

30	26
78	44
60	48
78	624
39	3



Sec 26-36-8 August 10-1900

North from South 1/4 Post Var 4° E  
(Stone in Road set by iron)  
7900 feet 330 Chans. E of 1/4 Post. ang. B.  
at both 1/4 Posts

connected South Var 6° 23' Dec 437

North from SW. corner Var 5° E

5639 feet, 78 links East of meander on left

Bank of Wis- River set Post from

SW Bearing which was hard to

Posted on page 126

identify, as marks were nearly

obliterated. Harret's nest in tree

where marked for meander

connected South and set 1/4 Post

3908 North of SW corner of proportional

distance between ear & meander

This sec. line crosses Wis River

at the foot of Hat Rapids

Bearings for 1/4 Post are

Jack Pine 8 N 15 E 14 1/2 links

do 10 N 66 E 59 do

Sec 26-36-8 cont'd Aug 11 1900

West from East 1/4 Post Var 5° E

7844 feet 69 South of 1/4 Post

connected East Var 4° 45' E Dec 88

set center at intersection of

connected 1/4 lines

Jack Pine 14 S 46 E 23  
do 12 S 15 W 65

distance from center E 1/4 Post 3891

" " " W " " 3953

" " " N " " 3971

" " " S " " 3921

county record

South from E 1/4 Post Var 7° 10' E

3953 feet 16 links E of Sec cor 1 ang Bearing

connected North 7° 20' E Dec 43/100

1976 1/2 set 1/8 Post } Rock 4x4 feet + 2 1/4  
High measurement

road to a creek running NE + SW and

one running SE + NW and intersection

of both S 89 1/2 E 49 1/2 links

Sec 26-36-8 Cont. Aug 11-1900

Set South  $\frac{1}{8}$  Part an N+S  $\frac{1}{4}$  line

Rock Pins 10 S 48  $\frac{1}{2}$  W 6  $\frac{1}{2}$   
100 10 N 37 W 8  $\frac{1}{2}$

East  $\frac{1}{8}$  Part an E+W  $\frac{1}{4}$  line

Part in open Swamp  
no bearings (none near)

North  $\frac{1}{8}$  Part an N+S  $\frac{1}{4}$  line

W. Pins 18 N 44 E. 100 Links

West  $\frac{1}{8}$  an E+W  $\frac{1}{4}$  line

Flat Rock S 75 E 19  $\frac{1}{2}$  links  
measurement made to west  
sid. of Rock Square face - Rock is  
1  $\frac{1}{2}$  feet high - 13  $\frac{1}{2}$  ft S E + N-W.  
2  $\frac{1}{2}$  " S W + N E

South  $\frac{1}{8}$  Part an West Sec line

W. Pins 14 S 61 E 39-

West from S  $\frac{1}{8}$  Part an E Sec line Var 4° 45 E

3944 feet 32 links South of  $\frac{1}{8}$  Part

connected this line East to  $\frac{1}{8}$  P

" Var 4° E DEC 134

This line is to used for Rod from

East Sec line for 19.72/100 chains  
for Town Belcan

finished Aug 1900

COUNTY

Page 126

on

copied

Reeds

Survey of Road from Monico  
to connect with road near Melue  
August 20<sup>th</sup> 1900

commencing at an Iron Pin  
which stands at a Point where third  
Street intersects East & West  $\frac{1}{4}$  line  
in Sec. 30 and 115<sup>th</sup> chains west  
of  $\frac{1}{4}$  Part Bet<sup>n</sup> sections 29 & 30 in  
Township 36 N Range 11 East, as  
shown by village Plat of Monico  
Oneida co wis.

Thence west on said  $\frac{1}{4}$  line Var 4 E  
2490 feet 20 links wide and SW

7933 Range line 634 South of

$\frac{1}{4}$  Part orig<sup>n</sup> B. badly burned

and cut for logs made new  
bearing (W Pins 24 N 48 E 185

connected for Rod for county

" Var 35 W DEC 799

copied on Page 394

county reeds

Road from Monico canty  
West from  $\frac{1}{4}$  Post on Range line between  
Sec 25 & 30 Town 36 Range 80 & 11  
Var  $8^{\circ}$  West

72.30 feet 5.15 South of  $\frac{1}{4}$  Post

Original Bearings

corrected East for county Road

Var  $120^{\circ}3'$  West

Made new bearings } W Pine 16 N  $22^{\circ}48'39''$

West from  $\frac{1}{4}$  Post Bet 25 & 26. Var  $7^{\circ}40' E$

I run on this course as I found a  
line said to be correct

8245 feet 5:19  $\frac{1}{2}$  South of  $\frac{1}{4}$  Post set  
by Millard goat Post has not  
been found - corrected line  
East for Co Road

corrected Var  $40^{\circ}3' E$  Dec 6.18/100

August 24 - 1800

copied on Page 394

county record

Monico Road cont'd Aug 24 1800  
West from  $\frac{1}{4}$  Post Bet 26 & 27 Var  $4^{\circ} E$   
4297 feet 3.51 South of center set by  
Millard = Verer Read  $335'$ . I corrected  
on this Post an run west an  
corrected Var  $105' W$

4101 feet 14 links South of  $\frac{1}{4}$  Post  
set by Millard corrected this East  
(after setting  $\frac{1}{8}$  Post 2050  $\frac{1}{2}$  East  
of West  $\frac{1}{4}$  Post) for Co Road  
also corrected line east from  
center for county Road

N West from West  $\frac{1}{8}$  Post an  $8^{\circ} W$   
 $\frac{1}{4}$  line in Sec 27-36-10 E. Compass  
adjusted an  $105' W$  I run north  
 $45^{\circ} W = 2800$  feet  $81\frac{1}{2}$  North of  
 $\frac{1}{8}$  Post set by Millard  
corrected  $48^{\circ} E$  for Co Road

copied on Page 394

county record

Monico Road Cont<sup>y</sup> August 25-1900  
 with compass on  $3\frac{1}{2}^{\circ}$  E & run  
 north  $45^{\circ}$  West from N  $\frac{1}{8}$  Post on  
 line between sections 27 & 28

Though ~~E~~ NE NE-28-36-10-E

2899 feet  $44\frac{1}{2}$  SW of  $\frac{1}{8}$  Post on  
 sec. line between sec. 21 & 28

converted SE for as Road

August 26  
 West from East  $\frac{1}{8}$  Post on sec. line  
 Between sec. 21 & 28 Var even needs  
 2031 feet 47 links North of  $\frac{1}{4}$  Post  
 original bearings

converted East for county Road

Var  $1.18^{\circ}$  E Sec 231  
 copied on Page 394

West from  $\frac{1}{4}$  Post between sec 21 & 28

Var  $1.18^{\circ}$  E county record

4163 feet 129 links North of corner set  
 by D. H. Baughman from org<sup>n</sup> bearings

converted East for county Road

" Var  $3.02^{\circ}$  Sec 310.

Monico Road cont<sup>y</sup> August 27<sup>th</sup> 1900

North from corner to Sec 20-21-28 & 29

Var  $3\frac{1}{2}^{\circ}$  East

3774 feet 128 East of  $\frac{1}{4}$  Post org<sup>n</sup> bearings

converted South for county Road

" Var  $5.37^{\circ}$  East Sec 339

on August 28<sup>th</sup> 1900

With compass adjusted on  $4^{\circ}$  East

& run North  $45^{\circ}$  West

4454 set Post at a Point to 33 links

South of Rightaway of N.W. RR

Thence North  $63^{\circ}$  W

421 intersect Lubolt & Menard

Wayan Road

finished at 1.00 o'clock P.M.

August 28<sup>th</sup> 1900

Posted on Page 394

County record

Sec 9 36-9 E north <sup>June</sup> 12 1900

North from S 1/4 Post var 6° E  
4013 feet 271 East of center set by <sup>measured</sup>  
concealed South var 953  
2006 set 1/8 Post Town Stump 14 E 105  
north from SW corner set flag at  
<sup>copied on page 196</sup>  
corner + 1/4 Post ~~to the~~ <sup>in my</sup>  
instrument with the needle and  
zero Werrin Reed 5° E var

South from W 1/8 Post on E & N 1/4 line  
var 726 which is an intermediate  
course <sup>between N S & line + N 1/4 S</sup>  
<sup>county record</sup>  
1/4 line

1948 intersect Highway  
2000 set Post for 1/4 Sec  
compass on 4° E var WP Stump 12578 1/4 W 73  
commencing at W 1/4 P. 9 chains  
East 1/4 line 950 or 38 Rods and set  
Post WP Stump 24 S 33 W 89. Pocket compass  
Still east 1575 set Post at NE cor Townshet  
<sup>13 Rods</sup>  
+ 2 <sup>18 St 10</sup> Pocket compass

+++  
no 14

Still east 1654. Set Post for NE cor  
of Stepletous land Still East  
1890 Antlers set 1/8 Post  
commencing again at a Point  
where Highway crosses see var about  
750 chains of W 1/4 Post three S E  
along N side of Highway var about  
560° E <sup>copied on page 196 county record</sup>

550 chains set Post at SE cor of Hardell  
<sup>Brick Stump 1/2 3 1/2 1/2 1/2 1/2 P. 100</sup>  
land - Still S E  
1550 chains set Post for SE cor of Townshet  
small WP Stump was 24 S 55 W 63. P compass  
350 S E at  
4825 set Post for SE cor of Stepletous land  
<sup>no 14</sup>  
finished now 13-7900

+ 2

50E 13-36-10 con<sup>XI</sup> Nov 20 1900

East from W<sup>1</sup>/<sub>4</sub> Post Var - intended to  
to Run on 3.5 1/2 W but it was not  
quite daylight + I used the 10 instead  
of 0 + I run on 30 W  
copied on Page 312

7414 fell 441 N of corner on Range this  
corrected line west to center

" Var 2° 10' W

Nov 27-1900

East from SW corner on Random run in

June 1900

3728 Set 1/4 Post 62 links East of Random  
(Shore 8 74 1/2 W 30  
Tamarac N 3 8 39)

North from South 1/4 Post Var 530 E  
which is an intermediate course -  
but as I found after leaving 1/4 Post I should  
have run on about 8° 20'

County records

(a man was killed here today)  
(Skidaway fell + cursed his head)

F 7639 Nov 28  
fell 372.8 E of 1/4 Post correct Var  
went back and set center

Dec 13-36-10E Nov 28-1900

Hemlock 12 N 54 E 39  
Maple 10 S 46 E 28

Distance to N 1/4 Post 3817

" " S 1/4 " 3822

" " E 1/4 " 3758

copied on Page 312  
" W 1/4 " 3656

1911 South of center set 1/8 Post

Cedar 10 N 71 W 9  
do 6 S 19 1/2 E 22 1/2

East from this 1/8 Post 415 W

3742 fell 43 N of 1/8 Post set by some  
one unknown to me but I used it  
corrected line west to 1/8 Post

1828 W of center set 1/8 Post

County records  
W.P. Shump 24 N 72 1/2 E 17 1/2  
do do 20 S 81 1/2 W 11 1/2

North from this 1/8 Post Var 745 E

(W.P. Shump 24 N 72 1/2 E 17 1/2) corner  
do do 20 S 81 1/2 W 11 1/2

Run north from this 1/8 Post Var 815 E

3768 fell 31 E of Post X X

corrected line South to where 1/16 Post

see 13-36-10 con<sup>xi</sup> Nov 20 1900

East from W/4 Post Var = <sup>12 1/2</sup> intended to  
to run on 3.5 1/2 W but it was not  
quite daylight & I used the 10 instead  
of 0 & I am on 30 W  
copied on page 312

7414 fell 441 N of corner on Remy line  
corrected line west to center

" Var 2 10 W

Nov 27-1900

East from SW corner on Random run in  
June 1900

3728 set 1/4 Post 62 links East of Random  
Shore S 74 1/2 W 30  
Tamarac N 3 E 89

North from South 1/4 Post Var 530 E

which is an intermediate course -

but as I found after leaving 1/4 Post & should

have run on about 80 20

county records

(a man was killed here today)  
(Skidaway fell & burst his head)

F 7639 Nov 28  
fell 372 E of 1/4 Post cannot Var 815 E

went back and set center

see 13-36-10 E Nov 28-1900

Hemlock 12 N 54 E 39

Maple 10 S 46 E 28

Distance to N 1/4 Post 3817

" " S 1/4 " 3822

" " E 1/4 " 3758

copied on page 312

" W 1/4 " 3656

1911 South of center set 1/8 Post

Cedar 10 N 71 W 9

do 6 S 19 1/2 E 22 1/2

East from this 1/8 Post 495 W

3742 fell 43 N of 1/8 Post set by some

one unknown to me but I used it

corrected line west to 1/8 Post

1628 W of center set 1/8 Post

county records

W Pine Swamp 24 N 72 1/2 E 17 1/2

do do 20 S 81 1/2 W 11 1/2

North from it's 1/8 Post Var 745 E

W Pine Swamp 24 N 72 1/2 E 17 1/2  
do do 20 S 81 1/2 W 11 1/2

run north from this 1/8 Post Var 815 E

3768 fell 31 E of Post x x

corrected line South to where 1/16 Post

Nov 29 - 1900 See 13 cont

Should be  
 copied on Page 312  
 Run East from N 1/8 Post on west Sec  
 line. Var 322' W. as there was no timber  
 along line & only run to intersection.

7 N + 6 1/8 line county record  
 finished at 11 AM

See 10 - 36 - 10 E

Don had run & connected E + W 1/4 line  
 timber cut on N side.

Zilkey onson put in the NW, SE + NE, SW  
 Sec the timber was cut on both east &  
 west I run with pocket compass  
 from 3 1/8 Post at S line west  
 was 10° W 4 tallies + 33 steps and  
 then intersected west line 10 steps N of  
 Post set by Tim Farnon

Spotted line East to Starting, find  
 there were no timbers of any value  
 along this line. 4/11/11 Nov 29 1900

Pocket compass  
 Does not go

SEC 14-36-10 E Nov 21 - 1900

There being no SW corner I began  
 at corner of 22-23-26-27. Set Post  
 all Pasted on Page 313  
 from org B. which are about all  
 gone. Put in new Post + 1 new bearing  
 1 spine 12 S 58 W 33 1/2  
 run north on 14-15 E

7573 full 961 W of corner which I set  
 July 11-1900 as a temporary corner  
 it being an a true line between  
 the section corners E + W - corner  
 Var of this line is 7° 00' ~~SE~~  
 commenced again at this tempo  
 corner I run N 7,15 E

7397 full 264 West of corner set by Don  
 I find the distance between the permanent  
 corners to be 1497.0 chanc 1/2 of this distance  
 is 748.5 - I moved temporary corner South  
 at right angles with E + W sec line) 98 link  
 This makes my Random 12 links East of  
 county record.  
 true corner at South end of Random



Sec 14-3610 Cont Nov 22 1900

and my tally stakes are set 8 links  
to far North and 12 links to far East

ALL COPIED ON PAGE 313

which leaves my departure 276 W of center  
and the whole line 12 links to far East  
378 1/2 as Equidistant. But the town corner  
of sec 10-11-12+15 and 14-15-22+23

Set 1/4 Post } N. Pine 12 S 48 13 1/2  
                  } DO 12 S 65 37

1896 North of true corner to 14-15-22-23

Set 1/8 Post } No trees near place  
                  } Bearing on Tam Root 3 link E  
East Line W 1/4 P Van 6 W Nov 23-1900

7340 feet 2 1/4 N of 1/4 Post.

connect Van 15 W Sec

South from N 1/4 Post set by Van 6 30

7474 feet 86 links East of true 1/4 Post. I  
moved Temporary Post South 44 links to have  
it on true line between sec corners  
This Temporary 1/4 Post was set by me  
last June on a true line between the  
county record  
corners Sec 12-14-23+24 and 15-16-21-22

Sec 14-3610 Cont Nov 22 1900  
and at proportional distance, but as had to  
Spring the end of Sec 14-15-22+23 South  
ALL COPIED ON PAGE 313  
88 links had to move Temp 1/4 Post to  
South 44 links

Set center at junction of crowned  
1/4 line { Tam 10 S 70 1/2 N 12  
                  } DO 7 N 42 E 25

Distance to N 1/4 Post 3787 SW Cor  
" " S " " 3787 Tam 12 S 4 1/2 E 13  
" " E " " 3670 " 18 N 16 E 14  
" " W " " 3670

at 1868 1/2 N of center set 1/8 Post Fin 7 S 38 E 10  
open 7 N 7 1/2 E 14  
1878 1/2 S " " " " Rich 8 S 55 1/2 E 18  
" " " " " Elm 5 N 21 E 26

1835 W " " " " Tam 12 S 87 W 23 1/2  
" " " " " DO 12 N 12 1/2 E 21  
= Nov 24 = 1 P.M.  
East from 1/8 Post N of center Van 10 W

3630 feet 24 W of Post I connected this W 1/4 Post  
= Nov 25 =  
West from 1/8 Post S of center Van 10 W

3685 feet 2 1/2 N of 1/8 Post, connected line East  
= to center of sec =  
county record  
South from N 1/4 Post on N 36 E line Van 6 10 E  
761 feet 2 links East of true 1/4 Post  
N 1/4 Post

Sec 14 - cont Nov 26 - 1900

I moved SW cor South 88 links + set  
 new Post <sup>defaced old post for Tan corner</sup> } Tamarac 12 S 4 1/2 E 13  
 DO 18 N 14 E 14

Run East on Random to Talley Stake 5600 ch  
 + set 1/8 Post 13 1/2 links W + 5 links North

of Random { cedar 5 S 2 E 21  
 DO 5 N 81 E 12 1/2

I then run north from this 1/8 Post 640 E  
 3738 feet 17 links N of 1/8 Post

corrected same back to center of  
 SW 1/4 + set 1/16 Post

set with pocket compass } Tam 8 N 79 E 55

This finishes 14

4) 5668  
 180.600

all copied on Page 313

county record

Sept 8 1917

Sec 11 - 36 - 10 E Nov 26 1900

South from center on my old

Random.

3740 to South 1/4 Post

1870 South of center set 1/8 Post

{ Skene 10 S 4 E 29  
 Rich 7 N 33 E 17

I then run East from this 1/8 Post 1010 W  
 3609 feet 6 links South of 1/8 Post

McNabb had defaced the corner +  
 Removed the Post & set 3 years ago

but the witness trees are ok  
 I corrected this line west from  
 center of SE 1/4 did not set 1/16 Post

Nov 27 - 1900

all copied  
 on Page 311  
 county record

Sec 34-37-9-E Twp 3-1900

East from W 1/4 Post Var 10° E  
8694 feet 69 links S of 1/4 Post / <sup>connect Var</sup> 10° 26' E

West Post on B. E. Post Set by D. H. V.

North from S. E. <sup>var</sup> Var 130° E } connect  
4173 feet 418 links 1/4 Post } Var 61° E

2086 1/2 feet 1/8 Post - WP. Stump 22 N 12 E 21

Subsequently new bearing for 1/4 Post

This Pass <sup>are</sup> <sup>as</sup> <sup>expired</sup> <sup>are</sup>  
WP Stump 10 S 38 E 27  
NP " 10 N 49 W 54

run west from this 1/8 Post

Page 234 Var 63° E

4258 feet 12 links S of 1/8 Post

as the center had been obliterated

4 run N from this 1/8 Post Var 65° E

4300 feet 128 links W of 1/8 Post

connect var } Set New bears

610' E. Trans 10 N 45 W 3 links  
<sup>county record</sup>

connected line S to South 1/8 Post

also set center of section at

Description of connected lines

Sec 34-37-9 Twp 4-1900

center of Sec

W Pine Stump 10 S 72 E 46  
do do 11 N 5 E 29

Distance to E 1/4 Post 42.47

" " W " " 44.47

" " N " " 46.48

" " S " " 38.73

2223 1/2 feet west of center set 1/8 Post

<sup>expired</sup> <sup>var</sup> <sup>Page</sup> <sup>234</sup>

WP Stump 10 N 18 E 18 1/2

do do 10 S 79 W 20 1/2

2123 1/2 feet east of center set 1/8 Post

WP Stump 10 N 43 E 22

W " do 10 S 17 E 27

South from W 1/8 P. on E + W 1/8 line

Var 12° E

1696 feet 45 links of 1/8 P. set by D. H. V.

West from S. E. corner Var 40° E

4065 feet 12 links S of 1/4 Post on B

connected this line east to same

2032 1/2 feet 1/8 Post

WP Pine 14 S 23 E 48

Cedar " 7 N 77 1/2 W 40 3/4

<sup>county record</sup>

SEC 34-37-9-cont DEC 5-1900

North from E 1/8 Post on South line Var 7° E  
3940. f. h. 10 1/2 E of 1/8 Post

connected South + set 1/8 Post at  
corner on Page 234  
Intersection of connected 1/8 lines

NP Stump 12 N 84 E 24 1/2  
NP " 11 N 82 W 34 1/2

This 1/8 Post is a NP Stump

Squared up + Marked it stands  
exactly where the Post showed to  
North from W 1/4 Post Var 2° E

4217 f. h. 77 W of corner orig E  
2108 1/2 South of corner set 1/8 Post

NP Stump 14 N 14 1/2 W 42  
WP do 14 S 20 W 51

Run East from this 1/8 Post Var 17° E

4298 f. h. 134 N of 1/8 Post set by D.H.U.

connected West to 1/8 Post +  
county record  
East from N 1/4 Post Var 15' W 15 1/4 E

4269 f. h. 13 links South of corner set by D.H.U.

connected West + set 1/8 Post at  
2134 1/2 NP Stump 18 S 58 E 20 1/2  
connected line all the way West

Dec 34-37-9-E DEC 6-1900

To N 1/4 Post

Run counts from N 1/8 Post on  
N + S 1/4 line on old Random and  
connect same back South

finished at 4 Post DEC  
6-1900

capus in Page 234 county record

4289	13400	(3, 12)
	12867	
	5330	
	4289	
	10410	
	1500	

  

4300	573	180
	134	180
	2292	
	1719	
	573	
	76782	
	4300	
	33780	

2494      10 1/2  
             27  
             28

2744  
27  
14 1/2  
2419

2496

See 3-31-9 E Dec 8-1900

South from N 1/4 Post. Var 9.30° E

400 Lake Thompson 700 East

COPIED on Page 192

7000 to South side of Lake T 600 East

409 full 470 W of 1/4 P. 109 Bearing

When I reach South boundary

Corner 6.35° E. 9 1/2 would be the  
corner Var to run N + 12° 20' to run 3'

S.E.C. of this line is 517

South from N.E. corner Var 3.30° E

4037 full 19 links E of Meander Post which

I set from org bearings both down  
and nearly gone made 1 new

Bearing Spine 8 N 46° 92

I found on Page 31 this Book when

I had measured distance across

Lake and found it to be

44702  
2170 to govt notes says it is 3940

Proportioned distance + set 1/4 Post

CO. R E C O R D  
160.3 246 of meander the corner2° 38'  
Dist 80.20Same  
1/4 PostL. SHORE LAKE THOMPSON E-W LINE 151  
See 3-31-9 cont Dec 10+11 1900

COPIED on Page 192

Between meanders is 24° E

Made bearing for 1/4 Post + Meander

meander } Within 8 N 9° 10' used same  
150 } DO 12 N 23 1/2° E 25  
1/4 Post 12 N 86° W 399 for meanderDistance from N.E. corner to 1/4 Post South  
is 4197 - at 2098 set 1/8 Post + X

West from E 1/4 Post Var 1.45° E

8373 full 305 North of 1/4 P. org. Bearing

Set center Intersection of 1/4 lines  
when corrected

	NP 16 N 20 1/2 W 96
	D. 16 N 70 1/2 W 113
Distance to N 1/4 Post	4203
" " S " "	4306
" " E " "	3481
" " W " "	4892

1 1/8 cedar 11 N 75 1/2° E 2 XX  
50 12 South 9 XX

at 210 1/2 N of center set 1/8 Post

W Pine	82 S 24 W 411/2
N "	15 N 92 1/2 E 58 1/2

county record

East from N 1/8 Post on N 8 1/4 line Var 3.45° E

3773 full 81 links N of 1/8 Post condition

canceled must to 1/8 P 459 E  
finished DEC 11-1900 gone E

152

SEC 7-40-8 DEC 18-1900

West from N 1/4 Post on Dams

Random Var 4 1/2 E

1994 feet 2.54 South of 1/8 Post

Set By Dams

27 woodshed across dam

4347 feet by offset

DEC for correction  
is 0.1268 which would set

1/8 Post N 253 60/100

corrected Var 2 15' 9N

found Dams corrected correct  
& found a trespass of 96 trees

SEC 1-39-7.E DEC 27-1900 Rams

North from S 1/4 Var 3 30' E

4266 feet 22 links W of 1/4 P. Set from

org Bearings. one is down & nearly  
burned up. the other is a stub 12 ft high

correct Var 3 1/4 DEC 52

East from W 1/4 Post set new Post from  
org Bearings both are dead stubs7468 feet 44 S of 1/4 Post - set new Post  
from west org B NP StumpSet center at intersection of correct  
1/4 line } N Pin 30 N 84 1/2 E 71

N Pin 10 N 47 W 58

Distance 8/4 Post 4001

" W " " 3967

" N " " 3855

" S " " 3861

at 20.0 1/2 East of center set 1/8 Post

Tamarac 9 N 54 E 29 1/2

W Pine 12 N 40 1/2 W 13

East from S 1/4 P Var 3 30'

4026 feet 15 links N of 1/4 P org B  
over

copied

Copied on Page 101

County Record

S&amp;C 1-39-7 E Dec 29-1900

Pasted on Page 101

connected this line from  $\frac{1}{8}$   
 Post which I set Equi distant  
 between  $\frac{1}{4}$  Post & See corner

NP	20	S	21	E	50
50	18	N	37	E	58

Reserve

County

South from  $8\frac{1}{8}$  an E+W- $\frac{1}{4}$  line

4016 feet 169 W of  $\frac{1}{8}$  Post

connected North to Swamp

S&amp;C 35-40-7 Dec 29-1900

South from N  $\frac{1}{4}$  Post on 3.30  
 7900 feet  $5\frac{1}{2}$  links West of  $\frac{1}{4}$  Post  
 This Post was there, set by B Hammond  
 I did not have the field notes, but  
 they were in camp when I came  
 at night & I found the Post was not  
 set right There is only one bearing  
 left a Birch 12 N 48 E 17. Field notes  
 Read " 10 N 16 E 20  
 I connected distance & course which  
 makes my measurement 7906  
 and distance 6 links

East from W  $\frac{1}{4}$  P. 1.019 B. nearly  
 gone East Bearing gone was  $3\frac{1}{2}$  E  
 7980 feet  $3\frac{1}{2}$  South of  $\frac{1}{4}$  Post  
 Set new post from orig. B. West  
 bearing is a NP stump  
 connected west & set center at  
 intersection of connected  $\frac{1}{4}$  lines  
 found some over trespass marks  
 on  $5\frac{1}{2}$  NW

A9035-40-7-8 DEC 30-1900

Distance to N 1/4 Post	3935
" " S 1/4 "	3975
" " E 1/4 "	3926
" " W 1/4 "	3954

1967 N. of center set 1/8 Post

NP 16 N 53 1/2 W 18  
 WP 12 N 71 1/2 E 27

center of section } DEOD WP 14 N 1/2 E 15  
 DO DO 14 S 68 E 36

South from NW corner which  
 (I set from 1 orig. B) Var. 3° E

3962 fell 141 ~~ft~~ west of 1/4 P.

corner N + set 1/8 Post 8 quadrants

Between 1/4 Post + corner

Book 65 25 E 16 NP 6 N 25 1/2 W 60  
 West from N 1/8 on N + S 1/4 line

Var 3.30

3912 fell 13 links N of 1/4 Post

connected this line East to 1/8 Post

1/4 Post on W side should be moved E  
 7 1/2 links beyond Post

Work done for Ross Timber Co

Finished January 1901

When I run South from NW corner  
 I did not have field notes to  
 set the Post - and when I did  
 get them I found I had started  
 from a Point 17 links to far  
 west. + when I set the 1/8 Post  
 I forgot to move it 1/2 of the  
 17 links. I connected the line  
 E + W through NW 1/4 from  
 the east end when I came  
 to W 1/4 Post I moved it 7 1/2  
 links east into line but  
 did not change bearings  
 so the course + distances are  
 both wrong



Sec 29, 38-105 E January 4-1901

Cut from NW 1/4 P. Van 4° E. Orig. B.

8305 fell 188. N of 1/4 Past orig. B.

North from S 1/4 P. Van 3° 30' E

8076 fell 283 W of 1/4 Past set by Doc

connected South 3/4 of a mile

copied on page 346

" Van from S 1/4 P 130° E

" " " N " " 3° 15' E

Set center + intersection of connected

1/4 lines W Birch 12 S 73 W 2

do 12 S 21 1/2 E 36

Distance to E 1/4 cor 4139

" " W 1/4 " 4166

" " N 1/4 " 400 1/2

" " S 1/4 " 4014 1/2

2007 1/4 South of center set 1/8 Past

W Pine 16 N 83 E 15

do Birch 12 N 35 W 24

2000 3/4 North of center set 1/8 P

Linden 8 N 25 W 22

Hemlock 11 S 26 W 15

county

road

Sec 29-38-105 E Jan 5-1901

2069 1/2 E of center set 1/8 Past

Tamarac 10 S 62 W 12

do 8° 35' E + 6 1/4

083 West of center set 1/8 Past

did not set

copied on page 346

South from W 1/4 Past Van 3° 30' E

899 fell 23 birches west of center Past

orig. B. aspen is down. set 6 in. diameter

st in stump 2 marked at 13 T

Tamarac as broken off 4 feet high

849 1/2 set 1/8 Past 71 1/2 E of Rand

W Pine stump 20 S 13 E 4 1/2

do do 12 N 83 E 37

set from S 1/8 P on N + S 1/4 line

Van 3 1/2 E

848 fell 19 N of 1/8 Past

connected line East from center of

S W 1/4 Sec

January 6 1901

county road

See 29-38-10-E Jan 7-1901

West from SE corner Van 330° E O.R.B.T

4100 feet 32 links N of 1/4 Post

2050 West of SE corner Set 1/8 Post

captured on

Spencer 6 N 33 E 11

Do 6 S 46 W 20

Pay 346

South from E 1/8 P. on E+W 1/4 line

Van 330° E

2069 feet 12 links West of 1/8 Post

connected line North

East from S 1/8 P. on N+S 1/4 line Van 340° E

4120 feet 7 links South of 1/8 P. Set by Don

at center of SE 1/4 Set 1/16 Post

Spencer 8 N 65 W 9

Do 8 N 87 E 7 1/2

Jan 7 1901

Jan 8-1901

North from E 1/4 Post Van 330° E

4566 feet 41 E of corner Set by Don

could not find Lost Bearings. Don

had made new bearing V. line 13 N 84 E 41

county record

See 29-38-10 E January 8-1901

2034 Set 1/8 Post } Tam 10 S 15 E 12 1/2

captured on

Spencer 7 N 48 E 23

connected line South from 1/8 Post to corner

West from N 1/8 Post on E & see line

4125

Paer 346 Van 330°

41092 feet 156 N of 1/8 Post

Vernier Read 20° E at west end of line

Jan 9-1901

North from E 1/8 Post on E+W 1/4 line

Van 40°

4035 feet 4 links West of 1/8 Post

which I set after running this line

connected South to Set 1/16 Post

Spencer 10 N 1 E 12

W Bich 10 S 30 E 21

West from NE corner Van 40° on Dours

Randall which is 216 South of corner

4093 feet 108 South of 1/8 Post

Set 1/8 Post Equidistant between 1/4 P. & corner

county record

Sec 28-38-10 Jan 9-10-1900

East from W 1/4 Post var 40° E

8000 I found I was about 900 to

copied on page 346  
 far N. I went back to W 1/4 Post and

Run east on 2° W

8077 fell 13 links W of 1/4 Post var B  
 connected from Talley 12 west to  
 Talley 8.

North from South 1/4 Post var B  
 var 40° E

when I came to E & W 1/4 line  
 I was 5 chains to far East and

and on examination I found  
 I had made a mistake &

had turned the Vernier on a

west var I am using a new  
 Transit with inside Vernier and

am not used to hence the error =

7819 base 912 E of 1/4 Post var B

Spruce stands & 66 E goat  
 cannot read

had made new bearing V. Post 13 N 84 E 47  
 county road

Sec 28-38-10 Jan 12-1900

Set center at intersection of

corrected 1/4 lines

copied on page 346

Hemlock 11 S 18 1/2 E 8 1/4

Spruce 9 N 20 W 37 1/2

Distance to South 1/4 Post 4050

" " N " " 3759

" " W " " 4029  
 4048

" " E

at 1879 1/2 N of center set 1/4 P

Tamarac 6 N 19 W 5  
 DO 6 S 31 E 10

at 2030 South of center set 1/8 Post

county Hemlock 8 S 64 W 19

DO 10 S 14 1/2 E 25

at 2014 1/2 west of center set 1/8 Post

across } y Birch 10 N 77 W 15

DO 7 S 77 W 23

at 2024 East of center set 1/8 Post

Sugar 14 N 11 1/2 E 37

y Birch 7 S 35 E 20 1/2

SEC 28-38-108 Jan 14-1901

West from N $\frac{1}{8}$  R on N+S $\frac{1}{4}$  line

copied on Page 346

Var 4 $\frac{1}{2}$  W

4074 full 75 links N of  $\frac{1}{8}$  Post

connected this line back 2037

NE NW is out and trespass made  
on SE NW.

East from S $\frac{7}{8}$  P on W SEC line Var 2 $\frac{1}{2}$  SW

4053 full 135 S of  $\frac{1}{8}$  Post

I did not intend to run on  
only 1 $^{\circ}$  W but the needle is not  
working good & I am on 2 $\frac{1}{2}$  SW

cannot Var 5 $\frac{1}{4}$  W SE-333.

Jan 15<sup>th</sup> 1901

East from North  $\frac{1}{4}$  P. Var 1 $^{\circ}$  W

4046 full 152 South of corner O.B.T

2023 Set  $\frac{1}{8}$  Post 76 N of Randam's line

empty

Tamarac 14 N 45 W 14

near

do 10 S 81 E 19

North from  $\frac{8}{16}$  Post on E $\frac{1}{2}$  W  $\frac{1}{4}$  line Var 4 $^{\circ}$

3884 full 102 $\frac{1}{2}$  W of  $\frac{1}{8}$  Post

SEC 28-38-108 cont Jan 15-16 1901

connected this line South  $\frac{1}{8}$   
Post. This finishes SEC 28

I found trespass on the north side  
of SE NW copied on Page 344

In SEC 299 found trespass on  
the E side of NE NW and on the west  
side of SW NE also on South side of the  
NW SE - The W $\frac{1}{2}$  NE of 28 has  
some good Barwood also some  
yellow Birch & Maple.

finished Jan 16-1901  
counts near

See 31-36-10 E Jan 16-1901

copied on Page 320  
 East from W 1/4 Past Nar 5<sup>th</sup> E

7914 fell 15 links N of 1/4 Past which I

Identified by the stump of the Tamarac

I found some new work done near the center and a fast marked center of Se with a blue pencil. but it was 148 links to far South. I was doing the work for Gilkey Dawson co. but will not do any more until I hear from - The east has been

So far Team 350

Men 800

Bond 200

Self 500

\$1850

county record

See 21-36-9 E Feb 1st 1901

East from center of B &amp; C. set by

B F Don Har 3<sup>rd</sup> 4<sup>th</sup> E

1050 interest Pelican River

1214 over Run

4050 1/4 Past 1.9 links N of Random

sancted most for Road

Layed out foundation for Bridge

work done for towing of Pelican

copied on Page 202 county record.

See 29. 38-10-E Feb 10 1901

North from W/4 Post Var. 3.36 E.

3915. fell 1.08 West of cor. org. BT Post Set  
Went South to cor. on Post

1957 1/2 and Set 1/8 Post	} Tamarac 16 S 38 W 15 1/2
346	

East from NW corner Var 4 E on base  
old Random4090 fell 108 South of 1/4 Post set by base  
Went west to Set 1/8 Post - 54 N of Rand

to 44 1/2 Equidistant to between 1/4 P. &amp; cor.

} Tamarac	8 N 4 3/4 W 17
	Do 7 S 8 3/4 W 7

Set 1/8 Post Bet. center and west 1/4 Post.  
Equidistant. on st

2083 West of center to 47 links S of Random

run January 24. 1901

} Tamarac	10 S 44 E 16
	Do 10 N 65 W 12

North from this 1/8 Post. Var 2 E

3952 fell 1.14 East of 1/8 Post  
corner record

See 29. 38-10-E. Feb 10 1901

corner Var 3.45 DEC. 288

FEB 25 1901  
West from N 1/8 Post on N + S 1/4 line  
corner on Page 346Var 4 E  
4116 fell 44 links South of 1/8 Postconnected both 1/8 lines in NW 1/4  
and Set 1/16 Post at their intersection

Tamarac 7 N 5 1/2 E 28

Spencer 8 N 6 1/2 E 58

corner record  
SEE of E + W 1/8 line 1.07

" " " " " 2.88

corner Var of E + W 1/8 line 3.20

finished at 5.30 PM

FEB 25 - 1901

See 20. 38-10 E Feb 13-1901

North from SE corner Var 3.45' E  
 4110 fell 123 West of 1/4 P. or B.  
 Post set by Dorr in 1896  
 Set 1/8 P. equidistant bet 1/4 P. + cor

copied on { Spruce 7 S 61 E 10  
 DO 5 N 21 1/2 W 8

West from E 1/4 Post on Dorr's Random  
 which intersect E Sec line 74 links

South of 1/4 Post Var 3.45' E  
 4214 fell 35 links S of center  
 Set 1/8 Post 1/2 distance back to  
 1/4 Post Page 344

{ WPine 14 S 21 W 6 3/4  
 DO 16 S 13 1/2 W 20 1/2

South from center on Dorr's Rand.  
 Var 1.0 E This Random is 45 links  
 west of center

4209 fell 170. W of 1/4 Post  
 Set 1/8 Post 1/2 dist. bet 1/4 Post  
 and corner  
 county record

See 20 Rand'n Feb 14-1900

Copied on Page 344

{ Spruce 14 S 89 W 28  
 Tamarac 14 N 36 E 12 1/2

East from S 1/8 Post on N + S 1/4 line  
 Var 4.30' E  
 4157 fell 12 links South of 1/8 Post

North from E 1/8 Post on S Sec line  
 Var 3.0 E

4172 fell 15" East of 1/8 Post  
 West S + Set 1/16 Post at the  
 intersections of corrected 1/8  
 lines { Hemlock 16 N 51 W 4 1/2  
 Cedar 8 S 55 1/2 E 26

Corrected 1/8 lines west + south  
 to 1/8 Posts

West from S 1/8 Post on N + S  
 1/4 line Var 4.30' E

4091 fell 2 1/2 links North of 1/8 Post  
 corrected line east to 1/8 Post  
 county record

Sec 20-38-10 Feb 16-1901

north from E 1/4 Post Var 230° E

Copied on Page Var 2° E

3846. full 31 links East of corner 015 B.

Went South to set 1/8 Post 1923

to corner cedar 8 N 85° E 25

Do 6 S 55° W 3  
 West from N 1/8 corner Var 2° E

4309 HIT Post in center

Set 1/8 Post 2154 1/2

Birch 11 S 6 1/2° E 10 344

Do 11 S 87° W 23 1

Outside Vermier got turned off  
 about 13° + I did not notice  
 Oregon got bearings  
 N 1/8 Post at N 1/8 Post  
 Feb 19 1901  
 an Electric

Run west from N 1/8 Post an E

SEC line Var 330° E at

2950 yellow Birch 26 in dia offset

North 3 links and continued

and offset line

Sec 20-38-10 Feb 18-1901

4309 1/2 Intersected Dows N + S Ranch

His Post set 3 1/2 E of His Ranch

and 27 + 3 = 30 North of My Ranch

I went to N 1/4 Post &amp; chained S

on Dows Ranch at

2046 came to Dows Post chained S

to center and found it was 85

links west of Dows center

and the whole distance between

N 1/4 Post is 3970. Dows

Post showed he moved 42 1/2

links East and 61 links North

I think some one has

moved his Post as I could

not find any bearings where

Post sets

This would make my distance

Between 1/8 Post 4267 and

my departure would be 90 links

Copied on Page 344

County record



Sec 20-38-10 E Feb 18-1901  
 If I have time tomorrow I  
 will try and reestablish  
 Dorr 1/8 Post

Feb 19-1901

North from E 1/8 Post on E & W  
 1/4 line. Var 3° 0' E

3908 fell 9 links W of 1/8 Post  
 Set 1/16 Post at Intersection  
 of cancelled 1/8 lines and  
 cancelled 1/8 lines East and  
 South to 1/8 Post

I then went to Dorr 1/8 Post  
 on N + S Random between the  
 center & N 1/4 Post & marked  
 it North 61 links North and  
 11 1/2 East & found the hole  
 where it originally stood and  
 found his being a cedar  
 10. N 64 W. S. whose cut NW  
 corner & marked the Post

Book finished Feb. 19-1901  
 Copied on Pen 344

east end

INDEX

Section.	TOWNSHIP.		RANGE.		CITY, OR VILLAGE.	ADDITION.
	N.	S.	E.	W.		
21	39		6	1		
10	39		6	2		
29	36		8	3		
33	36		8	4		
18	39		5	5		
8	39		6	6		
17	39		6	7		
11	38		6	8		
1	38		6	9		
8	39		6	10		
1	36		8			
33	38		9			
2-1	36		9			
0+31	37		8		12 1/2 days	6250
3	36		9		1 "	500 RR + B. 200
35	36		8		4 "	42000
2	35		8		2 "	10-
6	39		8		4 1/2 "	42250
2	36		10		6 "	3000
33	37		10		10 1/2 "	5250
33	37		10			
33	37		10			
Survey of Road for Covida co commenced in Towns 35-R 9-10 and town 36-9. E						
Survey of Road for Covida co commenced in Town line Bet Towns 37 + 38 & Bet Sec						
3	35	N	9	E		
13	41	"	8	E		
	37+38	N	9	"		
	36	"	9	"		
22	37	"	8	"		
16	42	"	5	"		
24	41	"	8	"		
15	41	"	8	"		
4			8	"		

20-38109

Section.	SHIP.			RANGE.		CITY, OR VILLAGE.		ADDITION
	N.	S.	E.	W.				
6	37	N	10	E				
25	37	"	9	"				
7-34	36	"	8	"				
4-9	35	"	10	"				
0-11	35	"	10	"				
12-33	41	"	9	"				
4	40	"	9	"				
3-24	36	"	10	"				
5	37	"	10	"				
29	36	"	8	"				
6	36	"	9	"			Dumping ground	
5	42	"	8	"				
1	42	"	8	"				
6	38	"	11	"			Three Lakes LAKE Side add	
33	37	"	9	"				
2-23	39	"	9	"				
25	42	"	8	"				
36	42	"	8	"				
30	42	"	9	"				
31	42	"	9	"				
33	37	"	9	"				
18								
20	36		9					
15	3+10		10					
14	37		11					
32	42		7					
8	36		9					
4	39		7					
26	36		8					
25	36		11					
28								
20	"		10					
9	36		9					
12	"		10					
21	36		10					
3			9					
36			9					

Look on Page 55 for line between 36 &amp; 9 E

4+9+3+10 36 9 E

FOR WHOM SWEYED.	WHEN			Page.
	Day.	Month.	Year.	
Menasha W W Co	20-21	DEC	1899	7
John Mason	21-22	"	"	70
Town Pelican	26	"	"	7
Gilkey Anson Co	27	"	"	72-7
Salsich & Wilson	1-5-11	January	1900	74-
"	10-15	"	"	82
"	"	"	"	89-
Stevens W W Co	17-22	"	"	88-9
W W Co	5-6	February	"	9
Leary Ames	20	April	"	9
City of Rhineland	24	"	"	9
Menasha W W Co	25-4	May	"	96
"	7-11	"	"	96-9
Oneida County	19-21	"	"	98-9
"	28	"	"	100
Town Sugar Camp	1	June	"	102
Mortensen Lbr Co	4	"	"	109
"	7	"	"	10
"	9	"	"	10
"	14	"	"	11
Town Sugar Camp	22	"	"	11
"	23	"	"	11
Oneida County	12-19	July	"	115
Wright Lbr Co	21	"	"	119
Town Pelican	31	"	"	121
Ross L	2	Aug	"	
Town	12	"	"	
W W Co	21	"	"	
"	28	"	"	
Stapleton	12	Nov	"	13
Gilkey Anson Co	16	"	"	13
"	30	"	"	
Robbins Lbr Co	3	Dec	"	
F Robbins	9	"	"	1901

Section.	TOWNSHIP.		RANGE.		CITY, OR VILLAGE.	ADDITION.
	N.	S.	E.	W.		
1	39		7			
35	40		7			
29	38		10			
28	38		10			
31	36		10			
21	36		9			
23	37		11			
20	38		10			
29	38		10			

*finished Feb 20-1901*

*" " 10*

*25-36*

*28*

*20*

*9*

*12*

*21*

*3*

*24*

*34 10*

### INDEX.

FOR WHOM SURVEYED.	WHEN		
	Day.	Month.	Year.
<i>Bass lbs co</i>	26	DEC	1900
<i>" " "</i>	30	"	"
<i>Brown + Robbins lbs co</i>	2	January	1901
<i>" " "</i>	9	"	"
<i>Gilkey ansers co</i>	17	"	"
<i>Town of Pelicans</i>			
<i>Jae Forsyth</i>	6	Feb	
<i>Manuska wooden w co</i>	13	"	
	10	"	

*can*