

31

4

74

74

PK 74

PAGES 1-18  
BLANK

29-30 } Should be  
 30-32 } 36.4 JUN 15, 1921 } on Page 12 19

Road for Town of Lynn  
 Set Post corner to 19.20 29-30 from  
 The Birch B.T. other gone  
 and run N bet. 29 & 30 was 40E  
 15756 FELL 29 E of corner to  
 7.8-17.18 - ... found stump of  
 the Sugar B.T. Did not connect this  
 line as it is nearly all Swamp  
 Made NEW Post and beam  
 for this corner to 29.30-31-32  
 Birch 15572 1/2 W 71

PAGES 20-48

BLANK

S.E. corner org: trees. Run west Var  $4.30^{\circ}$  E  
 3677 fell 5.94 north of South  $1/4$  Post. org: trees  
 South  $1/4$  Post. org trees Run North Var  $4^{\circ}$  E  
 87.24 fell 4.60 NE of N.  $1/4$  Post. found org: trees  
 S.E. cor: Run north Var  $4^{\circ}$  East  
 8057 fell 1.82 E. o NE. cor:  
 East  $1/4$  P. Did not find it Set new Post  
 and made new bearings: ~~Sugar 20 N 53 W 15~~  
 Birch 12 S 43 W 19

E  $1/4$  P. Run west var  $3^{\circ}$  E  
 8225 fell 102 South of W  $1/4$  Post found new  
 Post set by D.H.U. in 1917 from org  
 trees (see see. 11 Dorrs book county record)

E  $1/4$  Post NEW. } Birch 16 N 40 E 51  
 } Hem 14 S 45 W 18

Center of sec maple 20 N 38  $1/2$  E 5  $1/2$   
 NE. cor. org: trees } 18 S 31 W 25  
 N  $1/4$  P. org trees Run E. var  $4^{\circ}$  E  
 4041 fell 108 N of NE cor

E  $1/8$  P. on S Line maple 7 N 41 E 8  
 } Hem 9 S 55 W 9

E  $1/8$  P. on N Line set Post no bearings given  
 N  $1/8$  P. .. E .. } Hem 14 N 58 E 17  $1/4$   
 } maple 10 S 81  $1/2$  W 6

S  $1/8$  P. on E Line } Birch 14 N 40 E 51  
 } Hem 16 S 45  $1/2$  W 18

Distance from center to N.  $1/4$  Post 39.91

" " " " S  $1/4$  " 47.33

" " " " E  $1/4$  " 38.70

" " " " W  $1/4$  " 43.55

$1/8$  P. N of center } Birch 12 S 75 W 18  
 } Sugar 22 S 88 E 39

$1/8$  P. E of center no bearings  
 West from S.  $1/8$  P. on E Line var  $8.10^{\circ}$  E  
 3781 fell 3 LKS South of  $1/8$  Post

East from  $1/8$  P. S. of center var -  
 39.61 fell 63 N of  $1/8$  Post

PAGES 50-76

BLANK

Survey of Road for Town  
 of Lynn bet sections 26 & 35  
 Town 36-4 May 1921  
 East from cor to 26-27. 34-35. 36-4

Var 4° E  
 7646. fELL 106 N of cor to 25:26.35.36  
 found stp of only trees a Hemlock & w  
 set a large cedar Post and  
 connected line west to corner for Road  
 set 1/4 P. bet 26 & 35 nothing for bearings  
 The road owner said he would  
 place an iron monument for Post  
 on place. iron monuments 50 links  
 N and 50 links south of 1/4 P.

North from 1/4 Post bet 26 & 35  
 8084 fELL 369 W of 1/4 Post  
 found Sugar down but mark  
 are plain. other gone  
 connected line south to 1/4 Post

PAGES 78-145

BLANK



## SUTHER OF Road For the

town of Lyon between sections  
34+35- and between 27+34-36-4.

Began at Cor. of 2-3-34-35.

This corner ~~is~~ Lost. I restored it as  
follows. The gov. field note read.

West between 2 and 35. 7950 Stram 20 runs  
N.E. 8000 Set corner to 2-3-34-35.

West between 3+34. 129 Same stream  
Runs SE. I found the two points given in  
field notes and also found the stream had  
changed its course. and set corner by  
proportional measurement between the  
points given in gov. notes

3 W. Pine stump 30 N34 $\frac{1}{2}$  W. 126

Run North from this corner Var 4 $^{\circ}$  E

1175. 500 RR track

8169 fell 277 West of corner to 26-27-34-35

Found the Sugar, Org tree OK, maple OK

Set NEW Post and Run West between  
27+34 Var 3 $\frac{1}{2}$  E

2500 Enter swamp

38 $\infty$  LEAVE "

4060 Someones 1/4 P. Not the original

6075 " " 78 P. OFFSE South 141 to road

8069 fell 127 North of corner of 27-28-33-34

in road OK gave the Decimals

For correcting both lines to a mr

White who says he corrected them

## WILLOW LAKE ROAD

JUNE 13-1921

Began at corner to 27-28-33-34

and placed iron monuments  
at all the section corners and 1/4 Post  
north to and including the Town  
line between townships 36+37 north  
Range 4 East by order of Town  
Chairman William Hauland

## SURVEY OF ROAD FOR THE

Town of LYON between sections  
34+35- and between 27+34-36-4.

Began at Cor<sup>n</sup> of 2-3-34-35.

This corner ~~lost~~ is Lost. I restored it as  
follows. The gov<sup>n</sup> field note read.

West between 2 and 35. 7950 Stram 20 run 8  
N.E. 8000 set corner to 2-3-34-35.

West between 3+34. 129 Same stream  
Runs S.E. I found the two points given in  
field notes and also found the stream had <sup>NOT</sup>  
changed its course. and set corner by  
proportional measurement between the  
points given in gov<sup>n</sup> notes

3/4 W. Pine Stump 30 N 34 1/2 W. 126

Run North from this corner Var 4° E  
1175. 500 RR track

8169 fell 277 West of corner to 26-27-34-35

Found the Sugar, Org tree OK. mark OK

Set NEW Post and Run West between  
27+34 Var 3° 1/2 E

2500 Enter swamp

3800 LEAVE "

4060 Someones 1/4 P. Not the original

6075 " " 1/8 P. off se South 141 to road

8069 fell 127 North of corner of 27-28-33-34

in road OK gave the Decimals

For correcting both lines to a mr

White who says he corrected them

## WILLOW LAKE ROAD

JUNE 13-1921

Began at corner to 27-28-33-34  
and placed iron monuments  
at all the section corners and 1/4 Posts  
north to and including the Town  
line between Townships 36+37 north  
Range 4 East by order of Town  
Chairman William Haveland

PAGES 147-176

# INDEX

Section	TOWNSHIP		RANGE		CITY of	ADDITION
	N.	S.	E.	W.	VILLAGE	
12	36		4			
27.34.35	36		4		Road	Forthc
26	35		4		"	"
27	28		4		and Placed iron monuments	

INDEX

# INDEX

FOR WHOM SURVEYED	WHEN			
	Day	Month	Year	Page
John WALLACE	9	DEC	1918	49
Town of Lynn	20	may	1919	146
"	13	June	1921	146
to Township 37-4 Townships				