

D.H. VAUGHAN #8

915°
E 03°
E 17°
W 3°
E 44°
3°

and
37.
on

5€

rec

No of
driving

1972

95

N.B7

IG

or.B7

BT

4

10
2

D.H. Vaughan's field notes
from May 12th 1915
to

3-39 1/2

23

39-77

Ran N from SW
corner on 3.15'

Book 8

D.H. Vaughan

Finder Please

8 return



0.51
5.51

(6.8' 7.7' 6.0')
4.1.2

SECⁿ 36. 39-10-E. May 12, 1915

WENT to NW. Cor. took Chars RUSSELL with me
as the Post at this Cor. has been removed.
WE found the rock we piled around the Post in
April 1901. Run East Var 00. on offset of 10 Lks
South so ast be in road

1800 C+N.W.R.R. Copied on Page 351

430 $\frac{1}{2}$ FELL 77 South of $\frac{1}{4}$ Post found Stumps of
both org BT's ok. SET Cedar Post and
WENT WEST and SET $\frac{1}{8}$ Post

EW Pine 30 N $10\frac{1}{2}$ W $212\frac{1}{2}$

" " Stb 16 S 16 E 68

WET to center of SEC which I set in April
1901 Post ok Run WEST Var 3° W

4200 FELL 13/4 South of $\frac{1}{4}$ Set by me in Apr 1901
came East and SET $\frac{1}{8}$ in open marsh
And run north Var 6° W

4670 FELL 29 WEST of $\frac{1}{8}$ Post
corrected line south to 2335 and set
Temp $11\frac{1}{2}$ Post no marks no bearings

the notes were taken on Page 86
in Book of Govt. field notes of
Towns 39-10-39-11 and 40-10

JULY 15-1914

MAY 17" 1915 SEC 12, 35, 11. SEE Pg 149

Began at E 1/4 Post. SEE Pg 149. JULY 15, 1914
 SEE flag and there and one at NE cor.
 Placed instrument on line between
 4016 between flags. Found an iron pipe
 for NE cor and one org" BT Var 3 1/4
 WEST from NE COR= Var 1 1/2 E
 7769 FEEL 96 S. of cor. found old post
 and both org" BTs dead. SEE NEW
 PG 81. WENT EAST AND SEE 1/8 P at
 1942 1/2 E EAST of NW COR***
 Sugar 9 N 24 1/2 E 18 1/4 SUGAR 9 N 24 1/2 E 18 1/4

" 12 S 75 1/2 W " 12 S 75 1/2 W
 WENT EAST AND SET 1/4 POST AT 388 4 1/2 35 3/4
 ALL COPIED ON SUGAR 9 N 24 1/2 E 18 1/4
 Pg 46 35 3 " 12 S 75 1/2 W 35 3/4
 WENT EAST AND SET 1/8 POST 1942 1/2 WEST OF
 NE COR SUGAR 16 S 33 6 9

WEST from EAST 1/4 VAR 1/2 E
 7503 FELL 3 1/2 LKS north of W 1/4 Post found the
 Stk of Pine ok. sugar down. mks ok
 SEE Post and made new bearing
 SUGAR 20 S 29 E 49 3/4

W 1/4 north from WEST 1/4 Post VAR 6 0 E
 4002 FELL 72 E of NW COR SE Post from
 VAR 70 STK of org trees. WENT SOUTH AND
 W 1/4. SEE 1/8 P SUGAR 14 N 36 W 44
 " 18 S 71 1/2 E 39

WEST from SE COR= VAR 1/4 E
 7914 FELL 4.19 South of SW COR SEE POST
 ORG BTs OK.
 SEE W 1/8 Post on SOUT Line AT 583 5/4

Hem 14 N 69 1/2 W 29
 Elm 16 S 83 1/2 W 37

SEE South 1/4 P Hem 10 N 42 E 10
 Birch 18 S 63 1/2 W 47
 SEE East Post at 1941 1/2 and 1043 3/4 N of Road
 Birch 10 N 22 1/2 W 48 1/2
 Hem 12 S 35 8 72 1/2
 County road

SEE e. 12. 35-11 Cont: 19 of May 1915 3

North from South 1/4 Post W 3 1/2 E
 7824 FELL 40 W of 1/8 P. WENT SOUTH AND SEE
 CENTER Y. Birch 12 S 21 1/2 E 53 1/2
 " no other.

DISTANCE TO N 1/4 Post 40.12
 COPIED on Pg 81 S " " 38.12
 " 39.3 " E " " 39.35
 " " W " " 35.69

SEE 1/8 P. E. of center AT 1967 + 3/4 LKS south of Road
 SUGAR 9 N 62 - E 69 3/4

no other

SEE 1/8 P. W. of center AT 1784 1/2 W. of center
 SUGAR 12 N 13 1/2 W 66 Hem 10 N 62 E 5 1/2

" 15.58 1/2 E 63 SUGAR 10 S 10 1/2 W 35 1/2

SEE 1/8 P. N. of center at 20.06 + 29 3/4 W of R
 HEM 10 N 62 E 5 1/2

SUGAR 10 S 10 1/2 W 35 1/2

SEE 1/8 P. S. of center at 1906 + 45 9 1/2 W of R
 HEM 14 N 79 1/2 E 19

" 14 S 85 1/2 W 38 1/2

South from 1/8 P. East of center VAR 3 1/2 E
 3909.49 W of 1/8 Post

WEST from S 1/8 Post on EAST Line VAR 1/4 E
 3955 FELL 11 1/2 N. of 1/8 Post Corrected
 Line east and SEE 1/16 Post in center
 of SE 1/4. MAPLE 12 S 6 W 5 1/2
 " no other

WEST from N 1/8 P. on EAST Line VAR 4 1/2 E
 3955 FELL 20 3/4 S. of 1/8 P.

South from E. 1/8 P. on N. Line VAR 3 1/2 E
 4003 FELL 78 E of 1/8 Post
 CORRECT ALL LINES in NE 1/4 and
 SEE 1/16 Post SUGAR 12 N 87 1/2 E 18

CORRECTED ALL LINES in SE 1/4.

MAY 23" 1915
 Counter reduced

SEC 12" 35-11-6 May 24" 1915 Cont

WEST from 1/8 N of Center Var 1/2° E.
3751 fell 10 $\frac{3}{4}$ North of 1/8 R.
Copied on Page 353

north from 1/8 Post W. of CENTER
Var 5° East 4 $\frac{1}{2}$ SW 1/16 Post

Came South and SET 1/16 POST in
N.E. 1/4. { Sugar 12 N 71 $\frac{1}{2}$ E. 19 $\frac{1}{2}$
County Birch 24 S. 34 $\frac{1}{2}$ W. 18

corrected Lines around SW.NW and
SE NW. finished Monday May 24
1915. This SEC was SURVEYED on
the application of T DODDS and other
RESIDENT OWNERS, under & SECTION
827 WISCONSIN STATUTES. RESIDENT
OWNERS, PAID in FULL. COST OF SURVEY
IS 143,60 = \$9.10 per description.

compt. recd.

May 27" 1915

SURVEY of road for town of Monico
WENT to S.E. COR of 20-35-11-E. found
Post SE by Dorr. org Bt's nearly gone SE
one is a stub. A cedar fence Post sets
where Post belongs. nothing for bearing
Run west Var 4° E. but need not changed
its course 400' west of cor" Var 2° E

350 ENTER SWAMP copied on Page 354
800 STREAM 10. COURSE SOUTH

1250 LEAVE SWAMP

4700 C + NW RR. offset S 300 at 4000
7200 offset S. 156

7951 FELL 1 $\frac{1}{2}$ N of cor" a stone OK
DEPARTURE 4.57 $\frac{1}{2}$ including offsets
SET a STONE with X on top S. W 1/8 Post

" a " " " " for 1/4 Post

nothing for bearings. CORRECTED LINE
from C + NW R.R. EAST to cor for road
completely re-read

SEC 33.37.10.E. JUNE 7" 1915

WENT to N 1/4 P. found STUMP ORG BT,
OK. SET POST and RUN SOUTH VAR 6° East.
4073 FELL 12 1/2 WEST of CENTER which
I SET in March 1899. SET CEDAR
POST and MADE NEW BEARING

OLD } Spruce 7 N 7 W 33 $\frac{1}{2}$ copied on
TAM: 19 S 72 W 15 $\frac{1}{2}$ Page 335.
Corrected onto center and runs SW
30 STREAM 15. RUNS SOUTH

100 OVER STREAM RUNS SW
2032 FELL 60' WEST of 1/8 P. SET in March 1899
2872 " 85 " " MC "

Corrected Line N to center and
run a pocket compass line
WEST and found my old 1/8 P
1 { W. Pine 12 S 23 W 20 $\frac{1}{2}$
" " 15 N 56 $\frac{1}{2}$ E 6

Then N to my 1/16 Post in NW 1/4
SET CEDAR POST { SPR 8 S 12 E 12
" " 10 N 73 E 17

JUNE 9 =

WENT NW COR found STUMPS of ORG
TREES OK. SET CEDAR POST and RUN SOUTH
VAR 4° E. N 1/8 Post on W LINE IS GONE
4012 FELL 82' E of 1/4 Post I ORG TREE NEARLY
GONE S.E. END AL GONE. SET CEDAR POST
MADE NEW BEARING { CEDAR 10 N 54 W 22 $\frac{1}{2}$
" 12 S 12 $\frac{1}{2}$ E 15

WENT N + SET 1/8 Post { W. Pine 18 N 38 W 47 $\frac{1}{2}$
at 2056 $\frac{1}{2}$. no other

MOUTH from SE COR. OK bearings made in Sept
1906 which are { W. Pine 6 N 21 E 21 $\frac{1}{2}$.

Intended to run north on 4° 15' E but made
a mistake in setting VERNIER and run on
5456 county record

4049 FELL 1,58 W of 1/4 P. I SET in 1899
CORRECTED onto 1/4 Post and prolonged

copied on Run 335
SEC 33.37-106 cont June 10" 1915

Line north Var" intended to be 15'. but is 6' 6" found this E 1/4 P. and Y. Pine "Stp." now. made for bearing S 18 N 85 E 47. Stands in small hollow 40 49 SEC 158 WEST of 1/4 P. found Post & SEC in 1899 old Thd. Pine BT. now a stump. Tom is gone SET new post. Corrected on to 1/4 Post and prolonged line north on corrected course. 8 run this line in March 1899 county road 4049 SET cedar post.

37-106

SECTION 27 AND 28 JU 11-1915 copied on
SET 1/4 POST between them TELPOLCION 54,73 1/2

SECTION 34 RUN LINE BET 33 + 34.

East from NW COR. VAR 2° 15' E PAYE 832
8205 FELL 2.78 N of CORNER & SEC IN DECE
county 1906. STEPS" of both trees ok. SETTED
and POST 4X4 in 3 1/2 FEET Long 1 foot in ground.
BENT WEST and SEC 1/4 P in open FIELD
East of wet marsh. 3 1/2 X 4 X 42 in.

Copied = JUN 11. 1915

South from NE COR 45' East on Part
of stream 25 runs SW. strong current
7701 FELL 4 1/2 WEST of COR & SET from org -
trees in SEPT 1906. SET NEW POST 4X4 X 36
BENT north and set 1/4 Post at 3 1/2 X 4 1/2 and 2 1/4
EAST of random. SET a CEDAR POST TO 1/4 P
and a CEDAR POST 50 LKS, both EAST & WEST
of it. CORRECTED THE LINE FROM COR TO COR
SET OUT 1/4 Post from org

bearings no line required 335

Rained came home JUNE 12 1915

HESSE said THE STAKES CO DID
NOT WANT ANY MORE WORK DID AT
PRESENT county road

1915
5 16
SEC 25-24.36.8 and 19430-36.9. June 16. 17

WENT TO 1/4 P BET" 25+30-36.8 on 9
Found post set by Dorr and stubs of
both org" trees. Run south VAR 730 E
4131 FELL 92 LKS W of cor" SET by DORT.
Which is a gray boulder 6 X 6 X 22 inc.
It is about 8 FEET W of wagon road.

Corrected line north to 1/4 P for road
The south 2000 ch. is in the road as
now located = JUNE 17-1915
North from 1/4 P BET" 25+30-36.8 + 9

Var 8° E

South from NW COR of 3036.9-E VAR 8° E
4157 FELL 18 LKS E of 1/4 P

CORRECTED LINE NORTH FOR ROAD

Copied on PAYE 127
north from SW COR of 19-36-9 E

Var 3 1/2 E

2076 FELL 8 1/2 LKS E of an 1/8 Post SET
by Dorr or monsle.

4152 FELL 26 EAST of 1/4 Post SET BY
DORR 18 YEARS AGO.

CORRECTED SOUTH FOR ROAD

COUNT RECORD
North from 1/4 P BET" 19424
on COURSE of LINE from the
COR. #OF. 19-24. 25-30.

4141 HIT the post at COR to 13-18
19-24. The bearings for

this COR. are ALL GONE. DROUG an
iron pipe 2 inches in dia and 36 inches

Long at the SW CORNER of 30 and
NW COR of 19 and the same at

WEST 1/4 Post of 19 and WEST 1/4 P.
of 30 at COR O.F. 19. 24-25-30

DROUG an iron pipe 2 X 60 inches
as this corner is in a wet marsh

DROUG IRON PIPES 1 1/2" X 36 inches
25 feet E & WEST of ALL THESE
MONUMENTS, EXCEPT at SW COR of
19. and their OR 1 1/2 X 60 inches

Road for Town of Schoepke

8 Sect. 13-35-10 E. June 22-1915

WENT to W 1/4 Post & SEC 8 13-35-10 E. JUNE 22-1915
 I did not find org 1/4 Post at that time.
 But I find it is 9 LKS W. and 48 1/2 South
 of the one 8 SEC. There has been a road
 cut out on this 1/4 Line running E & W in
 this section. I surveyed this road Nov.
 19 1911. And I have to correct it.
 I found my Survey is correct at the
 East 1/4 Post, but is 48 1/2 Links to far north
 of west end.

WEST from E 1/4 Post on old Line & Var 100
 8674 fell 48 1/2 N of W 1/4 P "org"

CORRECTED LINE East for road as
 follows AKA Point on corrected Line 4648
 turned an angle N 44 W - run 473 ch
 Thence N 48 1/2 W 6.00
 " N 66 1/2 W 3.00 "
 carried on Road " N 69 1/2 W 3.00
 3.01 " N 82 W 2.50
 " S 48 W 14.33
 Thence WEST on true 1/4 Line 20.00 Ld
 WEST 1/4 Post of SEC 13

Thence N 61 1/2 W 8.64
 " N 30 1/2 W 2.00
 " N 3 1/2 W 5.75
 " N 49 1/2 W 3.50
 " N 30 1/2 E 2.25
 " N 12 E 2.00
 " N 33 1/2 E 1.75
 " N 48 E 3.50
 " N 61 1/2 E 4.00 county road
 " N 20 1/2 E 3.25
 " N 9 E 2.50
 " N 36 W 5.00
 " N 50 1/2 W 2.00
 " N 48 1/2 W 7.30 to Line bet SEC 11 + 14 and 4.89 East of me and 11.82 West

of SE corner of SEC 11.

carried to Page 10

~~at 46.56 E of W 1/4 P turned angle N 44 W~~

Road for Town of Schoepke cont

SEC 13-35-10 E cont. June 23 1915

NORTH from WEST 1/4 P. VAR 3.45 E
 1400 ENTER SWAMP MOSTLY TALL HEAVY THICK
 3070 STRAW 15 LKS wide runs SW
 3916 FELL 11 East of COR. NE BT OK
 carried on Page 301

WEST from CORNER to 13-14. 11. 12

VAR 415 E on my OLD Random
 1000 LEAVE SWAMP

1200 ENTER "

1631 to Shore of LAKE & SEC 11C 25N of
 where random intersects LAKE

{ W. Birch 7 N 33 E 23
 " 6 S 84 E 46 1/2

WENT me on W. SHORE of LAKE on Line
 bet 11 + 14 and run WEST on true
 Line which in now 1908 for Pommer.

1057 my 1/8 Post on Line new
 3017 COR to 10-11. 14-15 OK VAR 15. N 32 W 21
 = JUNE 25 1915 =

WEST from SE COR of SEC 10 VAR 23 1/2
 3850 ENTER SWAMP
 4007 FELL 51 1/2 north of 1/4 P OK

WEST from 1/4 P. bet 10 + 11 VAR 21 1/2
 on my OLD Random
 1000 LEAVE BETTER SWAMP

3300 ENTER "

4002 FELL 141 North of COR. SEC 11
 by proportional measurement
 SEVERAL YEARS AGO { Birch 14 N 40 W 22
 " HEM 9 S 65 W 36

CORRECTED LINE bet 10 + 15 EAST for
 road, for the Town of Schoepke
 county road

county road

Continued

10 SURVEY OF ROAD FOR SCHOEPKE JUNE 24
 Thence north 59 1/2 west 4.75 on Lake Shore
 " " 75 1/2 " 7.00
 " South 88 1/2 " 9.00
 " " 80 " 3.00
 Castledan " 74 1/2 " 5.00
 Payson 301 " 80 " 7.75 To W. end of dam
 " " 60 " 1.42 To Little bet
 bet 11 and 14.
 Thence WEST on SEC² Line 2.930 chains To
 corner 10-11-14, and 15

Thence WEST on SEC² Line 8019 to corner
 to SEC². 9-10-15-16 whole dist² of road
 surveyed 2 miles and 3/4.

finished June 25" 1915

JUNE 28 1915 $\square \square \square$ car^{by road}
 RANGE LINE bet² 8+9 - TOWN 37
 Began at 1/4 bet² 19+24, with flag at
 cor. to 13.18.19.24 SET LINE STAKES
 for road. Var 2° E. SEC 1/4 from evidence
 of three old residents Post sets in center of
 N+S road and on the line running E + W
 COR was identified by the 2 Pine BT's.
 now Stubs. Set on iron pipe 1/2x30 inches
 for Post and an $\frac{1}{2}$ iron pipe 1/2x30 inch &
 37 1/2 LKS East and WEST from corner

North bet 18+13 Var 3 1/2 E

4073 FELL 102 3/4 LKS W of 1/4 Post, identified
 by stumps of org² trees, and an old
 Post placed iron pipe same as
 at SEC² corner. CRECTED LINE SOUTH
 for road, for town of Pine Lake and
 copied on SEC 18 P. and an iron pipe 37 1/2 LKS

North from 1/4 Post bet² SEC² 13.18 Var 2 E
 4028 FELL. 15 1/2 E of cor. Stumps of org tree
 are ok. marks plain. PAGE 214

WENT TO 146² and CORRECTED LINE
 SOUTH to CORNER for road. for Pine
 Lake COUNTY RECORD

1915

SURVEY OF ROAD FOR THE TOURIST OF
 PINE LAKE JUNE 28" 1915
 commencing at the 1/4 POST bet 19+24
 in TOWN 37 RANGE 8+9 E.

Thence north on range line to cor²
 7-12-13-18 Thence north on line bet²
 7+12+16 2 chains

Distance	Var 2° E	Distance
" 43 "	436	
" 4 "	575	
" 6 "	938	
" 2 1/2 "	500	
" 1 1/2 "	840	
" 80 1/2 "	375	
" 85 3/4 "	237	
" 42 1/2 "	518	
" 13 "	272	
" 8 1/2 "	1256	
" 9 1/2 W "	903	
" 2 9/4 E "	1117	
" 41 "	1512	
" 61 "	547	
" 36 "	1334	
" 28 1/2 W "	1482	
" 44 1/2 1/2 "	986	
" 48 1/2 "	869	

" WESTON E + W 1/4 Line of SEC² 6 226
 to 1/8 Post WEST of CENTER " " 3691
 Thence north on west 1/8 Line " " 1462
 to W 1/8 Post of SEC 6. T 37 NR 9 East
 +++ N 9 1/2 W Var 2° E 2123

12 SURVEY of Road for town of Ping

Lake June 28 1912

commencing at 1/4 P. Bet 19 + 24 - 37. 8 + 9
Thence north on SEC C. Line 953 5 ch

to a stake which stands on^w Line 0518
Bet^w SECS 7 + 12. And 1462 N of^{1/4 P. bet 1/2 1/4}

Thence N 48° East Var 2° E

Thence North 58° East Var 2° E

43 "

4 " "

6 " "

21 1/2 "

1 1/2 "

80 1/2 "

83 3/4 "

42 1/2 "

13 "

8 1/4 "

9 1/4 West

29 1/2 East

41 "

61 "

36 "

28 1/2 West

9 1/2 "

13 1/2 "

48 1/2 "

West on E + W 1/4 Line of SEC 6 22 6
north W 1/8 Line 36 91

To W 1/8 Post on north Township
37 - N.R. 9 E East Total 305.52 ch:

= 3.3/4 miles and 22 rods

Note

Survey at first on West line of Sec 24 (in road). No post or P.T.
Had evidence of 3 Men, all agreed as to P. of E. All on N.B.S. roads
Set flag at Sub Cor 18 (B) pine trees. Now stobs O.K.

Lake

SEC-6-37-9 E JUNE 29-1915

13

Went to N 1/4 Post found old Post and
NW BT. it is dead. SW Stb OK.

Run west Var 3° E

43 13 fell 13 S of cor set from 3 org trees.
found an overrun of 1.26. Proportions
same and set 1/8 Post at 2060 WEST
of 1/4 Post } W. Ping Stb 30 N 61 1/2 W 43

Copied on 1 Page 213
WEST from CENTER Var 3° E

22 19 to Lake

3800 over "

43 67 fell 7 south of 1/4 Post
set 1/8 Post at 2082 1/2 W of center Iron Pipe
SOUTH from W 1/8 Post on WEST Line line
3691 Var 3° E county record
3691 fell 65 East of 1/8 P Iron Pipe
CORRECTED NORTH to 1/8 P for road

SEC-31. 38. 9 JULY 6 1915

WENT TO NW COR found Post & Set from
ORG trees in DEC 1915. Run East Var 4° E.
600 LEAGUE SWAMP copied on Page 266

49.81 fell 201 North of DORR 1/4 Post
found stump of SETREE. NW TREE IS
DOWN MARKS OK. SET NEW POST AND

REMARKS S.E. STUMP. FOUND AN OVER
RUN OF 7.95 PROPORTIONED SAME AND
26.01 EAST OF NW COR. AND 23.80 W
OF 50 1/4 Post } W. Ping Stb 11 S 80 1/2 E 43
" . 20 S 84 1/2 W 50 1/2

WENT TO S. 1/4 P. SE Post from org trees. both
DEAD. RUN NORTH VAR 5° W

22 07 WGT boggy marsh. about 800 S. of Lake
48 32 OVER LAKE

79.74 FELL 4.56 1/2 E. OF DORR 1/4 P. SEE ABOVE
DEC 5.724 change course 3° 15'

County Record of Field notes
WENT TO W 1/4 P found STBS of org trees
marks at found Post & Set about 12 years ago

14 SEC 31-38-9-E Contd July 9th 1915

Run East Var 4° East

1415. to Aug: Dorches Road copied on


2367 " LAKE or floating bog

5600 ONE "

8286 FELL 19.6 N of 1/4 Post. It is not a good Post. but was set by some one who had run from NE to SE corner

and as his random is PLAIN and LOOKS 8 USED his Post. DEC 2.366 change course P.21 as the center of SEC is in LAKE. I went to East shore of Lake at TALLY 5600 eh and CORRECTED LINE at this point turned a Right angle from CORRECTED LINE and run N. to N Shore of Lake 1088 chains then WEST to CORRECTED EAST & WEST 1/4 Line 9.46 chains. and at intersections of these took the angles of some

Page 266 County Record



found at 1088 N of ENE 1/4 Line to run South to E & W 1/4 Line on course of N + S 1/4 Line & WOULD be 1.05 WEST 9.46 + 5600 + 1.05 = 5600 - 9.46 - 1.05 = 45.49 which is the

Distance to W 1/4 Post from center 4549

E 3737

" N 3993

" S 3981

SET me. on north Shore of Lake 29.05 South of N. 1/4 Post. { Y. Pine 10 N 7 W 30

W " 5612 38 6 32 1/2

SET 1/8 P W of center 23.56 East of WEST 1/4 Post near Lake shore { Spruce 5 N 6 1 W 6

.. 5 5 1 1/2 6 5 1/4

South from W 1/8 P on N Line Var 15° E

3981 FELL 19 East of 1/8 P WENT North and at TALLY 2044 CORRECTED Line North to 1/8 Post

SEC 30. 38.9 JULY 9th 1915

EAST from W. 1/4 POST Var 6.15 E
SEE PAGE 164 NOV 1914

750 LEAVE SWAMP

3785 top of hill about 200 E of LAKE

5788 FELL 19 N of DORRS bearing for center of SEC and 3 LKS South of 1/4 Line. And 276 East of center. in LAKE

This makes my departure 16 N of center found an over run of 13.26 proportioned same & SET 1/8 Post W. of center at 2780 East of W 1/4 Post { W Pine St 12 N 7 E 5

North " 16 S 20 E 17 "

South from W 1/8 Post W of center Var 215 E
3812 FELL 9 1/2 W

north from W 1/8 Post on South Line Var 2

3812 FELL 9 1/2 W of 1/8 Post W of center
CORRECTED LINE South to 1/8 Post

and SET TEMP 1/16 Post

WEST from TEMP 1/16 Post Var 5 1/2 E

2690 FELL 9 0 N of 1/8 Post SET in Nov 1914
CORRECTED LINE EAST to 1/16 Post

Copied on Page 264. County Record

SURVEY of Road for SUGAR Camp
commencing at W. 1/8 Post on South Line
of 31. Township 38. N. R 9 E East

Thence N 11 1/2 W on Township Line 580 eh

" 11 1/2 WEST 2897 "

" 31 1/2 " 700 "

" 26 1/2 " 1000 "

" 3 " 825 "

" 23 1/2 E 425 "

" 89 " 250 "

" 73 " 900 "

" on 1/8 Line 2044 "

to WEST 1/8 P on N Line of SEC 31 1906

Thence N north on 1/8 Line --

to 1/16 in S.W. 1/4 of SEC 30 Same Town

Thence WEST on 1/8 Line 2691 "

to 1/8 Post on Range Line 3750 "

Thence North on Range Line N 1/8 P of 30 3750 "

17914

of

¹⁶ SURVEY OF ROAD FOR TOWN HARRISON

COMMENCED JULY 12th 1915 FINISHED
COMMENCING AT N. END OF ROAD. SUPPOSED
TO BE AT N 1/8 POST ON LINE BET SECTIONS 20
AND 21. T. 35. N.R. 8 E.
Then N Var 4° 15' 1972 to cor to SEC 2
16-17-20. 21. FOUND 2 ORG TREES MADE NEW
BEARINGS { T Am 12 N 52 1/2 E 65 over 13'
{ sugar 10 S. 64 W 63 ^{Boggy ground} 39 1/2
NORTH BET 16 + 17 Var 3 1/2 E ^{over} 4.87

3500 ENTER BURNED SWAMP. TIMBER DEAD
4450 STREAM 25 YRS WEST
7100 LEAVE SWAMP
7800 ENTER " "
8264 FELL 235 EAST OF COR TO 8-9-16. 17
FOUND THE 2 ORG BRS, AND THE JACOB
STAFF USED BY DEPT U.S. SURVEYOR
NOW LIM LYING UNDER MOSS 16 INCH BELOW
SURFACE. SET NEW POST + ~~MADENEL~~

NORTH BET 8 + 9 Var 3 1/2 E
500 LEAVE SWAMP
1500 ENTER "
2500 LEAVE "
3500 ENTER "
4043 FELL 208 EAST OF 1/4 P. FOUND
BOTH STBS OF ORG TREES AND POINT
OF ORG POST. SET NE POST AND RUN
NORTH BET 8 + 9 Var 5 1/2 E
900 LEAVE SWAMP
4208. HIT POST COR TO SEC'S 4-5, 8 + 9
FOUND STB OF S.W. ORG TREE. THE NE
TREE IS A STUB 10 FT HIGH MARKS OK
THIS TREE IS 80 LKS DIST INSTEAD OF 60
WENT SOUTH AND FOUND FENCE POST
WHERE 1/8 POST SHOULD BE. RUN A LINE
WEST FROM THIS 1/8 P. 4020.
CORRECTED LINE FROM 1/4 POST 60 FT
8 AND 9 SOUTH NORTH END OF HARRISON
ROAD. FOR A ROAD FOR SAID TOWN
JULY 15th 1913.

copied on Page 349 1915

SECTION 31. 39-10 E JULY 16th

WENT TO W. 1/4 P. FOUND POST AND
STUMPS OF ORG TREES MARKS ON NE.
ONE OK. POST SETS IN WIRE FENCE.
RUN EAST VAR 1 1/2 E TO MISS TIMBER
2510 OFFSET N 100 TO MISS. BARN
7746 FELL 137. SOUT OF 1/4 P. YIELDING OFFSET.
CORRECTED LINE WEST FOR ROAD
FOR TOWN OF SUGAR CAMP
===== County record =====

SECTION 38-12 E JULY 19th 1915

WENT TO W 1/4 P. SET POST FROM SOUTH ON
TREE. IT IS DEAD, BUT MARKS ARE OK
Run N. Var 3 1/2 E
NEW BEARINGS { T Am 8 N 55 W 86 1/2
{ .. 10 N 44 1/2 E 43 1/2
38.30 FELL 8 1/2 E OF COR SET POST 2 ORG TREES
WENT SOUTH AND SET 1/8 POST. 1800
SOUTH OF COR { Spruce 7 N 57 W 11 1/2
{ T am: 10 S 69 E 8 1/2
SOUTH FROM W 1/4 POST VAR 3.30 E
2640 INTERSECT LAKE LOOKED FOR MC. DID NOT
34.73 OVER .. SET MC. FROM SET TREE EAST
AND FELL 25 E OF POST. WENT BACK AND
FOUND ORG POST IN BOG ON SHORE OF LAKE
MADE NEW BEARINGS { Y. Pine 12 N 16 E 59 1/2
+ BET NEW POST { T am 12 N 40 W 69 1/2
CORRECTED LINE NORTH AND SET 1/8 POST. 2000
EAST SOUTH OF 1/4 POST { W. Birch 10 N 49 W 29
{ .. 6 S 2 E 12 1/2
this Line is all SWAMP + LAKE but 600 s

¹⁸ SEC" 1238-11 JULY 20 + 21 1915

Gr' NE. cor. is in Lake & began at me
on South Shore of a point of Land which
extends a short distance East of East
Line and run West on $\frac{4}{5}^{\circ}$ E. by S.

5/4. Then south 4.54. Then east 32 to Lake
and set me where N Line is said to
intersect Lake {W.Pine 18 N 34 W 26 1/2
S 42 1/2 W 1/2

WEST from me on N Line 4°
1500 ENTERS SWAMP AND CREEK BOTTOM
2250 STREAM 40 LKS WIDE RUNS S.SW
2689 bend in same stream
3040 OVER bend of "
3600 LEAVE SWAMP N
3884 FELL 234 S.outh of 1/4 Post
WENT EAST AND CORRECTED LINE FROM
ME WEST 408. AND SET POST 278 FEET FROM 'AK

SURVEY of Road fortown of¹⁹

TRIPOLI in 36.4. JULY 29th 1915
Began at corner to SEC⁸ 21-22-27+28.
Run north Var 3°30' E. The bearings for
this corⁿ Tamm 12 N 72 W - gone
original Birch 9 N 20 E - found down oak
Cedar going ~~67~~ found down. SET UP
not given.

new, Dead Pine 9 N 66 E 73 1/2


8000 did not find 1/4 P or corner
~~17227~~ 17227 fell 4.75 E of where NTS + E + W
17227 Lines cross both Lines are plain NO BT
could be found. Went south and at
8088 fell 3.59 1/2 ~~NE~~ East of cor^e to 15-16-21.27
found steps of 3 org trees. Set post +
made new bearings. W. Pines sub 285 85% 32%

Went south + SE 1/4 Post on org line and on my random which has been my Random for the whole distance, at 4044.

Bearings for 1/4 P. W.Pine stp 22 S 6 1/2 W 34 1/2


Began again at cor. to 15-16. 21-22
and run north Var 4.15 East. Aug 2nd 1915
Rained all day. Aug 3rd Rained all
day. Broke up camp and came home

① ^{abided on Page 1st}
SEC" 5. 36-9 E. CLUGUST 29/1915
WENT to Dorrs 1/8 P. South of center.
Post was down & rotten. SET CIN IRON PIPE
for Post, found Stump of DORRS NW BT ok
Run north UAR 4° W. County
21.22 1/2 FELL 32. E of Cent. Stps" of Dorrs ok
Prolonged corrected Line N. across R. Range
East from UAR 3 1/2 W Record
1992 FELL 3 BLKS N of Dorrs 1/8 P. SET CEDAR
Post Dorrs BT A Stp but ok. Went to
center again. Prolonged E + W 1/4 Line W.
Pass RIFLE Range



²⁰ SEC 5-36-9 E cont Aug 30. 1915

Took the angle of 1/4 lines at center
as shown below on this page



SEC 6, 36-8 E. Sept 10 1915
WENT TO NW COR found Post & SET from orgⁿ BT's. SEE Page 45 Books of 1909. Copied down Page 125 County
Run South Var 14° East Record
2110 to Lake (on corrected Line)
2526 over " "
3132 fell 75' East of Dorrs 1/8 P.
Am not sure the Post is exactly right it was lying down and I did not have Dorrs notes His bearing is there a stump now. CORRECTED LINE to come

²¹ SEC 2, 36, 13 E SEPT 14. 1915

WENT TO SW CORⁿ found EAST BT OK, WEST one is down, MARKS OK. SET NEW POST, AND RUN NORTH. VAR = 4° E.

8118 FELL 67 LKSⁿ EAST OF COR. SET POST from SUGAR 128 11° E 20 AND STⁿ OF SUGAR WHICH STOOD N 9° E 35 both LINDS GONE. FOUND A# SHORTAGE OF 36 LKS PROPORTIONED SHORTAGE, CORRECTED LINE SOUTH AND SET 1/4 P AT 3982.20/100 AND 32.85/00 W OF RAND { SUGAR 12 S 18 1/2 W 31 BIRCH 26 S 60 E 15

CORRECTED LINE SOUTH TO # SE CORⁿ
= 15 =

EAST FROM SW CORNER VAR 4° E
4091 FELL 95' N OF 1/4 POST. SET POST BOTH LINES OK

NORTH FROM SOUTH 1/4 POST VAR 5° EAST
4000 ENTER TANⁿ + SPRUCE SWAMP

4400 LEAVE "

8110 FELL 17' EAST OF 1/4 POST NW TREE OK. THE SW ONE IS GONE MADE NEW BEARING { SUGAR 10 N 45 1/2 E 36

EAST FROM NORTH 1/4 P. VAR 3 1/2 E

1970 FELL 15' N OF 1/8 P. SAID TO BE DORRS
CORRECTED LINE W. TO 1/4 P

NO WEST FROM W 1/4 P VAR 2.5° E

78.14. FELL 8 3/4' N. OF 1/4 POST. FOUND BOTH ORGⁿ TREES DOWN. MARKS OK
MADE NEW BEARINGS { HEM 12 N 64 1/2 E 14
} DO 18 N 61 W 38 1/2

WENT WEST & TO CENTER { BIRCH 12 N 71 W 39 1/2
} HEM 12 S 30 E 43

DIST. E. ON 1/4 P. 4129

" .. S .. 3981

" .. E .. 3784

" .. W .. 4030

over

SEC 2 36-73 Cont Sept 17-19 15

SET 1/8 P E of CNT AT 37 84 + 6^{ft}s of Random
 { Sugar 9 N 63 W 48 1/2
 " 9 S 8 1/2 E 25

NORTH from 1/8 Post East of Center Var 7° 6'
 4246 FELL 12 WEST to 1/8 Post
 CORRECTED Line South to 1/8 Post
 Line from Enter. E. to 1/8 Post
 CORRECTED Line from CENTER S. to 1/4 Post
 finished at 5.30. P.M.



SEC 2 37-7. E. SEPT. 23-1914

Went to S 1/4 Post which I set from Spots
 of org-trees. Oct 8 1914.

Run N. Var 5° E

40.00 Var 5° E

60.00 " 6 " E

8300 FELL 2.94 W of 1/4 P. SET NEW
 POST from Stump of the Pine BT
 Var at N 1/4 P 7° E

WENT SOUTH to TALLEY 40.00 chains
 and CORRECTED LINE, and SET Line
 Stake AT 3800. on CORRECTED LINE
 WENT to TALLEY 2000 chains and
 SET STAKE 1/8 P. { W.PINE 18 N 50 E 11
 " " 18 N 5 W 13 1/2

SET Line STAKE about 200 EAST



SEC 2 6-39-7-E SEPT 24 1915

Began at m.c. on EAST shore of Lake.
 SET Post from Stump of W.Pine org tree
 The maple is down but marks are ok.

Run EAST Var 4° 6'

22.28 FELL 48. N. of 1/4 Post. found stumps of
 both org trees. They are very rotten. Made
 new bearing { W.PINE 16 N 53 W 91 1/2

North from South 1/4 Post Var 3 1/2 E

1421 INTERSECT LAKE & SET LINE
 { W.PINE 36 S 84 1/2 W 24 1/2
 " " 16 S 82 1/2 E 10.

SEC 3. 38-7 E. SEPT 28. 1915

WENT TO NE COR " found IRON
 MONT. SET by W^m ALLEN and
 myself in May, 1893. ALSO SET of
 of bearing made by Dorr in June
 1893. Run south Var 3,30 E ASL.
 1390 FELL 6 LKS East of 1/8 Post
 SET by his bearing is { W.PINE Stp 18 N 74 1/2
 East 29 3/4 } CORRECTED LINE NORTH.
 WEST from N 1/8 Post on E Line Var 3 1/2
 354 to East Line of VILLAGE PLAT.
 ANGLE at this point from 1/8

Line South to E Line of VILLAGE PLAT
 is 55.55' ANGLE from 1/8 Line North

to VILLAGE PLAT is 124.45. COURSE of
 EAST Line of PLAT is N 34° W and it is
 958 ch to N.E. CORNER of PLAT.

THENCE South 56° W 4.42 ch to
 E. LINE of STREET

WEST from N.E. COR. VAR 4° E

4007 FELL 5 9/12 S of 1/4 POST

WENT EAST and SET 1/8 P. at 2003 1/2
 { W.PINE Stp 20 N 75 W 37 1/2

SOUTH from EAST 1/8 on Line
 Var 3 1/2 E. SEPT 30 1915

3.68 to a point 150 feet North EASTLY
 from the center of THE CTN WY
 Railroad track which is more
 EASTLY Line of their right of

way. ALSO SET STAKES about
 100 FEET apart on northerly Line
 of said right way South EASTLY

to the northerly Line of the PLAT

of the VILLAGE of Tomahawk LAKE

SET on IRON monument at N 1/8 Post
 on east Line and at east 1/8 Post on

" north Line, ALSO at a point where
 south Line of the NE. NE. int. intersects VILLAGE

PLAT, and WHERE WEST Line inter-

-SECTS Right of Way
 finished in the rain Sept 30 1915.

²⁴ SEC "3. 36-10. E.

WENT TO EAST $\frac{1}{4}$ Post foun Post
And B.T. & SET in Sept 1906
Run South UAR 13° East
3783 FELL $2\frac{1}{2}$ W of COR SET by Dorr
TOOK his bearings } Tamil N $34\frac{1}{2}^{\circ}$ E $47\frac{1}{2}$
copied on Page 308 } " 18 S 54 W 8
WEST from S.E. COR UAR $15\frac{3}{4}$ W
1843 to $\frac{1}{8}$ P & SET in 1906
Then run north 17° found
OLD LINE & run & CORRECTED in 1906
REMARKED it N to $\frac{1}{8}$ P. which is OK
& the run E UAR 23° W to E. $\frac{1}{4}$ Post
Run WEST from N $\frac{1}{8}$ P on E Line
UAR $15\frac{1}{4}$ WEST to $\frac{1}{16}$ Post found a post
and B.T. & SET in 1906 ok N.B.T. is down
county record

SEC 2. 36-10. E Oct 6" 19. 15
East from W. $\frac{1}{8}$ P N Line which is
SET 1899. TREES both down post ok.
Put a Break Rod with Break
Attached, for Post UAR 45° E
2033 FELL 81 N of $\frac{1}{4}$ Post SET NEW
Post from S.E. B.T. now a stub.
made NEW bearing $\frac{1}{8}$ P. SET 36 N $63\frac{1}{2}$ W
copied on Page 308 county record
East from N $\frac{1}{4}$ P. UAR 10° E
4070 fell 86 N of cor SET new post from
stumps of 3 of the org trees REMARKED
the stump of Pine. DEC Chang COURSE
corrected UAR 30° W. came west and
SET $\frac{1}{8}$ P at 2035 and 43 S of Random
SW. Pine SET 24 N 9 W 5
" " " 18 S 27 E 4

37-10 OCT 13-1915
Copied on Page 26+27-3435²⁵
COMMENCED AT COR TO 26+27-3435¹⁵
And run north UAR $43\frac{1}{4}$ E
4285 CENT of Wagon Road ORG $\frac{1}{4}$ P
Stood in center of road of this road
8139 FELL 34 W of COR & East B.T. is a stub
is ok. SET new Post went south
and set an iron bolt $1\frac{1}{2}$ + 18 in e
drove an iron bolt $1\frac{1}{4}$ X 36 in e 15 LKS
north of $\frac{1}{4}$ P.

North from cor to 22. 23. 26 & 27
UAR 40°
1.10 over CREEK 20 wide runs west
500 LEAVE CREEK bottom
40.00 Did not find $\frac{1}{4}$ Post 326
8000 " " " CORNER
12000 " " " Post
16000 " " " CORNER
20000 " " " $\frac{1}{4}$ Post

= OCT 15 1913 =
20210 found $\frac{1}{4}$ POST & SET in Jan 1912

" Post and bearings OK
Run S. UAR from $\frac{1}{4}$ P. betw 10 & 11
29.50 to lake

31.82 over
41.86 FELL 2OLKS east of cor & SET in
Jan 1909 from ORG. Bearings
and made new $\frac{1}{8}$ P. 10 N $43\frac{1}{2}$ 30
W. 11 S 5 E 68

CORRECTED LINE NORTH to $\frac{1}{4}$ P and run
NORTH on CORRECTED LINE UAR 7° East
42.15 FELL 2 LKS W of COR OK JUST AS I
LEFT it Jan 1912 SEE PAGE 70 1912
PICKED UP MY RANDOM AND AT
158.71 FELL 1092 W of COR E 0.10.11.14.15
County Record

NORTH BEG $2\frac{1}{3}$ UAR $3\frac{1}{2}^{\circ}$ E
2300 Enter Tam. & cedar coblation
4297 found $\frac{1}{4}$ Post 9.08 E East found,
both bearings down. Marks are
PLAIN, SET new Post and made
322 new bearings SEE NEXT PAGE

copied on Page 322

1915

26 SECTION LINES IN 37-10 E CONTACT 16

1/4 P bet CEDAR 7 N 63 E 28 1/2
SEE. 2 + 3 " 8 S 63 W 36 County Road
North bet 2 + 3, the second time
Changed course 12° Var 8 1/2 N
43.65 fell 5 Lks. W. CORRECTED SOUTH
and set 1/8 P. { WPine Stp 28 S 88 1/2 W 38

North from 1/4 P. bet 2 + 3 Var 4° E
400 LEAVES SWAMP according Page 322
3922 FELL 46 East of COR. SET Post from
3 org bearings. made new ~~last~~ bearing
County record { WPine Stp 28 S 81 E 40 1/2
CORRECTED LINE AND SET 1/8 POST AT 1994 1/4, CIS
A found a shortage of 14 Lks.

Copied on Page 326

WENT TO WHERE COR. TO 14-15.22.23
Should be, was not able to find
SO I SET TEMP COR. FROM MY RAND.
which at 158.77 had been 1092
West of COR. TO 14-15. 22. 23. SO I SET
TEMP COR. AT 79 38 AND 546 CASL
OF RANDOM SET A LINE STAKE SOUTH
AND MARKED A TREE NORTH OF CORNER
AND CORRECTED LINE ON MADE
" bearing { WPine Stp 28 S 81 E 54. N.G.

WENT NORTH AND SET 1/4 POST
BET 14 + 15 119.06 N OF COR. TO
22.23-26-27 AND 819 EAST OF RAND.
{ a gray boulder 6x6.2 ft high
{ bears N 89 1/2 east 137 dist
this is all at present
county record

SURVEY OF Road in 36-4 for
TOWN OF LYNN. BEG. ON IN JULY 1915
AND COMPLETED UP TO CORNER TO SEC'S
15-16. 21 + 22 SEE PAGE 19.

NOU. 18" 1915
North from COR to 15-16. 21 + 22
Var 4° E
8016 FELL 93 EAST OF COR. SET POST
from SW org tree. MADE NEW
bearing { WPine Stp 36 N 78 1/2 W 131
CORRECTED LINE SOUTH + SEE 1/4 P.
AT 40.08 AND 46 1/2 W. OF RANDOM
{ WPine Stp 36 West 84

= NOU 20-1915 =

North from COR to 15-16-9 + 10
Var 4° E
3600 ENTER CEDAR SWAMP AND AT
4000 SET LINE STAKES AND LEFT
IT UNTIL CONDITIONS ARE
BETTER. THERE IS TOO MUCH SNOW
AND WATER. CAME HOME AT 6 PM!

= DEC 14" 1915 =

BEGAN WHERE LEFT OFF NOV 20 1915
5575 STREAM 20 LKS WIDE
8000 DID NOT FIND CORNER LEAVES SWAMP
17296 FELL 131 WEST OF COR. TO 3-4. 33. 34
TOWNS 36 + 37 RANGE 4 E AND SET POST
FROM NW BT. A PINE STUB. COTN NOTES
CALL FOR HEMI FOUND A SHORTAGE OF
237. PROPORTIONED SAME. CORRECTED
LINE SOUTH AND SET COR. TO 3-4-9-10 AT
7907 N OF COR. TO. 9-10-15-16
CORRECTED VAR 3° 40' Gray boulder 2x3 FEET 18 in
height bears S. 52 E. 66 1/2

DEC. 757 high bears S. 52 E. 66 1/2
SEE 1/4 Post BET 3 + 4 54.36 South of COR. TO 3-4
33 + 34 TOWNS 36 + 37. R 4. WPine Stp 20 S 77 E 65
28 S 78 W 27 1/2
SEE PAGE 31 - For balance of line

²⁸ SEC 29.39.7.E. NOV. 24. 1915

WENT to me on East shore of Lake, found stumps of org. trees marks OK set Post and made new bearing {W.Pine Stp "14 N 6 1/2 W 49
" " 12 S 24 E 69

Run East Var 3 1/2° East
23.32 fell 12 1/2 N. of cor. set Post from stumps of org. trees OK

North from S.E. cor. Var 3 1/2° East
80.89 fell 70 3/4 East of cor. found Post set by Dorr found stub of org tree but it is a sugar. and is not called for in Govt notes made new bearing {W.Pine Stp "14 S 33' 1/2 E 85

came South and set 1/4 P. at 40 44 1/2 and 35 4 3/8 W of Rand

{W.Pine Stp 30 S 65 E 20
" " 36 S 25 1/2 W 58

came S + set 1/8 P 1/8 Post at 20.22 8/4 and 17 65/100 West of Random
[W.Pine Stump 28 N 27 1/2 W 4

copied on record
corrected lines S. to SE cor. DEC. 875
" from SE cor W to me
and took angle of SEC lines at SE cor. which is, 90° 05'

WEST from ECSE 1/4 Post Var 3 1/2° East
40.45 fell 18 1/2 South of Dorr's center
80.89 " 29 1/2 " W 1/4 Post. found Post set by Dorr also org. trees

DEC. 3647 change course 12°

angle bet' 1/4 Line. South 89 20°
S. SEC Line and E. Line at SE cor. 90° 05'

WEST from S 1/8 Post one East Line on an intermediate course bet E & W 1/4 Line and South Line. magnetic course

310 1/8 N E SEC Lake + set m. corner.
W.Pine 16 N - E -

This completes the lines around Lot 4
which I will now subdivide into lots + blocks

SEC 33.39.7 NOV 29. 1915

WENT to N 1/4 POST SET Post from stumps of org. trees. East one is a wind fall. marks OK. Run East Var 4 1/2 East 40 61. fell 36 1/2 north of corner.

found stump of tree marked by B.F. Dorr, in April 1900. His notes say he found found org. trees. Set new Post and made new bearing

new {W.Pine Stp "28 S 42' 1/2 E 35 3/4
Dorr's " " 24 S 45 1/2 W 32 1/4

WENT WEST and set 1/8 Post at 20 30 1/2 and 18 1/4 South of random {W.Pine 30 N 67 E 8 1/4
" " 24 N 62 1/2 W 24

South from East 1/8 Post on north line Var 3 1/2°
2105 center of C + NW RR track

=NOV. 30-1915 =

3975 fell 11 links East of Dorr's 1/8 Post
corrected line North to 19 87 1/2
and set Temp 1/16 Post. It sets in
N RR fence to right of way

Surveyed a piece of land in
E.C. 4 SEC 19.39-7 for John Grundy
as follows to wit: commencing at a
gas pipe on South shore of Mud Lake
the bearing is. W Pino 14 S 35 1/2 West 76 1/2
Thence S. 30° West 2.72 to a cedar Post
in swamp. Thence S 49 3/4 East 5.73 to
a pine tree 14. marked + on W. and N
sides. Thence North 81 East 12 1/2 to a
gas pipe. on shore of Mud Lake the
bearing is a Map 7 N 82 W. 34 1/4 marked
BT. Copied on page 104
county record

19
20 SEC 36-10-E DEC 2" 1915

WENT TO NE CORNER FOUND POST & NEW
BEARINGS AND ONE ARE² - THE NEARLY GONE
IT IS A STUMP & SET POST FROM IT SEVERAL YEARS
AGO AND MADE NEW BEARING
copied on Page 315

Run WEST VAR 4° E

125 LEFT bank of PELICAN RIVER
675 over bend of River to left bank
1350 LEFT bank again
1480 To right bank of River
7632 FEELL. 14.63. North of cor. var 3° E
found ~~off~~ a shortage of 5' 0"
Proportioned shortage and set
1/4 Post at 3754 and 7.19-661/100
South of Rand { W Pine 12 N 27 63
SET WEST ~~to~~ 1/4 P. S. lin { --- 10 S 82 1/2 E 33 3/4
at 56.31 W of NE cor { N. Pine 14 S 82 1/2 E 25 1/2
and 1079 1/2 S. of Rand { no other ---
County record

Run west from N 1/4 Pos. on corrected
course. changed course 10.54. Var. 13 1/2 E
1907 fell 10 S of 1/4 P. corrected line East

SEC 29-36-10 DEC 4" 1915

WENT TO N 1/4 P. ON EAST LINE FOUND POST
AND BEARINGS & SET AND MADE DEC 7-1897

Run south VAR 45° E copied

2116 FELL 1 1/2 LINKS EAST OF 1/4 P. O.K.
PROLONGED LIN SAME LINE SOUTH OF
2130 SEC 44 POST 3 LINKS WEST OF RANDIN
NO BEARINGS. SEC COR IS GONE.
BUT 1/4 POST IS CORRECT
CROSSED RIVER AT 9.50 SOUTH OF 1/4 P
AND BEND OF RIVER 1550 LEAV BEND AT 17.50
on Page 319

WEST from east 1/4 Post VAR 3° E
1000 OLD COLE ROAD ~~counterset~~
4159 FELL 1 1/4 LINKS N of end & set in DEC
1897. BEARINGS ARE } TAM 12 N 39 1/2 W 16
SPRU 8 S 44 E 13 1/2

copied on Page 319
SEC 29-36-10 CONT'D DEC 5" 1915
WENT TO N 1/8 POST ON W LINE FOUND
BOTH TREES & MARKED FOR BEARINGS
TAM 12 N 88 E 47 { ~~counterset~~
{ DO 7 S 72 1/2 E 51 1/2 } SET WHERE EE
I HAD ONE DEC 18 97 RUN EAST VAR 3 1/2
8370 FELL 95 1/2 S OF 1/8 POST CORRECTED
LINE FROM ECLL 6000 CHAINS WEST
TO 1/8 P. FINISHED SUNDAY DEC 5 1915

SURVEY OF ROAD FOR TOWN OF LYNN
BROUGHT FROM PAGE 27. NOV 13-1915
AND CONTINUED DEC 13-1915.
CORRECTED LINE SOUTH & SET 1/4 POST BET
9+10 AL 39 53 1/2 N OF COR TO 9-10-15-16
DEAD CEDAR 10 S 65 E 42 1/2

10 S 87 W 72 1/2
THESE BEARINGS ARE CUT OFF 4 FEET ABOVE
THE GROUND - FINISHED AT 10 AM. DEC. 16
IT IS SNOWING QUITE HARD NE WIND

SEC 26 39-7-S 6 P 24" 1913

WENT TO M.C. ON E SHORE OF LAKE FOUND
STUB OF PINE TREE & MAPLE IS DOWN MARK
OK RUN E VAR 4° E 22 88 FELL 48 N OF
1/4 P. MADE NEW BEARING

{ W Pine 16 N 53 W 91 1/2
RUN N OF RT. ANGLES TO LAKE AND
SET M.C. { W Pine 36 3 84 1/2 W 24 1/2
3 Y " 16 S 82 1/2 E 10

POSTED ON PAGE 108 COUNTY REC

32 SEC 8 35-11 DEC 20 1915

East from NW COR^Y VAR 4° E
9785 FELL 1.95 S OF NE COR. found SW sub 10ft high mark OK. made new
ORG tree down and Post and new bearing (W.P. SEP 36 N 61° E 29.1
Bearing by Dorr Oct 8 1898
new bearing } SUGAR 10 S 13 W 19 1/2
called } on Page

DEC 1. 99. Change course 1° 16' corrected
Var 5.10 E. Went W and set 1/4 Post at 50 to co^{py} " HEM #11 S 27 1/2 W 87 3/4
48.92 and 97 1/2 N of Rand: [Sugar 10 S 13 W 19 1/2] 174 FELL 1/4 S of me. Located me
no other

went W + set 1/8 P. at 24.46 & 48 3/4 N
Random } Birch 14 N 35 E 12 3/52

no other near

did not have time to correct line
from W 1/8 P west to NW COR^Y

Expect to come back & finish this
SEC^Y soon it is a bad one came home
at 1245 AM DEC 22 1915. no help.

SEE CENTER OF Pg 48 for balance
of this SEC^Y corner record

N from SE COR Var 3 1/2 E

See 4-38-11 can't find

Var 10 1/2 W

DEC 4.38-11 DEC 28 1915

WENT TO S.E. COR. FOUND SET TREE A
235 TO LAKE - bearings for W.M.
225 OVER LAKE - TEL POLN 42 W 66 3/4
48.92 and 97 1/2 N of Rand: [Sugar 10 S 13 W 19 1/2] 174 FELL 1/4 S of me. LOCATED ME
from Stumps of orig^Y trees
CALLED ON CHAS RUSSELL, VY HAS RUN
THIS LINE MANY YEARS AGO AND HE
SAID NO SURVEY MARK HAD EVER BEEN
FOUND ON THIS LINE. IS FOUND AS
A RUN OF SHOTGAGE OF 8.53. AND AS
WOULD NOT DO TO SEE MORNINGS. AND AS
HE SAW CORNERS BETWEEN BY PROPORTION
S IT WOULD BE IMPOSSIBLE TO GET
IN ANY WHERE NEAR WHERE THEY
WERE AND DIVIDED THE DISTANCE INTO
EQUAL PARTS. MAKING EACH 1/2
MILE 3750. WENT EAST S.E. TEMP^Y
COLDER DEC 550 AND 76 N of Rand
DEC 29 -

WENT FROM SE COR VAR 3 1/2 E ✓

225 LEAVE LAKE
40 TO FELL 912 W OF COR OK 19 1/2
FOUND AN OVER RUN OF 290
PROPORTIONS OVER RUN SET EAST
1/4 POST AT 41 49 3/4 AND 4.65.63/100
CASE OF RAND } POST SETS IN OPEN
+ PAGE 25 FIELD. IRON MONUMENT

25 from NE CORNER
225 TO MEAN 24 1/4 Shore of lake
SEC POST FROM EVIDENCE GAINED IN
1912. MADE NEW BEARING
9 PM SEP 16 N 35 1/4 E 62

no other corner
line went Var 17 1/2 E Record

34 SEC 438-11 Cont DEC 29 1915

6950 E to me on W. shore of Lake
Bkt Sections 5 + 32
found an overrun of 5.90
Proportions same and set NW
corner on ice at 57.30

Dec 30 =

went me on north shore of
medicine lake ~~set~~ in Sections
& ~~11.~~ Set Post from big trees and
run north Var 9° E
1100 Enter swamp copied on Page 373
4645 intersect lake
9050 leave "

9625 to medicine lake
12640 FELL 744 W of NW cor. on
Dec 587. change course 32°

found an overrun of 354
Proportion same and set Temp cor
at 4630 N of me bkt - 8+9 and
8010 S of NW cor. in medicine
sprung Temp cor on E + W SEC
Line N 363 1/2. Sprung Temp cor = off
N + S Line W. 119. and set cor = to
4+5. 8+9 on ice { spruce 8 1/2 W 1/2
{ W pine 10 S 7 1/2

my notes for S. line will now read
WEST from SE. corner Var 5° E
7424 FELL 439 S. of SW cor. on ice

Dec 5.90 change course 32°

SET S 1/4 P. 3712 and 2 1/2 N of Rand
" E 1/8 P on { Birch 10 S 24 E 20
South Line at " 7 S 88 1/2 W 54 1/2
18556 + 109 3/4 north of Rand office
{ no bearings

Dec 31-1915 { county record
north from SW cor = Var 410. E

44800 OVER LAKE

4480 4900 to medicine lake
8027 FELL 3 3/4 LKS W of NW cor

SEC 4 continued DEC 31-1915

SET me on S shore of medicine lake at 44°
north of SW cor " W Birch 5 N 13 E 12
copied on Page 373 L. " " S 6 W 30. SE
SET me on N shore of spirit lake at 4480
N of SW cor { Y. Pine 14 N 75 W 15
{ no bearings near..

found an overrun betw SW cor. and me
on North shore of spirit lake at 4.37.
Proportioned same and set 1/4 P on ice
at 4437 N of SW cor no bearings

WEST from East 1/4 Post Var 1° 45 E

3000 to lake { 1/8 LK 2 from me 2
5600 OVER LAKE { S 43 LK 2 from me 2
6250 to " { S 43 LK 2 from me 2
7887 FELL 343 south of 1/4 Post on ice { 2
43 South of me. 2

Set center of SEC 3944 + 171 N of 122
Random Post is on lake no bearing lake

SET 1/8 Post East of center at 1972
W of E 1/4 Post on { no bearings
in wet marsh. lake -----

SET East 1/8 P on S line on ice. N. B. 20
" me" on W shore of stone 1/2 ne
lake on south line nothing for B. center
this post is 2600 W of S. east cor.

Set S 1/8 Post on ice at 2075 no B. 2

Set north from S 1/4 Post Var 1/4
1100 to wagon. county record
1600. to lake.

4295 FELL 86 W. of 1/4 P on ice
went south and set 1/8 on ice

DIST to S 1/4 Post 3 9 4 3 1/2

" " W " " 3 9 4 3 1/2

" " S 1/4 P 4 2 9 5

3rd SEC 438-11 Jan 1st 19-16

SET me on East Shore of Spirit Lake
ET 4900 Y. Pine 1/4 S 34° E 41
copied 1 no other near on Page 373
EAST from 1/8 Post South center Var 45° E
3.836 FELL 38 N of E 1/8 Post
came west and set 1/16 P in SE 1/4
" WEST and set MC 5.50. East
of 1/8 P. S. of center
Y. Pine 1/4 N 30° W 89
no others

south from 1/16 Post in S 34° E 1/4
17.50 to LAKE county record
1.15. fell 16 W of 1/8 P.
came N + set MC iron mon.

SEC 39 #11E Jan 6" 19-16 me.
went to what is said to be the west
shore of LAKE and on Line bet 19 &
30. It is a W pine set with marks OK
the "gout" notes call for 2 Birches.
Put, & run WEST Var 43/4 E
850 FELL 1130 SOUTH of CORNER to 19-24-
530. found NW tree with marks OK also
a bump of S.E. tree with marks SET a post
466 Lang. 4 1/2 feet in mud.
I am satisfied the Line bet 19 & 30
was not run by deputy US Surveyor
as org. trees at NW cor are nearly gone
made new ones } copied on Page 380

Have made up my mind to locate
LINE cor. on ice. but must wait until
a Berg comes home
SOUTH from NW cor Var 43/4 E
W 1450 LEAGUE flowage county
10 043 fell 20.00 East of cor OK
41 went N and set 1/4 P. Y. Pine set 15 West 86
receded } 15.323 W 73
N 1/8 P on W Line } Head Tam 10 N 78 E 66
sets in flowage } " " 8 N 27 W 87

No good except West line

SEC 30-39.11. Cont. Jan 9" 1916

went to cor of 17-18-19-20. found Post
and stp of Y. Pine. it is N 45° W 6 instead of N 45° E
Run south Var 40° E copied on page
2156 fell 78 1/4 East of me which I set
from the oak bt. it is down had to
get it out of ice Post sets 40 LKS in
LAKE. made new bearing 380
Y. Pine 8. N 15 1/2 38.
found distance is 2170 my dist is 2156
a shortage of 14 LKS. corrected Var 2° E

South from N. Mc bet 19 & 20 Var 2° E
1765 over lake to me set Post in lake

Have concluded that it not possible
to find any good monuments on line
bet 18 & 19. 29 & 30 or bet 30 & 31. and will
the line bet 19 & 30 from NW cor to lake
on a course that will conform to G.O.C.
Survey as near as possible

** East from NW cor Var 4° E
250 LEAGUE swamp
5146 to lake and set 1/4 P. Birch 10 N 3/2 W 11
elevation Oak 10 S 53 1/2 W 11 1/2

Found an overrun of 881 my measurement
15546. Cor 18 4265. Proportioned over
run and set 1/8 Post 3407 east of NW cor
and 17.39 west of me

*** SOUTH from W 1/8 P. on N Line Var 235
2010 3/4 SET TEMP 11/16 P

*** 1150 ENTER FLOWAGE
and run west Var 4° E
3422 fell 27 S of 1/8 Post. strayed to 3407
moved temp 11/16 Post west 015 1/2

Corrected both 1/8 Lines onto 1/16 Post
which is Y. Pine 10 N 53 1/2 E 1/40

W 1/8 Sub 16 N 41 1/2 60 1/2
prolonge E & W 1/8 Line & set to lake
to lake & set me over

This sec is to no account as to Survey
34 38 SEC 30. 39-11 Cont'd Jan 9. 1916

Angle at 1/16 Post is angle betⁿ See Line
and N+S Line at 1/8 Post is 88°45'
me on east & W 1/8 Line Birch 10 N 53 1/2 W 29 E
copied on □ □

3 SEC 19-39-11 Jan 11 1916

North from SW Cor Var 3 1/2 E.

1000 LEAVE FLOWAGE

4021 FELL 75 3/4 W of 1/4 P in cent o Road
Correct Var Page 380

East from W 1/4 P. Var 5° W
96 11 FELL 85 S. of 1/4 Post Which I Set by
Proportional measurement. I had set
N ms 3 days ago, found stump of
Aspen tree and had evidence
of Bear et al that he had the trunk
of this Aspen chained to stump and
is now under the ice. made new
bearing [Aspen] 10 S 22 1/2 W 32
found a shortage of 78 and set 1/4 P
83 N of South mc. Birch 10 S 84 W 92

DEC-884 change course 30

went to mc & set 3 days ago bet bet
sec 19.30 and prolonged east 5.53 to 96 E
distance from mc given in U.S. notes
this makes whole distance of line 5.699
county

North from S 1/4 P on ice Var 4°

1900 LEAVE Lake reeow

6437 FELL 27 1/2 W of N 1/4 Post 109 E
bearing, and Post set by Graham ok

DEC 41 change course 2.25

SET CENTER of SEC 10 Post nothing for
bearings Post sets on N side o Road
about 200 East of Swamp

Distance to N 3323 1/4 Post 3323

S 31 1/4 .. " 31 1/4 -

" E .. " 43 77 -

" W .. " 52 34 -

Copied on Page 380

SE 19-39-11-Jan-12" 1916

39

as E & W 1/4 Line has a gout monument ^{1/2}
at both ends, it must be correct but
at center of sec there is a shortage
to S 1/4 P of 886. I have run the range line
from 1/4 P bet 19+34 South to Town corner.
and have Dorrs notes for town line bet
sec 6 & 31. and as this shortage should be
proportioned in the 2 1/2 miles, I moved
my 1/4 P bet 19+30 South 7.08, and set 777 C
on line bet 19+30 on bet 19+30 OS
corrected. It is on a var of 4 1/2

" my first line bet 19+30 from S 1/4 P
to SW cor and set 1/8 P by proportional
measurement bet mc and S.W. COR at
3246. East of SW cor and 100 south of
Random WP line 16 N 11 E 48

No others

North from W 1/8 Post on South Line Var 5° E
4015 FELL 3 LKS E of 1/8 P which I set by
proportional measurement between
center & W 1/4 P 3051 East of W 1/4 P

Fenecc Post S 16 W 58

" S 11 1/2 E 60

Went South & set 1/16 Post W P in 10 N 38 W 17 1/4

EAST from 1/16 Post in SW 1/4 Var 4 1/2 W
24.63 FELL 43 1/4 South of 1/8 P South of center
Corrected, line west & set mc on west
shore of lake 1 Birch 12 S 15 W 12
Cut out random corrected line 2.00 feet
and platted 12 lots 100 feet wide

" One lot 116-5 x 200 feet deep

finished Jan 14 1916

Destroyed monuments on
Survey in SEC 30 in the interior

County record

40 SEC 9-38-6 Feb 1st 1916

WENT TO CENTER WHICH I SET IN MAY 1902
found Post and bearing OK. Run S. Var 5° E
2175 to Lake 5.25 to wagon road
2800 over

4281 FELL 68 East of 1/4 Post. found Post
I SET in May, 1902. found Post and
Stump of org. bearing marks OK.
Corrected Line N and set 1/8 Post at 40 ft
{ W Pine Stp. 10 S 50 E 21

R C R = feb - 2nd 1916 =

WEST from CENTER Var 7.15 E

3986 FELL 32 1/2 North of 1/4 P found both
bearings I made in May 1902
SET NEW POST
WENT E and SET 1/8 P at 1993. and
1671 S of Rand { W Pine Stp. 14 N 26 E 8
8 S 2 W 7

South from W 1/4 Post Var 4° E

3969 East of corner. Set an oak Post from
Stump of both org trees

Went N and set 1/8 Pine Stp 18 S 17 W 37 1/2
1/8 P. at 1984 1/2

East from SW cor Var 4° E

3950 FELL 202 N. of 1/4 P OK
SET 1/8 P at 1975 + 102 S of Rand
OAK. 4.523 W 24

East from 1/8 P South of W 1/4 P 4° 15' E

West from 1/8 P. S of center 4° 15' E

3955 FELL 16 1/2 S of 1/8 Post

South from 1/8 Post WEST of center Var 9.15
2350 to wagon Road

4133 FELL 21 1/2 East of 1/8 Post
WENT north and SET 1/16 in SW 1/4
{ W Pine Stp. 16 WEST 5
20 other

SET a Post 10.00 S. of 1/8 P E. of center and 10.00
South of 1/16 Post in SW 1/4

SEC 23-37-8. May 7th 1916

Began a mc. betw 22 + 23. and run E. Var 2° 15' 30" E
2100, offset N. 250 to N line and run G
on Var 2° 15.6

4088 fell 32. N of 1/4 P. I SET in 1902
SET W 1/8 P on N line { B. Pine 15 N 59 1/2 E 28
copied on page .. . 14 S 55 W 6

South from N 1/4 P. Var 2° 1/4 E. 147

8041 FELL 134 1/2 W. of 1/4 P SET new oak Post in
South edge of road from both org beamys

" on is a burned Stp, none is burned stub

12 ft high marks plain on both trees
made no bearing { B. Pine 15 N 10 1/2 W 55 3/4
as I have run the N. S. & W Lines in 1902
& set new 1/4 Posts on the N and South
Lines also west line. and as the east line
is nearly all River and flowage, and the
last 1/4 P. is gone I concluded to use the N &
1/4 line as a base line and set center mid
way between N and S 1/4 Posts. So I set center at
40 30 1/2 from each 18. Pine 10 N 4 1/2 W 1.41 and
set 1/8 P S of center at 2010' N of S 1/4 P

{ OAK 6 S 60 W 26 1/4

" 8 S 62 E 53 3/4

WEST from center Var 3 1/2 E

1451 to lake and flowage

3100 over .. equal .. Record

4158 fell 19 3/4 S of 1/4 P. on iron pipe even
with surface. { SW cor of Log house

IS N 12 E 44 1/2 distant I set this Post and
marked building in Apr 1902. WILL get
a boat and try and set 1/8 P VV of cent
in a small island in south side of
Lake and flowage

Got a boat and set 1/8 P. W of center
nothing for bearings

N from 1/8 P W. of cent Var 3 1/2 E

1550 over lake, 4069 fell 1.12 W of 1/8 P.

Corrected Lines and SET MG at 1590

{ B. Pine 8 N 83 E 15 | Scaled 4.160 ft across on
No others near | 8 1/2 S 2.68 E CCS

42 SEC 23 continued May 2 1916

East from S 1/4 P Uar 3 1/2 E
2096 fell 5 LKS S of 1/8 P & set in 1902

North from E 1/8 P on S line Uar 3 1/2 E
2010 1/2 SET Line stakes and went to 1/8 P
S of center and run E Uar 3 1/2 E
copied on Page 147 County Record

East from 1/8 P S. of CENT Uar 3 1/2 E
2096 FELL 20 1/4 N. of 1/16 P. Which SET by
using the same distance on E & W 1/8
as on S. See Line, and the same distance
for Nts 1/8 Line as it is from S 1/4 P to 1/8 P
S of center nothing for bearings at
1/16 P. Prolonged N 45 1/8 line in S E 1/4
as corrected. about 12.50 to R. bank
of WISE River and SET me
1/8 Pine Stp 10 S 2 1/2 W 63

SEC 25-38-7 May 8-1916

went to N.E. COR. SET new Post from
Stps of org trees made new bearings
copied on Page 1/8 Pine Stp 16 N 37 1/2 E 34 1/2

W " " 16 S 26 E 12 0

S. from NE COR Uar 40 E 9 8
5476 #3 + 77 = 5553 FELL 42 1/2 W of me. which
I SET from Stps of org trees but
had to SET 41 LKS N of where it belongs
on account of flowage. 5553 + 41 1/2 = 5594 1/2
whole dist to org me. found an over run
of 10 LKS. proportioned same and SET
1/4 Post at 40 07 S. of NE COR. NO BT
SEE N 48 P. on East Line at 2003 1/2
1/8 Pine 12 S 15 W 36 1/2

corrected line N from 1/4 P to NG COR
WEST from NE COR Uar 40 E

42 to me which is 1/4 S. found old Post
856 in 1885 on Line made new bearing
ELM 1/6 S 4 1/2 E 64 1/2 - SET 1/8 P at 213 1/2 LK
1/8 W Pine Stp 24 S 64 1/2 W 78 1/2

County Record

SEC 25-38-7 G cont May 10 1916³

Angle at NE COR from W to S is 90 28
at N 1/8 P. on E Line turned on angle of
90.28' from S to W on run W 2130. Thened
same angle from W. to S. and run 2003 1/2
The East has same angle to 1/4 P
and ~~at~~ at 2136 FELL 8 LKS of 1/4 P
Corrected Line to 20 1/8 P
1/16 P in NE 1/4 1/8 Pine Stp 18 N 48 1/2 W 21
no other Record
1/8 P W of E. 1/4 P. 1/8 Pine Stp 18 N 48 1/2 W 21

SEC 30-38-8 E May 11-1916

Began at NW cor which I set May 8. SEE PAGE

42 SEE 25-38-7. Run East Uar 4 0

57474 FELL 519 1/2 N of COR at end of

Road. I set cor to 19. 20-29. 30 SEVERAL

YEARS ago and my bearings are OK

Corrected Line West to NW cor for

Road for Town of NEWBOLD.

DE C 6.95 change course 4° corrected
from W to E 00 from E to W 1° W

Posted on Page 162

SEC 18-38-8 May 13 1906

Began at W 1/4 Post which I set in
Oct 1908. Post has nothing near for
bearings. Rock piled around it.

Run E Uar 00 - 7500 SET LINE STAKES
and began again at W 1/4 P and run
SOUTH Uar 3 1/2 E. COUNTY RECORD

4012 FELL 2 1/2 LKS EAST of COR. Stps of org trees
came N and set 1/8 P 1/8 Pine Stp 16 N 20 24 E 25 1/2

EAST from S 1/8 P W Line Uar 00
7500 SET LINE STAKE and went to SE COR
found Post I set in 1906 new Uar 14 N 2. W 84 1/2
I found Stps of org trees in 1906
N from S.E. COR Uar 3 1/2 E. on old Rand
7862 FELL 1.23 W of COR & SET in 1906 no bearing
Rock placed around Post. SEE PAGE 44

44 SEC 18-38-8 May 17-1916 cont from page 43

SET N 1/8 P. E Line 1965 1/2 S of NE cor nothing
near for bearings.

SET 1/4 P. E Line at 39.33 W Pin Stp 17 N 89 E 6
Copied on Page 17 " 15 N 70 W 28

SETS 1/8 E LINE 1965 1/2 nothing for bearings

PICKED UP E & W 1/4 Line and at 7521 FELL 530
N. of 1/4 P. Dec. 720 162

PICKED UP South 1/8 Line and at 7511 FELL 281 N
of S. 1/8 P. one line.

S. 1/8 Line is nearly all in lake. I USED the
S. 1/8 Line as a base line and set 1/16 P in SE 1/4
20.00 W of S. 1/8 P on East Line { W Pin 8 N 62 W 26
" " 8 S 42 1/2 E 31

SET 1/8 P.S. of cent 4000 W of S. 1/8 East Line
(y. Pin 10 S 6 E 64 34
no others)

SET 1/16 P in SW 6000 W of S. 1/8 P. on E Line and
3811 E of S. 1/8 P. W Line { W Pin Stp 18 S 50 E 45
no other near

center of SEC Good Post but nothing for B.T.
N from 1/8 Post S. of center Var 3 1/2 E 45°
55.48. FELL 140 W of 1/4 P. which I set on the
evidence of James CLARK found old
Post said to have been set by Dorr
made new bearing { W Pin 8 N 12 E 103
Set 1/8 P. N of cent in wet swamp

County { Tam 8 N 70 E 5°
East from 1/8 P. N of cent Var 3° W
3877 FELL 202 S of 1/8 P. Went W + SET 1/16
Post in NE 1/4. nothing for bearings

South from 1/16 P. in NE 1/4 2 1/2 E.
500 enter swamp 1200 leave swamp. 1350 enter
swamp. 3000 leave swamp R Record

3857 FELL 18 1/2 W of 1/16 P. in SE 1/4
North from 1/16 P. in SW 1/4 Var 3° E

2000 1/4 FELL 23 1/2 E of 1/8 P. W of center
corner lines betw lot 1 on NWNE. also betw SE NE

& SW NE. and NE SE. + NW SE. NESW + NWSW and
bet Lot 2. & NW SW and bet. NW NE & SW NE
finished May. 19 - 1916

5 SURVEY of Road for Town of Harrison

Began at N 1/8 P. E bet 20.21 and run N Var 3° E
as located and road built East + South.

Run North Var 3° E SEE Page 16 This book
JULY 29" 1916. 1916. Began again at cor to
16-17. 20. 21. 35. 8 E and run W. Var 4° E

2800 Enter CREEK bottom

3200 STREAM 20. Run S

3400 LEAVE CREEK bottom

8345 FELL 478 S of cor. found SW BT

Made new lineable 12 S 67 E 28

SET 1/4 P bet 17+20 at 2172 and
239 N. of Rand { HEM 12 N 66 W 9

{ Birch 14 N 81 E 16 1/2

SET E 1/8 P bet 17+20 at 2086 + 119 1/2 N of Rand
{ HEM 12 N 79 W 34 3/4
W Pin Stp 30 S 1/2 W 57 1/2

POST SETS on top of rotten Henry stp

N from E. 1/8 P. bet 17+20

3.50 ENTER WET SWAMP

600 OUT " "

1100 TOP OF HILL 40 FEET ABOVE MARSH

8150 FEET 57 1/2 W of Temp = 1/8 P Which

is 2086 1/2 W. off of cor to 8. 9. 16. 17

in same course as line bet 17+20

corrected to this 1/8 P and prolonged line

in SE 1/4. This whole line is parallel with line

bet = 16 + 17 = JUNE 25-1916 =

North on East Line in SEC 8.

1525 ENTER SWAMP

2500 LEAVE "

3900 ENTER "

4450 LEAVE "

5967 to center of road at 1/8 Post and

corrected through 17 to 1/8 Post and

" Line bet = 17+20 from 1/8 Post

to corner. Commencing again

at a point on line between 17+20 1657

W of corner. Then N 21 1/2 W 125
" North 7.00 over

46 SURVEY of Road for Harrison cont.

SET Thence N 9 1/2 W 316

" N 35 1/2 W 650 to East ^{1/8} Line in sec 17 at
a Point 1600 ft North of 1/8 Post.
MAGNETIC COURSE VAR 00

=====
COMMENCING AGAIN AT COR² TO 16, 17, 20-21
Thence South 11 1/2 R 5^o E 5° C
1972 to COR² of 16-17-21-22. Same line & run
in July 1972.

SEC² 35-35-8 May 27 1916

7.5 WEST from E 1/4 P 6° E.

1.1 3832 FELL 1.20 S of CENTER & SET 3 years ago
came EAST + 20' 1/8 P. HEM 12 N 11 E 59 3/4

RUN SOUTH VAR 3° E

S 3997 FELL 97 W of some ones 1/8 Post
came N + SET TEMP 1/16 P a small HEM
for Post

=====

SEC² 35-35-8 May 28 1916

WENT to South 1/4 P a stone 8x8 inches
Run N VAR 3° 20' E

53 1971 Brooks 1/8 Post on Line.

8845 FELL 8 LKS W of 1/4 P. in road. Set an iron
PIPE 2 inches and placed Rock and
Cinders around it and in it
WEST EAST from W 1/4 Post dry trees VAR 2, 50 E
1500. OFFSET N 20 LKS

East from W 1/4 P (OK) VAR 250 E

7974. FELL 11 1/2 SOUTH of 1/4 P. OK.

WENT W + SET CENTER OF SEC

{ SUGAR 10 S 50 1/2 E 60

}. 10 S 21 1/2 W 37

DIST² to N 1/4 P 4124

" " S " 4021 SET 1/8 P.S of CENTER at

" " E " 4001 20 10 1/2 and 2 LKS of R E

" " W " 3973 nothing for bearings

North from SW COR² VAR 3° E COR² is a stone
4031 1/2 FELL 11 EAST of 1/4 P SEE NEXT PAGE

SEC 35-34-8. Cont'd May 29 1916

SEE S 1/8 Post W LINE. nothing for bearings
WEST from 1/8 P.S. of center VAR 3° 20' E
3996 FELL 53 W of 1/8 Post
CORRECTED. EAST and SET 1/16 Post in SW 1/4 an
old Pump Point for Post. NO bearings.

SET 1/8 P. WEST of CENTER Elm 28 1/2 W 28 3/4
Maple 18 S 50 E 16 1/2

NORTH from 1/16 P. in SW 1/4 VAR 3° G

2021 FELL 1 1/2 LKS W of 1/8 Post. connected line
South to 1/16 P. and SET an iron Pipe at
600 N of 1/16 P. at N.W. COR² of a 3 acre piece
of Land owned by SEVERE CHRISTENSON
SURVEYED a road 50 LKS wide from a point
25 LKS N of 1/16 P. in SW 1/4 running parallel
with 1/8 LINE 5° EAST to Highway

SET 1/8 P. north of CENTER at 60.83. or 2062 S.
of N 1/4 P. Elm 8 N 42 1/2 W 27 1/2

Sugar 12 S 58 E 30 Run West on 1/8

LIN 5,23 to center of Highway. merrill road
Surveyed a road, the center of which is 25 LKS
South of this 1/8 Line, and runs East from Highway
to 1/8 P. ALSO a road beginning at a point
25 LKS EAST of Post in center of SEC running
north PARALLEL with N+S 1/4 Line to a point 25 LKS
EAST of 1/8 P. and connecting with road running
W to Highway. finished at 4 P.M. May 30 1916

SURVEY of road for TOWN of Harrison
117 SEC² 1/4 35-8-E May 31 1916

WENT to M.C. bet² 14+15. Set Post from SW
L.R. which is down + rotten marks OK. made new
bearing { J. Pine 10 S 33 W 9. Run south VAR 3 1/2 E
75.37 FELL 75 W of COR². found an overrun of
4.37 proportioned same and set 1/4 POST
at 4246 N of COR² { cedar 8 N 66 1/2 E 16 1/2

Birch 12 S 4 1/2 W 36

SEE N 1/8 P. W LINE at 6369. { W Pine 12 S 60 E 48

IV of SW 1/4 COR² ---- { SEE S 1/8 P. W^{LINE} 2123 N of COR² no bearings OVER

3 SURVEY of road for town of HARRISON in cont
secⁿ 14. 35.8. commenced May 31-1916 cont
East from N 1/8 Post on W. Line June 1st 1916
UAR 4^oE
81 82 1/2 fell 2.87 1/2 south of 1/8 Post which is set
running S SOUTH from NE corner (W B T A
Stump marks OK) UAR 3^oE
39.90 fell 7 LKS East of 1/4 Post in center of N + S road
THE WEST BIRCH is OK. WENT N + S E 1/8 Post
{ Sugar 18 N 75 E 60
{ Hem 10 S 49 W 58
CORRECTED 1/8 LINE WEST TO 1/8 Post for road for
TOWN of HARRISON. finished at 4 PM Jun 2-1916
SECTION 8-35-11 JUNE 9. 1916 OTHER TREES GONE
BEGAN AT N.W. CORⁿ NE BIRCH is a stp marks OK
RUNS UAR 3.50. intended to run on 4°
31.00 East End of McGinnis Barn
77.50 East + West road. SW cor of SECⁿ is gone
105.63 fell 12.77 West 10 = off P. org trees
found a shortage of 14.37 Chang course 6.56
Set TEMPⁿ corⁿ on true line at 7042 and
8.51 1/3 East of rand course of twilin 10.45
S " made new EW PINE 16 N 56 1/2 W 7
Run WEST UAR 4^oE
= Monday June 12th 1916 =
1000 Did not find 1/4 Post. no tamare near.
74 8000 found where 2 trees had been felled for
corⁿ am sure they were felled by U.S.
Surveyor, bⁿ no iron marks on them. The
original line is marked very plain and
the trees are felled toward it. The gouty
notes call for tamarae trees and the
ones felled are a Birch + sugar, and the
courses and distances do not agree with
the gouty notes & believe this is the orgⁿ
corner, but trees are rotten where iron
marks should be. and concluded
not to use this corner still west on
the same course and line
4031 1/2 FELL 11 East of 1/4 P SEE NEXT PAGE

copied on Page 840 352
 SEC 8 Cont'd JUNE 13-1916

12175 Center of C + NW RR Co. R R track
 16718 fell 729 South of cor on Range Line
 found a shortage of 0.390 proportion
 same and set Temp^o corner to
 7-8-17-18 at 78°40' and 342° N. of Rand
 did not find 1/4 Post b/c E W E 8m 7+18
 Spent nearly 1/2 day looking for it
 Sprung Temp^o SEC cor^o South Line N 84 Lks
 at Right angles with true line betw SE
 cor^o of 8. & SW cor^o of 7. Sprung Temp^o
 SW cor^o of 8 on WEST line as CORRECTED
 betw NW^{cor} of 8 and 1/4 P betw 17+18. East
 81 1/2. and set cor to 7-8-17-18
 S 1/4 P ----- { Sugar 12 N 51 E 153 1/4
 " " " " 8 S 53 1/2 W 153 1/4
 SEC S 1/8 P at 3918 W of SEC cor.
 " SW cor at 78 36 { Sugar 16 N N 38 1/2 W 22
 " " " " 10 S S 53 1/2 W 3
 SEC W 1/4 P. at \$3457 S of NW on true line
 And 811 East of Random Birch 15 N 6 1/2 W 28 1/2
 " " " " 12 S 7 1/2 E 43.
 South from W 1/4 NAY 17° E canvas
 3546 fell 1 2 Lks W of corner
 SEE S 1/8 P W line at 1773 + 1 Lk E of Rand
 record { Birch Stb 16 N 16 1/2 W 14 1/2
 { Maple " 14 S 18 E 28 1/2
 EAST from W 1/4 Post Var. #45'
 8772 fell 1.97. 1/2 N of 1/4 P. Set new from the
 WEST org^o tree ok but is A. Tom"
 instead of SPRCE East FREE going
 DEC^o 2513 change course 17°
 ANGLE OF W 1/4 Post 77.15' ~~20~~
 North from S 1/4 Post Var 10° E SEE Pg.
 7258 fell 9.9 Lks W of 1/4 Post 32°
 DEC^o 1.364 change course 47'
 Set center H E M 15 N 4 E 1.73
 Dist to N 1/4 Post 35.52' No other
 " " S " " 3706 Green timber
 " " E " " 4377 near
 " " W " " 43951

copied on Page 352 county record
50 SEC" 8-35-11 Cont. JUNE 21-1916

SET 1/8 Post S of center at 1853 and
24 1/4 East of Rand { Hem 12 N 35 E 10
Do 12 S 85 1/2 W 23 1/2
East from S 1/8 Post on W Line Var 3° C
41.57 fell 23 N of 1/8 Post. Corrected Line
W to 1/8 Post finished JUNE 21 1916

SEC 17. 35-11 JUNE 21-1916 1 PM
South from NW cor SEC 8-
copied on Var 1.45' W Page 354
36.66 fell. 33 N of org 1/4 Post
SET 1/8 P. abt 1838 1/2 and 16 1/2 E of
Random { Birch 16 N 72 1/2 E 14
count tree { Sugar 18 S 60 1/2 W 23
SET W 1/8 Post on N Line at 1959 E of NW
cor on true Line { Sugar 16 N 62 1/2 W 34 3/4
" " 16 S 35 1/2 W 31 1/2

SEC" 22. 40-14 JULY 10 1916
NE CORNER. SET Post from org trees EAST one
is down marks ok Birch ok runs HAPPEE
The Birch is said to be a sugar. course and
dist to east tree is ok course to birch 110° off
Rust South Var 3/4 1/2 1/2
7266 fell 1/2 East of corner No 1/4 Post

South from N 1/4 P Var 1.45'
7266 fell 1/2 East of 1/4 Post SE tree ok NW
one down & rotten SET new Post (cedar)
DEC" 165 change course 6'

East from N 1/4 Post. Did not have
any field notes. And started by guess
on 4° E 4000 SEC Line stakes.
field not same as SET abt 23 LKS to far N
3997 fell 22 3/4 N of corner. same
W + SET 1/8 Post at 1998 1/2 + 23 S of Rand
{ Sugar 18 N 57 1/2 E 43
" 10 S 42 E 32
CORRECTED LINE W to 1/4 Post

51 SEC 22-40-14 cont JULY 12 1916

NORTH from SW cor Var 3 1/2 E East
4000 have been on line all the way
Did not find 1/4 P and old or old line
7863 fell 3 15 W of cor Set Post from N tree
South one is as per and dist is 16 instead of
66 came S. & set 1/4 Post at 3931 1/2 and
157 1/2 East of Rand " fir 10 N 42 E 40
cedar 10 S 9 W 23 1/2

East from W 1/4 Post Var 5 1/2 E 6.75 to Lake
1501 over lake

7956 fell 4.56 N of 1/4 Post
change course 3° 50' corrected Var 1.46
DEC" 5.73. went W + SET center
center of { Tarn 18 N 72 E 14 1/2
SEC" cedar 7 S 87 W 14 1/2
DIST to N 1/4 POST 3491

" " S .. . 37 65
" " E .. . 39 94
" " N .. . 39 62

omited " south from NE corner Var 3 1/2 E
7198 fell 13 1/4 E of cor Set Post from W B Tuk
and Stp of East which is down & rotten
SET S 1/8 P. 1799 1/2 N of SE cor cedar 12 N 29 E 14 1/2 :
" 1/4 Post abt 3599 HEM 18 S 21 1/2 E 22 1/2
+ 68 1/2 W of Rand HEM 14 N 9 E 15
" 12 S 29 E 14 1/2

*SET N 1/8 Post on east line in open wet swamp
no bearings. SET 1/8 P. S of center abt 1887 1/2 N 87
{ Sugar 14 N 26 E 23 1/2
" 18 N 48 Birch 16 S 9 1/2 W 30 1/2

SET 1/8 P. E of center no bearings
East from 1/8 P. N. of center Var 2.45
3993 fell 28 S of 1/8 P. went W + SET 1/16 Post in
center of NE 1/4 Sugar 8 N 28 E 14 1/2
HEM 18 S 59 W 11.

CORRECTED LINE W to 1/8 P and prolonged line
west 1.00 chains to Lake + SET m.c 75 E of Lake
a balsam tree 5 in dia for Post. East from 1/8 P. NE 1/4
fell 24 W of 1/8 Post CORRECTED LINE South
to 1/16 Post and grant at 4 PM JULY 14 1916

SEC 3-38-7 JULY 26-7-1916

Run the WESTERLY Line of VILLAGE PLAT
located from Rod at SW COR and L-Iron Rod
for 1/16 Post in center of NE 1/4 and made new
bearings for same { W Pine Stp 18 S 1/2 E 39 LKS
 $\{ \text{do } 40 \text{ do } 18 S 88 \frac{3}{4} W 63^{\circ}$

~~W E S T~~ from 1/16 Post in NE 1/4 Var 2.20 E
1986 ft L 15 N of mc set by Dorr.

corrected this Line 5.50 and 850 chain
West of 1/16 Post, and set Line Stake south of
corrected Line for school ground as per
need by Alice Choate.

Think it will be changed as it takes
about 1/2 of STORE building.

JULY 27-1916

SECTION 10 35-13, AUGUST 1st 1916
Began at mc bet " 3+10 one east side
of Stone Lake, found STUMP of Pine and
the Hem- tree org trees, also a HEMI
made by H.J. OTWIG C.E MILWAUKEE
in January 1908 { Hem 14 S. 66 E. 40 LKS = 26.5 feet
Run E var 2106 am using 100 feet tape
179 feet from OTWIGS TOLLE Stake on Line
1383-1 feet fell 4-2 feet South of corner
Did not find any org begin, but

" find OTWIGS, + POST

corrected line west to mc,

south from NE CORNER UGR 400 E,
ANGLE at NE CORN: at present 1591²⁰'
2.00 Enter Swamp

6:00 LEAVE "

2677 SAMES 1/4 POST 25 FEET & AST
3478-6 ft. fell 2 ft East of 1/8 P set by
H.J. OTWIG, & USED IT. post + bearings,
OK { W Birch 12 N 50 E 35-1 ft

W Pine 16 N 25 W 77-6 feet

found an overrun of 18 ft. corrected line
N. and set 1/4 Post at 2652 ft + 1.33/100 ft
W of Rand { Sugar 15 S 63 1/2 E 7 ft
 $\{ \text{do } 12 S 88 1/2 W 33-5 \text{ feet}$

SEC" 10, 35-13 E. AUG 2 1916

ANGLE at NE COR is now 91.17 or 88.43
W from E 1/4 P. on angle 91.17 from S. to W
or 88.43 from N to W.

WEST from EAST 1/4 ANGLE 91° 17.5-88-43-N
++ 676 feet to Lake + set mc. W Pine 28 N 2 1/2 W 4-4
Set N 1/8 Post on E Line G 1/3 26 and 1.33 ft W
of Rand { Sugar 8 N 2 1/2 W 20-3 ft
 $\{ \text{do } 10 S 42 E 25-3.5^{\circ}$

VV WEST from N 1/8 Post East line ANGLE 91-17
867-4 to lake + set mc W Pine 28 N 2 1/2 W 4-4
WEST ++ East 1/4 P WEST ANGLE 91-17 S. to W
+ 676 to lake + set mc { Y Pine 1/4 N 58 E 2-2 ft
 $\{ \text{do } 20 S 32 E 5-5^{\circ}$

went me on N line on W side of Lak org Pine
down. W Pine Stp 36 N 54 E 17-8 NEW

Run WEST on OTWIGS Line UGR 326 E
1412 FELL 4 ft S. CORRECTED LINE EAST

Run South on OTWIGS LINE FROM N LINE
87° and magnetic course is 630 E
Started on this course on OLD BLAZES.
200 LEAVES SWAMP and ENTER SLASHING
1800 " SLASHING

2586 FELL 319 East of 1/4 P. found marks on the
Birch and the marks on sugar were
lying on top of decayed stub. Someone
had set new post + made new bearing.
The Post is a little to far east. I used it
DEC 1. 133. Change course 7° 4
CORRECTED onto 1/4 P and prolonged
line south. my ANGLE at N.W. CORN is now
94.04. changed course 7° 4 and run south

needle reads 15' W var .

1118 OFFSET W 1 foot to miss large pine

1412 STREAM 20 ft WIDE RUN SW OUT LGD of
STONE LAKE

2613 FELL 69 W of Post cor to 9-10-15-16
ORG TREES. WENT N and SET 1/8 Post at
1306-5. and 34-5 East of Random

② 1/8 P. should be { Birch 15 N 46 E 23
1200 E 5/10 W { CEDAR 10 S 47 W 21-7

54 SEC 10-35-13 continued

N 1/8 Post on west at 12.93 + 159 1/2 W of R

Went east mc on S Line W side of lake
found remains of org trees. Post & bearings
by obw19

Run west on his corrected line Var 4° E
1040-2 1/10 fell 4 1/10 south of his 1/8 P
Correct Var 3.37. The course of N Line
on W side of lake is 3° 15'

COURSE 1/4 Line from W 1/4 P is 33°
" N 1/8 " " W to East 3° 16'
" S 1/8 " " " 3° 40'
= Sept 4" 1916 =

South from S 1/8 P on East Line Var 4° E
165 stream 15 ft runs SW
260 leave swamp
531 fell 2 ft E of m.c. org B.T. set iron mon"

55 SEC 33-36-4 E AUGUST 21-1916

WENT TO SW COR. ON IRON 2x2 INCH IN ROAD
RUN N VAR 2° F POSTED ON PAGE 3

200 STREAM 20 RUNS EAST

1200 LEAVE CREEK BOTTOM COUNTY RECORD

1225 CENTER 500 RR

3969 FELL 50 EAST OF 1/4 POST

CORRECTED LINE SOUTH AND SET

1/8 POST W. PINC STEP 20 S 73 1/2 W 67 1/2

" " " 20 S 12 1/2 E 65 1/2
COMMENCING AT A STAKE WHICH STANDS ON
SOUTH LINE EQUI DISTANT BET' SW COR. AND
W 1/8 POST THENCE N. PARALLEL WITH WEST LINE
1607 INTERSECT SOUTH LINE OF RIGHT OF WAY OF

500 RR COPIED ON PAGE 3 COUNTY

1984 SET TEMP = 1/16 POST. RECORD

THEN WEST ON OR NEAR 1/8 LINE

1989 TO 1/8 POST THENCE N ON SEC LINE TO
TO W 1/4 POST FOR ROAD FOR THE TOWN
OF LYNN.

SEC 31-36-4 E AUG 22-1916

WENT TO S 1/4 POST, IN CENT OF ROAD AND
RUN N VAR 5° 05' E

3970 TO CENTER OF E & W ROAD ON E & W 1/4 LINE
8026 FELL 15 EAST 1/4 POST

FOUND STUB OF ORIGINAL BIRCH B.T.

THE HEMLOCK IS LYING DOWN MARKS ON
BOTH BK. SET NEW POST AND MADE NEW
BEARINGS; SUGAR 8 N 78 1/2 W 35
ASKEN 7 S 76 E 40

CORRECTED LINE SOUTH TO E & W ROAD FOR ROAD
FOR TOWN OF LYNN.

RUN A LINE N FROM N 1/4 POST INTO SEC 30
2000 FT ROAD VAR = 5° E.

Posted on Page 3 column 1 in
Red ink county record

56 SEC = 16-35-13 Oct 3" 1916

N 1/4 Post. Set new Post from org. trees ok
Run South Var 3 1/2 E East

10.00 Log road. SW. NE.

1300 Stream course west of SW

83800 LEAVE SWAMP

7938 FELL 296 1/2 East of 1/4 N tree ok
South one down set new Post
Dec = 3.7345 change course 2° 8'
corrected Var 1.22

W 1/4 Post. NEW Post. org. trees. Cedar ok
Hem. dead, and stands N 69° E. instead
of S 69° E. Distance is 2 Links.

Long bet= trees. org Post standing
Run East Var 3° E

1500 to Logging road bears N E & SW

4200 LEAVE SWAMP

7700 ~~FELL~~ 113.5 of 1/4 Post
Corrected Var 3° 45' E.

WENT W AND SET CENTER

{ Cedar stp 10 N 22 E 4

{ 14 S 67 W 23 1/2

Dist to N 1/4 R 4002

.. E .. 3849

.. S .. 3936

.. W .. 3851

E 1/4 P org. trees both dead set new Post
and runs Var 50' E on org. line

3941 fell 218 W of corner, found NW stp
of org. tree. Also new bearings made
made by otwig in 1908. 72 1/2 E

S 1/8 P on E Line { Hem 8 N 72 1/2 E 14

Birch 14 S - 16 - W - 16

1/8 P. of center } { Sugar 12 N 20 1/2 W 19

1/8 P. S of center } { Birch 18 S 31 1/2 E 21

1/8 P. } { Birch 7 N 17 1/2 E 18

1/8 Post East of Center } { Cedar 9 S 49 1/2 W 11

W GSE from 1/8 P. on East Line Var 3° 45' E

3924 fell 6.5 of 1/8 Post. Set temp = 1/16 P. in NE 1/4

North from Temp 1/16 Post in NE 1/4 Var 2° 10' E

1973 fell 16 W E East of 1/8 Post. South of center

57 SEC = 13. 36-13. E Oct 10" 1916

East 1/4 P. - South tree ok N ongoing made
new bearing 15.4441-12.20-E 23

Run N Var 4° E

1468 offset east 3 links to miss large pine tree
1600 enter swamp.

2773 stream 20 runs E. trout stream

3952 fell 57 1/2 W of corner the sugar which
stands S 85 E is down marks ok
other all gone made new bearing

{ Cedar 8 S. 84 W

S 1/8 P on E Line { Cedar 16 N 42 1/2 E 38
{ No other ---

NE cor. Run W Var 3 1/2 E

4038 fell 195 S of 1/4 Post found cedar

Q stp 8 feet high marks ok hem 90'

844 P N 1/4 Post NEW { cedar 12 N 85 W 8. 1/2

E 1/8 P N Line { fir 8 N 52 W 22
Hem 12 S 51 E 17

Run P.C Line S from E 1/8 P. N Line

" " " " W " S " " " E "

+ AET stp at intersection.

not much timber on either line

all poor swamp but 400 chain's

SURVEY OF ROAD FOR THE TOWN

of Tomahawk Lake Oct 24 1916

Commencing at the West 1/8 Post on the
North Line of SEC 8 - T. 38 N. R 7 E
Thence S 86 W 404 Var 4° E

"	N	88 1/2 "	57.0
"	"	66 "	317
"	"	62 "	675
"	"	64 "	1003
"	"	59 "	1088
"	"	82 "	190
"	S	42 3/4 "	601
"	"	21 1/2 "	499
"	"	11 "	1110
"	"	1/2 E	2028
"	copied and page 394	12 "	1348
"	"	4 "	297
"	"	24 1/2 W	531
"	"	5 "	389
"	"	14 1/2 E	353
"	"	36 1/2 "	299
"	"	48 "	765
"	"	46 2/3 "	753
"	"	15 "	340
"	"	12 3/4 W	281
"	"	30 W	625
"	"	5 1/2 "	377 or 181 on this
comes across line betw.		72 1/8	1100 W of corner
Thence S	10 1/2 E	462	
"	"	13 1/2 W	397
"	"	23 1/2 W	751
"	"	20 "	240
"	"	1/2 E	348 to center of

Hazelhurst & McNaughton road.
made bearing for Point of intersection
W. Pine St 24S 85 1/4 E 55

SEC 15-39.R. 6 DEC 5-1916

Began at E.M.C. on N Line, found org tree
which is at am 8th. marks ok. found post set
Dort in 1906. Run W. Var 3 1/2 E.
8 fells 14 1/2 N. of me, found 3rd of y pine
which is NW 288. went East and S 6 E 1/8 P
found a shortage 6 1/2 Lks. proportioned same
and set 1/8 P at 1092 E of W.M.C. and 836 W
of E.M.C. Post sets in flowage nothing
for bearings.

Offset on page 67

South from E 1/8 P. on N Line Var 3 1/2 E
830 Leav. flowage

1025 Road

2715 of SEC E 3 Lks to miss building

3450 offset W to Line. am 50 Lks from lake

5000 over lake to C. N. and S. P. R. 2 ft N of W rail
flowage

6000 Entry open marsh

8000 set line stakes. and went to E.M.C. on S
Line org tree gone am iron mon. set
under instructions of B. F. Dort. used it
and run W. Var 2 1/2 W.

7000 Enter open marsh.

1015 Road - 2975 c.m. + S.E.P. RR track

3045 1/4 P on line. found another run of 1 Lks

3145 SEC E 1/8 P on S Line at 1144 1/2 N of E

M.C. and 20.00 1/2 E of S. 1/4 Post

{ Y pine 15N 5 1/2 W 198

{ W " 12 S 198 50 3/4 E 1,44

Picked up my Rand's for E 1/8 Line and at
7999 fell 283 W. of 1/8 P.DEC change course
CORRECTED line at 50 + 80 line stakes
on each side of RR track.at 33.16 set M.C. on short Kewausego Lake
(33.16) { Y pine 1/4 N 40' W 67CORRECTED LINE TO FLOWAGE AT
South of E 1/8 P on N Line.
corner around

SEC 15 39-6 cont'd Dec 7 1916

Commencing The East Line as a base line. dis Thg East Line is nearly all in LAKE, also both ~~sec~~ NE and SE corners. SEC 11/16 Post in center of NE 1/4. { Y.Pine 12 S 47W 28. Set mc on a whte E 1/8 Line Leaves flowage 8.92 south of E 1/8 P. on N Line { Y. Pine 12 S 47W 38

and began meander of flowage
 S. 62° E. 200 copied on page 67
 N 54° E 200 small bay extends SE 400
 N 43° E 500 and is 1.50 wide
 N 80° E 700 along flowage
 N 21° E 400
 N 63° 1/2 E 400 along shore of LAKE
 S 33° E 200 " " " to N mc
 on E Line

commencing again at 2nd mc on E Line South of NE corner
 Then S 57 W 10.00
 " S 20 E 100
 " S 5 - E 200 to a chicken house
 " S 22 E 370 " Right of way of the
 C.M. & St. P. R.R. at shore of LAKE

LAKE Extends 375 eh. South of S mc on E 1/8 Line. It is 5.25 eh from this mc E to Right of way of C.M. & St. P. R.R.

Commencing at iron pipe which stands on E 1/8 Line 4.21 eh N of mc E (an iron pipe). Then on an angle of 84° from South to N " " " " 114.15 from Line behind me. Then on angle 75° fr back Line dist on first angle 2.48 eh #163-63

" " 2 1/2 " 340 224.40
 " " 3 1/2 " 2.63 to Right of way of the
 C.M. & St. P. R.R.
 county record

SEC 2-36-8 E. Jan 5 1916

NW COR set an iron pipe 2x 48 inches the top of which is striped with red & white mc on N side of LAKE on W Line set same kind of monument as above. M.C. O.S. side of LAKE on W Line set same kind of monument

SW CORNER same. kind of monument
 Bearings. Var 4° East

NW COR { W. Pine Stump 16 N 48 E 73

" " " 16. S 41 1/2 W 65

mc S. of NW COR { Tam: 8 N 85 W 47 3/4
 Survey 8 N 11 E 44 1/2
 orig Pine Stump

mc. N of SW COR { W. Pine Stump 26 N 84 W 107
 W. Pine Stump 12 N 35 1/2 W 95

SW COR " " " 18 S 68 E 38

mc E. of NW. " orig trees ok

DIST from NW to SW CORNER 91.92

"	"	"	NE	
"	"	SW	SE	9819
"	"	NE	SE	
"	"	SE	COR TO E 1/4 P	3901
"	"	S	"	5023
"	"	SW	"	4690
"	"	"	W	4781

S 1/4 Post W Pine Stump 10 N 82 W 41

" " " " 10 N 77 E 38 Vaughan

E 1/4 Post " " " 14 S 49 1/2 E 16 1/2 Dorr

mc W of SE cor orig = tree. now sap

Copied on page 115 County record

Bearings for S 1/4 Post W Pine Stp 10 N 82 W 41
 new bearing " E " " " " " 10 N 77 E 38

" " " " " W Pine Stp 12 N 46 E 30

SEE PAGE 69. This book.

62 SEC 16. 39-11 Jan 24 1916

NW COR found Cedar ok, also post set by
some local surveyor. OK. RUN VAR 3.30 E
1852 FELL 2 LKS S. of 1/8 P SET BY SOME ONE
UNKNOWN TO ME Post and BTR WELL marked
CORRECTED LINE W. TO CORNER
NW COR = S. Var = 3.30 East, at R.T. angles with
N. Line. Copied on Paper 379
3969 fell 7 1/2 W of 1/4 P. found
Stp of Pine Spruce is down found good Post
OK. SET N 1/8 P on W Line Cedar 6 N 1/2 W 16 1/4
County record Spru: 7 S 79 W 34
CORRECTED LINE N to CORNER
E. from this 1/8 P. PARALLEL WITH N. Line
1852 SET Cmp 1/16 P and Run N.
197 1/2 FELL 31 E of 1/8. MOVED 1/16 P.S. 9 LKS
and corrected line from " " N. and W.
-- to 1/8 Posts
Finished Jan 25 - 1916

SEC 10-39-6 E. January 30 1916
Went to S 1/8 P on Line bet 10 & 11 found an
iron pin and bearing oak 10 N 82 E 15 feet
This post was set by M. E. MONSELL 20 years ago.
Run N 47° 15' E 127.5 FEET to a cedar post
new bearings 3. Pine 8 N 6 W 9 feet Paper
Copied on WPine 8 S 48 1/2 E 7-3 FEET 62
Thence S. 43° E 266 feet an drove a pump
Point. Thence S 43 E 4 feet to shore of lake.
Thence northeasterly along shore of lake to
a point 75 feet measured at right angles
to to line S 43° E Thence N 43 E 19 feet and
drove a pump point made bearing oak 12 N 79 1/2 E 32 feet Thence N 43° W 321 feet to a cedar
post made bearing 3. Pine 14 S 80 15' E 7-5 feet.
Thence S 47 45' E 75 feet to place of
beginning

County record

Sec 27-4 2-7 Feb 16 1916

S 1/4 P. found NW tree O.K. SE on gon. SEC pos
and run N. Var = 4° E.
2.00 to Whitesand Lake
14.00 over
2.300 to
4.2.00 over
● ● 80.77 fell 272 W of N 1/4 P. found N.E. tree
xx dead marks OK S.E. one gone SET Post and
made new bearings W. Pine Stp 24 S 1 W 51 1/2 J " 24 S 8 W 31 1/2
000 DEC 3.363 Change course 1° 56' = Var 2° 4'
WEST from N 1/4 P. Var 4°
4086 fell 80 S. of cor: found org trees
are gone but had been restored
by new bearings made by me 10
years ago old WPine Stp 30 N 4 1/2 W 22 1/2
new ... stp 30 S 67 1/2 E 68
** found I had made a mistake in setting
N 1/4 P. Had use S.E. tree for the N.E. tree.
Changed it as I found Stp of N.E. tree.
● ● 8101 fell 2.64 W of N 1/4 P as corrected
000 DEC 326. Change course 1.5°.
South from N.W. COR = Var 3° E
4020 fell 2.5 E of W 1/4. found Post
set many years ago WELL marked.
org trees gone found roots only
W 1/4 P. East
11.00 enter swamp
18.00 to lake
31.00 over ..
38.00 to lake
40.00 SET Line stakes and went to N.M.C. on E
Line found d.W. Pine tree & Stp marks OK
ALSO Post which is OK. SET FLAK at post
and went to M.C. on S. side of lake betw
34435 found post & W ERGOK with
instrument at S. M.C. chained N on Line
6205. over lake to M.C. Found an overrun
of 1.05 proportioned overrun and
SET 1/4 P. at 4150 + 70 = 4220 f

84 SEC 27-42-7 E Cont Feb 19-1917

mc bet 34 & 35. and 4070 N of S.E. COR in Lake
Picked up E + W 1/4 Line random and at
8110. fell 3.66 N of E 1/4 P. on ice.
Dec 4.51 change course 235
SET center { Y. Pine 10N 68W 281
W " 75 84 W 324
SET 1/8 P. N of cent { WPine 12S 41 1/4 E 73 1/2

SET 1/8 PW of center on ice no bearings near
" 1/8 W 1/8 P. on N Line did not set if

SET N 1/8 P. on W Line Nothing for bearings
{ W Pine Stp 24 N 54 1/2 W 3 1/4
MC N of cent " " 10 N 55 E 29
MC W " " { Y Pine 12 N 30 1/2 E 74
W " 75 20 W 25

This mc. is 3.09 W. of center
mc N of cent. is 4.24 N of center

N. from 1/8 P. W. of center Var 24'
3.850 fell 28W of 1/8 P. Corrected
Line south to lake and set mc 6.10
N of 1/8 P.

[Spru = 6 N 33 1/2 W 26 1/2
5 N 3 E 23 1/2]

SURVEYED A PIECE OF LAND IN L03
AT THE EXTREME ~~E~~ SOUTH END OF SECTION
LOT #3 AS FOLLOWS TO WIT
COMMENCING ON EAST SHORE 1720 CH
N. OF SOUTH 1/4 P. AND 50 LKS E OF N + S 1/4
LINE. THENCE WEST PARALLEL E + W 1/4
" 634 CH TO LAKE ON W SHORE OF L03
THEN SOUTHEASTERLY, EASTERLY AND
NORTH EASTERLY TO STAKE AND THE
PLACE OF BEGINNING. CONTAINING TW
~~ACRES~~ ACRES MORE OR LESS.
FINISHED ON 27-42-7 IN A REGULAR
BLIZZARD. SNOW SHOE 4 1/2 MILE TO BOULDER
TUE CAM TO MINOCQUA AT 5.15 PM

Sec 10-36-10 E March 5-6-1917 65

SW COR found post SET by Dorr. ALSO
ORG. TREES. THEY ARE BOTH DEAD AND THE
MARKS ARE NEARLY BURNED OFF.
NOTHING GREEN FOR NEW BEARINGS
RUN USR 175'E

2/17 found Dorrs' 1/8 P. 20 E. of LINE
4234 FELL 41 W of 1/4 P. found Dorrs post
and Stp of WEST org tree. The East
is a stub marks nearly gone
North from W 1/4 P. USR = 1.75'

4032. FELL 49 3/4 W of NW COR found
POST & SET in Sept 1906. STUMPS OF
ORG. TREES OK. CORRECTED LINE S
AND SET 1/8 P. { SPRUCE N 30W 7.34
found ALLENS bearing Post gone
county record

66 SEC 14-42-5 APRIL 26 - 1918

Began at W. mc on S. line found one
ORG tree down marks OK. other tree
gone. NEW B. OAK 12 N 65 W 76 3/4. SEC
Flag on E side of lake which set
from evidence of CAL Doris and
other information which was satisfactory.
E. from W on tree distance 37 00 ft to org
mc. found an overrun of 155 set S 1/4 P or
16 S. 5.87 E. of W. mc. And run N. UCA 4° E
334 LCAUE LAKE.

1.235 wagon road

156 1568 to lake

2000 ft over.


5600 to lake

6045 over "

7150 to "

8000 set line & stakes and began search
for m. corners. did not find. April 17
Looked 4 hours for m. corners and the.
NW. cor. did not find them went to
center set by Lynn Vaughan in
May 1916. He had run E & W 1/4 line from
E to west lug set to E and his center is 4000
E of W 1/4 post. & then correct my N 45
1/4 line on to his center and 37.87 fell 4.006
W. prolonged my corrected line N.
5612 intersect lake and set mc. no bearings
center. { aspen 5. N 83 E 19 1/2' dist to S 1/4 P 37.87
5. S 20 E 29 1/2' " W .. 4040

CORRECTED LINE FROM CENTER S. TO LAKE 1787
Layed out from E & W 1/4 150 FEET E. S. TO LAKE
and parallel with N & S 1/4
1493. and set mc. 150 FEET E OF NTS 142 mds
from point on E & W 1/4 line 150 feet E of center
turned an angle of 165° from the west to
S.E. 1075 to a stake on shore of lake.



Sec 23-42-5 April 18 - 1917

South from E 1/4 P found Post & SEC m
1903. one org ok but dead. Run S on old line
UCA 4° 3 1/2 W

1350 flowage line (lake is low)

1501 River

2795 over river

3829 FELL 4.29 W of S E cor. found Stps of org trees
maple all gone but low stp pine has marks.
Set post and made new B. W Pine 3 1/2 N 79 W 68
Dec. 11. 40 change course 6. 6. 6.

1/8 P is in RIVER CORRECTED LINE N from River
at. 1501 south of E. 1/4 P. turned a right angle
and. run west

1020 to river and flowage

1804 over "

2000 turned and. RE A. south and run to 419 to
Lake + SEC mc. on west line of lot 4 SW CORNER OF LOT 4. W. Pine 3 1/2 north 64 1/2
north on W line of lot 4 from mc which

is 80 LKS N. of SW of lot 4 in lake

1800 from SW cor" or 1720 from mc
intersect lake + set mc } Hem 85 58 W. 40
} 85 2 1/2 E 56

CROSS SEC Lot 4 on east side of lake
set mc. on E line on flowage south of 1/4 P

var 4° E W Pine 6 N 16 E 41

" " 8 N 38 1/2 W 66 1/2

W from E 1/4 P. var 4° E W Pine 85 61 E 9
444. to flowage & set mc. " 8 N 84 E 11

7 + 8

68 SECTIONS 25+30 - 39-8 and 9 May 15. 1917

Began at N 1/8 P. found Post and B.T.S. 8 made
in 1901. which are { W. Pine 10 N 6 1/2 W 12 1/2
} " " 18 S 66 1/2 E 207.

my old notes read South from NE cor of 25
Var 8° E. 50 enters swamp

200 LEAVE SWAMP COPIED on Page 107

1790 Gilmore CREEK runs S.E.

2130 Same stream " S.W.

2550 " " S.E.

2950 LEAVE CREEK bottom and ascend steep hill

2009 FELL 14 W OF 1/4 OLD bearings nearly gone
SET Post 6x6 nothing for bearings

Today 8 runs south from 1/8 as above stated

2004 FELL 15 W of 1/4 P. found my old Post burned
off. SET NEW Post and cont'd S on CORRECTED LINE

625 Enter swamp

1100 bend in same stream. (Gilmore creek)

1250 OVER bend in "

1500 LEAVE SWAMP

3929 FELL 1/3 E of me. on WIS RIVER

SET an oak Post from Stps of orig. trees
oak is all gone but roots. small oak grown
around it. The pine had fallen down and
has been cut off 6 feet from roots. some
MARKS LEFT. MADE NEW bearings
Var 8° E --- { W. Pine Stp 20. N 25 E 120 1/2
} 7. " 8 N 5 E 53

SET post on CORRECTED LINE in CENTER of Wagon
Road 2774 South of 1/4 P. { J. Pine Stp 12 N 85 W 37

} " " 14 S 41 E 52

The Post is small pine root driven even with
surface county record

Copied on Page 115.

SEC 2-36-8.E. May 15 1917 69

NE COR. SET iron monument where
Org. Post is covered by fill of new
State road. It is 33 FEET SOUTH and 33
FEET E of fence post standing in NESE
COR. of SEC 35-37-8 and is the second
Homer McLaughlin's field at this date.
HAVE ALSO SET iron monument at SE
COR of this section and run N Var 7.30 E
3880 FEET 24 E of 1/4 P. on iron monument
SEE Page 61. This book county

4593 FELL 28 1/4 E of me. SET iron mon.
found Stp of org. tree.

North from this me. Var 830 E

4855 FELL 144 1.47 E of NE COR.
CORRECTED LINE South to me. and the
South to SCHOOL HOUSE. Record

SEE DORR'S NOTES FOR THIS SECTION

— copied on Page — — —
SEC 136-8.E. May 18-1917

Began at E 1/8 P. on N Line which is set
last summer. No Bearings. Post is in road
near N. Wagon track Run west Var 2 1/2 E
18 1/6 FEET 1/4 P on Line 607 ft W of 1/8 P.
SET STAKE on S Line of Highway.

409. # ft E. of 1/4 P. SET STAKE for E. Line of a
50 FEET STREET which runs S. 10 1/2 E. angle

From N Line. Taken from East to South 1030
is 7930'. Run south on E Line of Street .. .
301 ft. and SET STAKE Then 209 + SET STAKE

Then 209. ft. Then 37.35 E
4.62-7 FEET STREET - The STAKE for the

2nd measurement along S. side of street
which is .510 ft from S. Line of Highway. Run

E parallel with N Line 207 feet and
so this lot is 209 ft on W Line, 207 ft

on South end. 292 ft south of Highway
and is 5 feet wide on E Line

S. from N 1/4 P var 6 1/2 E 4904 1/20 49 W of Dorr
center found an OVER RUN of 521.8 ft 1/8 P
N of center at 2663. S of 1/4 P contains

70 SEC 1.36-8 Cont May 19 1917

WENT to N 1/8 P on E Line set by Dorr
 SET flag at 1/8 P. N. of cent " and at the
 N 1/8 P. on E Line placed instrument on line
 between flags. And SET a line of stakes to
 the intersection of NTS 1/8 Line in NE 1/4
 and SET 1/16 P. in center of NE 1/4
 County 3 W. Pime 8 N 80 1/2 W 58
 Record Spruce 5 N 85 E 57.
 1/8 P. of center W. Pime Stump 28 S. 35 1/2 E 29.

= SEC 1-39-9 May 22 1917 =
 To locate SW which is gone & found
 where orig. Lin intersects South
 side of Lake and where it leaves
 " SET MEETINGS.
 S. m. Pime 18 N 56 W 27 1/2 copied on page
 W " 10 N 63 E 25 48 29
 " W Pime 20 S 79 W 79 county record

SET S.W. COR 539 S. OF S. MC 20 ~~1/4~~
 W Pime 8 S 70 E 38
 R. oak 7 S 30 E 45 1/2

KUR East Var 19° E
 7.9 FELL 3.35 ft of m.c. found
 on. overrun of 5.46 prolonged
 same and SETS 1/4 Post at 4350 E of
 S.W. COR. W Pime Stub 18 N 11 W 87 1/2
 " " " NO. 05th 611154
 SET 1/8 P. on S Line. at 21.75. E 0 SW COR
 W Pime Stump 20 N 60 E 13
 " " " 24 S 13 E 11 1/2

Made NEW bearing me on S Line
 on. W. Shore of Lake ^{of breed note}
 Tom 14 S 27 E 11
 W Pime 18 N 4 L W 27 1/2

North from me on N Shore of Lake WEST
 Lin Var 3 1/2 E This me is said to be 939 N of
 SW COR but is 1206 dist. over lake bet.
 means is at fault. my me on south

copied on Page 291

71

SIDE OF LAKE 15.39 LKS. SOUTH OF LAKE
 SHORE. Did not find W 1/4 P or NW COR
 BEGAN CHAINING AT N 777 C. WHICH 1206
 N OF SW COR

WENT N 1/4 P WHICH HAD BEEN SET BY ALLEN
 EQUIDISTANT BET' NE AND NW CORNERS
 WHEN THEY WERE BOTH OK. SO I PROLONGED
 LINE W FROM N 1/4 P. VAN 250 E 4217. SAME
 DIST. IT IS FR. NE COR TO N 1/4 AND SET NW COR
 W Pime Stub 28 N 25 1/2 W 28 1/4

Stub 40 S 27 E 26

PICKED WEST END AND 8012 FELL 222 E OF NW CORNER
 SET N 1/8 P ON W LINE. nothing FOR bearings

" W 1/4 Post W Pime Stub 18.31 1/2 W 33 1/2
 " " " 165 66. W 76

" S 1/8 P ON W LINE nothing FOR
 BEARINGS

E. From W 1/4 P Var 5° E
 911 to Bay of Lake County record

1600 OVER " "
 8186 FELL 797 N. of 1/4 Post 2.867 m.mg 1909

North from S 1/4 P Var 4° E
 6700 FELL 2.89 E. OF N 1/4 P. WENT S. AND SET
 CENTER OF SEC 1. Y. Pime Stub 18 S 73 E 14

" " " Stump 18 S 84 W 19

DIST. TO N 1/4 Post 3973: DIST. TO E 1/4 POST 39.96

" " " S " 2727: " " W " " 41.90

SET 1/8 P. W. OF CENT. W Pime 18 S. 85 W 57

" " " 14 S. 71 E 73

N. from 1/8 P. W. OF CENTER VAR 5° E
 1750 ENTER SWAMP

2250 OVER " OF breed note
 4060 FELL 33. E. OF 1/8 P. W Pime 20 S. 26 1/2 E 23 1/2

South From 1/8 P. W. OF CENTER VAR 5° E
 3255. FELL 73 W. OF 1/8 P. SET 1/16 P. IN SW 1/4

Birch 8 N 15 1/2 W 50

W Pime 10 S 02 E 36

W. From 1/16 P. IN SW 1/4 Var 7 1/2 E
 2098 FELL 112 N. OF 1/8 P. OVER

72 SEC 9-42-5-E JUNE 2 1917

WENT to S.E. COR^Y found Post and bearing
made in 1901 found org^Y bearings at that
time. SET FLAG at post and went S 1/4 P and
SET FLAG, and placed instrument on LINE
bet^Y Flags 2.52 EAST OF 1/4 P in flowage.
40.00 WEST OF 1/4 P. (began chaining at 1/4 P.) VAR 2%
did not find ~~the~~ corner.

87.00 could not find mc. on W. Shore of Lake
OFFSET South 4.97 to shore of Lake

98.50 to open swamp with small lake incense
11540 OVER SWAMP AND LAKE.

i2045 FELL 26+^{1/2} = 523' CORNER. OK found St^Y of
orig^Y tree^Y which stands S 84 E 48. SET new post
and made new bearing SPRUCE 7 N 51 W 90
found an overrun of 15 LKS proportioned overrun and
SET TEMP^Y COR^Y on corrected line 4005 WEST OF
S. 1/4 Post. 162 1/2 SOUTH OF Random change course 229
corrected 7.29. DEC^Y for correction 4.04.

Sprung Temp Cor^Y on E-W Rand^Y South 32 LKS

" " " " N+S " EAST 42 ..
And set post cor^Y to 8.9.16.17 W Pine St^Y 14 1/2 88 1/2 E 33 1/2
" " " 165 65 1/2 W 27 1/2

NOTES now read South from NW COR VAR 15' EAST
7700. FELL 308 1.94 W OF COR^Y

COURSE OF N+S Line is 2° E. COURSE OF W LINE IS 43° E
ANGLE OF SW. COR from E to N is 88 1/2.

SET W 1/4 Post at 38.50 S of NW COR. and 118 1/2 E
of Random. J. Pine 10 N 8° E 69 1/2
OK. 8 S 61 W 10 1/2

SET S. 1/8 P on W. Line at 1975 S. of 1/4 Post and 179 1/2
E. of Random.

SET mc. AT S. OF NW COR and 68 E of Rand^Y
2207 S of NW COR and prolonged corrected line N
to shore of Lake and set mc. Did not see it
EAST from W 1/4 P.

on angle of 88 1/2 or VAR^Y of 43° E. parallel with
26.65 1/2 offset N 69 E to miss building S. Line
32.26 1/2 Shore of Lake and set mc. W P STP 30512 E 181

SET FLAG at NW COR^Y which is ok.

" instrument. South Shore of Lake. Found it
2207 across lake to instrument
3799 Found a post said to be the W 1/4, but no
evidence to sustain it.

~~87402~~ COULD NOT FIND S.W. COR^Y AM 252 WEST
END OF E. 8000 CHAINS STAKE ON LINE COMING
WEST FROM SOUTH 1/4 P. STILL S ON SAME COURSE
VAR 15 E.

12030 FELL 333 W. OF 1/4 P bet 16+17. found W. Pine
ORG tree. This tree is down has fallen N.E.
TAM^Y is gone. SET new post and made new
bearing W Pine Stump 30. S. 70 W 58 1/2
found an overrun of 30 KKS.
DEC^Y 277. Change course 135 CORRECTED
VAR 150. PROPORTIONED OVERRUN and SET TEMP.
COR^Y at 8020 S. OF NW COR^Y and 1010 N OF 1/4 P.
BET: 16+17. and 222. E. OF Random.

EAST from S. 1/8 P on W. Line VAR 43° E and parallel
with S. Line 20.00 SET 1/8 P NO BT 2050 Flowage
4784 over Flowage. 5215 to Lake + set mc. W P STP 30 N 12 E 181
EAST from W 1/4 P. VAR 43° E

2665 to Log house offset N 69
3226 1/2 to Lake and set mc. W Pine St^Y 30 N 12 E 181
SET W 1/8 Post on S Line. Pine 16 N 4 1/2 W 70 1/2
North from W 1/8 P. on S. Line Parallel with
N+S SEC Line, or South Line of SEC. VAR 1 1/2 E
20.06 FELL 28 W OF 1/8 P. X 2002 1/2 E

Sec 25. 38-8 J 15" 1917

Began at N 1/8 Post on W. Line Which
set several years ago. Post sets in open
swamp 450 ft. of bay of Spider or Curran Lake.
Run E Var 45° E
150 to lake copied on Page 166
2145 over lake
84.80 fell 326 N. in 1914 or 15. an iron Pin 1/2 x 14 in
corrected line W. Lake for road for the
Town of Newbold.

= JUN 16-1917 =

Survey of Road for town of Newbold
commencing at a point at the end of
Road in Sec 26-38-8. on the N 1/8 Line

59 W.E. of N 1/8 P on W. Line of Sec 26

Thence N 72° E 6.50 chains

" 42 " 3.50 "

" 82 " 2.50 "

" S 25 1/2 " 6.50 "

" S 13 1/2 W 2.00 "

" 33 E 7.00 "

" 86 " 2.75 ... cross Sec

Line on this course of 248 chains, 10.69 south of
N 1/8 P + 836 N. of witness corner

Thence S 79° East 950 chains

" 400 "

" North 82 1/2 " 2.50 "

" 47 1/2 " 4.75 "

county " 66 " 11.00 "

" 1/2 " 245 - to N 1/8 Line

of Sec 25 2918 East of N 1/8 Post on W. Line of 25
and 5562 West of N 1/8 Post on E. Line of 25

Thence E. on 1/8 line 5562 to E 1/8 Post of 25.

Whole length of road surveyed 120.57 chains

= 1 1/2 miles + 57 links record

finished JUNE 16" 1917

South from N 1/8 P on W. Line var 3 1/2 E

1905 fell 35 W. of witness corner

corrected where road survey intersects

it 836 N. of W. E. and 1069 S. of 1/8 P.

Sec 4-37-7 June 25-1917 75

NW cor found stumps of 4 orig trees.
Run East Var 4° E copied on Page 85.

29.00 to small lake

3500 over "

3948 fell 14. East of 1/4 Post found

Stump of the pine orig LREG.

Maple gone, made new bearing,

center W. Birch 18. S79 E 30.

reced no other. Set oak post.

Sec 23-39-6 JUNE 27-1917

N.E. Cor Iron Pipe and orig trees

Run W var 33° E.

200 LEAGUE swamp. Var 2:30° E

465 to shore of lake

1043 over lake copied on Page 72

21.98 fell 3 LKS South of 1/8 P. See book 5. Page 6

corrected line E. to corner and

Surveyed a piece of land as land toward

commencing at a stake which stands

on shore of lake 11.67 ch. W. of N.E. Cor.

and 37 LKS N. of Sec 26 Line. in gout lot 9

Sec 1/4. Thence South on an angle

of S. 106 W. 5.04 ch to center of road

commencing again at a stake

which stands on shore of lake 7.86 chains

W. of N.E. Cor and 50 LKS South of Sec 26

line Thence westward along shore of lake

to sec line. Thence NW. E. to a stake

which stands 37 LKS N. of Sec 26 line and

11.67 ch W. of N.E. Cor. commencing again

at the stake which stands 7.86 ch W. of N.E.

Cor and 50 LKS S. of Sec 26 line. Thence

on an angle of S 106° 15' W 5.30 chains known as

the Lamson lot. County record

South from N.E. Cor var 30° W

360 to small lake thence westward along

shore of lake, and swamp to a stake at S.E.

corner of Lamson lot 530 ch S. westward from shore


Copied on Page 66
76 SEC 13. 39-6 June 28-1916.

East from SW Cor = Var 3 1/2 E
2004 fells. of 1/8 P. & set 6 years ago

Corrected Line W. to cor.

Surveyed a piece of land described as
Follows to wit:

commencing at an iron monument which
stands on SEC Line 9.40 chains E. of SW
Cor. Thence on an angle N 73° from NW N
6.15 chains more or less to the S.W. cor of golf
Links see book 7. county record
NORTH from SW Cor Var 4° E SEE book 7
250 to LAK



SEC 28-38-8 E July 2nd 1917

SW Cor found iron monumt set by me
Terasago it is 2 feet long. Top is bent
over. Run N. in road

39-78 fell 15. E. of 1/4 P found stp. &
marked SW Ptn 1/4 S 68 E 28 1/2

Went # S and set 1/8 P. found monsell's
1/8 Post 4 inches south and a little west
EAST from S. 1/8 P. on W Line var 3°
4121 fell 66 N of 1/8 P in center of road
Set 1/16 P. in cent of SW 1/4.

This Post sets in a wet open marsh
and is 4 1/4 x 60 inches and is a cedar

Copied on Page 169 Volume 1
South from 1/16 P. in SW 1/4 Var 4° E
1.25 have open marsh

39.84 FELL 77 W 1/8 P. found stp of hem
& marked for bearing in 1904
Hem 12 S 33 1/4 E 26 1/2

Chas Riley has promised to drive an iron at
this 1/8 P. I have driven a short oak stake
Corrected Line N to 1/16 Post in SW 1/4

= JULY 5th 1917 =

Began at 1/8 P. on Post E Line ok. SEE
SEE 27 Book 4. Run W. on true line
4141 to 1/8 Post S. of cent SEE Book 5 P. 66
Drove new post in road just W of cent

• Set flag at 1/8 P. N. of cent instrument at
cent Line - flag at 1/8 P. S. of cent and
chained S. 19.90 to 1/8 P. still south on same
course 19.90 set S. 1/4 P. Nothing for bearing

county road

8 EAST from S. 1/4 P. Var = 3 1/2 E
4010 FELL 58 N of SE cor. SW tree ok. SEE

one is down fell S. Stump ok. There
is too much frost or ice to set new
post. To bra shak said he would put
in a good & dry post

SET 1/8 P. on S Line Whi Ptn stp 16 N 1/2 W
Run N from E 1/8 P. S. Line Var 17°
1980 FELL 9 LK W of 1/16 P. Corrected line south

78 SEC 13-38-10 JULY 12 1917

AS.W 1/4 R. NW COR^W on N 74 P are gone
or never have been established, I
Began at Cor to 13-14-23 & 24 which
had been set by B.F. Dorr by proportion
His bearings are: HEM: 128° 60' 1/2 W 27 1/2
copied on Page 145. 29 1/2 E 23 1/2
Run N Var 5 1/2 W I intended to start
on 00 Var, but I was told the road was on
SEC^W Line which runs on 5 1/2 W
2300 Road angle EAST 34°
3300 Ent swamp
4200 ~ open swamp

9000 to Ditch

23700 offset W and at

23446 fell 24 27 E of corner
Found an overrun of 77 Lks and
set Temp cor to 11-12-13-14 at
80 26 1/2 and 8.27 W of Random
Went to NE Cor in road. did not
find cor^W but Located it from center
of N+S and E+W roads and an old
Random running west on Var 2 1/2 W

80.04 FELL 7 W of SOMEONES COR^W N.G.
8912 FELL 4.09 JULY 14" 1917 NOF Temp^o

Cor. Corrected Random onto
Temp corner a prolonged line
103.00 to Lak Gout^W dist. 80.10 + 743 = 87.53
Found an over run of 15.47. Sprung Temp
corner west at right angles with corrected
west line 516 - 8912 + 5.16 = 94.28
743 + 129 = 872 whole length of N line is
94.28 and line be 11 + 14 872 to me.
nothing for bearings to cor. or mc
Var of N line is 1° E county record
The shore of Thunder Lake where I see
me is 5 feet or more above the lake and
pine and hemlock stumps are plenty but
fire has burned them & think the orig^o
me might have been here, as the court
notes call for pine and hem. it is hard wood

SECTION 13-38-10 E continued

79 Went to West 1/8 Post on South Line
Found Post and bearing set by B.F. Dorr.
Set a new Post. Run North Var 3° E
1200 LEAVE SWAMP AND ENTER SLASHING
Some of was made several years ago
and some last winter

= JULY 15" 1917. =

STILL North on 1/8 Line copied on

2200 LEAVE SWAMP

4200 Rhinelander and 3 Lakes Road

4700 ENTER SWAMP

5600 LEAVE "

6200 Enter " Page 341

8089 FELL 52 1/2 E of 1/8 nothing for
bearings. Post is a dry tamarac
on stand 200 S. of Ditch and 9.25
E. of west end of ditch. DEG 6.49

SET 1/8 P at 2024 W of cent and 1/16
Post in SW. 1/4 Did not mark either
made a line west from each post
Var 2° E County record

80 SEC^o 15-39-6 JULY 17-1917

Began at 2nd me. S. of NE cor

Thence N. on SEC^o Line 480 feet

.. S 58° W 480 ft Line 52-5 "

" N. at Right angles 80 " = 291

" S 58° W. or at Right angle 248-5 ft

" S at Right angles


Began again at 2nd me. and run west
at R. C. From SEC Line 50 feet

Thence N 32° W 481-5 to a point of intersection
with Line running S. 58° W from SEC Line

Prolonged this line S 58° W 160+200+200
and set stakes at each point

Began again at. at a stake which stand
on shore of lake and is S 58° W 50 feet
from me No 2. Then set stakes on shore
of lake at 160+200+200= 560 feet
Then N 32° W 486 feet to a stake which
360 feet W of the stake at intersection
of lines running S 58° W and N 32° W

Copied on Page 67 Vol 1



Copied on Page 143

SEC^o 24.37-8 Aug^o 6 19.17

81

Began at E 1/4 P. on iron pipe or pump point
3 1/2 ft long driven 2 inches below surface
BGT flag at 1/4 and center of section (iron
pipe 3 inches above surface) placed instruments
on line bgt flags. Chained west. in road
4085 bgt flags. Set an iron pipe for 1/8 P.
2696.10 East of center course of line is 00 Var
center of SEC^o was set by men on gell.
Also N 1/4 P. which is an iron pipe.

North from center. Set flag at center
an N 1/4 P. instrument on line between flags.
39.08 bgt flags course of line 2 45° E

N.E. cor = steps of org L 1/8 P. high marks
Plain an iron pipe 3 6 x 2 in 8 inches below surface
and pipes of same dimensions set both E & W
37 1/2 links distant. N from E 1/4 P. flag at N.E. cor + 1/4 P.
Run W. Var 1/2 E vari. 164059 1/2 bgt flags

4264 f ell 52.5 south N 1/4 P. Set an iron pipe
for 1/8 P. on N line. Also for N 1/8 P. on N line
1/8 P. N of cent. Set an iron pipe for 1/8 P. on E line

South from E 1/8 P. on N line. Set flag at
this 1/8 P. and 1/8 P. E. of cent within instrument
on line bet flags. Found distances between
flags 39.83. Flag 1/8 P. N of cent and at

N 1/8 P. on E line and SGT center of
N.E. cor at intersection of 1/8 lines. An iron
pipe for post near large fence post run W on
offset of 4 LKS N to clear fence. Set instrument
10.00 W of cor and 4 LKS from fence. Flag at cor =
For back sight 3960 fell 33 N of S 1/4 inclining off SGT
This 1/4 P. is a free post marked 1/4 S.

Set an iron pipe for 1/8 P. on S. line
North from S. 1/4 P. Var 2 3/4 E on off SGT of

6 LKS W 39 12 fell 23 1/2 E of cent
S. from 1/8 P. E. of cent Var 2 3/4 E
4020 f ell 8 W of cent. Set an iron pipe for post
Set 1/16 P. in S. 1/4 an iron pipe 1/8 P. S. of center
on iron pipe run E to 1/16 post & K

82 SEC^o. 13. and 24 39-6 Aug 14 1917

SURVEYED A PIECE OF LAND IN SEC 13
described as follows.
Commencing at a Stake which stands
at S.W. corner of Golf Links Grounds,
and on shore of Lake. Thence E 15° E
Var 4° E. ~~497.4~~ FEET Pasted on page 66
Thence due East 100 " county record
" N 15° W W 452-8 " to shore of
Lake Then EASTERLY along shore of
" to place of beginning 100 FEET
more or less. Iron pipe at each corner

in SEC^o 24 A PIECE OF LAND described
as follows Copied on Page 72
Commencing at an iron pipe which
stands 600 FEET E. of NW. corner
of said SEC^o 24 and on N. Line of
said SEC^o 24. Thence S. 15° E 158
FEET to an iron pipe County Record
Thence S 75 1/2 ° West 648' to W Line
of said SEC 24 248 FEET SOUTH OF NW
COR. This point on W Line of 24 is in
SMALL LAKE. Thence N. on W Line
248 FEET to NW COR. Thence E E on
N Line 600 FEET to PLACE OF BEGINNING
The SW. COR. of this piece of Land is
61 LKS. SOUTH OF ME. ~~ME~~

34 SEC 15-38-6 BEGAN 2

Began at a Stake which stands on
Shore of Lake 610 FEET Southwesterly
From 2nd me South of NE COR. Thence
S.W. 50. Then S.E. 50 along shore of Lake
angle from Stake 610 from me. to the
Stake 100 FEET SW SE is 126 1/2° copied on
Began at 1/16 P in N 1/4 and run E. at
Right Angles with NTS 1/8 Line. 724 FEET to
Lake and set me. Page 68

SURVEYED A PIECE OF LAND in Lot 19-SEC 15
commencing at a Stake which stands on
Shore of Lake 85 feet N. of 7m.e. on line
betw Lots 1 & 5. Thence W. parallel with
1/8 Line and 85 FT N of same 435-5 FEET
the NE COR. N on an angle from E to W
of 74 1/2 to a Stake which is 100 FEET
N at Right Angles. Thence parallel
1/8 Line 414-5 to Shore of Lake. Then
southerly 100 FEET more or less to
the place of beginning containing
93 1/2 acres county record pg. 68

84 Copied on Page 161
SEC 3. 38-7 August 16-1917

SURVEY OF SCHOOL grounds in Lot 3
commencing at a stake which stands
on 1/8 Line 500 W. of 1/16 Post in NE 1/4
Thence South at right angles to 1/8 Line 36 1/8
chains. Thence N. parallel with N Line of
said Lot 3. 36 1/8. Thence N. at right angles to
N Line of said Lot 3. 36 1/8. Thence E. on N.
Line of Lot 3. 36 1/8 chains to place of
beginning containing ONE acre.

County record

AUGUST 18. 1917

SEC "35-36 & 7, SURVEYED A
PIECE OF ground in the NE corner
Contained square acre. for School
Gronds for the Town of Woodboro

ALSO ON SAME DATE COPIED as
SURVEYED on acre of Land in S.E. N.W. of
SEC 35-36 AS FOLLOWS to wit
Commencing at a stake which
stands on E and W 1/4 Line 3700 chains
E of W 1/4 P. Thence E. on said 1/4 Line 3000'
Thence North ~~E. 125~~ N 71° E 125 chains
Page North at right angles to said
E + W 1/4 Line 227 chains. Thence South
71° W. 125 chains. Thence W. parallel
with said E + W 1/4 Line 300. Thence
S. at right angles to said E + W 1/4 Line
227 chains to place of beginning 43

For town of Woodboro

County record

I THINK THIS
SHOULD BE

5-36-7 MGR 2017
SINCE IT WAS DONE

For WOODBORO AND
THERE IS A SCHOOL
symbol in OLD PLAT BOOKS

SEC-3. 39-10. AUGUST 20" 1917 85

BEGAN AT SW COR. Found cement Post
8x8 inches, also roots of orig. Pine.

Run N Var 3.10' E on fence line
22.11 FELL 29. W of m.s. found maple stub with
marks ok. Pine is down & rotten made
NEW Bearing W Pine 20 West 44.

Corrected Line S. to cor.

" Var 2.20

SW cor. Run E Var 4° E am at wire fence
course may be wrong at 3000 Var 145° E
4600 offset N. 2.15

500 ft to lake

5746 over lake

6685 same "

7476⁶⁷⁶⁸ over " FELL 305 S. of E. cor" ok

This departure includes offset
57m. E on W. shore of lake at 49 59 E.
of SW cor Dec 4.08 change course 2 1/2°
Found a short line betw m.c. and SW cor
of 617. Proportioned short line, and
set a stake did not mark it or
make bearings. I saw Jim Lawler
Dan Graham and AL Denton et.al.
and the all say the S. 1/4 was and
is at S. end of road and on line
with fence going W. From end of
road said to be and believe is
on N + S 1/4 line. and I advised them
to use it. my line as corrected is 62ks
S of where S. 1/4 P is said to belong

When the parties interested found
the work done by Graham was so
close to mine. They concluded all
his work good. Let things be as they
were. AUGUST 21-1917

County record

SEC 3-38-7 AUGUST 27-1917

BEGAN AT N $\frac{1}{8}$ P. ON E LINE iron mon doors
bearing $\frac{1}{2}W$ from Stp 16 N 20-8 38
Thence N on SEC Line 3 $\frac{1}{2}$ 5.16 ch copied on Page 161
" S 5045 from E Line 573 to VILLAGE PLD.
" S on angle of 90.55' from Line behind me
or S 33.05 E 224. County record
" East at right angle to SEC Var 3 $\frac{1}{2}$
354 to place of beginning

SEC 538-11, AUGUST 29-1907

BEGAN AT CENTER OF SEC SET BY DORT
His bearings ok RUN E. VAR 10 $\frac{1}{2}$ E.
1700 to GRAVEL hogsback 21.00 own it
3861 f E 1.08 N OF THE WHICH IS 43 LKS
copied north of E 1/4 P in Lake
on Page SET 1/8 P. E OF CENt nothing for
bearings CORRECTED Lin over hogs
374 Back This hogsback is a gravel
pit but is not opened except in
county Lot 3. Which would be the NW. SE
decimal for correction 2.9 record
change course 210° corrected var 8.26

August 31 1917

SEC 27.39-11 E

Began at center of SEC set by
Dort in MAY 1906 copied on
RUN W VAR 5.15 E Page 382
30.80 DORRS 48 P on LINE. POST SEC
in open marsh no bearings
PROLONGED LINE W to Lake.
about 10.00 ch

SOUTH from 1/8 P. W. of CENt VAR 1/2 E
This LINE is PARALLEL with W. SEC LINE
5.80 LEAVE open marsh
10.00 intersect flat Linden Beach
County record

SEC 32.39-11 E SEPT 3rd 1917 87

SURVEY of a piece of Land in Lot
⑦. COMMENCING at a STAKE which
stands on N. Shore of Medicine Lake
and is S. 52° W. 165' from a line on E Line
of Lot 7 as surveyed and established
AGREEABLE to OWNERS of Land on THE + W
SIDES of said East Line.

Thence N. W 21 4° E 3.00 Thence S 82° W 59°

Thence S. 6.00 To a Stake which stands
on shore of Lake { Page 12 S 39 E 8

Thence N 81° E 3.18. Thence N 31 E. 3.18 to place
of beginning containing 3 acres.

SEC 9. 36.9 E SEPT 4 1906

piece of Land on N end of THE N.
as follows to wit: commencing at
E 1/8 P. on N Line. Then E on N. Line 2880
to N.E. corner. Then S. on SEC Line 7.80.
Thence W parallel with N. Line 27.60 to
446 P. in N.E. 1/4 Thence N. on 1/8 Line 780 to
1/8 P. and place of beginning. containing
2.99.96 ACRES.

Copied on Page 196
E 1/8 P. on N Line new { Page Stp 14 N 10 W 30

Iron Pipe for Post { TEL POLE S 11 E 121
N.E. corner Post

N 1/8 P. on E Line ok County record
at east an iron pipe 780 S. of E 1/8 N LINE
{ TEL POLE S 36 E 59 1/2
780 South of N.E. cor. iron Pipe 1/2 24.
{ W Pipe Stub 12 N 20 W 15 1/2

SEC 14.42-5 E Sept 11 1917

commencing on line which runs N 75° E from point 150 East of center of sec. and 2.35 chain from 1/4 line (155 feet).

Then S on angle of 12 1/2° or on a quar of 2 1/2 E. 9.47 chains or 625-2 feet.

Thence East on angle of 11 1/2° or 75° E Var 2 1/2 E. 285 chains or 188 feet to Lake



SEC 22.42-5 E Sept 11 1917

Sout from N.E. cor. steps of orig. tree & Post
Run South on cut outline Var 15 W
2069 to LAKE, Nome.

5635 over Lak. fell 613. 1/2 W of m.c. found
Stump & made forme 17 years ago found
The pine org tree at that time. came N and
Set me on high bank of Lake 1809 S. of NE cor
Set instrument at me on N shore of lake
and lined onto me on S. shore of lake and
prologed about 400 ft. Mr Smith said he would
finish the line N to cor.

SEC 11-# 36-4 Sept 14" 1917

N.E. Cor. found 8E + S^t trees. Stumps now, marks
Set Post + made new bearings. Birch at
equis { Hem^m 9. N 45 W 18
Spruce 10 S 46 E 17

Run West Var 4° on Pay. 6
4500 LEAVE Timber + Enter OLD burning
9500 STREAM RUNS S.E. 15 Lks wide,
Low ground + swamp old slashings to
15790 FELL 507 N of cor to 3-4-9-10.

which is set by proportion in Dec 1914
a gray boulder 2x3 feet 18 inches high
bears S 52 E 66 1/2. Post is OK and is
in the center of road which is cut out
4 rods wide. They are grading it

This date Sept 15 1917.
Dec 3111 change course 1750 corrected
Var 5.5°

found a shortage 202. Proportioned
shortage, and set temp cor at 7875
West of N.E. cor " and on the line as corrected
Gout dist" of N line is 7975

oo

Run S. from Temp cor " Var 3 1/2 E which
is Right to Random on N line.

1675 Stream 15 Lks wide course E asterly.
This stream is overflowed and bottom
is covered with water 1 foot deep. The
bottom is 700 ch wide. A large family of beaver
have a high dam about 40.00 N of line
200. over bottom. 4000 chains enter open
swamp

80.00 found evidence of cor. at 7800 + 200 East
will try it again from the East.
This Sunday Sept 16. Did not want to
work today but conditions demanded
it. com^t record

N.E. Cor. Run South Var 4 E
3984 fell 161 1/2 E of 1/4. Found the ironwood
ok. Hem^m down + rotten. Set Post and
made new bearing { X. Birch 18 S. 29 E 19

SEC" 11. 36-46 Cont" Sept 17" 1917

Dec" E line from NE cor to 1/4 P 405
Change course. 2.26 Var 1.46

South from E 1/4 P Var 4° E

45.22 fell 1.80 W of SE Cor. found SW tree down
marks ok. others gone. Set Post and made
new bearings; Cedar 10 N 4° E 38
12 S 32 W 24

Dec" 40 change course 2.15' correct Var 6.15'
West from SE cor Var 4° E changed to 3/2

7992 fell 66. S. of SW cor. found Stb" of NW. org tree
Set new Post not a thing for bearings
Post is in SWamp. Everything burned & dead
copied on Page 00

Picked up my random from Temp" NW cor
and at 8047 fell 1.73 E of SW cor

As had run the Line bet" 9+10 and
had the Length of Line and knowing the
Cor to 2 + 3 + 3 + 35 was lost. I took the

distance of the E line of 11 and the the
" " " 11 5 6 E, 9+10 and added them
to gether making me distance 8136.
And moved Temp" cor N 89 Lks making
the W line 8136

my notes for N line now read.

West from NE cor Var 4° G. changed to 3/2
7875 fell 1.60 N of NW set Post and made bearing

(Birch 4 S 45 E 86 E. 9 no other bear
N 1/4 P. set at 39 12 1/2 W Pine Stb 30 S 45 E 12

" " Run South Var 3 1/2 E.

8320 fell 2 2 W of S. 1/4 P which gst at 39 96

and 33 N of Rand" W Pine Stb South 35 1/4
W 1/4 P set equal dist" bet corners.

W Pine Stb 18 N 11 1/2 W 31

" " 18 S 7 3/2 W 36

East from WEST 1/4 Post Var 5 1/2 E.

7769 fell 1.98 S. of E 1/4 P

Set CEnt of SEC { Spruce 10 S 80 E 26

8 S 20 W 15

county record

SET 1/8 P. N of CEnt Birch 18 north 15 3/4

" " 3 S " " 20 S 30 E 20 1/4
copied on Page 00

" " E .. . Birch 538 W 32 3/4
Hem 8 22 E 14

S 1/8 P. on E line Birch 538 W 32 3/4

N 1/4 P. " W " Sugar N 63 W 19 1/2

N 1/8 P. " W " Birch 538 E 38

E " " " E " Hem 12 S 15 1/2 E 30 1/2

E " " " N " Elm 24 N 6 E 57

= Sept 20 = " 165 S 31 W 22

West from 1/8 Post N of CEnt Var 6° E

2762 to flowage of beaver dam

4006 fell 86 South of E 1/4 P corrected line

from flowage E. to 1/8 Post

East from 1/8 S. of center Var 6° E

3895 fell 43. S. of 1/8 P.

Set Twp Boundary 116 P. in SE 1/4.

Hem 10 N 23 W 17

Run N. from Temp 1/16 P Var 5 1/2 E

2136 fell = Sept 21 - 44 E of 1/8 P

North from 1/8 Post E of CEnt Var 2 1/2 G
4068 fell 7 1/2 W 1/8 P.

Set N 1/8 Post on East line (Hem 10 S 2 1/2 E 22
" 8 S 2 1/2 W 21

corrected line from 1/8 P. N. of CEnt
West 15.00 Through the timber
finished Sept 21 - 1916

Dist to N 1/4 P 4024

" " S " 4293

" " E " 3699

" " W " 4070

county record

92 SEC "5 36 8 E. SEPT 24" 1917

N.W. cor. found Post & SET and bearings
made in May 1911. SEE book 7 Page 159.

Run E UAR 5.45 E

4006 FELL LKS S. OF 1/4 N. 1/4 P. found THE S.E.
ORG FREE STANDING but dead Post & SET in
May 1911. N. ORG FREE OK but dead

SET W 1/8 P. on N Line. W. Price sp. 20 S 50 1/2 E 31
South from W 1/8 P. on N Line UAR 11. 15. E
57.30 fell 3 LKS W. OF SOMEONES 1/8 P. have
not much CONFIDENCE in this 1/8 P. but
the PARTIES & I am working for seem to
think it is all right. And I call it
doubtful county record

SEC 27 + 18 - 35 - 8 Oct 15 1917

93

NW COR of 18 "iron mon" ok RUNS UAR 3 1/2 E
4014' 2. FELL 1/2 LK. N. O. S. 0 1/4 P. OK

SEE 1/8 P. AT 2007 1/4 ON IRON MON. THEN
EAST FROM 1/8 P. AT 2007 1/4 ON IRON MON. THEN
1500 ENT LOW GROUND. 301
3000 OVER LOW GROUND
6300 ENTER SWAMP.

7300 NO CORNER

9500 LEAVE SWAMP

12690. FELL RUE ROAD

14766 FELL 560 SOUTH OF COR TO 89 J6-17
DEC 378. CHANGE COURSE 210

found a short 96 334. SET TEMP COR TO 7-8. 17. 18
on CORRECTED LINE AND 270 N OF RUE
AND 7140 E OF COR TO 7+12.-13.-18

OCT. 19. RUNN FROM TEMP COR UAR 3 1/2 E

1500 LEAVE SWAMP

3000 ENT. SR "

5000 LEAVE SR "

15915 LEFT bank WIS RIVER

16281 OVER RIVER.

17516 FELL 161 W OF COR TO 5. 6-31-32 T. 35-36 R. BE
found Post SET by DOGF. SEE NEW Post

DEC: FOR CORRECTION 92. CHANGE COURSE 31
SET MC. ON LEFT BANK OF RIVER AT 159.87
ELM 165 51 W 32

B. ASH 155 73 E 22

Men forgot to bring pouch. Have no scribe
South from TEMP COR on CORRECTED LINE FROM
1800. LEAVE SWAMP

2200 ENTER "

4200 LEAVE .. | : OCT 20 | found E 1/4 P OF
18 about 1/400 W OF LINE. RUN N. UAR 7° W

Found 1/4 P. WAS OPPOSITE OF 3800.

800 ENT SWAMP. 3864 FELL 77. W OF TEMP COR
found an overrun of 451 BET E 1/4 P OF 18 AND
MC. BET 546 ON LEFT BANK OF WIS RIVER

PROPORTIONED OVERRUN AND SET TEMP COR
N + S LINE 48.91 N. OF 1/4 P AND 157.60. S. OF MC
WHOLE LENGTH OF N + S LINE FROM 1/4 P 666' 17 + 18 + MC

IS. 198.51. Cont'd dist 15-194.00

Sprung Temp cor on E + W Line N 2.17

" " " Naslme E 36

and set Post cor to 7-8. 17.18 { Tans N 15W15

{ 5 S 87 1/2 E 24 1/2

Picked up my Rand bet 7 & 18 and at 714 of FELL 187
S. of cor to 7-8. 17.18 found a shortage of 1.60 Proport-
-Lined same and set E 1/4 P bet 7 & 18, at 1956

{ Aspen 10 S 72 E 78 DEC 6.91

SET 1/4 P at 3912 { J. Pine 10 N 36 1/2 W 156

10 S 71 W 122

SET W 1/8 at 5868 W of cor. 1272 E of NW cor No Obj. 2
course of line as CORRECTED 624 E

" Line from E 1/4 P of 18 is 11 W.

My Random from E 1/4 P. of 18 now reads
N from E 1/4 P of 18 Nort 7° W 1090 FELL 36 W
of corner to 7-8-17-18 DGC 88.

North from W 1/4 P. of 7 OK Var 3° E 400 1/2
FELL 3. W. of NW cor OK.

E from NW cor of 7 Var 5° E

14335 FELL 158 N of cor to 4-5-8-9. OK

Found a shortage of 7.65, DGC 112. Proportion 10.10
Shortage + set Temp cor at 7594 W of
cor to 4-5-8-9. and 6741 E of NW cor or
Sprung Temp on E + W Random N. 2.55 and
64 1/3 + 2.55 from corrected line = 359 1/3. So
true corner is 359 1/3 N of true line bet: NW cor
of 7. and cor to 8.9-16-17.

Sprung Temp cor on N + S Line W 293 + 77 3/4 =

370 3/4 W. of true line bet: cor to 7-8-17-18

Note now read. N bet: 7 & 8 Var 3 1/2 E

8230 fELL fELL 2.93 E. of cor to 7.8-17.8.

DGC 3.56

change course 150

corrected var 152.0 SET E 1/4 P. of 7 at 41.15
and 146 W of R Random

SET S 1/8 P. at 2057 1/2 N of FELL cor to 7-8. 17.18 and
7.3 1/2 W of Random

SGC 2 8 1.7 + 18 cont Oct 22 1917 95

MY NOTES NOW READ.

E. from NW cor 07. Var 5° E

6741 fELL 2.55 S. of cor to 5-6-7-8 Var 5° E

DGC 373. change cours CORRECTED VAR

SET N 1/4 P. of 7 at 29.43. 1.1034 N of Random

Had found a shortage of 3.59

J. Pine 8 N 42 1/2 E 98

" " 7 S 85 1/2 W 115.

SET S 1/8 P. on East Line of 18 of 18. at

2045 and 18 E of Rand { Spruce 10 N 77 W 8

10 S 85 E 12 - - -

MY NOTES NOW READ

North from cor to 7-8-17-18 Var 3 1/2 E

8230 fELL 2.93 E of cor to 5-6-7-8

DGC 356 change course T.50 = 520 E.

SET E 1/4 P. of 7 at 41.15 and 146 W of Random

J. Pine 9 S 89 E 89

" " 10 S 102 E 31 1/2

SET S 1/8 P. on E Line of 7 at 2057 1/4. and 73 W of 8

J. Pine 10 S 36 1/2 W 114

" " 8 S. no other ment

South from N 1/4 P of 7. Var 5° E

872 to Lake { 1/16 Post in SE 1/4 of 7

1656 over " { J. Pine 8 S 10 E 57

3135 to wet marsh .. 8 N 13 W 91

3704 over "

8289 fELL 67 1/2 E of S. 1/4 P

East from West 1/4 P. Var 6 1/2 E

6902 fELL 25. South of 1/4 P

SET E center of 8 S. in open field

dist to N 1/4 P 4240 -

" 3 .. 4049 = 8289

" E .. 3861 = 7902

" W .. 8041

SET 1/8 P. S. of center. W. Pine 8 P. N 85 W 21 1/2

" " " S 81 E 41 1/2

E. from 1/8 P. S. of center Var 6 1/2

3889 fELL 113 N of 1/8 P made a mistake

in setting, H. E. Yermer and R. V. R. on 745

SEC 7 418-38-5 cont Oct 24. 1917

WENT to W 1/4 P. of T and run S. Var 3° E
 4006 to SW COR of T. SETS 1/8 Post on W Line
 of T. in open field No bearings near
 WEST from 1/8 P. S. of center of T. Var 6° 15' E
 3158 fell 19 N of 1/8 P. SEC 418 P SET 1/16 Post
 in SW 1/4 of T in open field No bearings
 = This is all in SEC 7 =
 SEC 18. - South from N 1/4 P. Var Var 3 1/2 E
 4350 LEAVE open field
 3750 Stream 75. Run SW
 8063 FELL 3.43 E of 1/4 P. found stub of Pine ok
 and Hem which is dead New Post.

W 1/4 P. is a fence Post ok Run E Var 5 1/2 E
 3400 Stream 25 runs SW
 6523 fell 63 1/2 S. of E 1/4 P. DEC 937 change course 31'
 SEC center of SEC Post SETS in stream
 DIST N 1/4 P. 4004 { WPines set 24 N 76 E 30 1/2
 " E " 4059
 " E " 3415
 " W " 3108.
 SEC 1/8 P. N of center an iron pipe 1/2 x 24. even
 with surface and Painted White.
 East from 1/8 P. N. of center Var 6 E
 9.96 to Lake
 2654 over lake.
 3605 fell 38 1/2 N of 1/8 P.

at 2654 run NW of offset N 285 and run
 West Then North 19.17 Var 3 1/2 S
 1917 fell 3/4 of a Link E of 1/8 P. corrected line
 South to lake and set me. { Pam 10 N 14 W 20
 " " 10 N 73 E 14

finished at 5. P.M Oct 25 1917

SEC 22 42-5 NOV 3 1917

VV 1/4 P. found on old Post and an iron bolt
 ALSO the roots of orig trees
 Runs Var 3 1/2 E.

4014 fell 18 3/4 E. of S.W. COR Found Augry old
 Post and roots of orig trees. DEC 4671
 Change course 16 corrected Var 2 5/9
 E. from SW COR Var 3 1/2 E

7.00 LEAVE open SWAMP
 2400 ENTER " "
 3000 LEAVE " "
 40.00 did not find 1/4 P.
 5500 ENTER open SWAMP.
 6500 orig line

7869 SEC 18 1/2 N of ^{SE} cor found Post A SEC 13 y Gars 4006
 The Pine is a STUMP Birch is down fell NE
 SEC S 1/4 P. at 39 35 ASPIRATION 26 E 33
 " " on S line 10 S 60 E 49
 SEC 1/8 Post 1967 S of P. Pine ID N 72 1/2 W 25
 1/8 P. W of Canks W Pines, BIR 14 N 69 1/2 E 81
 SEC 1/8 P. on S line N 73 W 28
 SEC 1/8 P. W of center N 73 W 28
 SEC 1/8 P. on S line N 73 W 28
 MAPLE 10 N 89 E 23
 W Birch 24 S. 69 1/2 E 13

SEC TEMP 1/8 P. S. of center
 " Permanent 1/8 P. S. of center

W from Temp P 1/8 P. S. of center Var 2 5/9 fell 8 N of 1/8
 1500 wet marsh with small boggy areas

1400 own " " " "
 3893 FELL 8 N of 1/8 P. WENT E to TEMP
 1/8 P. S. of center and moved it E A 2 LK
 Qs given above. and Correct Line. West + 2d
 1166 P in SW 1/4 W PINE 14 N 73 W 28
 " " " 14 S 27 W 28

S. from 416 P Var 3 1/2 40 10 fell 3 W 48
 corrected line at 416 P and corrected

Prolonged line North from W 1/4 on Sling.
 5200 Road 5550 to lake and set me nothing for B.T.
 corrected N + S 1/4 line from 1/8 P. S. of center
 N. to lake and set me nothing for B.T.
 finished Nov 6 1917

98 SEC 1-39-10. DEC 20 1917

Began at W. 1/4 P on iron pipe which
I placed here in March 1909. SEE
my field book No 6 Page 72, and County
Record 348. Run E. N. W. 210. E.

2700 to meter lake

5200 over " "

5300 over road to field

6392 FELL 388 1/2 S of 1/4 P. Found Roots
of org trees. and Post which is in fence
Dec 608 change course 3°. Var 5.10

South from N.E. cor Var 4 1/2 E.

5327 mrc on line

8383 FELL fELL 54 1/2 W of me bet 7 & 12
found an overrun of 22 feet M. corners
SET S.E. cor on ice at 235 S. or N. me.
and 41 E. of random Dec 65
change course 21° E 1/4 P is 24 Lks W.
of a line drawn from N.E. to S.E. cor
as E 1/4 P is 24 Lks W. of true Lm. whole dist of
E & W 1/4 line between lines is 64.16. So I set
center of sec at 32.08 on ice.

Dist to W 1/4 P 32.08

" " E " " 31.84

" " S "

West from S.E. cor on ice Var 4° E
1375 Leaus Lake & center open swamp

2378 fELL 230 N. of SW cor NEW
bearing March 16. 1909.
sec next page { W Pine 10 N 55 W 29

course of S. Line 5° 51'
N. from S 1/4 P Var 4° E. 1424 to lake
4073 FELL 100 ft East of cent. had
SET center but found chainman had
made a mistake in marking tallgs
of 10.00 and whole distance of E & W 1/4
line is 73.92 instead of 6392. This mistake
occurred at 30.00 and from there on
East found whole distance bet. E & W
sec lines on E & W 1/4 line 174 1/2

99

SET center at 370 8 E of W 1/4 P. and
3684 W of E 1/4 P. on lake meadow.

SET 1/8 P E of center at 1844
" " " W " " " 1854.

Distance E S 1/4 P 4073 -

*** SET S 1/4 P. at 3564 W Pine 30 N 28 W 59 1/2
Aspen 8 S 63 92 E 16

SET W 1/8 P. on S line nothing for bearings
found the length of S. line from SW cor
to lake is 5763. Out dist is 6936 my dist
from S.E. cor. W to W shore of lake is 1375
Out " dist" is 1064. There is so much
discrepancy in Govt measurement, I did
not endeavor set me. and SET S 1/4 P by
proportion bet me. and SW. cor and SET
it equi dist b/w S.E. & S.W. corners
1/8 P E of center W Pine 16 north 226 on shore
of lake Post is in lake

1/8 P W of center W Pine 30 N 43 W 67
angle from E & W 1/4 line


dist. from center to N shore of lake is 60°
Set a stake 927 W of center E 2 N 8955 9003
and run a line N. to lake 1238.

this line divides lot 4. in center
North from 1/8 P W of center
parallel with N & S 1/4 line 365
to lake. and prolonged it
S. from 1/8. 1018 Then E at R.A.
212 to lake

The Stake 927 E of center is
on W. shore of lake

The line run N from 1/8 P W of center
divides lot 4 & 5

North from 1/8 E of center at R.A. to 1/4 line
about 1600 ft lake did not chain it



102 SEC 3-36-7 April 19-1918

Began at E $\frac{1}{8}$ P. on N Line set by Dorr found his bearing SW Pine Stab 12N 14E 28 Set in in Sept 1893 set an iron pipe for post and made new B.T. SW Pine Stab 12S. 54 $\frac{1}{2}$ E 52 Run South Var 4 $\frac{1}{4}$ E 1350 Enter Swamp 1850 0 U.E. T.S.W. map 3965 fell 105 E of Dorrs 1/8 P. E. of center found his bearing SW Pine Stab 10S 84W 5 found a short post of 1255 Set 11/16 P. in NE 1/4 An iron pipe at 1/8 P. E of center & 1/16 P. Corrected Line N. from 1/16 Post to 1/8 P. N $\frac{1}{4}$ P. in center of road. A Stake on N and Sout Side. of side of road Run South Var 4 $\frac{1}{4}$ E 25 Enter Swamp 2300 LEAVE "

2466 fell 25 $\frac{1}{2}$. E. of Dorrs 1/8 P. found His. Bearing a stump has been a windfall set new post and made new bearing SW Pine Stab 26S 43E 36

----- copied on pages 174-5
SURVEY OF ROAD FOR THE TOWN OF Woodboro April 17-19-18 36-7.

To determine the place of beginning. I began at the 1/4 Post between Sections 20 and 21. T. 36. R. 7 E with vernier adjusted on 3 $\frac{1}{2}$ ° E Var and run # 1159. Then N 32 FN 11° E 5350 Long old road

Then N 32.. 472 " " " to the junction Woodboro and 101 road and place of beginning. Then C N 62 W 1800 to Post and SW Pine Stab 16N W 59° plan old RR grade commencing again at a stake which stands in center of same old RR grade known as the Oneida and Cassian grade. from which a W. Pine Stump 14 in dia bears N 67 W 46 LKS dist This stake is in SE 1/4 of SEC 8

36-7 new county record

Road continued apr 20 1918 103

Then S. 37 $\frac{1}{2}$ E 454 To an old RR grade
 " 42 $\frac{1}{2}$ " 421 on " " "
 " 35 $\frac{1}{2}$ " 882 " " "
 " 37 $\frac{1}{2}$ " 361 " " "
 " S 17 $\frac{1}{2}$ " 276 " " "
 " S 16 " 277 " " "
 " 32 E 637 along side of hill
 " 11 $\frac{1}{2}$ " 362 " " "
 " 14 $\frac{1}{2}$ W 498 " " "
 " 3 $\frac{1}{2}$ E 683 and across Rice Creek road
 " 31 $\frac{1}{2}$ " 397 on old grade on dam
 " 38 $\frac{1}{2}$ " 1341 " " "
 " 46 " 2059 " " "
 " 43 " 265 " " "
 " 17 $\frac{1}{2}$ " 248 " " "
 " 9 W 1450 " " "
 " 10 " 303 " " "
 " 17 " 308 " " "
 " 30 " 648 " " "
 " 20 " 239 " " "
 " 4 " 245 " " " to intersection

road line run April 17-1908 and to a post in center of R grade from which a W. Pine Stab 12N 26W 26

" " " 14 S 9 E 66
Then S 4 $\frac{1}{2}$ W 1328 on old grade
 " " " 8 502 " " "
 " " " 17 " 742 " " "
 " " " 11 " 296 " " "
 " " " 9 $\frac{1}{2}$ W 262 " " "
 " " " 29 " 2246 " " "
 " " " 34 " 639 " " "

to intersection of Woodboro & Marion Road on line between SEC 20 + 29 36-7 N.C.R. E $\frac{1}{8}$ P.

Pages 174-5

record

new county

Book. T. 36-R7

Copied on Page 57

104 SEC " 14-35-11 April 24" 1918

NE Co- found Post & Set from orig Lins
many 17-1915. orig Lins OK this date
Run S South Var 5.35

4039 FELL 57 E. of 1/4 P. found my bearing
made several years ago ALSO Stps of orig trees
drove an iron pipe 16x 1/2 inches for Post
Dec" for correction. 1.33 + change ourself
corrected Var 4.50

Set N 1/8 P on E Line at 20.19 1/2
an iron pipe for post W. Birch 14N 44W 49
new record .. 10S 42W 19 3/4

Corrected Line N to Cor for Road

for town of Schoepke

WEST From N 1/8 P on east Line Var 3.45
2065 Center of Old Road and Left it

Copied on Page 17

SEC " 4-38-9. Apr 26-1918

E 1/4 P. found my bearing made in
June 1907. A W. Pine Stp 28N 46E 64

Set an iron bolt 20x 1 inch for post

Run north Var 10 3/4 East

47.20. FELL 2 1/2 LKS E of Cor a piece of

N W Tree is lying at the Stps
new with iron marks still plain

new CORRECTED Line S to 1/4 P. and
SET STAKES 37 1/2 LKS W of Line

Copied on Page 133

Section 33-39-9. April 26-1918

SE. Cor: There is a post in center of road
some say it is one & set in 1906. The bearings
are all gone. found a piece of one beside
a stump and think it is NW orig tree.
Post would come 27 LKS E of one in road
North from new Post Var 5 1/2 East
3667 fell 59 3/4 W of E 1/4 P found my

old bearing W Pine Stp 28N 46W 82

new W. Pine Stp. 36. S. 57 E 82 1/4 new record
Run N on corrected Line 18 33 fell 18 W of
1/4 P. SE Post from old bearing line run for road

Copied on Page 28

SEC " 7. 35-11 May 2 " 1917

105

went to SW Cor with Tony Weenink
who identified the stumps of two of the
orig trees. found an old post which is
OK. Post is near E side of road
Chained South in road. Var about 5 1/2 E

40 3848 Found 1/4 Post 13 1/8. one orig B.T. it
is down but still has iron marks

Run north from SW Cor Var 4 1/2 E

3962 FELL 2 3/8 E of of 1/4 P found one orig B.T.
down & rotten Post is nearly in center of
road near E wagon track

Copied on Page 121 - new record

SEC " 30. 37-11 May 3. 1918

AS I had run the E + W 1/4 Line and
the parties who are having this
work done do not want to go to the
expense of having this SEC line properly
Surveyed. I used the E + W 1/4 Line as a
baseline line for my notes of this
1/4 Line. See County Record marked
Dorris field notes.

Set 1/8 Post in road 32.20 E of of WEST
1/4 Post. Run N Var Var 1° E -

8963 to old E + W Line then W on this line
10.00 to Lake Copied on Page 121 new record

E from W 1/4 Post 175 stream 40 runs NW
1068 center of bridge over same stream
Computed acreage E. of stream & lake
in Lot 2 = 31.29 1/10 acres described as
follows. Beginning at a point in center
of bridge on E + W 1/4 Line in SEC " 30-37-11
and 1068 chains E. of west 1/4 P. of said
SEC 30. Thence E on said E + W 1/4 Line to
the SE cor of said Lot 2. and 3220 E of W 1/4 P.
and 21.32 chains E of center of bridge. Then
N. Var 1° E 19.63 chains. Then west on old
line 10.00 to lake. Then southwesterly along
shore of lake & stream to place of beginning 31.29 acres

106 SEC 25-37-10. May 4 1918

E 1/4 P. found Post & Set from orig trees and
bearings made in 1900 1898

Run N. Var 3° E

1.75 STEAM 30 FEET N.Westerly

2445 ~~ft~~ to South Line of right of way of Soo RR
3956 f GLL 178 W of. of M^c found Post & Set in
1900 and one orig tree

Went South and corrected line at South
Line of Right of Way, and found dist ane to
E. 1/4 P to be 2486. Run East from this Point
to Lake at right angles with corrected line
8.00 Then it is 1.60 N. to Right of Way of Soo RR
S. Then measured E. at right angles at 10.00 N of 1/4 P
on corrected line from 10.00 distance is 1050
at 2000 ch it is 15.28. at 2486 it is 800.

The 4 measurements are 1068

Posted on pay 100 1050

New Recor 528

800

1) 3446 (861 1/2 Total 34.46 = 861 1/2

Average distance N + S is 25.13

E + W 861 1/2

TOTAL acreage 21.65 1/100 This piece of Land
is in SEC 30-37-11 and a part of lot 2

SET TEMP WEST from E 1/4 P. Var 0°
3000 intersect Town road

at 2000 chains Set T drift 1/8 P.

" 4000 " " Center in Road

" 6000 " " 1/8 P

Run N from 1/4 P E of Center parallel with center line
1462 Right of way of Soo R.

N. from center parallel with East line
1487 Soo Right of way

from a point 10.00 West of run N Parallel with East line
1462 to Right of way of Soo RR

at center of W 1/2 of NE 1/4 or 300 feet of
E 1/4 Post it is 1422 N to Right of way

SURVEY of Road for LHC
Town of Harrison May 7th 1918

commencing at SW. of SEC 7.35-8
Thence east on SEC Line 32.28 ch

" Northon 1/4 20.24
" East .. 1/8 38.61
To South 1/8 Pon E Line of SEC 7 6.42

Thence E on same course

	N	77 1/2	E	Var 4° E	1.66
" "	32	"	"	"	3.68
" "	8	"	"	"	5.62
" "	81	"	"	"	3.77
" "	68	"	"	"	2.65
" "	59	"	"	"	2.50
" "	66 1/2	"	"	"	3.73
" "	79	"	"	"	3.70
" "	27	"	"	"	6.20
" "	64	"	"	"	2.18
" "	86	"	"	"	4.87
" "	34	"	"	"	1.55
" "	10	WEST	"	"	1650. to

West end of road supposed to begin N 14974 ch
1/8 line and 10.00 W of N 1/8 Post on East
of SEC 8

149.74 = 1.78 MILES

108 SEC- 32 38-8 MAY 13. 1918

SW COR in center of road. No bearings
Run N Var 4° E
200 ft to 1/8 P & set many years ago

North from W 1/8 P. on S Line
850 ft wet bottom

200 1/2 to 1/8 P in SW 1/4 then N to RIVER
copied on May 21 new record

East from S 1/8 P. on WEST Line
219 95 1/2 to 1/8 P

SEC" 5-378. MAY 13 1918
Began at W 1/8 P. on N Line in center Road
Runs S Var 1/2 E
40 ft 4032 same distance as it is from
WEST 1/4 Post to SEC" COR
THEN E. PARALLEL with N Line to River
Took the angle at W 1/8 P on N Line
with 1/8 Line running South in road
and found it 88 1/2° Thus ^{Town Line}
Copied on May 21 new record
SET 1/8 P E of W 1/4 P in center of road on iron pipe made bearing
STGL Post 10 N 67 E 37 Post is about 1.50
feet north of stream at bridge

SEC- 19.37-10 MAY 16" 1918 109

SW COR- iron Pipe in road NEAR NW corner of
Run E. Var 4° E { Y. Pine St P 16 S 69 1/2 E 70
19.34 top hill 75 E. of Lake
30.70 (75 E. of Lake
49.25 Enter Spruce Swamp
79.96 FELL 87 1/2 N of COR to 19.20.29.30
Corrected Line WEST. SET E 1/8 on S.
Line in open swamp
S 1/4 P. { Y. Pine 10 N 86 E 73
.. .. 88 1/2 N 86 E 62
W 1/8 P. S. Line { W Pine St P 24 N 73 E 15
100 others near

This is all parties want done at present
They own S E SW & SW SE. S E SW is ~~over~~
1/2 LKE

Dec" for correction 1090 change course 6° 15'
copied on ~MAY 17 = May 21 new record
I did not have my notes for S.W. COR
yesterday. but have them now, and find
the post should be 12 links farther N. but
post I had it located exactly E + W
and I moved 1/4 Post and 1/8 Posts
into line, ALSO TOLLEY STAKES.

Had to change course & distance of
bearing at 1/4 Post + 1/8 Posts

Copied on Page 1 new record

110 SEC" 136.8 JUNE 14 1918

N.E. Cor. found an iron Pipe Set by Doerr it had Brick PLACED around. Org=4 trees gone NEW. {TEL POLE 10 S.E. 25 FEET

" " 10 NW 60 " copied on Page
Began 150 feet W of NE Cor. and on N Line)
See Pages 69 & 70 this book and Page 115
County Record) Run South at right
angles with N Line 1 new record
1588.5 feet fall 1.48-5W of 1/8 Post
Set by Doerr on iron pipe 8 inches below
surface. 2 feet North of south end of
large gate DEC" fo correction. 10/100
See Page 972 1/1000. Mailed Tally 283
E 29.2990

111

SEC" 25-42-5 JUNE 29" 1918

East from CENTER Var 2 1/2 E
2095 FELL 1 LK. N of 1/8 Post set by POWELL
1273 W of of 1/8 Post and 822. E. of
CENT S Post { Y. Pine 14S 44W 30 Var 4 E
{ no others near

Runs from this Post Var 445' E and
parallel with the N & S 1/4 Line
1227 to Lake and set m.e.

{ Y. Pine 10 N 21 1/2 E 11 1/2
" " 10 N 89 1/2 E 11

North from CENTER along old fence

3876 Var 4 1/2 E
3886 FELL 9 LKS E of N 1/4 P. found Post
had moved. Placed it in the
orig position CORRECT LINE. S
to 1/4 R SET 1/8 POST 19.38
{ W. Pine N 32 W 22

as org B.T. for N 1/4 Pos is a
stump quite rotten & faced new
and marked it again

112 SEC 23-42-5 JUNE 30-1918

SURVEYED A PIECE OF LAND FOR MRS HORNER AS FOLLOWS.

COMMENCING AT E 1/4 POST THEN SOUTH ON SEC LINE 4.20 CHAINS (SEE PAGE 67 THIS BOOK) AND SET POST $\frac{3}{4}$ Y. PINE 14 N 85 W 23 THENCE AT RIGHT ANGLES FROM E LINE 1000 TO LOW GROUND OR OLD FLOWAGE. AND SET POST. THEN NORTH 30 LKS TO LAKE OR FLOWAGE. HAVE RUN THE E + W 1/4 LINE FROM E 1/4 P TO LAKE. SEE PAGE 66

SEC 14-42-5 JULY 1. 1918

A PIECE OF LAND IN LK 10

COMMENCING ON E LINE 25 FT N OF THE S.E. COR IN CENTER OF ROAD THENCE N ON THE E. LINE 742 TO LAKE AT MC AN IRON PIPE THENCE N. 72° 45' W 280 FT OVER BAY OF LAKE

" S 47 W 467 " TO THE RIGHT OF WAY OF SAID ROAD. THENCE SOUTHWESTERLY ALONG SAID RIGHT OF WAY 880 FEET TO THE PLACE OF BEGINNING

SET AN IRON PIPE FOR POST INTERSECTION
RIGHT OF WAY { Y. PINE 8 N 70 1/2 E 21 4 FEET
" " 10 N 10 E 29 4 "

copied on Page 151 New Recd

SEC 36-35-11 JULY 7" 1918 113

NW COR. I SET THIS CORNER 4 YEARS AGO SEE COUNTY REC'D FOR SE COR. OF 26-35-11. TODAY I FOUND THE PINE BT. HAD BEEN SAWED DOWN 8 INCHES ABOVE THE SURFACE, AND THE SIGN POST PULLED UP, BUT FOUND THE COR 6 INCHES BELOW THE SURFACE.

RUN EAST VAR 3.30 EAST 4008 FELL 2.97 NORTH OF N 1/4 P. FOUND THE SUGAR DOODM AND ROTTEN, BUT MAKES OK " ASPENS " " MARK NEAR 250 GONE. SET POST AND MADE NEW BEARING, SUGAR 10 N 1/4 W 23 1/2 CORRECTED LINE

WEST TO COR FOR ROAD
DEC 7.41 CHANGE COURSE 4° 17'
CORRECTED VAR FROM W 647 W

SET W 8 P. ON N LINE DID NOT SET IT
copied on Page 151

EAST FROM N 1/4 P VAR 3° E
40.68 FELL 469 N OF NE COR FOUND ORIGINAL TRES - DEC 11.50

CHANGE COURSE 4° 39' VAR 3.39 W
SET E 1/8 ON N LINE. (BIRCH 10 N 69 E 26
CORRECTED LINE WEST FROM 1/8 P TO 1/4 POST
FOR ROAD FOR THE TOWN OF SHOCKEY
NEW COUNTY RECD DTHURSTON

114 SEC 11- 39-6 JULY 11- 1918

A piece of Land in gout Lot 4 SEC
11 39-6 commencing at a Point which
is N 47° 15' E and 1275 feet fr^t the E 1/8 Post
on the West Line of Said See. 11 which is
an iron Pin, and an oak tree stands N 82 E 9
feet distant.

Thence N 43° W 60. feet there s. S. 47° E 75 feet
Thence S. 43° W 60 feet. Thence N 47° 15' E 75
feet to Place of beginning This Piece of
Land is an addition to a piece of Land which
is Surveyed for A. J. Balger Jan 30 1916.

ALSO a piece of Land described as follows
commencing at same point. Thence N 43° E 60
feet. Thence S 47° 15' E 75 feet Thence S. 43° E 264
feet. Thence southeasterly along shore of lake
to an iron pipe which stands 75 feet from the
line running S 43° E. measured at right angles
Thence N 43° W 240-3

A PIECE of Land in Lot 4 SEC. 11. 39-6
commencing at a cedar Post which stands
N 47° E 1275 feet from S 1/8 P on West Line. Thence G
N 47° E 75 .. Thence N 43° W 60 feet Thence S 47° W
75 feet. Thence S 43° E 60 feet to place of beginning

PIECE NO 2 = commencing at a cedar Post
which stands N 47° E 1275 feet from S 1/8 Post betw.
SEC 2 10+11 Thence N 43° W 60 feet Thence S. 47° West
75 feet. Thence S 43° E 264 feet. Thence northeasterly
along shore of lake to an iron pipe which is 75 feet
measured at right angles. The C.G N 43° W 270 feet
to place of beginning PIECE NO 3

commencing at cedar Post which stands N 47° E 1200 feet
from S 1/8 Post on line betw. sections
10+11 Thence N 43° W 60 feet Thence S 47° W 75 feet
Thence S 43° E 240 feet to an iron pipe on shore
of lake. Thence northeasterly along shore of lake
to an iron pipe 75 feet measured at right angles
The C.C. N 43° W 264 feet to place of beginning
bearing for 1/8 Post looking N 82 E 15 feet. bearing for
cedar Post 1275 from 1/8 P and N 47.5°
{ 1. Pines 8 N 6 W 9 feet
{ W " 8 S 48 1/2 E 7-3 feet

JULY 11+12-1918

115 AUGUST 10-1918 SURVEY OF ROAD FOR

THE TOWN OF SCHOEPKE Copied

commencing at the 1/4 Pos between
Sections 27+28 in Township 35 north
Range 11 East. Thence on section
Line 3900 chains to corner of Sections
21+22. 27+28 on. Page 151
Thence North 1925 chains to Pelican
Lake and Brandon road at a point said
to be the South 1/8 Post on line between
Sections 21+22

WHOLE LENGTH of road SURVEYED 5825 chains
course and distance above given
are center and line of road.

SEC 28-35-11 AUG 9+10 1918
East 1/4 Post. found steps of org: trees
Run North Var 3 1/2 E
1400 Enter swamp on exactly on org: line
2600 Leave " "
2200 Enter " "
2700 Leave " NEW Record "
3000 Enter " "
3800 Leave " "
3900 did not find car but set pos "

August 14 & 15 1904

¹¹⁶ SURVEY OF ROAD FOR TOWN OF PELICAN

1/4 Post betw 16 + 21. 37-10 E

This 1/4P is in edge of field bearings gone
but Post is OK. HESS has promised have an
iron pipe placed where Post stands

Run E ast. Var 4° E 1 1/2 East

1500 Stream 10 runs SW

3739 fELL 8.8 N of CORN Stp's to org. trees at
Corrected Line west to 1/4P for road

Posted on Page 151 11260 Record

E ast from cor to 15-16-21-22 Var 3 1/2 E

8377 fELL 12.48 N of CORN road. Is set this
Post when surveyed road for Town of Pelican
Dec 14 for correction 14.89. change course 8.30
correct var from WEST to E 5° WEST

Corrected Line west to cor

Did not find 1/4 Post or set new one

1500 Stream 25 runs South

SEC 30-43-5 Sept 10-1918 ¹¹⁷

^{Stps of E}
N. 1/4 P. Found post & set from org. trees
in Oct 1911 marks are gone on Stups
nothing near for be arms
Run South Var 4° E

10.00 Enter ALDER bottom

18.00 WINCHESTER Spurr of C. + NW RR.

1985 Stream 20 runs SWESTERLY

3247 INTERSECT LANK Lake it extends E 7.00
6725 O UGLY LAKE by triangulation offset

East 3.00 on South Shore of LAK. flag
on north shore is N 830 W

8569 fELL 1.22 E.O.F. 1/4P. & SET 7 years ago

SEE Book 7 Pages 36 + 38
MADE NEW bearing 1/4 PINE 14.822 W 1.18
Dec 14.37. change course 50° Var 3-10°

E ast from N 1/4 Post Var 3° E
500 Stream 25 runs South change course 440
1050 WINCHESTER Spurr Var 14.6 W

3961 fELL 324 N of NE cor. found Post by
Dorr & DHU E BT down marks OK

W Stp is very rotten & burned no marks
South from NE cor Var 3° E

250 leave swamp

1000 Enter "

2500 LEAVE "

32.00 Enter "

3952 fELL 1.35 E. of m.e. found west tree dead
and broken off just above marks which
are OK. found Stp of Spruce no marks
found an overrun of 3.76. proportion
Same and 8gt 1/8 Post at 2 1/10 and 68.39/100
WEST of Random. Change course 1.57. Var 13°

WEST from N 1/8 P. on E Line Var 5° W.

7854 fELL 2,15/2 S. of Dorr's 1/8 P in center road
found distance on corrected Line to
N & S corrected 1/4 Line 8.73 and
the N 1/4 P is 1.80 SOUTH of true
Line Line bet N.W. and NE corners
Set 1/8 Post # North of center at
18.95 S of N 1/4 P and center would be at

SEC 30, 43-4 cont'd Sept 14, 1918

3790 South of N 1/4 P and in Tank Lake
 Set E 1/8 P. on N Line { Hem 10 N 3 E 48
 " " 6 S 8 W 37

South from E 1/8 Post on N Line ran 2° E
 1000 Var is now an even needle
 2196 fell 87 W of 1/8 Post in NE 1/4 and
 *** 1986 W of 1/8 P on E Line, and same
 dist. from 1/8. P N of center.
 Corrected Line from E 1/8 P. on N Line
 on to 1/16 P. and prolonged it south.
 This Line is supposed to intersect LAKE
 Martha at about 2500 ft 3160. Grown over
 *** 1/16 Post in NE 1/4. { Tam 7 N 5 E 14
 " " HEM 7 S 80 1/2 W 61

found. The distance from center of
 SEC to N 1/4 P 4013 + to South 1/4 P 4556

Set 1/8 P # South of center at 2263
 no bearings

East from 1/8 Post South of center
 Parallel with South SEC Line
 and run E far enough to intersect
 E 1/8 Line on South shore of what was
 Lake Martha now grown over

Set M.C. on South shore of Tank lake
 and on N + S 1/4 Lines { Birch 14 S 79 W 26

Rained Rained Rained

finished Sunday Sept 15-1918
 and came home at 11:45

SEC 2. 35 - 9 Sept 28. 1918¹¹⁹

NE COROK both LINES green
 Run South Var 4° E

500 Enters swamp
 4000 did not find E 1/4 P.
 7563 fell 2. M.E. of S.E. COROK
 Found a shortage of 3.52
 Proportioned shortage and set
 E 1/4 Post at 31.38 South of NE COROK
 Timber all dead no bearings
 # N 1/8 P on E Line at 1869. S. of COROK
 { B. ash 12 N 1/2 W 32
 " " 8 S 51 W 12 1/2

Set S 1/8 P on E Line at 3825 N. of S.E. COROK
 Nothing for bearings
 Run a Line WGS from N 1/8 P on E Line
 about 2000 ch to someone's line
 chained 10.00 and broke tape

N 1/4 found post & set from org trees in 1904
 Run South Var 3° E. Run South Var 3 1/2 E
 80.00 Set Line stakes, and we all
 searched for S 1/4 P. but had no success
 came home as I have promised to go to
 27+34-38-11 on Monday then will go
 back and finish when I come home

Copied on pages
 New Record

went to NW cor. found Post, a very old one and cruisers marks made many years ago. But the org^{nt} + reg^s are gone.

Run South Var 3 $\frac{1}{2}$ E.

500 LEAVE SWAMP


6800 to wet boggy swamp, has been lake
7273 over swamp

7476 offset N to miss Porch of Peaks house

8226 set line stakes and looked for corner
and m^corners, but did not find them
Found a post said to be N 48 on E. Line

Run South Var 3 $\frac{1}{2}$ E

38.89 fell 78 E of someone's 1/4 P no good
but came to 1/8 again corrected line
From 1/4 R but it was N.C. as it made the
NE Cor and m^c N. of it way to far East
will locate cor by chiming bout from lake
106 Then run W. 642 as called for in US notes
and try until find the point where these
two measurements will agree with shore
of lake and establish the N.E. cor at that
point Oct 1st 1908



Determined point where cor^{nt} must be
and drove a small iron rod nothing but Bt^r
8041 fell 209 south of NE cor.

Set E. 1/8 P. on N Line at 60.3 $\frac{1}{2}$

notating for bearings.

Set N. 1/4 P. at 20.10 nothing for bearings
could not locate the west shore of
lake, lake has grown over, and west
shore is swampy but the shore
corresponds very close with distance
given in U.S. notes

went to NW cor. found Post OK made
new bearing & Aspen 14S 66' 12W. 39

Run South Var 4 $\frac{1}{2}$ E

1800 enter creek bottom

1950 creek 20 runs SW

2200 leave bottom & enter swamp & low ground

5800 stream run SW

8 663 fell 6 lks^s west of cor^{nt} found my
old post and st^p of SW org tree

Set S 1/8 Post on W Line at 2141

{ sugar 28 N 45 E 1 link
{ hem 14S. 68 W 27

East from S 1/8 P on W Line Var 3 $\frac{1}{2}$ E

2500 stream 20 R W of NW

8334 fell 98 N. of S 1/8 P. one little. which I
set in August 1907. SEE PAGE 208 Dens
Book of Field notes and Book 5 Page
138 of my private record.

as I have run all exterior lines of this
sec^{nt} and set th N 1/4 P. East 1/4 P and

1/2^o west 1/4 P. and found the orig^{nt} S. 1/4 P.

and know it stands at links N of line

line and now set 1/8 P. south of center at 4127

EAST of S. 1/8. Post on W. Line. This 1/8 P. south

center is on N + S 1/4 line. I run the N + S 1/4
Line now: 131905 { 1/8 P. S. of center

new point { Spruce 10 West 7 lks
Corrected line from 1/8 P. S. of center

WEST and set 1/16 P. in SW 1/4 at 2063 $\frac{1}{2}$

{ sugar 7 N 62 E 29 $\frac{1}{2}$

" 8 N 85 W 21

South from 1/16 Post Var 4 $\frac{1}{2}$ E

2158 fell 13 W of 1/8 which I set in August 1907

corrected line N to 1/16 P.

123 SEC "36-39-6 Oct 16-1918

I want to locate a piece of land in Lot 4 on which J.A. Olmsted has built a boat house and must restore N 1/4 Post now gone and as I have used this 1/4 to survey an island for U.S. Government it will refer to my notes made at that time May 1903. See Page 74 Dorr's book of field notes. found E. me on island but where on island is gone. Run West from this E me. to NW Point of island Var 4° E.

2935 found original line 10 LKS S of my Rand and set 1/4 Post { W Pine 11 N 89 1/2 W 1.22

Began at a point on see Line 1.50 west of 1/4 P and run south at right angles to see line 600 off see W 136 9.72 fell 68 E of a monument on shore of lake which is 3.54 W. of 1/4 Post and at right angles to see Line

then surveyed the piece of land on which J.A. Olmsted has erected his boat house

commencing at the monument above mentioned.

Then N 16° E. Var 4° E. 65 feet

" W at right angles 60 "

" S 76° W at right angles 94-5 "

" Easterly along shore of lake about 63 feet to place of beginning.

Made bearing for monument on shore of lake at place of beginning.

J. Pine set 16 N 11 E 27-3 feet

SEC 12.35-10 Oct 26 1918

123

S.E. cor' made new bearings

{ Spruce 10 N 43 E 81 about
fir 10 S 65 W 51

Post is 10 links W of an old post which has been used for corner

Run West Var 3 1/2 E.

1700 leave swamp

3300 enter "

4396 fell 430 South of 1/4 Post. both

trees are down found an old post and a line running from it

new bearings } Tam 5 N 65 W 19
Spruce 10 S 15 W 32

Set E 1/8 Pons { Lime sugar 12 N 54 E 49 1/2

Cherry 18 N 33 W 12

corrected line E to corner

North from S.E. cor' on my Rand of Lasting and see 1/8 Post 1980 North of S.E. cor

Birch 12 N 58 W 36 1/2
" 108 55 W 52

E. 1/4 P found Dorr's bearing fir 10 S 57 E 85

His Post had been moved. restored it and made new bearings } Nothing near

Oct 30-1918

Run West Var 15' W

1600 enter swamp

4183 found Post set by Dorr on his corrected E + W 1/4 JS 12 North of line

N 1/4 P trap has been cut. sugar ok

Run South Var 64 1/2 E east

3950 cross Dorr's corrected 1/4 line E of far

7906 fell 35 W of S. 1/4 P

Center of see Birch 16 N 55 E 16
Hem 10 S 72 W 23

Dist. to N 1/4 P 3956

" " 3950

" " E " 41 83

" " W " 41 83

1/8 Post E of Center { Birch 7 N 38 W 34
Cedar 8 S 44 E 23

South from 1/8 P.E. of Center Var 645
3960 fELL 7 1/2 W of 1/8 P

Set 4/16 Post in SE 1/4. at 1980

WEST { cedar 7 N 58 W 15
" " 6 S 36 E 12 1/2

~~WEST~~ ~~EAST~~ from S 1/8 P. on E Line Var 30° W
2144 FELL 46 N of 1116 Post

Corrected Lines around SE.S.E. and set
iron pipes posts at the 4 corners
at SE corⁿ. The pipe is 3 links E of
true cor as it could not be driven.
At the true corⁿ.
The S^tat road is 8 Lks West of SE cor

At the request of Mar Banta
I have computed the acreage
which is 42,981/100

Deel Deducting The road from the
42.98 acres. $42.98 - 1.85 = 41.13 \frac{1}{100}$
acres

118 PS 8
Branch 10 S 82 E
10 N 24 E 10

E 1/4 Post found Post in July 1911 ALSO my bearings made at that time. Run West Var 3/26
6342 to wet marsh

7074 0061

8002½ set line stakes and went to the NW cor found an iron manⁿ. Post. + bearing found post and bearing W Pⁿ N^e 51° 18' S 57. E 54 which fit and made July 1911.

SEE Dorr book of field notes Page 93

Run South from 14° E 3810 crossed E & W road 7.15
E of TALLEY 80.02'2

1970 found a Line Spotted E+W but no com
Line was only 16 years old set line
stake at 800m. WILL SET TOWARD BOARD
OF SUPERVISORS tomorrow.

Picked up E + W 1/4 Line and set
Temp " 1/4 P at 38° 25' South of NW Cor:
and T928 WGST of East 1/4 P found random
was 891 North of Post. Set Post and
made new bearings} aspen 10 N 45 W 65
Post is E of R.R. of way { W. Pine Stb 14 S 40 E 74
Went EAST and at S ET TGM. 1/16 P.

126 SEC = 10° 38' 7" NOU = 14° 1918

and E + W 1/4 Line of 9

CENT OF SEC. found an iron pipe in west side of road and stump of Dorrs bearing Run E Var. E.

2000 hit Dorrs 1/8 P. now replaced with fence Post # orig Post is her L. Pittley said he set fence post exactly where 1/8 Post stood 4000 Set 1/4 Post found a part of Stump of the NW org tree. NOU 15" — NE Birch 10 N 25W 58 WEST from cent on same course as had run E 3993 Set WEST 1/4 Post { W. Pine + 28 Stump 12 S 54 1/2 E 8 Countinued E + W 1/4 in SEC 10 West into SEC 9 on same course

4116 Set Post about 250 East of WEST shore of Little Carr Lake { S. Pine stp 18 N 40 W 5

" " " 24 S 50 1/2 E 66
The E + W 1/4 Lines in SEC 9 + 10 are for road
= NOU 16 = 1918

SEC = 11 - 38 - 7 NOU = 16 - 1918.

127

W 1/4. SEC 10. Run E. ast Var 4° E at E 1/4 P Var is 275 PROLONGEING EAST into this sec At 4000 Var is 10° E.

" 5500 " " 4 E

7990 HIT IT

Began at a stake which stands on WEST line of State road from which a W. Pine Stump 16 bears N 3° E about 25 Lc Then began SURVEY ROAD AS FOLLOWS

Then C E S 42 W 239

"	N	85	W	281
"	S	86 1/2	"	791
"	N	87 1/2	"	260
"	"	79 1/2	"	168
"	"	28 1/2	"	212 at 183 on this course + 1/4 Line
"	"	49 1/2	"	195 at 4930 E of W 1/4 Post and
"	S	69 1/2	"	155 - 3060 WEST of E 1/4 Post
"	"	69	"	251
"	"	84	"	210
"	N	85	"	145
"	"	70	"	247
"	"	76	"	120
"	S	57	"	205
"	"	40	"	283
"	"	40 1/2	"	142 to E + W 1/4 Line E. of W 1/4 P of SEC 11
"	W on 1/4 Line 1/2	Set Post	{ W. Pine	88 88 E 61
"	N	44 1/2	W	509
"	"	48	W	740
"	"	30	"	642
"	S	51	"	843
"	"	62	"	652 to E + W 1/4 Line in SEC 10
"	"	739	W of E 1/4 P + Set Post	{ S. Pine 10 N 52 E 35
"	"			{ aspen 10 S 69 E 29 1/2

¹²⁸ SURVEY OF ROAD FOR THE TOWN OF

Tomahawk Lake, nos^o 13 to 22" 1918
Commencing at the N.C. where the E + W
1/4 Line of sec^o 9. Township 38 N. Range 7 East
intersects Little Carr Lake

Thence E east on said 1/4 Line 4116 to 1/4 E 1/4 P of 9
" " " 1/4 Line in SEC 10 3993 .. 1/4 P b e^t 10+11
or to a lake which stands on 1/4 Line 3993 N of E 1/4 P
of SEC 10 - - - - - 3 W. Pine B # 89 E 35

Thence N 22 E. 652 { - smoother

"	N 51	"	843
"	S 80	"	642
"	S 48	"	740
"	S 44 1/2 E		509

S 44 1/2 E 509 to a stake which is on E + W 1/4 Line and
1710.E. of W 1/4 1/4 P lot sec³ 10+11
Then E Easton 1/4 1/2 to a stake in W line 8S. 88 E 59 1/2

"	N 40 1/2 E	142
" 40	E	283
" 57	E	205
S 76	"	120
S 70	"	247
S 85	"	143
N 84	"	210
N 69	"	251
N 69 1/2	"	159
S 49 1/2 "	"	195
S 28 1/2 "	"	212, 183 on this course, cross E + W 1/4 Line
S 79 1/2 "	"	168, 4930 E. of W 1/4 Per of Sec 11
S 87 1/2 "	"	260
N 86 1/2 "	"	797
S 85 1/2 "	"	281
N 42	"	239 to west line of new state road and set post { W line stp / 6 N 30t

Instrument adjusted on 4th East Van for Survey
of above road Novth 21st 1918

$\frac{18668}{26 \frac{3}{5}}$ rods = 2 1/4 miles 66 2/3 chains or

Survey of road for Tomahawk Lake Nov 22, 1918
commencing at the east 1/4 Post of Sec 12 in
in Township 3 S. N. R. 7 E.

Then west on 1/4-mile	5762
" N 27 1/2 W	2024
" 81 1/2 "	1725.150 W to S E C Line
" " 71 "	0626.719 to W Line of
" " 79 1/2 "	540 Right of Way. C & W

To East Line of State high way
and SEC Post {W. Pine Stump¹⁰ S 10 E 24.
Whole distance 107.47 = 1 1/4 Miles and 32 Rods.

130

SEC. 12-36.4 DEC. 9th 1918

S.E. COR: org tree S. Run West Var 4.30° E
3677 FELL 5.94 North of S. 1/4 P.

DEC 1.49. Change course 8.30°
Corrected Var 13° E. 41° E

E 1/8 P. on S Line { maple 7 N 41° E
Hem 9 S 55° W 9

S 1/4 P. org trees Run north Var 4° E
8724 FELL 4.60 E of N 1/4 P. org trees
DEC 5.27. Change course 3°

N 1/4 P. OK. Run east Var 4° E
4041 FELL 108 N. of N.E. cor org trees
DEC 2.67. Change course 1 1/2°
Corrected Var 2.30° E

E 1/8 P. on N Line { no bearings given
copied on Page 49 small books of courses

S E COR Run N. Var 4° E
8057 FELL 182 E. of NE COR Record

DEC 2.258 change course 5° 42'

N 1/8 P. on E Line { Hem 14 N 58° E 17 1/4

maple 10 S 8 1/2 W 6
Sugar 20 N 33 W 15 } S 1/8 P. on
Birch 12 S 43 W 19 } E Line

S 1/8 P. on E Line { Birch 16 N 40 E 51 } E 1/8 P.
Hem 14 S. 45 1/2 W 18

WEST from E 1/4 P. Var 3° East

8225 FELL 102 S of W 1/4 P. DHV SGT last fall
from org BJ. SEC 11. 36-4

DEC 1.24 change course 42'
Center of SEC { maple 20 N 3.8 1/2 E 5 1/2
" 18 S 31 W 25

Distance to N 1/4 P 399 1/2

" " S 47 33 1/8 P. S. of center
" " E 38 70 Birch 24 S 10 W 3
" " W 43 55 Hem 12 N 45 E 10

1/8 P. N of center { Birch 12 S 75 W 18
Sugar 22 S 88 E 39

1/8 P. " " NO bearings given

West from S 1/8 P. on E Line Var 8. 10'
3781 FELL 3 Lks S of 1/8 P. East from 1/8 P. S of
center Var 39 61 FELL 63 North of 1/8 P.

SEC 12-42-5 Jan 6 1919

131

me on south shore of lake on
west line. found the stp of org tree
it is has marks ok. made new
bearing { Root of W Pine. Stp 185 22 W 62.
Run N Var 4° E.

2400 OVER LAKE

2550 " flowage

4705 FELL 4.27 W of cor set by me in
sec book J. Pages 137 to 142

DEC 9.50 change course 5° 12'
correct Var 1° 12' W.

Set 1/4 P. on E 7.18 N of me

" N 1/8 on W Line 200 N of lake 2 flw wgs
W 1/4 P. Run E Var 3° E

8064 FELL 2.42 N of 1/4 P.

DEC 3.0. change course 143°

N 1/4 Post. OK. See Book 3 Page 137 to 142

~~1/4 P. on E Line Run E. Var 1~~

N 1/4 Run South Var 2° E

800. to lake

2000 over "

1970 FELL 1.42 W of S 1/4 P. 10 1/2 B. T + Pw
DEC 1.674 change course 54°

Center of SEC { Y. Pine 15 N 43 1/2 W 40
(W " Stp. N 77 1/2 W 65

Dist to N 1/4 P 40 17 Dist to E 1/4 P 40 29 1/2
" " S " 39 53 " " W 1/4 P 40 32

1/8 Post N of center { W. Pine Stp 20 3 19 W 29
" " " " Stub 18 19 E 17

1/8 Post W of center { W Pine Stp 18 N 60 W 23
" " " " 12 S 63 E 23

N 1/8 P. on W Line No BT Post is 200 N of lake

West from 1/8 P. N. of center Var 0. on offset N
of 505. as point extends about 500 N of 1/8 Line
2200 LEAG Lake

3907 FELL 6.52 N of 1/8 P (no bearing) at

147 N of true line

at 10.00 on corrected line. West of 1/8 P.

Point is 2.00 S of off line 4.5.05 N of 1/8 P
or Point extends 3.00 N of 1/8 line as corrected

133 SEC " 12-42-5 cont Jan 18-1919.

North from 1/8 PW of center var 2° E.
 800 to Lake
 1700 over Lake at 1250 on this Line Lake
 Extends east 400
 2550 to Lake //
 2693 fell 22 W of Camp Post on Line as
 Corrected on offset line.
 Land at this point extends N of 1/8 Line 3.62
 and 500 E of this point. Land extends 5.50
 North of true line
 Corrected N+S 1/8 Line south to 1/8 P
 West of center
 Corrected E+W 1/4 Line from center
 West to 1/8 Post
 finished at 4.45 P.M.
 and came to Deer Park Lodge 545

SEC = 14-42-5 January 19. 1919
 Began at center of SEC which set
 about 4 years ago. and runs out on corrected
 line to south shore of bay to Spider Lake
 prolonged line south 1077 to N Shore of
 Manitowish Lake { J. Ping 12 for me.
 Then N 72 E Harbor 541 and 50 Lks. Fr. H.W. Mar
 S 80 " " 330 " " " " "
 N 89 " " 765 " " " " "
 " 64 " " 583 " " " " "
 " 11 W " Birch 533 " 25 " " " "
 " 19 E " " 323 " " " " "
 " 22 W " " 354 " " " " "
 S 23 E " " 403 " " " " "
 N 26 W " " 833 Saloon 50 " " " "
 N 46 W " " 261 " " " " "
 S 39 W " " 456 " " " " "
 S 59 W " " 1024 " " " " "
 N 88 1/2 W " " 166 " 25 " " " "

Melinda

133 SEC 28 41-8. March 11. 1919

NW Cor found my B.T.s made in
 Jan 11 1908. Hem 12 NN 16 1/2 E 18
 8 S 558 W 16.

Run East U Cir 4 1/2 E

2675 to Lake

6900 over Lake

8348 fell 4 1/3 South of NE cor. N.E. Brdg ok
 deer 509 - change course 30°

Set m.c. on W Shore of Lake at 2619
 W. of NW. cor { Cedar 6 N 9 W 24 1/2
 " " 7 S 41 E 31 1/2

Corrected line W to cor " Var 5° 05'
 Went to me on N. Shore of Lake on W line
 found my bearings made Jan 10. 1908. when
 I set this m.c. from Stump of orig tree.
 Run North U Cir 4.30 E ast

2065 fell 1 1/2 Lks W of cor

Corrected line 300 South from
 corner, and 450 N of me.

Angle at NW from N. line to W line
 is 90° 05'. Prolonged W line as
 corrected south from me ~~about off on~~

of 90° 5' and run E 800 feet measured
 8 feet from N.W. 800 feet about 200 feet
 on corrected west line then E at RT
 angles 800 feet and set post on ice. Then
 measured E. from E from NW cor on
 N. line 800 feet then south parallelly
 west line 1148 feet and set m.c. 15
 FEET N of shore of lake { Hem 7 N 13 E 23
 WP Meios 44 W 12

It is 37 feet E of me to Warner's cor.

" " 27 " W man laws
 " " 12 " from " man laws on W line to lake

The N line at me is about 70 feet
 south of some ones N.E. Deer Lake shore
 The NW cor man laws property is
 about 25 feet south of line

* Birch 20 N 58 1/2 W 20-4 feet Birch 15 72 E 21 1/2
 Hem 7 S 23 1/2 E 12-5 " man laws N.E. 1/2

¹³⁴ SEC 31-36-7 March 17, 1919

at N.E. cor. found my bearing made
in June 1908. C.W. Pmg 26 N 9 1/2 W 75
also the NW org. tree lying down
Run South Uvar 4° E.

1293 center of Soo RR track

1450 enter swamp

2760 stream copied into

28 over "

7968 fell 227 E of corner. Found
8 E "ps" of original trees. Set new post.
Set 1/4 Post at 39.84. nothing for BPs
" N 1/8 " 19 9 2 spruce 7341E 5 1/2

Corrected Uvar 20° 34'

WEST from N 1/8 P on E Line Uvar 4° E

2839 center of Soo RR track

7640 stream 25. Pms. 8 SW rapid

8095 fell 82 south of 1/8 P which I set June
13-1908. SEE Book 6 page 30. also Page 52
County Record. corrected line west

at 4047. Stream is 1140 south, and center of
Soo RR track is 290

at SW cor of NE of NE Soo RR at cent is 1.62. N.
and stream is 850 south.

Center of Soo RR is 12.93 south of NE cor.
and 7.01 ~~SW~~ North of 1/8 P on E Line

* Stream is 706 south of 1/8 P. and 1407
south of RR.

It is 7.75 easterly along Soo RR track
to a point where stream intersects
the right of way Soo RR

there is a curve in Soo RR track near the
center of the NE 1/4 of SEC 31 - track

bears more to the North

County Record [#] 1919

March 24 ^{Entered} 1909

on Page 125. New record

⁵³⁻¹³³
SEC 33. 39-7 March 20, 1919 ¹³⁵

Began at center of SEC set by
B.F. Dorr. and prolonged N+S 1/4
Line South 10.00

Then west at right angles 1000

South at " 9.33 to

shore of lake. copied on page

thence S 36 E 6.50 ¹³³

" 365 E 4.00 ¹³³ new record

" S 49 E 4.00 to a point where
N+S 1/4 Line intersects lake
thence N on 1/4 Line 18.90 to an iron
sp pipe which stands on N+S 1/4 Line
and 10 chains south of center of SEC

SEC 34-36-8, April 4 1919

SEC cor SEC pages 61 & 64 Run west on state road
Uvar 4° E } CGdar 10 IV 26 W 49

3997 1/4 Post on LINE } .. Y S 7 E 54

E 1/8. P. on S. Line. S. Gt a hub for post and
placed a stake 37 1/2 LK N+S of hub

West from S 1/4 P. Uvar 6° E
4000 to SW cor { W Pmg 10 N 37 1/2 E 58 5 ft high

{ Stp 1/4 S #1W 43
SEC stakes both N+S. and 37 1/2 LK from cor
" W 1/8 P. on south line. placed Blake S both
N+S of hub in road which is 1/8 P.

25 JULY 1909

136 SEC 28-37-7 April 14 1919

Went to E 1/4 Post which I set in May 1912. See Book 7. Also Count Record Page 4 or Dorrs Record offield notes by 87
Run West Var 4° E

7924 FELL 80 South of W 1/4 P in center of N & S road, at the intersection of road from the west. Made new bearing { W P St 16 S 82 E 122 1/2 14.. 18 N 58 W 55 ✓

Corrected line from 6.000 ch. E. to 1/4 P
April 18

North from S 1/4 P. S.G.E., in May 1912 See County record marked Dorrs notes. Page 87 7988. FELL 153 W of N 1/4 P. Set by Ira Smith. made new bearings 1/2 Pm 14 N 1/4 W 190 ✓

Run West from N 1/4 P on cutout road 2014 Smith's 1/8 P on Line Posted on Page 4028 NW corner Ling found NE step of old tree { NEW W Pmest P 16 N 32 1/2 E 46 16 S 15 W 62 WEST FROM N SOUTH From NW cor in road 3998 to Flag at W 1/4 Post Set N 1/8 P. on W Ling { W Pmest P 12 N 52 E 41 1/2 12 S 42 1/2 W 35

CENTER OF SEC { W Pmest P 26 N 59 1/2 W 36 28 S 76 E 56
Dist to N 1/4 Post 3986
1/2 " " S " " 4002 Reused
New corner " E " " 3978
" W " " 3946
SEC 1/8 P N of cent { W Pmest P 10 N 71 1/2 W 26 1/2 Step. 14 S 11 1/2 E 93

SEC 1/8 Post W of center { " " 14 N 86 1/2 W 76 1/2 " " 14 S 49 E 70 "

WEST From 1/8 P. N. of cent Var 3 1/2 E 3982 + GLL 37 S of 1/8 P { W Pmest P 18 N 22 1/2 E 59 1/2 1/2 12 S 11 E 29 1/2 "

SET 1/16 P in NW 1/4 { W Pmest P 12 N 4 1/2 W 12 Var 1 1/2 E 12 S 68 E 30 1/2 For balance of 28 SEC bottom of next page

137 SEC 27-37-7 April 15" 1919

Began at W 1/4 Post SEC SEC 28 Run East Var 4° East

4054 fELL 18 S out of cent Set by C. D. Vaughn His bearings are { W. Ping St 18 N 66 E 41 1/2 var 4° E 16 S 70 W 8 var 4° E found he had corrected line E from center found his tally stakes all the way to E 1/4 P. brushed out the line and set some new stakes and brightened old ones North from center on corrected line 4010 Kit N 1/4 P. new Bts; W Ping St 10 S 51 1/2 E 34

Posted on Page 108 1/2 P. 18 N 76 W 68 E. from N. 1/4 P 700 LEAVE SWAMP 80.00 Did not find NE cor went to E 1/4 P and run N Var 4° East

April 16 1919

North from E 1/4 P Var 4° E 1800 Ente Enter swamp 108 108 2900 LEAVE SWAMP Page 108 3735 FELL E of cor Found ALLEN'S Post and steps of old trees

SEC 28 37-7 cont April 21 1919

East from 1/8 P N of center 3 1/2 E

3996 FELL 12 N of 1/8 set by me in May 1912

Corrected line west to 1/8 P

Corrected line around SE of NW 1/2 and S 1/2 NE Posted on Page 108 new road Run South from N 1/8 on E Ling Var 2° E 1998 FELL 12 E of E 1/4 P corrected line west

138 SEC 28-37-7 April 14-1919

E 1/4 P. Set by myself in May 1912
Run W 1/4 N 4° E
7924 fell 80 south of W 1/4 P in center
of E & W & N & S Roads made new
Bearings SW Pine Stump 16 N 58 W 55

" " " 16 S 82 E 122 1/2
S 1/4 P set in May 1912 { pine stump 20 S 66 E 17 1/2
Run North 1/4 N 2 1/2 E } .. 20 S 15 1/2 W 5

7988 fell 153 W of 1/4 P set by Ira Smith
Mod G NEW Bdry Pines 14 N 14 W 190
center of SEC W. Pine Stump 26 N 59 1/2 W 36

Dist to N 1/4 Pos 3986 1/8 Post N of cent
" " S " 4002 W Pine Stub 10 N 7 1/2 W 26 1/2
" " E " 3978 " S Pt 14 S 1 1/2 E 93
" " W " 3946 "

1/8 P. West of cent { W Pine 14 N 86 1/2 West 76 1/2
" " " 14 S 49 E 70

West from N 1/4 P on cut out road
2014 Smith's 1/8 P on Line

4028 NW COR on line { W. Pine 16 N 52 1/2 E 46
NEW .. 16 S 15 W 62
NW COR Run South in road to Flag at W 1/4 P
3998 to W 1/4 P or

SEC Tree 136

139 SEC 16-36-11 April 5 1919

went to S 1/4 P & found Post by Dorr from org
trees Run N W 1/4 3° E
8246 fell 682 E of N 1/4 Post found Post A 862
where Dorr had set one His bearing is
SW Pine (now Stp) 12 S 77 E 80

Came South and at TALLEY 4100 corrected
line and found the center of SEC 1 1/4 LKS
E of my corrected line
Corrected line South to TALLEY 3200 ch
line passes through the corner of Cook camp
about 6 feet from NE cor.

Posted on Page 65 new co record

140 SEC 9-37-10 May 14 1919

S 1/4 Post set by me in 1898 B.T.S gone
Run N.E. 3 1/2 E North
1500 Stream 25 Runs SW
5700 Old Stella Lake Road
8215 fell 205 W of 1/4 P set by me 1909
B.T. Dead { W pine 20 N 85 W 30 1/2
made new ones { 10 S 35 E 23 1/4
Dec 2.50 change course 1° 25'

SW cor. S. Pine Stump is all that is left of org trees
- " NEW { S. Pine 12 N 44 1/2 W 54
{ W .. 15 S 78 W 49

Run N.E. 2° E 19.99 found an old 1/4 P
3998 FELL 11 N of 1/4 Post found stump of
S. E org tree + set new Post.

East from W 1/4 P Var 00
350 Enter SW corner
900 LEAGUE " Posted in new
7600 ENTER wet marsh
8195 FELL 12 LKS N of 1/4 & set in 1898 from
org trees. Went west and set center
of section S. W. Pine Stump 30 N 74 1/2 W 52
18 S 36 E 30

Dist to N 1/4 Post 4030
" S " 4185
" E " 4209 County road
" W " 3986
Set 1/8 Post South of center
Correct line from center WEST to 1/4 P
West line from 1/4 South to SW corner.
and set 1/8 P on W line { S. Pine Stump 24 S 62 E 48

Finished May 17 at 10 A.M. Nixon
has one of his disagreeable spells
always wants to do different from
what I want it done HE is a baby
about his food and a place to sleep
HE ought to live in a palace and have
servants to wait upon him

Sections 27 34-35 36-4 May 20 1919¹⁴¹

Began at cor to 2-3-34-35 Towns
35 and 36 N Range 4 E
This cor is lost but I restored it as
follows. T U.S. Surveyors notes say
W. bet 2+35-7950 Stream 20 runs NE
8000 set cor to 2-3-34-35 Then west bet
3+34-129 same stream runs S.E. I found
stream had not changed its course.
found the two points mentioned in field
returned by US Surveyor and set corner
by measurement between points
{ W. pine Stump 30 N 34 1/2 W 126

Run N. var 4° E Posted on Page 146
1175 Soo R.R.

8169. FELL 277 W of cor to 26-27-34-35
found sugar ok set new Post

West bet 27+34 var 3 1/2 E
2500 Enter swamp back of 36-4
3800 LEAGUE " "
1060 Somes 1/4 P. but not the org
6075 " 1/8 P
" OFFSET SOUTH 1/4 New record
8069 FELL 127 N of corn road OK
this includes offset



SEC 19 368 May 27 1919
Began at N 1/8 Post on E line. Set
By Dorr and run west N 4° E
2475 to squash or long lake and set
" in { S. pine 10 S 89 E 35

The south line of this runs on 4° 15'
" North " " " 345
" E + W 1/4 " " " would be 415
1/8 Pine "

Posted on Page 76. Record of 36-8
New record

142 SEC "34-36-9-E June 31 1919

Began NE cor ~~sec~~ see NW cor 35 on
page 121 this book, and page 141 County
Record. Run W Var 4° E.

4193 FELL 84 1/2 N of N 1/4 Post set by Dorr
in 1897. Found cedar + double birch both
down. Post badly burned. Set new cedar
Post. NEW bearings. Bould 4x6 NW + S.E. with
yoke bearing 84 E 30° E. This shaped ~~hole~~
HOLE on W. side. It is about 3 inches deep and
and is about 3 inches on each of its 3 sides XXX
before correction 2000. Change course
1° 10'. CORRECTED VAR 2° 50'
= JUNE 5 =

WEST from N 1/4 Var. 3° E

1100 enter swamp

3300 leave " Copied on Page 1324

3700 Enter "

4178 FELL 1/63 N of NW cor

found Post in center of road.
bearings made by Dan gone nothing
near to make new

south from NW cor in road Var 3° E

4182 07 FELL 40 W of cor.

found org. bearings all down
and nearly burned up. nothing
for NEW ones

Run E from SW cor Var 3 1/2 E
= JUNE 6 1919 =

1450 Met SWamp

2675 over " New county record

4149 FELL 27 1/2 S of S 1/4 P. Found ~~old~~
east org. dead marks OK. VVGST
one down + rotten { NEW MEMO 50 1/2 29

East from S 1/4 P. 4° E

4181 FELL 199 1/2 N of cor found Post?

Set about 10 years ago from org trees
made NEW bearings } ELM 16S 68E 52

Set E 1/4 Post from random of Oct 1918
} Birch 8 S 8 1/2 W 16
} Spruce 8 N 16 W

SEC 34. 36.9 cont June 9 1919

143

W from ~~E~~ 1/4 P Var 2 1/2 E
875 Logging Road Copied on Page 1328
6450 WIRE FENCE

8365 FELL 1/43 N of 1/4 Post which is set at
4103 Equidistant bet NW + SW corners
Post is 25 E. of E Wagon rut. no B.T.S. ⁷

N from S out 1/4 P Var 4 1/2 E

8322 FELL 93. E. of N 1/4 P. Kee 1/2 change course
corrected Line South 2 1/2 to 1/8 P

Set center of SEC. { Birch 8 S 69 1/2 W 9
Birch 12 S 53 E 12 1/2

DIST to N 1/4 P 42 42

" " S 40 80

" " E 41 76

" " W 41 89

1/8 P. S. of center { HGM 14 N 85 1/2 W 29

"} 15 N 11 1/2 W 14

North from 1/8 P East of center Var 5° E
43 1/4 FELL 70 W of 1/8 Post which is set at
this time. { Sugarloaf S 22 W 36 1/2

no other near

WEST from S 1/8 P on E Line Var 4° E

4180 FELL 70 S of 1/8 P. { Hemlock 20 N 31 W 9 1/2

"} 20 S 12 1/2 E 30

Sgt 1/16 Post in SE 1/4 Y. Pine Stp 16 S 36 E 7

{ Sgt by pocket compass

South from 1/8 P E of center

2098 FELL 10 W 0 1/16 P.

Set 1/8 P N of center at 6201 { Birch 8 N 21 1/2 E 15 1/2
Maple 10 S 66 E 23

W from 1/8 P N of center Var 3° E

4185 FELL 185 N North of 1/8 Post in road which is
at 2052 Sout of NW cor + 10 E. of random
{ TEL. Pole with 2 notches

{ Bears N 35 1/2 E Iron pipe for Post

1/16 Post in NW 1/4 SGT 100 south of center of small
swamp No bearings

South from 1/16 P in NW 1/4. Var 3 1/2 E.

2070 FELL 17 1/2 W of 1/8 P W of center. out

144 SEC 34-36-9 Cont JUN 14 1919

1/8 Post west of center { Birch 12 N 43 E 18 1/2
Copied on 138 W. Pine 4 S 7 W 34
To hot to work. am tired out will finish
later on new record at the Bay

145 SECTIONS 18-19-30-31-38-8

June 23" 1919
Began at West 1/4 P 0 18-8 one piled around
Post run South on old random line 3 1/2 G
2010 fell 1 1/4 links W of 1/8 Post 3 years ago
40 10 " 2 1/2 W of corner ok
connected N for road for Newbold
South on West Line of 19. Var 3 1/2
3548 Enter open marsh Copied on
3830 leave marsh 149 Book of 38-8
44 50 ENTER " New County
48 50 LEAVE " ? road
8117 FELL 67 E of cor to 30 + 31. found
Stamp of my bearings made May 1916
See Page 42 this book
connected line N for road for the
Town of Newbold

South from NW Cor of 30-38-8
44 44 P 2030 found 1/8 P on line
Set line stakes bet 1/8 P & corner

This is a survey of road for the
Town of Newbold

40.58 1/2 X cor -

146 SURVEY of Road for TOWN of NEWBOLD

JUN 26 1919

commencing at a Stake which stands on west
Shore of Swamp Lake in Lot 3 SEC 26 T39 N Range 8 E
The bearings for which are { J. Pineskell S39 E 41

1	Thence S	52	E	201	.	.	-8 East	61 1/2	
2	"	84	"	189	Then	N	7	W	355
3	"	N	49	"	639	"	3 1/2 E		954
4	"	33	"	150	"	"	4	W	256
5	"	56 1/2	"	233	"	"	33	E	160
6	"	29	"	711	S	87 1/2 E			284
7	"	11	W	511	"	"	73	"	218
8	"	48 1/2	E	382	"	N	82 1/2	"	188
9	"	66 1/2	E	283	"	"	67	"	280
10	"	83 1/2	"	1088	"	"	57	"	351
11	"	55	"	6311	"	"	63	"	454
12	"	40	"	387	"	S	83	"	234
13	"	44	"	611	"	N	45	"	466
14	"	31 1/2	"	405	"	"	70	"	160
15	"	58	"	160	"	"	85 1/2	"	630
16	"	28	"	916	S	59 1/2	"		271
17	"	68	"	363	"	"	77	"	353
18	"	70	"	580	"	N	77	"	587 51
19	"	78	"	272	"	"	21	"	488
20	"	67	"	587	"	"	35 1/2	"	387
21	"	55	"	199	"	"	62	"	478.
22	"	21	"	525	"	"	87 1/2	"	356
23	"	11	W	242	"	"	75	"	51
24	"	11	E	607	To Range Line betw Range 8 & 9				
25	"	8	"	347	and betw SECs 19 & 24				
26	"	13	W	469	Township 39-NR. 8 & 9				
27	"	47	E	216	and 3 1/2 S of SEC 10				
28	"	82	"	638	corner to 13. 18. 19 24				
29	"	87 1/2	"	159	Copied on Page 150				
30	"	62	"	450	Book 39-8				
31	"	78 1/2	"	646	NEW COUNTY				
32	"	East	"	765.	Record				
33	"	47	"	950					
34	"	27	"	514					
35	"	21	"	468					

147 SURVEY OF Road for TOWN NEWBOLD

JULY 17-1919


commencing at corner to Towns
37 & 38. Range 7 & 8 E in center of road
The org. trees are grubbed out, but I had
Tally stakes set on this line.

Run North Var 3 1/2 E on my old alignment
Arun in Feb 1908. See Dorr's book of notes Page
Page 173 copied on Page 150 new County
2001 fall 22 East of my 1/8 P. road Book 38-8
4002 " 44 " 08 1/4 P. bearings gone
Post is ok. Connected line South to corner
on road error.

North from west 1/4 Post Var 2 1/2 E
3970 fall 36 West of 1/8 Post I set in
October 1908. See Dorr's book of notes
Page 173 connected line South
to come for road for Newbold
Copied on Page 150 Book of 38-8

SEC 12 42-5 JULY 26-1919

Began at NE COR of Lot 1
 Thence N 68° W on & near shore of Clear
 LAKE
 1300 chains var 3.30' E
 Then South var 3.30' E
 4.70 chains
 Then West at right angles
 6.60 chains
 Then South " " "
 2.81 chains to mud LAKE
 At 2.00 on last course it 59 Lks
 to WGS^{to} Line of Lot 3. Measured at right angles
 and at ~~C.P.~~ The intersection of West Line it
 is 15 Lks South on West Line of Lot 3 to LAKE
 At 200 ch on last course about ^{measured}
 IT IS 73 LKS ~~W.G.S.~~ to mud LAKE



sec. 35 37.8 JULY 25 / 919

center of SEC set by Dorr

Run E. on an offset North
 4088 fell 108 1/2 ft of 1/4 P in road
 corrected lineBEGAN at Center SEC by Dorr, OK
 offset N 19 Lksat 2044 offset South 19 Lks
 and SEC 1/8 P on iron pipe 2 feet long
 3850 am on line and 37 1/2 Links west ofRight of way of Chicago and NW RR
 Then southerly about 950 to old road
 at ~~Cross~~ R.R. crossing

Copied on Page 150 Book 37-8


Survey of road for Town of Newbold
 commencing at 1/8 Post E of center of
 SEC 35. 37.8. Thence east on 1/4 lines
 1806 to stake which stands on 1/4 line 37 1/2
 links west of NW R.R. cos Right of way
 then southerly parallel with said right of way
 and 37 1/2 ft from same about 9.50 chains
 to intersection of old road at R.R.
 crossing, New County road

150 SEC" 6. 37-7 JULY 27 1919

M.C. on W. shore of Birch Lake. found Stb
the Pine org tree. Set new post and run
W.C.S.T. made new bearing N.W. Pine S. E. 20 S 38 W 35 1/2
Var 4.30° E.

2000 State highway

3053 fell 2.26 N of me think I found the
NE org tree of Birch Birch stub marks are
nearly gone. Iron marks all gone. but it
checks with org line from NE corner East and
distance from me South of this one
corrected line East to me
copied on Page 25 Book 37-7



Copied on Page 151 Book 37-8

SEC 32-37-8 AUGUST 8, 1919

SURVEY of Road f^t & TOW of NEWbold
commencing at a P^t in center of the
State highway 2 1/2 N. of the
South 1/4 Post of SEC 32. 37-8.
Then N. E. north on or near the N.E.
1/4 Line in said SEC 82 40.00.

The course of this line is 13° E Var.

I know the N. 1/4 Post was there in Jan. 1899
but was nearly gone. See Count record Page
155 The course of the E & W Lines of

this SEC is 13° E Var. and as the N
1/4 Post is now gone I have done this
made this survey as near correct as
possible. as the NE and NW corners are said
to be gone and as Sac Lake in 30 and
another lake in 32 will have to be crossed in
order to resurvey them. Thought this would
answer at present time.

SEC 27-39-6 AUG. 22 1919 151

went to C or to 26. 27. 34. 35 found org tree
were gone. But found Stump of bearing
made in Nov 1907 { N.W. Pine S. N. 71 1/2 and
a new one this date

{ N.W. Pine Stb 36 N 46 1/2 W 120 on root of
{ Oak 12 S. 40 E 114 1/2

The bearing made in 1907 has been cut
down close to ground with scw. and some
one has driven a nail in side of Stump
N. From S.E. CORNER 4° E.

3388 fell 85 1/2 E of org N.E. found a

shortage of 62 1/4 ft proportions
copied on shortage and set 1/8 P at 1964
new county Shortage and set 1/8 P at 1964

{ N.W. Pine Stb 30 N 34 E 36
{ " 30 N 83 W 31 on page 151

152 SEC. 9. 36-8 - AUGUST 22 1919

1/8 P N OF CENTER SET by Dorr in 1897
found St P of W. Pine 30 N 3 W 2 3/4

Set N Post and run South U 2.45' E

1402 fell 3 8 E of Dorrs center

found Post and Sugarok green

.. Stp of Hem^m marks gone

Set NEW Post and run W Uar 9.10'

Dorr said he run it in 920 which
course was true line + distance to
Lake was 1450.

1400 Top of high bank on waters edge

The Lake has since Dorr been flooded
by dam at outlet and shore has washed
away and taken dorr's me away

Set Post and made NEW B.T. Pine stp 20 S 6 1/2 E 2 7/8
copied on New county record

WEST from Dorrs 1/8 P N of Cnt Uar 7.45'

20 SET Line stakes and last it

31 36-8 7

SEC' 30-35-10.E Sept 24th 1919 153

went to southwest corner which I

Set by proportional measurement

in 1900 to 1910 - found Post and Bt. OK

Run north Uar 3 1/2 E

6800 intersect b19 open swamp

7890 Fall 1320 West of NW corner

which I set from SW BT in 1910

found Post and stump of SW, old tree

Set E 1/4 P at 39 ft 5

{ cedar 10 N 15 E 4 1/2 copied on post

{ Hem 16 S 42 W 55 1/2 121 county

W. from E 1/4 P Uar 3 1/2 East record

1700 Enter swamp

5800 To Hog back 200 rods NEW record

6000 Enter swamp

SEPT 26

SEC 31-38.8 Sept 29. 1919

SURVEY of road for Town of NEWbold
commenceing at a Stake which
stands on the east line 4015 N.
of Township line and in center of
a road. From which a an Elm tree
~~was~~ 16 inches in diameter was
north $\frac{1}{4}$ West (Var 4° East 1.10 dist.)
Then N 63 W 2.3 0

"	37 W	3.1 2
"	26 "	1.9 2
"	60 "	7.9 9
"	S 82 "	4.5 2
"	88 "	14 8
N	60 "	22 0
"	68 "	29 3
"	37 1/2 W	36 1
"	34 W	40 8
"	18 1/2 "	21 5

*Sept 29. 1919
New Survey
S. S. C.*

6 1/2 " 31 to the E & W 1/4 line.

of SEC 31-38-8-

Whole distance 39.41 chains

= 78 Rods course and distance
above given as the center and
line of road. The courses above
given are all magnetic and
on a 4° East variation

SEC 139-5 Oct 22 1919 155

me on East shore of Mud Lake.
found th white Pine orig. tree 30 miles
other tree gone. Run East Var 5 1/2 East
550 enter Swamp
800 over

630 7 fell 20 1/2 N of corner found
Stumps of the SW 1/4 NE trees.

Set an iron monument ~~as~~ found an
an overgrown of 14 links proportion
a corner and set 1/4 Post proportion
distances. Then found the stump of
1. Pin. So my notes now read.

East from me Var 5 1/2 E

22 9 5 1/2 fell 77 3/4 N of 1/4 P set an
iron pipe for Post 2 x 18 inches
59 8 feet east of me it is 70 1/2 ft east of P
Set E 1/8 Post on N line an iron Pipe
2007 W of NE corner. 54 lkgs. of road

South from NE corner Var 3 1/2 East
492 1/2 to 1/4 P found Stump of Norway
Set an iron pipe for Post

South from East 1/4 P Var 3 1/2 E
406 3 fell 23 1/4 E of corner in center of
old road. A fence runs west from
a point about 16 feet west of corner

West from SE ~~#~~ corner
2750 enter swamp copied an Poy's NEW
4000 leave

4049 fell 52 1/2 S of 1/4 P found the
Stump of red oak orig tree

Made new Post and corner
by Pines 12 S 31 E 34

10 N 23 E 13
West East and set 1/4 P. at 2024
NW Pines 14 N 35 W 16 1/2
County reversed

Sect 1.39-5 cont Oct 25 1919

South from E 1/8 on N line was 3 1/2 E
 44 9 1/2 feet 9 8 E of 1/8 P.
 Set 1/16 Post in SE 1/4 { J. Pin 10 N 50 E 28
 comes on Page 1 new " 8 S 48 E 25 1/2
 East from 1/16 P in SE 1/4 var 3°
 feet 4 links S of 1/8 P no bearings Post lies
 in west edge of Sprucey swamp quite out
 country record

SEC. 3-36-10 NOV 20 1919

WENT TO 1/16 Post in NE 1/4. found
 both trees & marked for bearings. The NE
 one is OK. NW one is down. There is a
 Tamaree about 14 inches which has blown
 down. The trunk is exactly where Post
 should be. Set the Post on the trunk and
 drove it in far enough so it stands at
 run west var 11°. Reckoned on Page 13
 2098 feet 9 links N of 1/8 Post. found the
 Tamaree BT OK. The fir is down.

Run west from this 1/8 P on ~~line~~
 comes 15 80 feet 6 links South of Post
 connected line east 1/16 P. in NE 1/4
 South from 1/8 P N of center line 20° E
 9.85 feet 40 links East of center
 connected line N to 1/8 P 1919 ~~found~~

SEC 19-36-8 SEC 1-1919

Went to SEC cor found my 1907 P 1/10 E
 and one of Davis bearings
 Run west var 4.45° E
 18 87 18 86 to me set post from Stump
 of old W. Pin. West from my S 1/8 P
 on E line var 4 1/2 E.
 700 to lake swamp copied on Page 16
 1200 .. Lake continued on next page

SECTION 19-36-8 cont SEC 1-1919 157

2000 set 1/16 Post on line no BT
 it is about 800 W to shore
 of lake
 Run south from 1/16 P var 3 1/2 E
 This is the course of E line
 46 50 because last E. enters swamp
 6 50 " swamp
 17 86 intersect lake and set M.C. no BT
 copied on Page 16 new record

Line between 25+36.35-10
DEC 22 1919

went to SE corners of 3.5 found my
 Post & new bearing Set in 1909.

Run west var 3 1/2 E
 47 09 feet 32 1/2 South of 1/4 Post
 which had been moved to west
 side of state highway and made
 new bearings
 copied on Page 5 { Y Birch St 12 N 84 1/2 E 38 1/2
 new record { 10 S 85 W 35
 Went East and set 1/8 P of 23.5 4 1/2
 { cedar 10 N 65 W 16
 .. 12 S 13 W 13

SEC 10+11-39-10
January 23 1920
South 1/8 Post 62 10-11
Post from Oak 10 N 84 E 26 1/2

The J. Pin marked by down is
 OK but measurement by tape is
 incorrect. The water is correct only
 800 ft above but it will be hard to
 place in exact location where the tree was
 when it is 220

158 SEC 32 - 39 - 11 March 30. 1920

W 1/4 P. found Stump of SW on the
SEE NEW Post and run East Var 3° E
130 to Lake

4020 over "

53.50 to "

6500 over "

9383 fell 419 N of 1/4 POK

Decimal 4.46 Change course 2° 31'

N from S 1/4 P Var 4° E

4131 intersect Lake

6200 over Lake

7415 fell 880 W of W 1/4 P. SEE BOOK 7 P 93
and County record Page 382
Decimal 1188 Corrected Var 2 1/8° W
Center of SEC { B. Oak 6N 31W 17.
" " 8S 6W 12

Dist. to N 1/4 P 3797

" " S " 3668

" " E " 4783

" " W " 4600

Correct E + W and all W from center
531 To Lake and lot around corner

{ B. Oak 5S 17E 30 1/2

Birch 4 S 85 W 5

1/8 P.E of center at 2396 { B. Oak 12 N 7 1/2 W 27
" " J. Pine 12 S. 22 W 63 1/2

Cut out 12 acres on N side of Lot 6
which is 2396 X 50. Set stakes at each
corner
Corrected on page 129

new county

Records

3975
1987

SEC 5-36 - 8. Apr 17 1920

W 1/4 P. ok Run south See 1045 E

5148 fell 45 W of center found

Post and bearings

Corrected line south to 1/4 P
copied in New record Page 21

SEC 35-38-7 April 12 1920

E 1/4 P found Post beside road
drove a hub in center of road

opposite Post and Chained west

~~2016~~ E The distance given by Dorr
(And set hub in center of road for

1/8 P. Chained West 20 1/6 And

Established N & Cor. Dorr distance

{ J. Pine Stp 12 N 6 1/2 E 18

" " " 12 S 75 1/2 W 87 1/2

NE Cor Run west Var 8° E (Dorr notes
1300 to Small Lake

1700 over "

~~2030~~ 2030 fell 6 N of Dorr 1/8 P. found
his bearing nearly gone a

W. Pine Stp 20 N 3 1/2 E 33

Made new { W. Pine Stp 18 S 82 E 50

Corrected line East to corner

N 1/8 on E L in NO bearing

Run west Var 6 E

1981 1/2 Set Temp 1/8 P + left it

copied in book 38-7

160 SEC 21-36-9 April 14 1920

Began at center of See which is in
The center of N + S and E + W Roads

Run N Var 3 1/4 E

4 1/2 fill 1/4 E of Dorr 1/4 P. Birch is
down Stump Pine has been cut Stump OK

SET of Post N of center

{ Ashen 10 N 10 1/2 W 26 3/4
" " 8 N 7 1/2 E =

N 1/8 on E Line which I left in 901 Post of
Run west Var 4 E
40 65 fill 123 N of 1/8 P connected line

East to 1/8 P

NE Corner found Dorns Post & BT's
Both are Stump now

Run west Var 3 E

40 53 fill 5 3/4 N of Dorr 1/4 Post OK
Set 1/8 Post on N line

{ Tam 10 N 35 W 66
" " 7 N 80 W 7 1/2

Scaled Some trespass made by W. Hardell
on Lot 1 or N E # NE

Copied on Page 85 - Book 39-6

SEC 34-36-8 April 16-1920 161

NE Corn^{er} found Post set by ^{ME} and my
BT made several years ago
Run south to 1/4 P in center of road
The pine BT & I made several years ago
CS OK.

Went from East 1/4 P Var 3 1/2 E
4000 and left the Town of Woodboro
are to make a road on this line, but
as there is no W 1/4 P, and this
Section has not been Subdivided
They are taking their own chances

Copied on Page 25-B 368

SEC 26-36-8 April 16 1920

Went from SW C

East from SW corner Var 1 1/4
39 59 fill 2 1/2 south of S 1/4 Post
found Dorns BT now a
Stump, which stands S-W 100%

Set W 1/8 P on South line

{ W Birch 12 S 11 1/2 E 6 1/2

North from W 1/8 P on South line

Var 3 1/2 E Copied on Page 145 B

2000 2000 and left it for road

T. 368

Began at center of sec: Set by Russell
Chained west on his corrected 40 fm.
at 1/8 P North of center and chained west
20.00 found a Post to which I had
Chained from 1/8 P on west line
found the two measurements overlapped
1.89 divided the difference and set Post
S Spencer 125 85 E 11

Chained West from center of road on West
line and on Dr. Russell's $\frac{1}{4}$ line

3848 to Center of Secⁿ Set 178 P NO BT
Run N from 178 P Start of Center Bas 3 1/2 E
1964 Fall 10% W of Post

Entered in S. DEC 5 34
Entered in Book 38 II Page 33

$$\begin{array}{r}
 29 \\
 47 \\
 44 \\
 \hline
 100 \overline{) 48744 (1 \quad 8 \quad 7 \quad 6 \quad 0 \\
 \quad 400 \\
 \hline
 \quad 874 \\
 \quad 800 \\
 \hline
 \quad 74 \\
 \quad 72 \\
 \hline
 \quad 26 \quad \text{W of east}
 \end{array}$$

Commencing at a hub in center of
of old road and on the E + W 1/4 line and
2.64 East of center.

Then west on 1/4 mi 4.86 this is
the south line of a 500 ft road.
Then N 14 E var 1/2 E 4.39 on W line.

Then N 14 E 6° 3½' E 4.39' on W Line

"	33	"	230
"	1/2 "	"	4.13 + 84
"	45 1/2 "	"	3.91 cost thread
"	81 "	"	383
"	36 "	"	800
"	10 1/2 W	"	400
"	11 "	"	600
"	49 1/2 "	"	300
"	54 "	"	264
"	58 "	"	293
"	35 "	"	215
"	12 "	"	198 to Section

12.

line about 300 feet of $\frac{1}{4}$ Post in sloping
course + dirt above given are the west
line of road since leaving the E + W $\frac{1}{4}$
line and the South line of road on the
E + W $\frac{1}{4}$ line

whole length 19.27 chains. The road is
50 links wide and contains an acreage
of 2.46 $\frac{1}{100}$ acres. Dated this 27th day
April 1920. Survey was made by
and under the direction of the board of
superintendents of the town of Three Lakes

copied in Book 39-11 Page 129-30

164 SEC³ 23-24-25-26 37-7 May 3-1920

Began at corner to 22-23-26-27

Set this cor 1 year ago from org B.T. Stps
made new bearings W. Pinestp 14 N 88 1/2 E 39
15 N 34 W 60

Run E Var 1 1/2

16026 3/4 fill 168 N of cor on Range line
found Post & set in 1899 down, found
" Stps of org trees, all are down
NEW. W. Pinestp 30 N 58 1/2 W 31
" 30 N 78 E 95 2 ft HI

Set Temp Cor on random at 7981 1/2

North from Temp cor Var 3 1/2 E

6895 fill 5 west of ME found Stps of org trees

This is the exact distance given by
the deputy U.S. Surveyor

South from Temp cor on Caretted line
from ME. Var 3 1/2 E East

8062 + 10 ~~1/4~~ 1 1/2 link E of corner of
as the ground was very rolling
and my chainmen were view at this
work I concluded to use the distance
80.00. And Set 1/4 bet" 25 + 26 at 4000
+ Set corner to 23-24-25 + 26

W. Pinestp 30 S 54 E 10 1/4
248 10 W 160

1/4 P bet 23 + 26 { W. Pinestp 20 N 76 E 35
" " " 30 S 8 1/2 W 70 1/2

1/4 P bet 23 + 24 " " 20 N 85 W 68
" " " 24 S 51 1/2 E 92 1/2

1/4 P bet" 25 + 26 " " 14 N 1/2 W 57
" " " 20 S 80 1/2 E 94 1/2

1/4 P. 24 + 25 " " 14 S 30 W 11 1/2
East 1/8 P bet between " 16 N 83 E 36 1/2

East 1/8 P bet between 24 + 25 1/2

W. Pinestp --- 18 N 55 W 63

" 18 S 78 E 68

- POSTED " on page 73-77-101

May 18-19 20

SURVEY OF ROAD TOWN of Harrison¹⁹²⁰

Began at cor to 2-3-33-34 35-8 E

Run N.W. Var ~~5 1/2~~ 5 1/2 E

7650 fill 2 5 W of cor found Pinestp L.E. Horn
Made new 3 W. Pinestp 12 N 74 1/2 W 34

Org Pinestp 16 S 51 1/2 E 53 1/4

Set Post and run N var 1 1/2

7902 fill 104 E of cor long SEP ok + old Post
Run N 4 1/2 E again

4079 fill 2 3/4 E of Lynns 1/4 connected
on to this 1/4 but run N var 4 1/2

4079 fill 2 5/8 E of cor DK

Went South to 1/4 P and changed E

2669. + Set Hub in th. Brandy road
and made B.T. W. Pinestp 20 N 52 E 52 3/4

Then S 26 1/2 W Var 1 E 55 8

" 38 " " " 40 8

" 60 " " " 26 4

" 77 " " " 31 7

" 76 1/2 " " " 21 7

" 72 1/2 " " " 114 4

" 9 1/2 " " " 90 8

" 25 1/2 " " " 57 9 to SEC.

Line bet 2 1/2 + 23 and 34 1/4 N of corner to
2-1-22-27-28.

Then S. South on SEC. line to a stake which
stand on line bet" SEC³ 33 + 34, and 34 1/4
N 0 56 of corner out town line and the corner
to 2-3-33-34

Then S 14 1/2 W Var 1 E 36 4

" 23 " " " 40 9

" 37 " " " 81 0 to

Harrison Road

posted on Post 73-77-101

SEC 23-39-6 May 24 1920

Went to N 1/4 Post Iron Pipe & Pipe found the N. Step of orgⁿ tree set a small Post as dam has promised to place an iron monument there.

Run South Var 3 1/2 E

88 1/2 Lake 1 Copied on Page 93

1617 over lake

2300 offset west 25 top of hill

Book 39-6

5500 offset west 25

8170 + all 3.52 E of 1/4 P. The State Highway Commission has constructed a road where org. Post stood and removed the Stumps of original trees and removed the Post it is now outside of the right of way. The Post and B.T. stumps were cut in May 1914.

Did the best I could to connect it the Post. And connected line from 2000.
20-00 Chain South to 40.00

SEC 31 38-9 May 28 1920

Meander corⁿ on east shore of lake on south line.

Found stub of original tree, marks drove an iron pipe for Post and made new bearing 1. J. Pin 8.5.29 W 29 1/2 instrument at Post turned it onto 1/4 P. on west shore of lake and run E on SEC line 150 ft set and set an iron Post then proceeded to plat 24 lots on East and North Shore of Silver Lake for Homer Stone.

Copied on Page 125 Book 38-9

SEC 13-36 8 June 18-1920

SURVEY OF ROAD FOR TOWN OF WOODBROOK
Began at my 1/8 P. West of center

Copied on Page 53 Book 36-8

Run WEST on 1/4 line 2002 to 1/4 Post. Found my old Post & one bearing nearly gone. NEW OAK 12 S 12 E 56.

Run N Var 4° E

4012. fell 1.29 W of corner to 11.12.13. 1/4

Corrected line South for road.

Dec. 3.22 change course 1.50

SURVEYED CL PIECE OF LAND
AS FOLLOWS

commencing at MC on E Line of Sec 13-35-10 Then N 6.22 Then W ESE 7.00 Then S 5.28 to lake. Then easterly along shore of lake to MC and place of beginning, for 1/4 Gro. Sochf

Copied in Book 35-10 P. 53

SEC 12.39-9 JUNE 22 1920

Began at W 1/4 P. found Stumps of trees & marked in May 19. 1919. and Post & set at that time. Run E Var 3 1/2 E 83 1/4 fall 7.29 S of E 1/4 P. found Post and cement BLOCK for Post
Corrected line West and set center of SEC + 1/8 Post West of center

Copied in Book 39-9 Page 41

I had run the west line and left 1/4 P as the original was gone. and as the S. 1/4 P is in lake and the range line is said to be straight an intermediate course must be equal distant betⁿ 1/4 Post.

West from center Var 4° E

4043 fall 30 west of 1/4 P. & set in 1909

found steps of my B.T's OK

Corrected line South for road for Town of Sugar Camp Post

SEC 24-36-7 July 2nd 1920

Bogged at West $\frac{1}{4}$ P. an iron $\frac{3}{4}$ +12 inch
which stand 3 links East of East Rail of
Soo R.R. $\frac{1}{2}$ W. Pine Stump 15 S 59 E $3\frac{1}{2}$

Run N Var $\frac{1}{2}$ E

3069. full 22 E of M.C. found Stumps of
both original trees connected line
S. Dec 00. 72. and set $\frac{1}{8}$ Post at 2000
N. of $\frac{1}{4}$ P. $\frac{1}{2}$ W. Pine Stp 10 N 65 $\frac{1}{2}$ W 21

Did not connect line S. of $\frac{1}{8}$ P.

$\frac{1}{4}$ P Post East on intermediate course
between S $\frac{1}{8}$ line and N SEC line
1.00 enter field Var 1.20 E
3000 leave field
to Lake + set M.C.

4400 intersect Tak and set Meander cor
§ OAK 10 S 45 W 03

N $\frac{1}{8}$ P. on W line Var 1 $\frac{1}{4}$ E

500' leave gravel Pit

1304 Soo R right off way

3160 to Lake and M.C. OAK 6 N 75 W 7 $\frac{1}{4}$

N M.C. on N Line E Var $\frac{1}{2}$ E

1549 center of Soo RR Track

2807 full 47 N. of $\frac{1}{4}$ P. SEC See 13

SET W $\frac{1}{8}$ H. Line) W.P. SEP 20 N 41 W

30 S 41 W

SEC $\frac{1}{8}$ P W of center in open field NORT

North $\frac{1}{8}$ P W of center Var 2.5

1994. Set $\frac{1}{16}$ Post in N.W $\frac{1}{4}$ $\frac{1}{4}$ 1994 N of $\frac{1}{8}$

4022 To W $\frac{1}{8}$ on N Line

S. from M. S $\frac{1}{4}$ P on $\frac{1}{4}$ line in 13

Prolonged 2.32 to lake + set M.C.

continued on Page 97 Book 36-7

SEC 13-36-7 July 5 1920

$\frac{1}{4}$ P. An iron pipe. NEW BT 7 Weeks ago

Run South on $2\frac{1}{2}$ E

3555 full 9 Lks W of M.C. found Stumps of
original trees and Post & setting
JULY 1910. Connected Line N + Set $\frac{1}{8}$ P. of
2004 South of $\frac{1}{4}$ Post SEE See 13. County
Record Page 77 W Pine Stp 20 N 22 $\frac{1}{2}$ W 13

20 S 5 $\frac{1}{2}$ E 6

South from $\frac{1}{8}$ P W of center Var 2 $\frac{1}{2}$ E

4376 full 47 W of $\frac{1}{8}$ Post

West from $\frac{1}{8}$ P S of center Var 2 $\frac{1}{2}$ E

4012 full 2.22 S of $\frac{1}{8}$ P Connected all lines
run + set $\frac{1}{16}$ Post Center of SW $\frac{1}{4}$

Dust to $\frac{1}{8}$ P S. of center

" " $\frac{1}{8}$ P W of "

" " S $\frac{1}{8}$ P on W Line

" " W $\frac{1}{8}$ P. on S line

South from center Var 5 $\frac{1}{2}$ E

2118 full E of $\frac{1}{8}$ P on iron Pipe
then cut off a strip of land 400 feet
wide from the east side of the NESW

SEC 30-40-7 July 16-1920

S E corner of Run N Var 3 $\frac{1}{2}$ E

1350 Stream 1925 less Stump

2750 to lake + set M.C.

copied in book 36-7 Page 53-4

¹⁷⁰ SEE 12-35-8 July 8 1920

N.W. Cor. found the bearings &
made 10 years ago when I
Surveyed the line between 11 + 12 for
Road and as the original trees
must be grubbed out & made new ones

The Bush has been cut down and
Stamp badly turned Set Part. a HUB
west of the center of the centers of
the Road

Run East Var 6° E

4060 Full 22 N of Cassel 1/4 Past
Found Brick ok Iron marks
nearly gone. The Hummock is down
and partly decayed. Much new
bearing. Henn 12 N 15 W 15

South from NW Cor. in Ross

4143 F W 3 1/2 E of 1/4 Post. found
The Blamp of Pine after.
Marks ok. Set N 1/8 P on W Lin
{ S 90 10 N 85 E 57
{ P 21 128 M 84 W 57

$8\frac{3}{4}$ P Set by Lynn Vaughan his
bearings are { Tarn 14 N W

Lynn had Run N from C. used
his compass & found he had run the
N line and Set 1/4 Pt Egy distance
between corners 30 60 Each way.

The line 1/413 South and east
from his 1/4 post.

east from West 1/4 on Lyons
Randall 50¢.

7360 Fall 2.78 South of 1/4 P
I think this 1/4 P is OK as I set SE corner
From stamp of a W. Priv Pow &
marked 12 years ago when I run
the East line of this Section 10 years
ago and know the dirt So I run from

SE comes N and found this E 1/4 C¹⁷¹P
at the proper distance and bound
Lynn had used it

WEST From E 1/4 Post on an offset of
2.78 to Lg. m.s Random Var 4°

4200' offset S 42°
7340' Full 8 South of W 1/4 P E of offset
00681. Then add ~~278~~ 278.

North From S 1/4 P Set by Lynn at
Equal distance between corners as the
South 1/4 P is gone on Lynde's land
Var 4 1/2 E

8238 Fall 3.98 W of 1/4 Post

Set for corrections 0483
change course 2° 46' east over
Set center of Section

DIST to N 1/4 Post

the ~~the~~ S " "
" " E " "
" " W " "

— — — — —
SEC 30.40-7 July 16 1920

S E Corot Run North over 3°

400 enter see amp

1350 Stream 30' rising Easterly
2750 Co Lake and let me. Which is
the NE cor of lot 4

172 Survey of Road for Town
of Lynn July 19 1920

Began at corner to 26-27-34-35
36-34. found Post & set east
Summer orig. trees have been
blown out when road was built
made new one Birch 30 N. E 5 $\frac{1}{4}$ this
will be blown out also. So placed
an iron monument for Post 2x2 x 18 inches
also placed an iron monument 50 ft.
due north and another 50 ft. due south
Run E Var 5° E \$

40.00 Set line stakes and myself & 6 men
 hunted for 1/4 Post but did not find it

Began again at same See corner
and run N Var 4° E
3900 Stream 20 runs S E
4067 found what I believe to be the
stump of the original "Tarn" tree
found where someone had spalled
tree years ago to mark the location of
this line. Set Post and made new
bearings { Root of crooked birch N 73° E 25
{ Birch 14 N 32 $\frac{1}{2}$ W 53-53
at 4067 fell 10 E of 1/4 P Dec 27
Correct line South to corner for road
copied on Pay to Book 36-4

SEC 2. 38-11 July 27" 1920 173

N 1/4 P. found one monolith for Post
Also 2nd Post and SE by down.
Run East South Var 3 $\frac{1}{2}$ West
9031 FELL 192 E 1/4 P.

S 1/4 P is gone. SW corner also gone
it is in flower bed and cannot be
reached.

W 1/4 Post is in lake X

E 1/4 P This Post was set by Fin
Lawler also the SE corner.

I found the N + S 1/4 line in SEC 11
had been run. found me on N side of
Virgin Lake also the 1/8 P West of
center. So I began at this me and
run N to 1/8 P. Corrected line onto
1/8 P and prolonged line north.

Adolph Klaes had the notes for this
line which shows a shortage of 1.75 ch
The 1/4 P bet. 2 + 11 had never been
found and Charles Russell had run
a line from SE cor of See 2 to SW
corner. (The SW corner was there at that
time. And Mr. Russell had restored it.)
and tried his N + S 1/4 line through See
11 onto it. and had let the 1/8 Post
above mentioned at the proper
distance and divided the shortage so
I reestablished the 1/4 P. between 2 + 11
at \$956

WF Lom E 1/4 P. over 3° E

4337 fell 416 E. of a point on N + S 1/4
line, which is 4258 South of N 1/4 P
I could not locate W 1/4 P or SW cor
and figured the W 1/4 P would be 4516
South of NW cor

Corrected N + S and E + W lines
copied on Pay 11 - Bok 38-11

S 1/4 Post { Y. Pine 15572 W 107 $\frac{1}{2}$
} 10 ft. 8 N 30 W 48 $\frac{1}{2}$

174 By C D Vaughan Deputy

SEC 36 35-11 in Book 9

env
S 80 35 35-11

175

In Book 9

EDU
176 SEC 2 D. 39-10

Page /ear

1

2

2

5

6

7

49

110

0-11

13

14

15

6

17

7

8

9

9-20

0

1

2

2

1

5

7

8

1

5

6

1

3

6

1

5

6

1

3

4

INDEX

INDEX

Section	TOWNSHIP		RANGE		CITY OR VILLAGE	ADDITION
	N.	S.	E.	W.		
36	39		10			
12	35		11			
20	35		11		Road on Line betw 20 & 29	
33	37		10		8 cut this sec up in 1899	
27-28	37		10			
34-35			8+9		Road for the towns of	
24-25	36				" " " "	
13	35		10		" " " "	
10, 11, 14	35		10		" " " "	
6, 7, 18	37		8+9		" " " "	
6	37		9		" " " "	
31	38		9		" " " "	
30	38		9		Road for The Town	
20-21	35		8			
16-17	35		10			
8-9	38		"			
31	38		12		Survey of Roads for Town	
12	38		11			
36			4		Col 2nd Regiment	
536			9			
636			8			
236			13			
237			7			
2638			7		SEE PAGE 631 MUNSELL	
338			7			
336			10			
236			10			
26, 27-34, 35,	37		15			
9, 10, 15-16	36		4			
29	39		7			
35-19	39		7			
19	36		10			
29, 36			10			
8	35		11			
4	38		11			
30	39		11			
19	39		11			
	38		6			

INDEX

FOR WHOM SURVEYED	WHEN		
	Day	Month	Year
Rex Wunderlick	12	MAY	1915
Odd Et al	17	"	"
Town of Monroe	27	"	"
Starks Co	7	JUN	"
" "	10+11	"	"
Crescent and Pelican	16	"	"
Schoepke	22	"	"
Pine Lake	24	"	"
" " Sugarcamp	28	"	10-11
of "Harrison"	29	"	13
Sugar Camp	6	JULY	13-14
Robbins Lbr Co	9	"	15
" " " "	12	"	16
W.N Gaurd	16	"	17
F.N Whitman	19	"	17
Jo Moon	20	"	18
WW Thayer	29	AUG	19
Munsell	30	AUG	19-20
Nellie Murray	10	SEPT	20
Starks Co	14	"	21
" "	21	"	22
Town of Lynn	24	"	22
A.L. Gettys, Chicago	28	"	22
John Grundy	30	"	29
Wausau Land Co	2	DEC	30
" "	4	"	30
Joe McGinnis	20	"	32
Batawa Club	28	"	33
Keobke & Collins	6	JAN	1916
" "	11	"	3
Mat Resnick	2	FEB	1916

INDEX

Section	TOWNSHIP		RANGE		CITY OF VILLAGE	ADDITION
	N.	S.	E.	W.		
	23	37	8			
	25	38-	7			
	30	38	8			
	18	38	8			
	16-17	35	8			
	32	35	8			
	35	34	8			
	14	35	8	"		
	8	35	11			
	17	35	11			
	22	40	14			
	3	37	8		Tomahawk Lake	
	10	35	13			
	33	36	4	Road		
	31	36	4	"		
	16	35	13			
	13	36	13			
	8				SURVEY OF ROAD FOR TOMAHAWK LAKE	
	15	39	6			
	2	36	8			
	16	39	11	-		
	11	39	6			
	27	42	7			
	10	36	10			
	14	42	5			
	23	42	5			
22	25-30	39	8+9	7-8		
	2	36	8			
	1	36	8			
	11	39	9			
	9	42	5			
	25	38	8			
	4	37	7			
	13	35	6			
	39					
	38					

INDEX

FOR WHOM SURVEYED	WHEN			
	Day	Month	Year	Page
monaham + lyman	1	MAY	1916	41
John J. O'BSIOLS + newbold	8	"	"	42
Town of newbold	10	"	"	43
christ deal	13	"	"	43
Town of Harrison	21	"	"	45
C. O'NEALE	27	"	"	46
Town of Harrison	30	"	"	47-8
" meagher "	9	JUNE	"	48
" INDIVIDUALLY	21	"	"	50
CURTIS of merrill	10/10	JULY	"	50.51
Town of Tomahawk Lake	26	"	"	52
KEITH & HILES, crandon	2	august	"	52-53
Town of Lynn	21	"	"	55
KEITH & HILES	3	OCT	"	56
" town	11	"	"	57
GEO F Bergfeld, St Louis	24	"	"	58
Oneida County	5	DEC	"	60
Johnson of 3 Lakes	Jan 5	JAN	1917	61
A.J. BOLGER	25	"	"	62
Robertson Chicago	Jan 30	"	"	62
WAUSAU Land & Lbr Co	Feb 16	1917	63	
CALUM DORLOT	5	MARCH	1917	65
Mark Engemann	16	APRIL	1917	66
Town of Newbold	17	"	"	67
County of Oneida	15	MAY	1917	68
John Remo	17	"	"	69
CARRABELLA SYLVERA	19	"	"	69-70
Joe. ILS.	22	"	"	70
Town of NEWBOLD	22	"	"	72
W.W. THAYER, ET AL	25	"	"	72
REYNOLDS of milwaukee	27	"	"	74
Mr. White	28	"	"	75
	2	JULY	"	77

INDEX

TOWNSHIP Section	RANGE N.	CITY S. E.	RANGE W.	CITY or VILLAGE	ADDITION
13	38	10			
15	39	6			
24	37	8			
13	39	6			
24	39	6			
15	39	6			
3	38	7		SCHOOL ground	
5	36	7		" "	
35	36	7		" "	
3	39	10			
5	38	7			
27	39	11			
32	39	11			
9	36	9			
14	42	5			
22	42	5			
11	36	4			
5	36	8			
7 1/8	35	8			
22	42	5			
1	39	10			
29	37	10			
13	36	7			
3	36	7			
14	36	7		SURVEY OF ROAD	
14	35	11		" " Road	
4	30	9			
33	39	9			
7	35	11			
30	37	11			
32	37	10			

INDEX

FOR WHOM SURVEYED	WHEN Day	WHEN Month	WHEN Year	Page	Year
C.J. MCALICK	JULY 12	JULY	1917	78	
C. C. DE WITT	JULY 12	JULY	1917	80	
Burkhart, Bodine & Gal	JULY 17	JULY	1917	81	
Reynolds & Lamson	6	AUG	1917	82	
	14	"	" "	82	
GEO BERKELD	15	"	" "	83	
Woodlawn Tomahawk Lake	16	"	" "	84	
Town of Woodboro	18	"	" "	84	
" " " "	18	"	" "	84	
See 827. R. S. D. Graham	20	"	" "	85	
Edinborough	27	"	" "	86	
Oneida County	29	"	" "	86	
D. H. Frank	31	"	" "	86	
F. C. Cheatham	3	SEPT	" "	87	
Ed Rogers	4	"	" "	87	
GEO SEYBOLD GEOL	11	"	" "	88	
Mr. Smith	16	"	" "	88	
STOLLE Lbr Co	14	"	" "	89	
Dr Westgate	24	"	" "	92	
H. G. Foster	15	OCT	" "	93	
Mike Lambright	3	NOV	" "	97	
C. W. Potts	20	DEC	1918	98	
Lottor Broadbridge	28	MARCH	" "	100	
Skinner et al	1	APRIL	" "	101	
Town of Woodboro	19	"	" "	102	
" " " "	20	"	" "	103	
Schoepke	24	"	" "	104	
Tenderseed	25	"	" "	104	
R. Maguire & Lightbody	26	"	" "	104	
Starks Co	1	MAY	" "	105	
" " " "	3	"	" "	105	
" " " "	4	"	" "	106	

INDEX

Section	TOWNSHIP	RANGE	CITY or VILLAGE	ADDITION
	N.	S.	E.	W.
7+8	35		8	Road for the
5	37		8	
32	38		8	
19	37		10	
1	36		8	
25	42		5	
23	42		5	
14	42		5	
36	35		11	
11	39		6	Road Town of Schoepke
28	35		11	
16+21	37		10	Road for town of Pelican
30	43		11	
34	38		9	
2	35		9	
35	36		9	
3	63	9	6	
35	12.35		10	
12	38		7	
10	38		7	
11	38		7	
9.14+11	"		4	Survey of road for
12	36		4	
12	42		5	
14	42		5	
28	41		8	
31	36		7	
33	39		7	
34	37		8	
28	37		7	
27	37		7	
16	36		11	
20	37		10	
7.34	36		4	
119	36		8	
14	36		9	

INDEX

FOR WHOM SURVEYED	WHEN SURVEYED			Page
	Day	Month	Year	
Town of Harrison	7	May	1918	107
Paul Fredrick	13	"	"	108
POLANDER	"	"	"	"
The two Haggerty's	16	"	"	109
Jno & Rmo	14	JUN	"	110
Robert LOUGLESS	29	"	"	111
Mrs. HORNET	30	"	"	112
Henry ROSS	1 JULY	"	"	113
TOWN of SCHOEPKE	7	"	"	114
A.J. Bolger	11	"	"	115
SCHOEPKE Town	10	Aug	"	116
Town of Pelican	15	"	"	117
WT Mokeman	10	Sept	"	118
MIS L.G. KELLOG	30	"	"	119
WOLF RIVER Lbr Co	26	"	"	120
"	10	OCT	"	121
JA OLMSTED	16	"	"	123
mark Banta	26	"	"	125
TOWN of Tomahawk Lake	13	NOV	"	126
"	14	"	"	127
"	16	"	"	128
"	22	"	"	129
"	9	DEC	"	130
John WALLACE	16	JAN	1919	131
Charles Doriot	19	"	"	131
T.J. Kroshar	14	MAR	"	133
Minalow	17	"	"	134
ELMER LYLE	20	"	"	135
COLLINS & SANDERS	4	APRIL	"	135
EMMCUEKER	14	"	"	136
HIGHLAND SHEEP CO	5	MAY	"	139
HIGHLAND SHEEP CO	14	"	"	140
STERLING Rosbush	21	"	"	141
Doctor Packard	27	"	"	142
Road for TOWN of Lynn	3	JUNE	"	142
LIBERTY LAND & MORTGAGE				
WOLF RIVER Lbr Co				
OUR				

INDEX

Section	TOWNSHIP		RANGE		CITY or VILLAGE	ACREAGE ADDITION
	N.	S.	E.	W.		
34	36		9	7	CORTE	
18-19						
30,31	38		8		Road for Town of NEWBOLD	
26,27,28	39		8		" " " "	
31	38		8		Road. Town of newbold	
12	42		5			
35	37		8			
6	37		7			
32	37		8		WORK done by C.D.U	
27	39		6			
9	36		8		Survey of Road for the	
31	38		8			
1	39		5			
30	35		10			
3	36		10			
19	36		8			
	25	35	10			
	39		6			
32	39		11			
5	36		8			
35	38		7			
21	36		9			
34	36		8			
26	36		8			
8	38		11			
23,24,25,26,31	37		7			
32	39		8		Road for town of Harrison	
-	35		8			
23,24	36		6			
23,29	39		6			
31,38	38		9			
13,33	38		10		Road	
13,35	35		10		Karle et al	
12,39	39		9		Road for Sugarcamp	
24,36	36		7			
13,36	36		7			
12,35	35		8			

INDEX

FOR WHOM SURVEYED	WHEN SURVEYED		
	Day	Month	Year
WOLF RING Lbr Co	9	JUNE	1919 143
Town of NEWbold	25	"	144
" "	26	July	146
" "	17	July	147
Lee "Mike" Leopinski	21	"	148
Town of newbold	25	"	149
L A DOOLITTLE	27	"	150
Town of NEWbold	8	AUGUST	151
MILIN CLUB AT MALL	22	"	152
MELTON M RIDGE	21	"	153
TOWN of NEWbold	29	Sept	154
Foresters	22	OCT	155
Augur Applekamp			156
J.R. JACK	20	now	156
Ski Woodbars	1	Dec	156-7
John Rice	21	"	157
Matthew Lambert	23	Jan	1920 157
Indianapolis Club	29	MARCH	158
Dr S. Duthgate	5	APR	159
Doctor Carroll	12	"	159
Guy Donley et al	14	"	160
Town of Woodbars	15	open	161
"	16	"	162
John Michaelisk	27	APR	162
Highland Sheep Co	3	MAY	164
Town of 3 Lakes	25	APR	163
Harrison	10	MAY	165
John Dornan	24	"	165
C. O. Dornan	24	"	166
H. Stone	29	JUN	166
Kabel Town of Woodbars		"	167
Kabel et al		"	167
Road for the Town of Sugars	29	"	168
J. T. & investment co	2	JULY	169
"	5	"	170
Al Larson	8	"	"

INDEX

INDEX

Section	TOWNSHIP		RANGE		CITY or VILLAGE	ADDITION	FOR WHOM SURVEYED	WHEN			
	N.	S.	E.	W.				Day	Month	Year	Page
26 27 34 35 2	36 38		4	11	Road for town of Lynn		Town of Lynn Thunder Lake Ldr co	19 27	July n	1920 n	172 173