

35-9

35
9

35
9

PAGES 1-8

BLANK

SEC² 2-35-9-Sept 27¹⁹¹⁸ 9NE cor² org trees ok. + greenRun South var 4⁺ E

500 enter swamp

40.00 Did not find 1/4 Post

7563 fell 2.17 E. of SEC cor² org trees dead

found a shortage of 3.52. Proportions

Same and set E 1/4 R at 3738 South

of NE cor. nothing for bearings

Set South 1/8 Post on E. Line at 19.12

North of SEC cor. nothing for bearings

Set N 1/8 Post on E Line at 1869. South of NE cor.

B. ash 12 N 12 W 32

" " 8 S 51 W 12 1/2

N 1/4 Post found Post which I set from the original trees in 1904. They are gone now only stump are left and marks are gone

Run South var 3 1/2 East

80.00 could not find cor 1/4 Post. It is in a swamp. Timber all burned and down

Set line staks and left it. may come back and run sout line. Help is hard to get

Run West from N 1/8 Post on East Line. var 3⁺ E

20.00 and left it for the present

SEC. 2-37-9 Sept 27 1918

PAGES 10-176

BLANK

INDEX

Section	TOWNSHIP		RANGE		CITY or VILLAGE	ADDITION
	N.	S.	E.	W.		
2	35		9			

INDEX

INDEX

FOR WHOM SURVEYED	WHEN			
	Day	Month	Year	Page
Wolf River Lbr eo	28	sept	1918	9