


RECEIVED & FILED # B 2003
 Onica County Surveor's Office
 FEB 2 1993
 Date
 Ev mgl
 OCS Area #

51074



Memorandum

This plat represents a retracement and reestablishment of a portion of the original township boundary and subdivisional lines designed to restore all corners on the boundaries of sec 31, T 40 N., R 5 E., in their true original locations according to the best available evidence, and the survey of lands in that section which were erroneously omitted from the original survey and not shown on the plat approved January 27, 1865

The position of the original record meander line of a lake in sec 31 is shown by an irregular line with numbered angle points. This meander line, as originally reported, was grossly in error, and therefore has been established as a fixed boundary, with the directions and lengths of the several courses adjusted to the points called for on the true section boundaries.

Survey authorized by Bureau of Land Management memorandum 1895014 "E," dated September 20, 1946

Surveyed by Hugh B. Crawford from October 13 to November 10, 1947, pursuant to supplemental special instructions for Group No 60 dated July 3, 1947

Latitude 45°53'53" N
Longitude 89°53'41" W.

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Washington, D C , January 26, 1949

This plat is strictly conformable to the approved field notes, and the survey, having been correctly executed in accordance with the requirements of law and the regulations of this bureau, is hereby accepted
For the Director

William F. Richards
Chief, Branch of Surveys

9 E C
9 H

2015