2 0 0 0				
	LAND CORNER PR	RESERVATIO	N RECORD	
	f this record to preserve the location d or inaccessible due to road constr			nument that may be
County:	City , Villa ge, Town:	Section:	Town:	Range:
ONEIDA	PINELAKE	15	37N	, GE
Describe what was found, its location and origin. If known, describe if the monument found is a 1/16 corner or other subdivisional corner; a monument called for in a deed; a monument shown on a survey map or plat etc and in what GL or ¼ - ¼ section or subdivision the monument is located. AT SOUTH SIXTEENTH CORNER BETWEEN SECTIONS				Approximate location within Section
15 AND 16,	FOUND 3/8" REBAR, SAME SHEET BY MILD STEFAN.	AS REFERE AUERAGE G	FNCED PS	
OBSERVATION OBSERVED	1° N 184, 330.41 , E 276, (ON 6-25-2015.)91. 62 ON	AD 83(2011)	15
AND SET	- SITE REVISITED POS A BERNTSEN STEEL NAIL I ERVED LOCATION ABOVE,	ST- CONSTRU MARKER (SM	icTION IM-I)	

Plan view map of landmark monument location with bearing and distance ties to a minimum of four described witness or reference monuments of concrete, natural stone, metal, live bearing trees or equivalent material or indicate datum & coordinates if tied out using GPS. Indicate what was reset.

NORTH

MAD # L 3 0 3 8
MALE #
DATE FILED 12-28-15
BY. 470
DESCRIPTION FILED
ONEIDA CO. SURVEYOR'S OFFICE

Seal:



PROFESSIONAL LAND SURVEYOR CERTIFICATE:

This land corner was referenced out in advance of road construction or other activity as an act of preserving survey evidence or monuments. This corner has not been tested for its accuracy during the course of this preservation. It is recommended that those using the corner position evaluate and verify it prior to use in a survey or other use.

I hereby certify that I am a duly licensed Professional Land Surveyor in the State of Wisconsin; that the location of this Survey or Land Corner was referenced by me or under my direct supervision and control and that the information shown on this record is true and correct to the best of my knowledge and belief.

L3038

L3038 - L3042

3709162000