



① Meander Cr. - North line - East Side Point
 at 73.114 (orig 7315) east of NW cor. set u.c.d.
 pipe on log tam. pole in marsh. No sign of o.g.l.
 corner. New B.T. Tam 5" - N 79° W - 0.419 ch.;
 Tam. 3" - S 69° E - 0.088 ch. (Coff & Burm
 3/31/59) See corner file

② Meander Cr & N 1/4 NE 1/4 at 20.076 set u.c.d. pipe for M.C. & 1/8 Cr.,
 27 ch (orig 35) east of Carol Lab. No sign of o.g.l. corner. New B.T. OR 4"
 N 45° E - 0.367 ch.; BW 5" - S 49° W - 0.127 ch. (Coff & Burm 3/31/59)
 See corner file

L7544

RECEIVED & FILED #	L7544
Onida County Surveyor's Office	
Date	8881.2.2.88V
By	<i>[Signature]</i>
OCS Area #	

③ Meander Cr - North line - West of Carol at 39.568 east of NW Cor.
 set u.c.d. pipe for new M.C. No sign of o.g.l. corner. New B.T. MS 6"
 N 27° W - 0.164 ch.; BW 8" - S 8° E - 0.335 ch. (Coff & Burm 4/1/59)
 See corner file

② N¹/₄NW¹/₄ at 20.076 set 1/2" iron pipe for 1/4 Cor.
New B.T. OR 11" S 50° E - 0.235 ch. (Coffey & Berrett 4/1/59)
Found 3/4" i.p. + BT^s oak 10" S 19° W oak 16" S 50° E Seymour 2-23-82

③ NW Cor. Sec 4 Found evidence of 3 O.B.T. & rotten wood in post hole,
set W.C.D. pipe in same. New B.T. OR 6" N 50° E - 0.236 ch.; OR 10" S 29° W - 0.348 ch.; BW 6" N 69° W - 0.642 ch.; BW 6" S 76° E - 0.484 ch. (Coffey & Berrett 4/1/59)
see corner file

④ W¹/₄ Sec 4 at 4.914 south of NW Cor. set W.C.D. pipe for 1/4 Cor.
OR 14" S 4° E - 0.88 ch.; BW 8" S 14° W - 0.37 ch.; MS 6" N 10° E - 0.4
(Berrett 11/17/60) see corner file

⑤ Meander Cor - d.s.d. line - North of Canal at 16.386 ~~at~~ south
of W¹/₄ Cor. set W.C.D. pipe for M.C. OR 10" S 27° W - 0.36 ch.; OR 7" S 85° E - 0.33 ch. (Berrett 11/17/60) Reset Tashp