


SEC. 22 T. 39 N. R. 7 E.



① MC South shore Bass Lake
 Brass cap - 20 south of Orig.
 OBTPW stp. 14" S12°E 15.115
 MS 5" S81°W 49.115, MS 7" N44°W 17.115
 See corner file

③ N¹/₄ See corner file

④ N¹/₄ NW¹/₄

RECEIVED & FILED #	1770
Florida County Surveyor's Office	
Date	APR 22 1989
By	
OCS Area #	

⑤ EMC (wit) see corner file

⑥ W¹/₄ NW¹/₄ set 1" i.p. BT^s MH 18" N66°E 17.00', MH 12" S12°W 21.45'
 Seymour 6/26/84

⑦ W¹/₄ 22 see corner file

⑧ W¹/₄ SW¹/₄ set new 1" i.p. as old was bent and lying out of ground.
 Location also was not quite correct.
 Old BT^s now old stp N15°E 3-05', PN 14" S87°W 5.73'
 New BT PW 10" S46°E 6.85'
 Seymour 2/7/84

1770