


SEC. 35 T. 39 N. R. 7 W.



① N<sup>1</sup>/<sub>4</sub> NE<sup>1</sup>/<sub>4</sub> found i.p. on err line by Wincentson  
 Set new 1" i.p. (northerly of err i.p.) on corrd line.  
 BT<sup>s</sup> MH 4" S 12° E 19.05', OR 14" N 83° W 19.83'  
 Seymour 5-11-84

② N<sup>1</sup>/<sub>4</sub> cor  
 Pw 28" N 51° W 60.1' (Griffin 1968)  
 See Corner file

③ EMC See Corner file

④ SMC See Corner file

⑤ W<sup>1</sup>/<sub>4</sub> NW<sup>1</sup>/<sub>4</sub> found i.p. from Nelson, Mentz 1955 survey  
 New BT<sup>s</sup> MH 10" S 13° W 10.05'  
 MH 12" S 89° E 33.10'  
 Seymour, 1984

RECEIVED & FILED #	1782
Oraida County Surveyor's Office	
Date	APR 22 1988
By	S 21
OCS Area #	

⑥ W<sup>1</sup>/<sub>4</sub> 35 See Corner file

1782

⑦ W<sup>1</sup>/<sub>4</sub> SW<sup>1</sup>/<sub>4</sub> Set 1" i.p. in swamp  
 BT<sup>s</sup> PW 18" N 57° W 63.45'  
 Tam 12" S 55° W 15.8' Seymour 6/7/84