


① NE corner GLO B.C. (maybe incorrect)  
 B.T.'s A 8" N 29 E 36 ; Pw 7" S 46 E 55 ;  
 A 9" S 11 1/2 W 41 ; Pa 6" N 16 1/4 W 115. (Dorr 1892)

② W/k on N. line. B.T.'s Pine 12" N 40 E 13 1/2. (Dorr 1892)



③ Center NW 1/4 B.T.'s Pine 12" S 9 3/4 W 34 (Dorr 1892)

④ N 1/4 corner SW 1/4. B.T.'s - M.H. 8" S 19 1/2 E 16 (Dorr 1892)


1811

⑤ W<sup>1</sup>/<sub>4</sub> B.T.'s - B.stp. N33<sup>1</sup>/<sub>2</sub>E 7; B.stp. N86W 10. (Dorr 1892) Reset Berndt's brass cap (WCD) to prop. location, BT's PW 24° N 78° E 114.85', OR 10" S42°E 41.30' (to ctr), BW 10" N56°E 34.90', BW 10" N48°W 19.48' (12/81 Seymour, Vissers) Mark: post on woods road

⑥ W<sup>1</sup>/<sub>4</sub> SW<sup>1</sup>/<sub>4</sub>. B.T. MH 6" S41<sup>3</sup>/<sub>4</sub> E 17. (Dorr 1892) Reset Berndt's i-p. using 1<sup>1</sup>/<sub>4</sub>" i-p. BW 24" S75°E 38.10', BW 10" S79°E 4.05', BW 10" N12°E 42.60' (12/81 Seymour, Vissers)

⑦ SW<sup>1</sup>/<sub>4</sub> B.T. MH 6" S41<sup>3</sup>/<sub>4</sub> E 17. (Dorr 1892) Reset Berndt's i-p. using 1<sup>1</sup>/<sub>4</sub>" i-p. BW 24" S75°E 38.10', BW 10" S79°E 4.05', BW 10" N12°E 42.60' (12/81 Seymour, Vissers)

S. 20. 38. N. 7. W.



① NE corner GLO. B.C. (maybe <sup>yes</sup> incorrect)  
 B.T.'s A 8" N 29 E 36; Pw 7" S 46 E 58;  
 A 9" S 11 1/2 W 41; Pn 6" N 16 1/4 W 115. (Dorr 1892)  
 See Sec 21 sheet

② W 1/8 on N. line. B.T.'s Pine 12" N 40 E 13 1/2. (Dorr 1892)  
 (see page 18/51)

⑤ Center NW 1/4 B.T.'s Pine 12" S 9 3/4 W 34 (Dorr 1892)

③ Center NW 1/4 B.T.'s Pine 12" S 9 3/4 W 34 (Dorr 1892)

④ N 1/4 corner SW 1/4. B.T.'s - M.H. 8" S 19 1/2 E 16 (Dorr 1892)

⑤ W<sup>1</sup>/<sub>4</sub> B.T.'s - B.stp. N33<sup>1</sup>/<sub>2</sub>E 7; B.stp. N86W 10. (Dorr 1892) Reset Berndt's brass cap (WCD) to prop. location, BT<sup>s</sup> PW 24" N78°E 114.85', OR 10" S42°E 41.30' (to ctr), BW 10" N56°E 34.90', BW 10" N48°W 19.48' (12/81 seymour, Vißers) Marker post on woods road

⑥ W<sup>1</sup>/<sub>4</sub> SW<sup>1</sup>/<sub>4</sub>. B.T. MH 6" S41<sup>3</sup>/<sub>4</sub> E 17. (Dorr 1892) Reset Berndt's i-p. using 1<sup>1</sup>/<sub>4</sub>" i-p. BW 24" S75°E 38.10', BW 10" S79°E 4.05', BW 10" N12°E 42.60' (12/81 seymour, Vißers)

⑦ N<sup>1</sup>/<sub>16</sub> Reset Berndt's i-p. using a 1<sup>1</sup>/<sub>4</sub>" i-p. BT<sup>s</sup> Asp 11" S60°E 8.43', BW 12" N16°E 58.00' (12/81 seymour, Vißers)

⑧ N<sup>1</sup>/<sub>4</sub> 20 angle iron on map by Northwoods Surveyors, 1973  
BT<sup>s</sup> Oak 12" N42°E 55.9', Oak 10" S36°E 47.2'