



Stock No 26273

Sheet 2 of 5

SURVEY NOTES

This survey was made by Milo E Stefan and party pursuant to the United States Department of Agriculture Forest Service Contract #53 56A6-8-00187 'Cadastral Survey for the purpose of subdividing, establishing corners and marking the boundaries of U S Government Lands on the perimeter and within Section 35 Township 39 North Range 11 East Fourth Principal Meridian Oneida County Wisconsin as shown on the plat map herewith

The original government subdivision survey of this township was done in 1859 by William Daugherty The south line of Section 35 was originally surveyed by Hiram C Fellows in 1859 Subsequent surveys by the U S Department of Interior General Land Office were done in 1941 These GLO corners were recovered and used as the control for this survey

The U S Government acquired title to the lands in Section 35 in 1931

Bearings between corner positions are true bearings by reference to a solar observation All distances shown thereon are in feet and hundredths of feet The control traverse was measured with an electronic distance measuring instrument Corners recovered restored and established by this survey are marked by the monument described in the map legend Each monumented corner position is referenced to blazed and scribed bearing trees as described as 'corner references'

CORNERS RECOVERED AND RESTORED

- 1 Section Corner to Sections 26 27 34 and 35 T39N R11E
Position found marked with a GLO monument a brass cap set in a 6' x 24 concrete cylinder in 1941

Corner References

12"	White Pine	S64 E	19 67 feet
5	Tamarack	S51 W	32 72 feet
6"	Tamarack	N67 W	20 21 feet
5	Tamarack	N24 W	38 17 feet
	Steel Sign Post	North	1 2 feet
	Steel Sign Post	East	1 4 feet

- 2 Section Corner to Sections 25 26 35 and 36, T39N R11E
Position found marked with a GLO monument a brass cap set in a 6' x 24 concrete cylinder in 1941

Corner References

8	Hemlock	N59 E	22 11 feet
9'	Hemlock	S60 E	18 48 feet
6	Hemlock	S35 W	46 20 feet
7	Hemlock	N54 W	17 49 feet
	Steel Sign Post	East	1 8 feet

- 3 Section Corner to Sections 2 3 34 and 35 T38-39N R11E
Position found marked with a GLO monument a brass cap set in a 6' x 24 concrete cylinder in 1941

Corner References

8	Cedar	N20 E	20 1 feet
7	Hemlock	S71 E	16 1 feet
12	Hemlock	S13 E	34 6 feet
5	Cedar	S38 W	32 5 feet
9	Red Pine	N37 W	16 8 feet
	6 x 6 Cedar Post	S28 E	9 feet

L1101



Stock No 26273

Sheet 3 of 5

CORNERS ESTABLISHED

- 1 South Sixteenth Corner Between Sections 34 - 35
Position established on line and at midpoint between the West Quarter and Southwest Section Corner to Section 35

Corner References

4"	Tamarack	N66 E	20 21 feet
14'	White Pine	S14 E	29 00 feet
	Steel Sign Post	East	1 00 feet

- 2 South Sixteenth Corner Between Sections 35 - 36
Position established on line and at midpoint between the East Quarter and Southeast Section Corners to Section 35

Corner References

10'	Sugar Maple	N74 E	34 44 feet
10"	Sugar Maple	N37 W	19 96 feet
	Steel Sign Post	South	3 2 feet

- 3 Northeast Sixteenth Corner to Section 35
Position established at the intersection of the North and East Sixteenth lines to Section 35

Corner References

13	Red Maple	N87 E	12 43 feet
18	Sugar Maple	S23 W	19 88 feet
	Steel Sign Post	South	1 2 feet

- 4 Centereast Sixteenth Corner to Section 35
Position established on line and at midpoint between the East and Center Quarter Corners to Section 35

Corner References

6"	Hemlock	S18 E	15 64 feet
12	Hemlock	S78 W	36 74 feet
	Witness Corner	North	25 06 feet
	Steel Sign Post Next to Each Witness Corner		
	Witness Corner	South	24 92 feet

- 5 Southwest Sixteenth Corner to Section 35
Position established at the intersection of the South and West Sixteenth lines to Section 35

Corner References

5'	Hemlock	East	22 96 feet
4"	Hemlock	N17 W	19 87 feet
	Steel Sign Post	North	1 7 feet

- 6 Southeast Sixteenth Corner to Section 35
Position established at the intersection of the South and East Sixteenth lines to Section 35

Corner References

8'	Red Maple	N80 E	23 20 feet
4	Sugar Maple	N3 W	20 82 feet
	Steel Sign Post	East	2 3 feet

11101



Stock No 26273

Sheet 4 of 5

- 4 Section Corner to Sections 1 2 35 and 36, T38-39N R11E
Position found marked by a GLO monument a brass cap set in a 6 x 24 concrete cylinder set in 1941
- Corner References
- | | | | |
|-----|------------------|-------|------------|
| 10 | Red Maple | N63 E | 22 6 feet |
| 20 | Hemlock | S35 E | 94 0 feet |
| 14" | White Pine | S11 W | 104 0 feet |
| 12' | Red Pine | N42 W | 88 1 feet |
| | 6 x 6 Cedar Post | S72 E | 1 3 feet |
- 5 Quarter Corner to Sections 26-35 T39N R11E
Position found marked by a GLO monument a brass cap atop a 2" x 36' iron pipe set in 1941
- Corner References
- | | | | |
|-----|-----------------|-------|------------|
| 6 | Sugar Maple | N84 L | 25 39 feet |
| 18' | White Birch | N87 E | 10 41 feet |
| 14' | Hemlock | S45 E | 27 69 feet |
| 8 | Sugar Maple | N29 W | 26 55 feet |
| | Steel Sign Post | West | 1 3 feet |
- 6 Quarter Corner to Sections 34-35, T39N R11E
Position found marked by a GLO monument a brass cap set in a 6 x 24' concrete cylinder set in 1941
- Corner References
- | | | | |
|-----|-----------------|-------|-------------|
| 18' | Hemlock | S43 E | 15 83 feet |
| 8' | Hemlock | N33 E | 26 14 feet |
| 13 | Hemlock | N63 W | 82 15 feet |
| 8' | Sugar Maple | S54°W | 106 38 feet |
| | Steel Sign Post | East | 1 7 feet |
- 7 Quarter Corner to Sections 35-36 T39N R11E
Position found marked by a GLO monument a brass cap set in a 6" x 24' concrete cylinder set in 1941
- Corner References
- | | | | |
|----|-----------------|-------|------------|
| 6 | Sugar Maple | N68 E | 57 38 feet |
| 8 | Red Maple | S39 E | 49 63 feet |
| 6 | White Spruce | S27 W | 11 39 feet |
| 12 | White Spruce | N59 W | 11 56 feet |
| | Steel Sign Post | East | 90 feet |
- 8 Quarter Corner to Sections 2-35 T38-39N R11E
Position found marked by a GLO monument a brass cap set in a 6 x 24 concrete cylinder set in 1941
- Corner References
- | | | | |
|----|-----------------|-------|-----------|
| 15 | Red Oak | N38 E | 20 0 feet |
| 8" | Red Maple | N61 E | 35 0 feet |
| 6' | Hemlock | S13 W | 58 7 feet |
| 10 | Red Maple | N20 W | 28 0 feet |
| | Steel Sign Post | S9 W | 1 4 feet |

L1101

Stock No 26273

Sheet 5 of 5

7 Center North Sixteenth Corner to Section 35

Position established at midpoint on a line between the Center Quarter and North Quarter Corners to Section 35 which falls in Spring Lake We therefore established two Witness Corners as follows

Witness Corner North on North-South Quarter line 545 27 feet North

Corner References

3' Tamarack	N61 E	20 33 feet
5" Tamarack	S83 E	40 23 feet
Steel Sign Post	North	1 7 feet

Witness Corner East on North Sixteenth line 611 35 feet East

Corner References

10 Cedar	N70 E	41 00 feet
8" Cedar	S9 W	19 75 feet
Steel Sign Post	East	1 9 feet

8 Center West Sixteenth Corner to Section 35

Position established at midpoint and on line between the Center Quarter and West Quarter Corners to Section 35 which falls in Spring Lake We therefore established two Witness Corners as follows

Witness Corner West on East-West Quarter line 793 31 feet West

Corner References

6' Sugar Maple	N55 W	27 40 feet
12 White Pine	N14 E	22 20 feet
14 Red Oak	N33 E	35 81 feet
Steel Sign Post	West	1 65 feet

Witness Corner South on West Sixteenth line 596 30 feet South

Corner References

12" White Pine	S80 E	18 72 feet
10 Hemlock	S58 W	13 30 feet
Steel Sign Post	South	1 6 feet

SURVEYORS AFFIDAVIT

I Milo E Stefan Land Surveyor registered in the State of Wisconsin hereby certify That I have surveyed and subdivided Section 5 T39N R11E fourth Principal Meridian County of Oneida State of Wisconsin in accordance with the rules of the survey of public lands and with the statutes of the State of Wisconsin The plat map and survey notes are an accurate representation of the corners recovered and established

Date of Survey October 1988



Plat is ready for filing

Milo E Stefan
 Milo E Stefan

Registered Land Surveyor
 State of Wisconsin
 Certificate #1558

Samuel Ayork 2/27/89
 District Ranger Date

11101