MAP # L1385

DATE FILED MAR 28 1995

BY DESCRIPTION FILED

ONEIDA CO. SURVEYOR'S OFFICE

TRANSCRIPT FIELD NOTES

ALFRED J. LUNZ AND JOSEPHINE P.KONKOL

LANDS, described in Records Volume 153, Page 308, of DEEDS, Oneida County, Wisconsin, and more particularily described as that part of Government lot 7, East of River connecting Dam and Sand Lakes in Section 17, Township 39 North, Range 9 East, of the Fourth Principal Meridian, in Oneida County, Wisconsin.

The purpose of this survey is to resort to extrinsic evidence to show the original location of the corner common to sections 16, 17, 20, and 21, and thereby locate the respective section lines between sections 16 and 17 and 17 and 20, marking the east and south boundary of Government Lot 7, in Section 17, Township 39 North, Range 9 East.

Recieved from Fottz & Assoc. From There Files.
3/14/95

COPY OF GOVERNMENT NOTES.

Sub-division of Twn.89 N.R 9 E, by W.E.Dougherty in Sept.22-29,1863. *Gov. Field Notes, Oneida County Clerks Office.

	Sub-division of Twn.89 N,R 9 E, by W.E.Dougherty in Sept.22-
Chc.	*Gov. Field Notes, Oneida County Clerks Office.
3004	*(Vol-2.P.604) North Btw. 21 & 22 Var. 8° E. W.Pine 12-S 56 E 8.
	Over Lake and set Meander Post. Y Pine 12-S 67 W 6.
4.5.0	Set 1/4-Sec Post Tam. 6-S 23 E 8
4000	Set 1/4-Sec. Post. Tam. 6-5 25 E 6 Tam. 6 N 84 W 10.
4300	Leave Swamp Brs. E&W. Birch 8-N 18 E 5.
THERMAN	Set Post for Sect. Cor. for 15, 16,21 & 22. " 8-S 27 W 15.
THE COLUMN TO A CO	*(Vol.2.P.605)
3900	North Btw. 15 & 16- Var. 8° E. Enter Tamarac and Cedar swamp Brs.NW & SE. Tam. 10-S 71 E 3.
	Set 1/4 Post. Cedar 10- N 85 W 17.
	Leave Swamp Brs. E & W.
8000	Set Post Cor. for sections 9, 10, 15 & 16. Y.Pine 16-S 76 E 16. Spruce 7-N 67 W 16.
	*(Vol.2.P.607)
630	North Btw. 20 and 21 Var. 8° E.
619	To Lake and set M.P. Tam. 6-S 35 E 29. Tam. 6-S 30 W 48.
6950	Over Lake and set Meander Post, W. Pine 30-S 75 E 23.
8000	
	*(Vol.2.P.608)
	North Btw. 16 & 17, Var. 70- 45: E.
4000	Set 1/4 sec. Post. Hem. 10 N 37 E 13. Birch 12-S 42 W 15.
	Birch 10 in. Dia.
8000	Set Post cor. to Sect. 8,9,16 & 17. Y. Pine 25- S63 E 13. Y. Pine 25- N-71-W 39.
	East Random Btw. 16 & 21, Var. 70-30: E.
8026	Intersect Meridian section line 40 lks. south of post. West Corrected Var. 70-47! E.
1	Circular Pond.
. ,	Leave Same.
4013	Set 1/4 Post. W.Pine 25 N 78 W 20. Fir. 10 S 20 W 12.
8026	Sect. Corner.
i	*(Vol.2.P.612)
2000	East Random Btw. 17 & 20 Var. 8° E.
8000	Intersect Meridian section line 36 lks. north of Post. West Corrected Var. 70-45! E.
975	Creek 75 lks. runs SW.
I	Lake & Set Meander Post. Hem. 10-N 80 E. 12 " 8-S 68 E. 7.
4275	Over Lake and set Meander Post. Hem. 8N 43 W. 10 6S 73 W. 10
8000	Intersect Section Corner.

Notes of Record

D. H. Vaughn's Notes

(From Dorr and Vaughn Record Book in Oneida Cty. Clerk's Office)
(Page 293) Section 17, T-39-N,R-9-E. 11-June,1902.

S W Corner original trees nearly gone, made new bearings, W. Pine Stp. 24-N39-W 362.

Run E. Var. 42 E. 3800 to Dam Lake, 4922 over Lake, 6278 to flowage, 7193 to thoroughfare, 7933 over thoroughfare, (Note: This could read either as shown or 7733, or 7433 checks at 7733), 8476 fall 46 N. of SE Corner.

S.E. Corner found both original trees but nearly gone, set post and made new bearings, Birch Stp. 12-N-462-W 63. corrected line west to stream and from stream to SW cor. for road.

(Page 293)

Sec. 16-39-9 June 14, 1902 SW Corner original trees, run E. Var. $3\frac{1}{2}$ O-E, 4138 fell 17-N of $\frac{1}{4}$ P found the pine down, mark 0.K. Set Post and made new bearings, birch 8-N-70-W, 81, Hem. 6-S-53E 37. Corrected Line W. to corner for road.

21-June, 1949.

Received of Genisott Engineering Company, one print numbered Plan 561-1, dated 20 June 1949, purported to show establishment of section line between sections 16 and 17, T-39-N. R-9-E., for one J.J.RAZY, and signed by F.R.Wincentsen, County Surveyor of Oneida County.

(1200-2100)

23 June, 1949. N.M.R. A.J.L.

Proceeded to check Plan 561-1.

Found plan 561-1, inconsistancy with incoation of buildings on premises and also inconsistancy in lines between or as shown on the plan and those run by A. Lytle former county surveyor.

Checked the corner to sections 16,17,20 and 21 as indicated on the above mentioned plan and could find no evidence of this corner being the original, also note that all bearing trees are relatively new possibly two-five years since scribed and no evidence of rooting, etc., Have been advised that this corner was a relocation and set by double proportion, so propose further check.

From S.W. corner, (F.W.corner), ran easterly along old randome to circular 4700 Chs.pond, (Note that this so called circular pond due to its natural formation good and reliable natural call), note that the original notes indicate distance from west side of circular pond to be 4426 chs., and Vaughn notes, though not complete, 4138 to 1/4 corner plus Gov. 413 from 1/4 corner to West side of circular pond for a total of 4551. I find distance 2.74 chs. long. Returned to keil marked 1/4 stake and ran south to county trunk D for control point and leave.

Statement:

Mr. and Mrs. Lunz both advise that they were informed by the previous owner that the east line of gov. lot 7 was somewhat east of the car and wood shelter, and that the south line of gov. lot 7 ran slightly south of the outhouse on the hill east of the corner.

(1330-1630)

24-June, 1949. N.M.R.

Checked with maping Div. of the Wisconsin Conservation Department reference notes and possible old history, none of interest or other that on file in this office found.

(1200-1900)

27 June, 1949. N.M.R. H.R.

8300 Picked up line from west side of circular pond and ran easterly. Fell on poplar corner stake and from rooting of owiginal S.W. tree found evidence of old stake, 0.9 ft. north and set new corner post, (4X4 Pine Post), to sections 15.16,21 and 22, also found BT, W. Pine Stub 12-S-65 $\frac{1}{2}$ -W 68.2 ft. could not identify author of scribe.

Natural call from circular pond, (west side) to section corner checks with government notes.

Leave and go to Meander post on north side of Sand Lake on line between sections 20 and 21.

Mr. Joe Pitlick pointed out said meander post and claimed that he personally set a iron bed rail in place where the original M.P. was located. The B.T. and post as now set checks with the original government notes. Mr. Pitlik further stated that old fence line on the north side of the lake, (Sand Lake), is not on the section line and further that the section line as he remembered it ran somewhat east of this fence, thirty feet more or less and further that he recalled that a certain party now deseased moved the section corner westerly and set the fence line accordingly.

*No declaration taken from Pitlik, hence it was my opinion that any statement or declaration made by him may be treated by the courts as unreliable. *See notes.

Rained out.

Ft.

- 380.7 Ran from original Meander Post on North Side of Sand Lake, northerly on F. Wintcensen Line.
- 380.7 N-100-31 W, (All true bearings) over lake to meander post recently marked, (3-5 yrs.) from this post old fence line Brs.N-00-20! W.
- N-90-40 W to FW. and AL. corner post, no evidence of original post or 315.8 calls. Thence.
- 724.4 N-10-51'W, to F.W. Meander Post at south edge of flowage and Dam Lake. Thence N-10-50 W., over lake to meander post found post down dug up point and set 3101.4 $1\frac{1}{2}$ " iron pipe. B.T. Birch stp. 10-N40#. e.2 ft.
- 1171.3 N-00-33'-W., to section corner for sections 3,9,16 and 17, evidence this to be good corner.

4997.1 Total distance from F.W. corner to N.W. cor sect 16.

S.R. Check location of section corner to 16, 17, 20 and 21, when located by D.Prop. should be S-410-13'-W and 29.7' from F.W. Cor. therefore search for original.

West from corner post for sections 15,16,21 & 22. checking control from natural calls.

5-890-291W and establish search area. 5,297

> South and east found evidence of original section corner from rooting of S.W. tree, Brg. N-270-E 17 lks. fell on marking and evidence of stake in ground. From this point N-70-E 28 lks. found rooting and evidence of the NE. tree, also from evidence of original point and N-462 W, and at 39.81 found Vaughns NW BT. (Vaughn claimed .63 chs. or 41.58 ft. found this short 1.78 ft,), scraped further and found two other points bearing from original S-46-E .7 and 1.78 ft. respectfully. Conclude the 1.78' point to be Vaughn's, therefore believe evidence found conclusively establishes the location of the original government corner for sections 16,17,20 and 21.

- East Corrected: N-880-54.6 E. to SE.corner section 16. and find this to be 13 ft. short of 5284.2 Gov. Notes.
- S-50-28.7'W, to M.P. on north side of Sand Lake, (Original). 671.7 West Corrected to SW corner Section 17.
- 5675.1 N-880-44.3' W., to sec. corner. 395.1' longer than Gov. Notes. and 81 ft. longer than Vaughn's Notes. Though find string errors in Vaughns notes, no doubt due to copying (6278 should be 6578, and his 7933 should read 7733 or thereabouts.)
- 543.4 N-880-43 W, to east side of river, line falls 3.7 ft. south of out house on hill.

Gov. Notes indicate from section corner west to east side of river as 643.5 ft. I find east side of river channel to be 838 ft., west of section corner, which indicates a general expected natural westerly movement of the channel due to erosion. A 617 ft. distance from F.W. corner to channel would indicate that channel was at one time west of present location, in stumps and the movement easterly which would be contrary to natural movement. (No channel core deemed necessary).

Northerly on section line between section 16 and 17.

1080.8 N-40-39.6! W to post at waters edge.

1256.7 Same Brg. to 1/16 cor., or NW cor. for SW-1/4/SW-1/4, sec. 16, in water.

Reference:

* Ante, \$ 234; post, \$\$ 406,408,409,422. Barclay v.Howell, 6 pet. (31 U.S.) 498,8 L.ed477; Ellicott V.Pearl, Fed. Cas. No. 4386,1 McLean 206, affd. 10Pet. (35 U.S.) 412,9 L. ed. 475; Phillips v.Stewart, 133 Ky.134,97 S.W.6, 29 Ky.L.1199,124 Am. St. 441.

**Stewart v.Carleton, 31 Mich.270; Diehl v.Zanger, 39 Mich.601.

Courses and distances.

Blake v.Doherty, 5 Wheat. (18 U.S.O 359,5L.ed.109.Newsom v.Pryors Lesser, 7 Wheat. (20 US.) 7.5L.ed 382.

Certified Copy.

Reg. Prof. Engineer