


7676 T 39 R 8 W

① N¹/₄ NE¹/₄ would be at 19.852 ch.
(Wis. Valley Imp. 1938)

RECEIVED & FILED #	1676
Oncida County Surveyor's Office	
Date	JAN. 18 1988
By	mar
OCS Area #	



② N¹/₄ Sec 31 at 39.705 west of NE cor & 39.205 east of NW
Cor. 2" iron pipe. PW 28" - S42°E - 1.679 ch.; PN (off) N7°W -
0.633 ch. (Wis. Valley Imp. 1938)

③ N¹/₄ NW¹/₄ would be at 19.602 (Wis. Valley Imp 1938)

NW cor. Sec 30 at 39.205 west of N¹/₄ Sec 30 &
70.152 south of W¹/₄ Sec 30 2" iron pipe. PN 12" - N26°E -
9.349 ch.; PW 14" - N10°W - 0.530 ch. (Wis. Valley Imp. 1938)

Indicates corner
I think

See corner file
(corner on steep bank)

W¹/₄ NW¹/₄ found 2" i.p. + BT^s Maple 8" S72°W 1.46'
Maple 7" S30°E 8.65' Seymour 11/10/80

W¹/₄ Sec 30 ³¹ Orig. cor. ~~found~~? orig. stp. in place. set
w.c.r. pipe. MS 4" - S4°W - 0.135 ch.; ~~open~~ 10" - S47°E - 0.370 ch.; ~~open~~
10" - S78°W - 0.330 ch. (Beard 3/58)
See corner file

W¹/₄ SW¹/₄ Iron pipe at 20.095. BW 9" - S82°W - 0.150 ch.;
BW 8" - N63°E - 0.220 ch. (Beard 3/58)
found 1" i.p. + BT^s BW 12" N88°W 9.90'; BW 10" N63°E 14.75'
left as is, correct location would be S36°22'17"W 2.67'.
Seymour 11/10/80

L676.

31-39-8L676

⑧ Meander Cor N1S1/4 line - north of Pier 2" iron pipe. PN12"
N26° E - 0.349 ch.; PW 14" - N10° W - 0.530 ch. (Wis. Vally map 1938)

⑨ SMC See corner file

L676.

L676.