


3. T. 38. R. 7



① N¹/₄ NE¹/₄ Pw 16° N 20° E 0.380 (Dorr 11/27/1893)
 Set new post, New B.T. Pw 11" N 0.150
 (Vaughan Reg. 10, 1897). 2" Brass Cap Iron Pipe
 by Lytle in 1947 New B.T. Pw 20" N 82° E
 37.5 ft. (0.568 ch); Vaughans Pw (Stp)
20" N 75° W 0.375 ch (Stg Map 1967)
 found (1976)

② N¹/₄ Sec. 3 Orig. N¹/₄ Cor. set temporary post by record from stumps
 of both B.T.'s. New B.T.'s Pw 11" S 68° E 1.847 ch, Bw 8" S 31° E,
 1.704 ch. (Hall) Found w/6 conc post w/brass insert and Pw 11", Bw 8" Seymour 1976
 See corner file

RECEIVED & FILED # **L797**
 Oneida County Surveyor's Office
 Date APR 22 1988
 By *[Signature]*
 OCS Area #.....

L797


③ W¹/₄ SW¹/₄ B.T. Pw 26" S 51° W 0.270 ch. (Dorr 11/22/1892)

④ N¹/₄ SE¹/₄ PW 22" S 55° E 13.8 ft (0.209 ch) (Lytle 1947) (Dy's map 1967)

⑤ C¹/₄ NE¹/₄ 2" Iron pipe with Brass cap. P 527° 542° E 34.9', Bolt head in P. Pole 574° W 54.2'
(Seymour 1976)

⑥ MC on ¹/₁₆ line and NS¹/₄ line - 2" I.P. w/brass cap

Sec. 3 T. 38 N. R. 7 W.



① N¹/₄ NE¹/₄ Pine 16" N20°E 0.380 (Dorr 11/27/1893)
 Set new post, New B.T. Pw 11" N0.150
 (Vaughan Aug. 10, 1897). 2" Brass Cap Iron Pipe
 by Lytle in 1947 His B.T. Pw 20" N82°E
 37.5 ft. (0.568 ch); Vaughans Pw (Stp)
20" N75°W 0.375 ch (Stg Map 1967)
 See corner file

② N¹/₄ Sec. 3 Orig. N¹/₄ Cor. set temporary post by record from stumps
 of both B.T.'s. New B.T.'s Pw 11" S68°E 1.847 ch, Bw 8" S31°E,
 1.704 ch. (Hall) Found w/c conc post w/brass insert and Pw 11", Bw 8" Seymour 1976
 See corner file

③ W¹/₄ SW¹/₄ B.T. P_N 26" S 51°W 0.270 ch. (Dorr 11/22/1892)
 found w/c (wood post alongside) New BT's to w/c Pw 18" S15°W 32.85',
 Bw 8" N69°W 19.00'
 (1/29/87 Seymour)
~~etc.~~ could not find Lytle's corner monument. This w/c needs to be
 and verified.

④ N¹/₄ SE¹/₄ PW 22" S 50° E 13.8 ft (0.209 ch) (Lytle 1947) (Sly's map 1967)

⑤ C¹/₄ NE¹/₄ 2" Iron pipe with Brass cap. P 5 27° S 42° E 34.9'; Bolt head in P-Pole S 74° W 54.2'
(Seymour 1976)

⑥ MC on ¹/₁₆ line and NS¹/₄ line - 2" I.P. w/brass cap

⑦ W¹/₄ 3 found WCD new BT^s BW 10" N 7° E 28.38' FB 14" S 56° E 11.90'
55' east of Lake MH 12" N 89° W 24.55', PN 6" N 58° W 29.50'
(1-27-87 Seymour)

See Certified Corner sheet by J. Rein 2/20/88
this WCD is not for ¹/₄ cor

(1-27-87 Seymour) WCD on ¹/₁₆ line and NS¹/₄ line

2" iron pipe with brass cap

found WCD new BT^s BW 10" N 7° E 28.38' FB 14" S 56° E 11.90'
55' east of Lake MH 12" N 89° W 24.55', PN 6" N 58° W 29.50'
(1-27-87 Seymour)

Sec 6 + 7 38-7

See 38-7 field Book
Pg 33 + 146, 148found, Sec 6; SMC on Lake Tomahawk, wcd
W $\frac{1}{4}$ 2" ip, S $\frac{1}{16}$ 2" ip west line, ~~SE~~

Sec 7; NW 7 2" i.p.

N $\frac{1}{16}$ " 2 poss. locationsW $\frac{1}{4}$ 7 2 poss locationsS $\frac{1}{16}$ " 2 poss locations~~W $\frac{1}{16}$ north line~~~~N $\frac{1}{16}$~~ E $\frac{1}{16}$ north line 1" i.p. needs further checking