

D.H. VAUGHAN # 5

5

D H Vaughan

July - 1905

BOOK NO <sup>5</sup> 4

opened JULY 19-1904 closed DEC 30-1904

all new bearings are made with  
instrument adjusted on 4<sup>th</sup>.

from Oct 10 to Dec 28  
my tape was 6 inches to long

Book 5



58

109

Survey of Road for Town of  
Minoeque July 19.. 1904

commenced and completed  
on above date

Beginning at a stake which stands  
on the line between S.E. 27-34 in  
Township 39. N. R. 6. E. and  
24.30 East of cor to S.E. 27-28-33-34

Stump 7 N 42 E 38  
" " 6 N 89 W 31

Courses	chains
N 5 1/2° E	232
" 12 "	401
" 27 1/2 "	207
S 85 " " "	222
N 25 " " "	411
" 55 " " "	745
" 73 " " "	323
" 76 1/2 " " "	763
S 75 1/2 " " "	756
N 87 " " "	647
S 61 " " "	973
" 76 1/2 " " "	823
" 84 " " "	876
N 58 " " "	491
" 56 1/2 " " "	794 To Minoeque and Hazelhurst Road and set Post

COPIED ON PAGE 79  
COUNTY RECORD

{ W.P. Stump 18 N 55 W 38  
NO OTHERS

This Post stands in SW SW 26 and near the  
center

Angle.

61°

10'  
20  
30  
40  
50

62

10  
20  
30  
40  
50

63

10  
20  
30  
40  
50

64

1  
2  
3  
4  
5

65

1  
2  
3  
4  
5

66

67

68

69

70

2 SEC 21-37-9 E July 24-1905

Went to NE corner. Set hub from a  
W. Pin Stub 12 N 57 1/2 E 94 which I marked  
in 1900 before org BT were removed

Run west on Var  
1200 Enter Swamp  
1600 Leave " copied on Page 221  
2300 Enter  
3432 fell 206 N of 1/4 P. " org BT  
Went East and set 1/8 P. at 17-16 ch  
and 103 S of Randam W Pin 20 N 14 W 107

Run South from this 1/8 P. Var on  
2638 Intersect Rhinelandes Road and set  
Post. {W Pin Stump 20 N 32 1/2 W 28  
This was done for Town of Rhine Lakes  
They wanted the road on 1/8 line but said  
" could not afford to have the section  
surveyed. and to get the road as near as I  
could to 1/8 line I know it is not but  
I know it is as good a guess as I can  
make under the circumstances  
county record

3 SEC. 23-36-8 E July 26-1905

Went from NE corner Var 550 E  
3174 fell 120 S of ME. which I set from  
both org. BT.

SEC far corner 366, corner Var 300 E  
Went East and set 1/8 P. not under near  
from wood post 3x3 in 3 1/2 feet long  
I found a short tap between corner  
and ME. which I proportioned and set  
1/8 P. at 1959. and 71 1/2 N of Randam  
Runs S from this 1/8 P.

1999 3/4 Chain. Then East to 1/8 P. which is c.  
Poly. 10 ins in dia. Supporting the wire  
of Rhinelandes Power Co  
found I was 24 links to far East  
Set 1/16 P. in center of NE 1/4.  
Distance to E cor. line 10 1959 ch  
Chain - you will find " more about this  
section in book 3 on Pages 151 + 155

SEC 36-36-10 E July 31<sup>st</sup> 1905  
Went to N 1/4 P found post I set 3 weeks ago the BT  
was cut + marks nearly obliterated. Made new  
bearing W Pin Stump 18 S 83 E 13 3/4  
as this 1/4 Post is only about 2500 ch west of  
Range line I run South Var 80 W  
9950 found Town line. Went E and found  
1/4 P. about 1700 ch. SO I went back  
copied to N 1/4 P. on Page 322  
= [August 1<sup>st</sup> 1905] =

South from N 1/4 P Var 30 E  
9846. fell 49 E of 1/4 P. which I set from  
The W Pin which stands N 30 E 15  
Went to NW corner Set Post from both org  
BT. aspen is down + rotten Pine is ok  
Run South Var 3 1/2 E. county record  
2150 Enter Swamp - 35 Leave Swamp  
4136 fell. 330 East of 1/4 Post which I set  
from the Linden which is nearly  
over

copied on Page 122

copied on Page 122



Copied on Page 322  
+ SEC. 36-36-10-E cont. Aug 1 1905

gone the Fir is all gone but the roots  
made 2 new bearings  
Hem 10 N 89 1/2 E 26 1/4  
Hind 12 S 20 1/2 W 17 1/2

East West N + set 1/8 Post { Birch 12 S 77 1/2 E 9 1/2  
{ Fir 8 S 58 W 23 1/2

I did not correct this line as same one has cut  
the timber in SEC 35 and trespassed 1,500 ch on  
the NW NW. at SW cor

Run East from W 1/4 Post Var <sup>715</sup> 150 W

7600 could not find 1/4 Post U.S. cor for 2 alder

I found the old line at 7000 ch. but set line  
line stakes at 7600 ch and went to NE

corner and run S Var 3 1/2 E.

corner is in Swamp + line was in Swamp  
nearly all the way

7936 feet 953 ch west of corner. This corner  
is gone except a small piece of the NW  
Birch. (And wolfgram who lives in NE cor  
of Sec 1) had made a box and put it over  
this piece and kept it for several years. I set  
a cedar post from this B.T. on the stump to it  
and piled rock around it.

Went North and set 1/4 Post at 3968 and  
476 1/2 East of Random { Cedar 10 S 76 W 32  
" 10 S 21 1/2 E 17

There is log of 1000 chains at this corner  
I do not think the U.S. surveyor run this line  
The correct Var is 1030 East

Picked up E+W 1/4 line at 7600 and prolonged  
it East on same course 715 E at

8129 feet 216 N of 1/4 Post SEE P 14  
Went west of set center

W Pine Stump 245 S 55 W 16 1/4  
Distance to N 1/4 Post 4983 4983  
" " S " " 4863 4863

" " W " " 4549 4574

" " E " " 3540 3555

This makes a peculiar section  
country record

SEC. 36-36-10E Aug 3-1905

Went north and set 1/8 Post at 299 1/2 North  
of center { Birch 10 N 5 1/2 E 14  
" 12 S 32 1/2 E 32

Copied on 322  
Run west from this 1/8 P Var ~~715~~ E  
a change in course from E+W 1/4 line  
of 14° 30' country record

corrected line E to 1/8 P  
SEE Page 14

### Survey of Road for Town of Cassian

East from cor to Sections 20-21-28-29. 36-6-E  
August 5 1905 Var 4 1/2 E

2100 Enter Swamp  
2474 to Right bank of Tenahawk River  
3387 " Left " " " "  
3462 feet 16 links S of MC org B.T.

Copied on Page 302  
East from this MC Var 4 1/2 E  
790 feet 5 links S of 1/4 P.

Set new Post from ang BT as they are nearly  
gone I made new bearings

{ B. Pin 10 N 60 W 110 1/2  
" 10 S 44 W 66

Corrected west for Road

East from 1/4 P. Bot 21 + 28. Var 4 1/2 E

3650 Enter Swamp  
4038 feet 14 S of Post Cor to 21-22-27-29  
corrected west for Road & set this cor  
2 years ago + made new bearing

East from this Sec cor Var 4 1/2 E

3600 leave Swamp  
2475 Enter " country record  
3500 leave " "  
3992 feet 95 N of 1/4 P. corrected west for Road

Survey of Road for Town of Cassin

Beginning car of SEC 20-21-28-29-36-6-E  
 Thence East on Sec line 1900 ch  
 " N 43 E 576  
 " S 72 1/2 E 494  
 " S 41 E 2,12 1/2  
 " S 4 E 273  
 " S 31 E 175  
 " S 18 E 155  
 " N 28 E 340 to Sec line  
 " East on Sec line 529 " 1/4 P  
 " " " " 4038 " Sec cor  
 " " " " 3992 " 1/4 P

Copied on page 66

copied on page 66 county

SEC 24 39-6E August 14 1905

went to S 1/4 P. Set Post from Stumps of Both org BT. and run N Var 2 1/2 E on a line run by Mansell said to be the N + S 1/4 line

1770 entered Lake and found Mansell's B.T. { WPine Stump 20 S 67 W 16

" " " " S 22 1/4 E 52 1/2

copied on page 66 county record  
 Aug 16 1905

went to S 1/4 P and run E Var 4 1/2

1056 to Top of hill over Pond

3262 " Lake

3733 " Top of hill over Lake

4113 fell 29 links S of Post 1 org BT and Post. cancel Var 4.40

SEC 70/100

cancelled line west and set 1/8 Post at 2056 1/2 and 14 1/2 N of Pond

WPine Stump 28 N 27 W 59

Blk oak S 31 1/2 E 44 1/2

SEC 18. 36-8 August 22-1905

went to center of SEC set by Mansell and approved by Dorr found three Post. 2 of them were very close together, the other stands 2 1/2 feet Nouth and a little west, all had used the same B.T. which is a WPine Stump 24 S 40 E 11 1/2. I run East Var 3.30-E

4240 feet 187 N of 1/4 P. 2 Posts here both set from the two org B.T. I did not use Mansell's Post. but used the one which stands East and a little north they are 2 1/2 feet apart  
 went west and set 1/8 P { Sugar 8 N 24 W 17 1/4  
 " 8 S 29 1/2 W 29 1/2

Found Mansell's Post a little S and west  
 canceled line west to 1/8 P

copied on page 119 county Record

changed S from center on Mansell's 1/4 line  
 12:59 found his Post in corner of fence

went South to find corner which is in an oat field. Found one west end and one E. The son of a Mr Polka who owns the oat field came and showed position by to the location of this 1/4 P. from marks he had made when the Post was standing, and from what I could find by measurements from one I think he is right. I am E from the Point he designated  
 Var 4 1/2 E

4235 feet 116 1/2 South of corner. both org BT made new Post and went west and set 1/8 Post

WPine Stump 10 S 28 1/2 E 17

Run N from this 1/8 P Var 4 1/2 E

4411 feet 67 west of my 1/8 P

cancelled line South 22 1/2 links and set 1/16 P

I set this Post as the 1/8 Post on Sec line N of SE corner is in lake I wanted an intermediate course. I then set flag at this 1/16 P and one at 1/8 P South of center placed instrument on line between the two and set a line stake between the two Posts

over

Run N from center Var  $3\frac{1}{2}$  E  
 1967 feet 1 link west of Mousells  $\frac{1}{8}$  Past  
 copied } WP in Stump 20 N 20 E 16  
 no other

3731 See Right of way on Page 119

3934 feet 2 links W of corner

The Stumps to the org BT as then the NE corner is cut very low marks cut off. The NW one is a round full marks on plain

The Soo Road runs through the NW Fraction  $\frac{1}{4}$  of this section an angle of S  $72\frac{1}{2}$  west Var  $3\frac{1}{2}$  E  
 Went South to  $\frac{1}{8}$  P. and run west Var 00

3266 feet 18 links N of  $\frac{1}{8}$  Past Set by Dorr

Run N from this  $\frac{1}{8}$  P Var  $3\frac{1}{2}$  E

275 See Right of way. went back to  $\frac{1}{8}$  Past and connected line East at 1025 ch west of  $\frac{1}{8}$  Past set Past and run N parallel with N +  $3\frac{1}{4}$  line count Record

1270 See Right of way. cut 20 acres off the East side of the NW Fraction  $\frac{1}{4}$  of this Sec The balance South of Soo R.R. belongs to Emery Nelson  
 Finished Aug 24 at noon

Found center of Section Set by Dorr Post had rotted off but lay when it fell on B.T. was grubbed out for Road. the other is White Pine 9 N 16 W 9  $\frac{1}{2}$

Started S on  $3\frac{1}{2}$  E. but at 156  $\frac{1}{2}$  found Dorr Talley Stake set flag of same metal Shows a Var of  $4^{\circ}.05'$  at

1995 feet  $\frac{1}{2}$  links W of Dorr  $\frac{1}{8}$  P.

2200 Enter open marsh. Small lake 200 East

3050 open " " "

3250 Enter marsh Very rust

3990 feet 3 links West of  $\frac{1}{4}$  Past. found Dorr Post and roots of Stumps of both org BT set Stake at each and new bearing

W Bink 10 N 41 W 28

connected line N to center and

Prolonged North

318 Entered at Lake + set MC + went to Book 12 N 64 E 7

South  $\frac{1}{4}$  Past and run E Var  $3\frac{1}{4}$  E

900 Enter wet marsh or open swamp

1450 open " " " " "

1500 Enter " " " " "

1896 open " " " " "

2032 feet 11 links S of  $\frac{1}{8}$  Past set by Dorr new bearing } Crotchety Pine Stump 16 N  $55\frac{1}{2}$  W 28  
 W " " 145 2 E 12

North from this  $\frac{1}{8}$  P on unlearned course Var  $3-35$  E  
 3848 Entered at Tomahawk Lake + set MC

This Stump is part of 2 WP in Stump 45 7 E 16 other Stumps which are no other near larger and both same

copied on Page 55 county record







and set  $\frac{1}{8}$  P. 2075 South of center  
 { WPine 16 1/4 N 32 E 14  
 .. .. 25 " 28 W 39

Went N + set center { WPine 22 N 27 W 50  
 .. .. 12 N 55 W 42

Distance to North  $\frac{1}{4}$  Post 4150

" " South " " 4150

" " East " " 4215

" " West " " 4178

Went west + set  $\frac{1}{8}$  Post { Tam 6 N 89 W 5  
 { Spun 6 S 42 E 47 1/2

North from  $\frac{1}{8}$  Post west of center var 1.55 E

350 Leau Swamp

3637 center C + NW RR Sept 23 - 1905

3700 Enter Swamp

4127 fell 23 1/4 East of  $\frac{1}{8}$  Post which I set at this  
 time { Tam 12 N 61 1/2 W 47  
 .. .. 22 S 35 1/2 E 41 1/4

I then went SE and set  $\frac{1}{8}$  Post N of center at  
 2075. north of center. { WPine Stump 14 N 17 W 28 32 1/2  
 { no other near on East of line

Run west from  $\frac{1}{8}$  P. north of center var 2.20  
 = Sept 25 1905 =

41.66 fell 32 links South of  $\frac{1}{8}$  Post.

Went E + and set  $\frac{1}{16}$  Post in center  
 of NW  $\frac{1}{4}$  { WPine 26 N 21 W 24  
 { Birch 10 S 66 1/2 W 19

corrected line north to  $\frac{1}{8}$  Post and E to  $\frac{1}{8}$  P  
 copied on page 314

Set  $\frac{1}{8}$  Post E of center { Birch 16 S 82 1/2 E 20  
 at 2107 1/2 E of center .. 8 S 84 W 30 1/2

South from  $\frac{5}{4}$  Post var 2.10 E

2300 enter creek bottom

2500 Stream 40 runs west

2600 Leau creek bottom counter record

4136 fell 38 1/2 E of SE corner new Post set by D.H.U

Went N + set  $\frac{1}{8}$  P.

{ WPine 10 S 70 W 37 1/2  
 .. .. 20 N 40 1/2 W 43

Went from  $\frac{1}{8}$  P. S of  $\frac{5}{4}$  P. var 1 1/2 E  
 4166 fell 54 N of  $\frac{1}{8}$  P. corrected line ident

copied on page 317 counter

South from  $\frac{1}{8}$  P. E of center var 1 1/2 E

2890 enter creek bottom

3100 Stream 50 runs west Record

3400 Leau creek bottom

4143 Hit  $\frac{1}{8}$  Post set by Miller

corrected line north did not set  $\frac{1}{16}$  P

|||||

SEC 25-36-10-E Sept 28 1905 - PM

Went to  $\frac{5}{4}$  Post. an iron pin on S side of wagon  
 track which I set in July 1905 run N var 30 E

4127 fell 5:35 E of corner. corrected line south

and set  $\frac{1}{8}$  Post { Dead Tam 12 N 3 E 45

" " " " 8 S 36 1/2 E 16

copied on page 317

Set  $\frac{1}{8}$  Post N of center from my Rand  
 I run in July 1905. 2628 1/2 N of center and

2 1/2 links E of Rand. { W Birch 14 N 17 W 22

" Pin 28 S 50 E 21 1/2

Run E from  $\frac{1}{8}$  Post N of center var 24 West

2937 fell 10 links N of  $\frac{1}{8}$  Post

corrected West to  $\frac{1}{8}$  Post

Went to NE corner and run west var 30 W

2999 1/2 fell 21 ch S of  $\frac{1}{4}$  Post on BT

corrected E + set  $\frac{1}{8}$  Post - corrected E to corner

correct var 36 E { B ash 8 N 36 1/2 E 19

Tam 16 S 29 1/2 E 48

Run South from this  $\frac{1}{8}$  Post var 5 1/2 E

690 Leau Swamp

3171 E.M. + St. C + NW RR

4330 Enter Swamp/6 counter

4685 fell 44 W of  $\frac{1}{8}$  P. made new BT

corrected line N + set  $\frac{1}{16}$  P { WPine Stump 15 N 18 11

{ Sugar 12 N 50 1/2 E 35 1/2 no other run

made 8 N 76 1/2 W 28 1/2 record

corrected line N + West from  $\frac{1}{16}$  Post and from NE corner to  $\frac{1}{16}$  P

I found the chainman had made an error of 10 chains in N + S 1/4 line. or had marked Talley Stake wrong. They had 50.00 ch marked 60.00 ch and my center is correct & have to move it East 15 links. which I have done

Copied on { W Pin Stamp 24 S 72 E 27 1/2  
 Page 322 county record

I then had to move my 1/8 P N of center 500 ch N. and set bears at 2491 ch N of center and 37 3/4 links west of Random  
 { Birch 9 N 18 1/2 W 37  
 Sugar 10 9 10 W 16 1/2

Run west from this 1/8 P Var 215 W  
 4413 feet 113 S of 1/8 Post. Canceled line East 1/8 Post  
 This is all in 361

SEC 20-37-8-E Oct 3rd 1905  
 went to SE corner found SE B.T. OK. NW Tree gone  
 Set new Post + Run N Var 3 1/2 E  
 3800 Enter Tans = Swamp  
 4000 could not find 1/4 Copied on Page 145  
 5000 Jean's Swamp  
 7600 ~~off set East~~ Enter Swamp  
 7740 ~~off set East~~ 274

Thence N at Right angles with ~~off set line~~  
 427. and fell 9 links E of corner 2013 BT  
 Note will read  
 8167 feet 285 West of corner  
 Went S and set 1/4 Post  
 county { Tam 10 S 50 W 15 1/2  
 .. 79 40 E 19

Run west from E 1/4 Post Var 3 1/2 E  
 500 Jean's Tans Swamp  
 9015 West boundary but NO 1/4 Post  
 record

Went to MC on N shore of Lake  
 Found both org B.T. West one is a stump 4 feet high  
 Set new Post and run N Var 00

When I came to Set M. Post I found the trees did not hook up for course and distance and I set Post at best I could to harmonize the discrepancy B.T. Read 1/8 Pin 12 N 70 E 6  
 Copied on { .. 12 N 80 W 13  
 Got notes Reads { .. 12 N 10 W 6  
 .. 12 N 70 E 19

When I run N from this one. Var 00  
 1510 feet set West marsh  
 1850 over .. Page 145  
 2000 d set West 140 ch. changed course to 4° E  
 I did this as I thought the line I found at this point would run to NW corner  
 5906 feet 491 West of corner which I set at the intersection of the 4 lines. could not find bearings as the fire has burned them out. and I know the corner North is gone  
 So I placed this one as near as possible in original position. and believe it is nearer its original than can be obtained in any other manner. There was a windfall  
 Passed over an N side of Lake milled a great many years ago. and the old line is nearly obliterated nearly to the NW corner  
 Went South and set 1/4 Post. at proportion-  
 - at distance. found an even run of 65 links. Set 1/4 Post at 1797. N. of meander county  
 full Pin ~~10 N 54 1/2 E 26 1/2~~  
 .. 10 N 43 1/2 E

record { W Pin 10 N 54 1/2 E 26 1/2  
 .. 10 N 43 1/2 W 20 1/2

Picked up my E + W Random Random  
 from E 1/4 Post. and at  
 7914 feet 448 ch N of 1/4 Post which is at  
 Proportional distance between one + SE cor  
 canceled line E to E 1/4 Post  
 Set an 1/8 P. South of E 1/4 P. W Pin 10 N 77 W 16  
 .. 9 S 59 E 33  
 canceled line N to 1/4 Post. This all in 20  
 Sunday Oct 8 - 1905





SEC. 23-36-7 E Oct 13 1905

went to E 1/4 P. which is an iron bolt 8 ins  
under ground on E side of RR track in fill  
and about 2 feet from E Rail

Set 8 corner on hill west of Post  
Set flag at 1/4 P. and at center of SEC. lit by  
Dorr. Placed instrument line var 2 45 E  
37.11 to center. Prolonged West. at  
2056 west found somebody's 1/8 P. No marks  
on Post and no Bearings

4112 Old road. orig. B.T. are glubed out and  
gone. as I believe Dorr set the center I  
think my line is correct and set  
1/4 Post at 4112 } W Pin Stump 24 N 48 1/2 E 47  
" " " " 14 S 12 E 59 1/2

Run South from west 1/4 P. var 330 E  
2050 wet marsh Copied on page 45  
2300 over wet marsh count Record  
2959 wet swamp  
3547 center of Soo RR track  
4006 fell 18 1/2 links west of corner in wet marsh  
corrected var 345 E

went N and set 1/8 Post at 2003 and 98 1/4  
links East of Random

{ W Pin Stump N 2 W 34 links  
" " " " 14 S 60 W 46 1/2 "

Run East from this 1/8 P var 2 45 E same  
course as E + W 1/4 line

2056 Set Temp 1/16 Post. Same distance from SEC line  
as 1/4 Post is west of center. 1/8 P.

South from 1/8 P. west of center var 345 E  
2003 intersect 1/8 line 28 links west of Temp corner as Temp  
corner is correct Set 1/16 Post at this point  
needle shows course of N + S 1/8 line at this point to  
be South var 2.45 E change of 12

corrected line N to 1/4 Post for road  
The reason for my doing this work in this  
manner is. The S 1/4 P. is in Lake. Meander

SEC 23-36-7

on west side of Lake is gone. and the one on E side  
is in 2 feet of water as Lake is very high SW corner  
is in wet swamp so it is not possible to run the  
South line to get 1/4 Post. neither can I get to S 1/4 P  
and consequently cannot get 1/8 P. South of center  
Oscar Jean's owns the land in SW 1/4  
and he is satisfied with this survey

Bearing for 1/8 P. west of center is a large boulder  
in SW Point of hill. There is a light colored vein  
about the center of this boulder, at a point where  
where the dark rock intersects this vein and  
the south side it is N 66 E. 83 1/2 links Post is a W Pin  
3 + 3 ins.

Set 1/8 P. E of center } W Pin 12 N 59 E 105 links  
Copied on page 45 } " Stump 18 S 35 1/2 E 33  
Road will be as follows  
commencing at E 1/4 P. Thence west on 1/4  
line to 1/8 Post west of center 57.67 ch  
Thence south on 1/8 line 20.03 "  
" west " " " 20.56 " to 1/8 Post  
on west Section line and 2003 South of  
W 1/4 Post. Oct 14 - 1905 Count Record

SEC 14 36-6 Oct 21 - 1905

went to 1/8 Post E of SW corner which I set on  
year ago + Run var 2 45 E.  
3948 fell 6 1/2 W. of 1/8 Post I set 1 year ago  
went S + set Temp 1/16 P. at 1974 ch  
and 32 1/4 E of Random

Set flag at S 1/8 P on west SEC line  
and instrument at Temp 1/16 P. and  
set a row of line line stakes between these  
2 points for road. corrected line S from  
Temp 1/16 P. to S to 1/8 P for road

This is all in 14  
County Record



SEC 23-36-6 E Oct 18" 1904

Went to SW corner identified by 4 org BT  
They are all stumps. Set Post + run E Var 3 1/2  
4000 1/4 P. could not be found  
4350 Enter Tarn + cedar Swamp  
5500 Lean  
8169 feet 20 links N of corner which is  
identified by stumps of 3 org BT NW one  
is a stub 7 feet high it was down & set  
it up and braced it. Set new Post and went  
west and set 1/4 P. Y Pin 9 N 6 E 88 1/2

Went west & set 1/8 P.  $\left\{ \begin{array}{l} \text{Stump 145 5 1/2 E 90 1/2} \\ \text{B Pin 8 N 61 E 41 1/2} \\ \text{Y Pin 145 31 E 79} \end{array} \right.$

corrected line west to corner for Road

Went to 1/8 P. E of NW corner and run S Var 3 1/2 E  
7750 met marsh

7900 over

8074 feet 16 west of 1/8 Post

corrected line west 8074 ft to 1/8 P for Road  
this 1/8 line may not be straight when section  
is subdivided but think Road will be  
inside the 4 rod limit.

This is all in 23 at present

Pos  
copied on  
Page 634

SEC 18" 43-8 E. Nov 2 1905

Went to Mc. on Tenderfoot Lak Bet 17-18  
found both org. B.T. Set new Post and  
run South Var 12 W  
20.00 Enter Tarn Swamp  
23.61 full 2.34 1/2 West of 1/4 Post which I set  
from. The N org B.T. South on gov.  
corrected line N to 1/4 Post.  
Correct Var. 4 1/2. SEC 5.34

Went to Mc. on west side of Lake between  
7 & 18. found the South B.T. down marks  
Plain on trunk of tree. N tree gone  
found a round one from 1/4 Post to island  
6 links South of Mc. chained west on Randsau  
1422 Var 3 1/2 E

1922 1/4 Post Both org. B.T.

Set new Post. and run South Var 4 1/2 E

3180 N Bay of Lake Hoop west of them N Point

Went to East 1/4 P. and run W Var 4 1/2 E

275 Lean Swamp.

1400 Enter old windfall (Small Hardwood)

2800 Lake 2 chains South of line. E Shore of Lake

3500 " 1.50 South of line

3990 Jitters of Lake

5280 over

7949 full 10 1/4 links S of 1/4 P Sugar B.T.  
is ok Hemlock down + Rotten set new Post  
Went East + Set Center Hem 10 N 32 W 25 1/2  
cedar 10 S 22 W 46

The N + S 1/4 line is an intermediate  
course bet E + W SEC lines

West line runs on 3 1/5 E = 800

East line " " 4 1/5 E

N + S 1/4 line is run on 4 1/5 E

Corrected line E from center to 1/4 P

SEC for correction 131

Corrected Var 3 1/5 E

Blazed N + S 1/4 line N to 1/4 P over

SEC 18.43-8-E cont. No 04 1905

Meander of Tenderfoot Lake in SEC 18.43-8-E  
From me BET 17-18

N. 83.10 W	ch along steep bank heavy timber
S. 86.45 W	" " " " " "
S. 69-- W	" " " " " "
N. 84-- W	" " " " " "
S. 86-- W	" " " " " "
S. 83-- W	" " " " " "
N. 74 1/2 W	11.00 " on Lake shore on ice
N. 37 1/2 E	6.00 " " " " " "
N 35 E	2.50 " " " " " "
N 8 E	2.75 " " " " " "
N 8 1/2 E	1.00 " " " " " "
N 65 E	2.75 " " " " " "
N 62 1/2 E	1.60 " on land over ice
N 35 W	1.00 " " " " " "
S 80 W	1.20 " " " " " "
N 67 1/2 W	2.25 " " " " " "

To me. BET SEC 7+18

From me BET 17+18 Rahr. Island is  
N 25° E about 1700 ch

SEC 7-43-8 MOU 5 1905

Meander of Tenderfoot Lake in  
SECTIONS 7+8

From me BET SEC 7+18

N 26 W	7.25 ch over bay of Lake
" 3 1/2 E	2.00 " " land near shore
" 2 W	1.50 " " " "
" 40 1/2 E	12.00 " " Lak. Shore line 100 W
" 58 E	2.75 " " Land
" 80 1/2 E	8.80 " " Lake " " 50 N
S 14 1/2 E	15.25 " " " " " 100
" 23 E	2.00 " " Land Rahr. Island S 33 E 500
N 48 1/2 E	1.50 " " " Rahr. Island S 33 E 500
" 58 1/2 E	4.60 " " " and Lake SEE map
" 45 E	2.00 " " " "
" 10 W	.75 " " " "
" 55 1/4 W	2.00 " " Lake
" 37 W	7.65 " " Bay 2 Lake notes
" 12 E	9.00 " " Bay 200
" 1 E	2.00 " " Land
" 64 1/2 W	2.00 " " SEE line 4 links E
" 74 W	2.25 " " Land SEE line 4 links E
" 44 W	15.60 " " Lake SEE notes
S 48 E	6.40 " along Lake shore
N 54 3/4 E	2.75 " over land Shore 50
" 50 1/2 E	11.50 " " Lake Bay 50
" 39 1/2 E	2.50 " " Land Shore 50
" 80 W	7.00 " " See notes
" 73 1/2 W	8.00 " " Bay Lake To me on STAT boundary. 83 links E of 29" mile Post

Small bay to left on course N 58 1/2 E 410  
 on course N 37 W - 765 SEC line Bit 7 + 8 200 W  
 " " " 44 W 1560 Bay 100 links for 300 ch  
 Then bay 1000 wide extends west 500 creek 5 links  
 wide enters west end of bay. The timber is all  
 dead along Lake Shore from end of this course  
 to Stat boundary  
 on course N 30 W 700. a green Point 1/2 of  
 which is in rich extends N 250 ch and is about  
 150 ch wide E-W  
 on last course N 73 1/2 W 800. a Bay extends  
 S W 350 ch

N from South 1/4 P Var 3 1/2 E Noo 6 1905  
 1350 Enters Swamp  
 2300 Leave "  
 2350 Enters "  
 3000 Lake George 200 west of line  
 3200 Leave Swamp + Enters Pine timber  
 3250 Same Lake 350 W of line  
 3400 " " 75 W "  
 3700 North Point Same Lake 400 west of line  
 4000. Set Temp center and run west Var 3 1/2 E  
 400 Lake George 75 links S  
 1000 " " 250 " "  
 2000 " " 400 " " Lake bears SW + NE  
 37 12 feet 29 links S of 1/4 Post found both org  
 B.T. and part of org Post

as I had chained from S 1/4 Post west to  
 corner and found distance 4042 ch. I carried  
 line E and extended same East 330 making  
 distance of this line same as SEC line from  
 South 1/4 Post to SW corner

Set center { Spur 8 N 42 1/2 E 25  
 18 ch 8 S 20 E 15 1/2

corrected N + S 1/4 line South from center  
 to S 1/4 P.

XXXXXXXXXX

SEC 35-36-9 E NOV 13 1905  
 Went to N 1/4 P. which I set last April and  
 Run South Var 40 E  
 2100 Enters Swamp  
 3200 Leave "  
 4550 Enters "  
 6500 Leave "  
 6975 creek 10 wide runs NW and enters Swamp  
 7500 Leave Swamp  
 8643 full 111 West of 1/4 P. which I set from  
 Stumps of org BT and other evidence of  
 org 1/4 Post.  
 DEC for correction 128  
 correct Var 40 40  
 went North and set in stake at 43 1/4 6 1/2  
 and carried line north to 1/4 P

Went to NW corner found Post set by  
 Dan. He had made 2 BT. { ashen 12 N 62 E 70  
 " 8 S 55 E 43 1/2  
 I made new bearing W.P.S. 36 N 8 W 59  
 Found Dan's Random running S Var 50 E  
 chained South. Poor chainman. Poor chance  
 to chain but found distance through 9676  
 as the Post set by Dan at SW corner was  
 not where it should be to agree with  
 Set notes. and as I could not locate  
 Dan's Random, exactly at south end  
 I did not try to set 1/4 P. as 1888.  
 and W Hardell would not try to have  
 the work done right I quit the work  
 and will not try to set Post  
 without running the line

||||



D  
S&C 34-36-10-E Nov 16-1905

Went to NE found Post & set from org B.T. in Sept 1905. Run South Var 20E

1300 Enter Swamp

1900 " creek bottom

2250 creek 25 links wide runs west

2650 leave creek bottom

3250 Top of Edge of Rock Copied on Page

3450 Enter Swamp

4112 fell 75 links E of 1/4 P. Long B.T. + Post

D&amp;C for correction 1.81

cancel Var 10E

Went north and set 1/8 P. at 2056. and 37 1/2 W of Rand

Post sets in creek bottom Tam 10 N 9 W 155

" 8 N 17 1/2 E 167 1/2

Corrected line north to 1/4 Post

County

West from NE. Corner (where I made new bearing) W Pin 18 S 33 W 82 Var 3 1/2 E

30.00 center of Johnsons RR

41.83 File 89 Sof. 1/4 Post. Set Post from 2

For 1/8 P; Org B.T. Birch is down maple OK

S&amp;C Page 1 made new bearing Item 10 S 48 E 37

cancel Var 2 1/2 E. D&amp;C for correction 2.13

West from N 1/4 P Var 20E

8700 Enter Windfall

4107 fell 4 links N of of Corner bound Post &amp; set 7 years ago. Both BT down.

marks plain made 2 new bearings

Cedar 10 N 52 1/2 E 39 1/2

" 8 S 23 1/4 W 52

the timber was all standing when I set this Post 7 years ago Went East and

Set 1/8 Post Tam 8 N 82 E 26 1/2

" 6 S 60 1/2 W 20 record

South from NW Corner Var 10E

They say the West 1/4 Post has never been found but I know the Gout line 4 links South 1/2 mile and no farther I run N from South West corner 7 years ago when snow was deep and I could not find it

my B.D  
S&C 34-36-10-E Nov 17 1905 cont'd

500 leave windfall + Enter Swamp

2000 " copied on Page 321 "

3600 Enter

3931 Looked for 1/4 P for a long time but could not find it at 4050 found Tamarack tree which was marked for line 42 years ago at 4100 <sup>4</sup> standing to 4300 ch there is an old blow down. that is nearly 40 years old and several small W.P. and aspen but they are all rotten & tried several W.P. but could find nothing to warrant my setting 1/4 Post from offset E 307 to my old Randam. chains South to

4891 and found my 1/4 Post 151 links E of Rand

This makes my dept an old randam

302 links west of N.W. corner

West made new bearings Item 14 N 34 1/2 W 33 1/2

Aspen 12 N 1 E 18

Went north and set 1/8 P. W Pin 14 N 8 E 22

at 73.36 1/2 and 226 1/2 E of " 20 N 20 W 23

all randam

East from West 1/4 Post Var 80E

500 Enter Swamp on low ground

2700 Leave

3700 Enter bottom to Marico creek

4740 Marico <sup>Branch</sup> creek

4675 Leave creek bottom Nov 19-1905

5400 Enter Swamp

5800 Leave

6200 Enter

7710 fell 31 South of 1/4 Post

cancel Var 8.15 East D&amp;C for correction .40

XXX E 1/8 Post on N SEC line

Item 10 N 21 W 5 3/4

W Pin 20 S 10 1/2 E 48

County record



South from N 1/4 P. Var 6 1/2 East  
 900 Enter cedar swamp  
 1350 Lean " "  
 1750 Spur of RR copied on Page 321  
 3800 Enter Enter " "

3800 Lean " "  
 4400 creek bottom " "  
 4563 cross E+W corrected 1/4 line  
 4750 Monico creek 25 links mid runs NW  
 4850 " " " " " " SE  
 4985 " " " " " " West

5750 Lean creek bottom  
 5550 Enter Hay meadow (Needle Shows 7 1/2 E)  
 6300 Lean " " " " " "  
 8050 Enter Tann Swamp " " " " " "

9908 full 188 West of 1/4 P. Found Post and Stump  
 of Tann with Rt. Plain. Stump + trunk of Spruce  
 is there but marks as gone. Made new  
 bearings } Tann 4 N 84 W 11 3/4  
 " " " " " " 4 S 55 E 33 1/2

Went N + set center at intersection of  
 Corrected 1/4 lines } W Pin 24 N 44 1/2 W 18 9/2  
 Post sets in creek bottom } no other near  
 Distances to N 1/4 Post. 4563 = 4908  
 set 1/4 P. S of center at " S " " 5345  
 " " " " " E " " 3646  
 " " " " " W " " 4064

Set 1/8 Post S of center at 2672 1/2 W Pin 10 N 4 E 49  
 " " " " " " 2281 1/2 taken 10 N 4 1/2 W 40  
 " " " " " " " " 163.6 W 44  
 " " " " " " 1823 W Pin 16 N 10 E 20  
 " " " " " " 2032 Birch 9 S 3 1/2 W 28  
 " " " " " " " " 8.5 39 W 3

N from 1/8 P. East of center Var. 4 1/4 E  
 850 Monico creek 25 links mid runs W low banks  
 985 " " " " " " SE " "  
 1160 " " " " " " SW " "  
 1700 Lean creek bottom " " " " " "

4328  
~~4328~~ full 15 1/2 E. of 1/8 P  
 copied on Page 321  
 West from N 1/8 P on E S 1/2 line Var 5 15 E  
 1000 Lean creek bottom  
 3909 full 36 links S of 1/8 P  
 Went E + set 1716 P in center of NE 1/4 SEC  
 and corrected line E from 1/16 P. to creek bottom  
 " South to 1/8 Post

1/16 P in center of } Tann 10 N 10 1/2 W 42  
 NE 1/4 } W Pin 24 S 57 W 31 1/2

N from 1/8 P. West of center Var 7 23  
 Should have been 800 mistake in course of  
 West SEC line

4757 full 49 1/2 East of 1/8 P  
 Went South + set 1/16 P. } Hem 12 N 83 E 37  
 " " " " " " } W Pin 24 S 58 W 29  
 corrected lines North and west to 1/8 Posts

I used my old Random made 7 years ago to  
 set the N 1/8 Post. The notes for this line are  
 North from SW cor Var 10 E  
 9782 full 302 links west of 1/8 P. same set Post  
 from both org. B.T.  
 cannot Var 80 E SEC for correction 308

Run S from N 1/8 P. to W 1/4 P. and prolonged  
 corrected line S to creek bottom

Finished Nov 23 1905

F. from N 1/8 P on W Line Var 5 10 S  
 4076 full 19 N of 1/8 P set 1/16 P in NW 1/4  
 } Hem 12 N 83 E 37  
 } W Pin 24 S 58 W 29

county record

course of W line 815  
 " " " " " " 1570  
 " " " " " " 1570

SEC. 7. 36-11. Sec 3. 1905

copied

Went to N & Corner found bath org B.T.  
Set new Post + run west var. 00  
I have Dons notes for what he done in  
see 6+7. his notes said this line am  
on an even needle.

4394 fell 79 links Sof  $\frac{1}{4}$  P. Set by Don

Aspen 10 N 13 E 24  
Fir 10 S 36  $\frac{1}{2}$  E 13 (Stump)

Set new Post and run E 1 set  $\frac{1}{8}$  P.

Torn 10 N 6  $\frac{1}{2}$  E 11

10 S 24  $\frac{1}{2}$  W 28

corrected line E to corner  
on Page 360

South from this  $\frac{1}{8}$  P which is E  $\frac{1}{8}$  P on  
north line of see Dons notes say  
N + S  $\frac{1}{4}$  line runs on 6  $\frac{1}{2}$  do not say W var  
E line of see " " 6  $\frac{1}{2}$

8 run ~~Set~~ 80 W Var

900 Stream 30 links wide across ~~N~~

7700 Set line stake, and went to S  $\frac{1}{4}$  P. Set  
by Don found his bearings

Both on down marks ok  
made new bearings

Found Dons Post could up with windfall 3 feet  
Deep. Run E Var 3  $\frac{1}{2}$  E

4008. fell 263 of corner. org B.T.

Went west and set  $\frac{1}{8}$  P. at 2004 and 13 south  
of Random

Aspen 8 N 50  $\frac{1}{2}$  E 34  
So 10 S 19 E 17

Picked up. N + S  $\frac{1}{8}$  line and at

7640. fell 540 ch West of  $\frac{1}{8}$  Post

corrected N to  $\frac{1}{8}$  P. Var 40 W

This is all I have to do in 7

SEC 4. 1905

The reason I run the E  $\frac{1}{8}$  line without  
setting  $\frac{1}{8}$  P E of center is the E line of see is  
straight. hence as the  $\frac{1}{4}$  line is straight the  
 $\frac{1}{8}$  line must be exactly correct

SEC 7 - 36, 11. cont. Dons notes 31

copied

NE cor orig B.T. NW cor org B.T. SW cor org B.T.  
SE " " " center Branch 13 S 12 W 31  $\frac{3}{4}$

edar 6 S 28  $\frac{1}{2}$  W 23  $\frac{1}{2}$

N  $\frac{1}{4}$  P SEE Page 30. S  $\frac{1}{4}$  Same Page

E  $\frac{1}{4}$  P Hem 12 N 62 E 20  $\frac{1}{2}$  WP org B.T.

" " 13 S 36  $\frac{1}{2}$  E 27

West  $\frac{1}{8}$  P on N line Pin 20 N 43  $\frac{1}{2}$  E 9

no other

N  $\frac{1}{8}$  P. on west line Skew 7 N E 49  $\frac{1}{2}$

W  $\frac{1}{8}$  P. on South " Sugar 13 N 57  $\frac{3}{4}$  W 28

$\frac{1}{8}$  P. west of center Pin 24 N 44  $\frac{1}{2}$  W 40

Dist from center to W  $\frac{1}{4}$  P. 51.60 Var 13  $\frac{1}{4}$  E

" " " " E " " 42.20 " 13  $\frac{1}{4}$  E

" " " " N " " 39.32 " 6  $\frac{1}{2}$  W

" " " " S " " 38.00 " " " "

Var of west  $\frac{1}{8}$  line 3  $\frac{1}{4}$  W

" " E see line 6  $\frac{1}{2}$  W

" " W " " 5 E

Dist of E see line 7420

" " S " " 4582

" " N " " 9782

on Page 360

Oct 17" 1906

Went N  $\frac{1}{4}$  P. found Post 9 set DEC 3 1906

" " NW corner found Post and 3 org BT

Pin 8 Var 3  $\frac{1}{4}$  E

5418 fell 483  $\frac{1}{4}$  N of Post

Went West & set  $\frac{1}{8}$  P } WP 20 N 76 E 6 DHO } same  
center } WP 20 N 43  $\frac{1}{2}$  E 9 DHO } line

Run South Var 1  $\frac{1}{2}$  E. 1801. fell 13  $\frac{1}{2}$  W of  $\frac{1}{8}$  P. Don

as there is no bearings for this Post it may  
have been moved. S of prolonged line

2550 Stream 30 runs west

2495 fell 20  $\frac{1}{2}$  E of Dons  $\frac{1}{8}$  P.

4975 went to N  $\frac{1}{4}$  P. and line South Var 2  $\frac{1}{2}$  W

2850 Stream 30 runs west and then SW

3953 fell 4  $\frac{3}{4}$  links West of Dons center

Went West and set  $\frac{1}{8}$  P } W. Pins 15 N 33  $\frac{1}{4}$  W 37  $\frac{1}{2}$

record

Sir 10 N 85  $\frac{1}{2}$  E 11

Surface 88 for balance of 7-36-11

SEC 2.35-8-E DEC 6-1905

Went to N 1/4 P & identified by Post set by Don  
There are NO bearings. were blown out this  
last summer, but Post is in same place & has  
used several times and know by wagon  
Road S+W and north Frank also says he  
will put a stone or iron monument in  
its place in Spring. Run South Var 6 1/2 E  
3100 Enter Swamp

4190 moisy creek 30 links wide runs SW

4300 leaves low ground

5650 Enter east Spence Swamp

6500 Leave Swamp

8183. fell 67 West of 1/4 P. both org B.T.

DEC for correction .82

change course 27

from N 1/4 P curved Var 657

= 7 =

Went to E 1/4 P & identified by Post & set from  
org B.T. in 1899 & new bearings made at that  
time old bearings are gone & new one has  
been blowed with dynamite made new  
bearings | W Pin 20 N 14 E 86

no other

Run South Var 5 1/4 E. in new Road

4101 fell 6 1/2 links E of corner which I set  
from 2 org B.T. which are to be removed  
for Road made new bearings

Sugar N 45 1/4 E 57

Y Birch N 44 W 57 1/2

Went north & set 1/8 P. at 2050 1/2 end 23/4  
links West of Random | Y Birch 18 N 88 W 62

Sugar 20 S 53 1/2 E 70 1/2

Went from E 1/4 P. Var 9 0 E

3800 Enter low ground

4200 moisy creek 25 links North

5000 Leave low ground and enter farm

6573 offset N 213 links

8243 fell 9 links N of 1/4 P which makes  
my departure 2.04

S of 1/4 P. I set this Post in 1898 bearings  
made at that time are ok and are

Sugar 14 S 5 0 E 139

So 18 S 37 W 107

DEC for correction 2.48

change course 125

curved Var 735

Went West and set center at intersection  
of corrected 1/4 lines. S Pen 15 S 10 E 83 1/4

no other

This Post sets in moisy creek and about 4 links  
from N Shore. creek runs SW

Dist: to N 1/4 P 4182 1/2

" " S " " 4000 1/2

" " E " " 4175

" " W " " 4064

Went South & set 1/8 P. 2000 1/4 S of center and  
50 1/4 links E of Random | Tam 8 N 63 E 35 1/2

" 9 S 20 W 11

650

East from 1/8 P. S of center Var 475 E

4158 fell 19 S of 1/8 Post

corrected line West to 1/8 P and from  
1/8 P N to center. and from center East  
to S 1/4 P.

Finished DEC 8 1905 at noon



S&amp;C 23-42-7-E Dec 9-1905

Went to S<sup>1</sup>/<sub>4</sub> corner found 3 org B.T. Found  
a post set which is OK

Run N Var 7.10

4004 fell 26 1/2 E of 1/4 P. This is the org Post  
+++ Bearing for same was Tam 6 N 86 E 637 but  
The tree is gone. canceled line South to corner

Went to S 1/4 P. found the Birch OK aspen gone

Made new bearing } W Pine 10 S 2 1/2 E 33

no others near

Set new Post. found a Post 3 1/2 links west and  
a line running north from same. found  
2 line stakes on this random lined on to same  
and Run N Var

100 Enter Swamp

250 Trees "

1500 Enter "

1800 Small Lake

3700 aspen

4048 fell 44 W of center set by Ore's I used it  
Went S and set Post on " for 1/8 P. NOBT

Went to center found canceled line E

Run E on this line Var 5.30 E

3900 found 1/4 P on line E BT OK

came West and set 1/4 P of 3950 no BT

Went to S 1/4 P and Run E. Var 9 1/2 E  
3800 fell 2075 of corner which is under file  
of Spur of R.R. set Post. and recent west  
and set 1/8 P. } Birch 10 S 12 E 34

no other

+++ made new bearing } Tam 5 S 15 06.9

North. from E 1/8 Post on South line Var 5 06

4286 fell 57 links W of 1/8 P. canceled line S to  
2143 found an E & W line at this point which  
is OK

S&amp;C 23-42-7-E Dec 11-1905

Went to W 1/4 P. Run N Var 4 1/2 E  
700 leave swamp

1000 Enter "

1900 leave "

20.00 Enter "

3920 fell 33 E of car set Post West B.T. E on zone  
Went S and set 1/8 P. at 1960 and 16 1/2 W of R  
Center of Boulder 374 feet and 2 feet N 64 32

East from N 1/8 P on West line. Var 5 1/2 E

1910 fell 72 S of 1/16 P. set by Oreil

canceled line West to 1/8 P

ST.P.R.R. is 500 ch E of S 1/4 P

" " " " 650 " N. S.E. corner

" " " " 500 " " E 1/4 on S line

Found trespass made by Riley on  
NE. SE. and scaled same amts. is as follows  
W Pine 13920 trees making but  
N " 12710 " " "  
E " 620 " " "  
27230 Feet

SEC 12-37-13 DEC 9" 1905 by Lynn Vaughan

Went to SW corner. Set Post from both org BT  
and run East Var  $3\frac{1}{2}$  E  
2200 Enter creek bottom  
2700 Leave " "  
3500 Enter marsh and low ground  
4000 could not find  $\frac{1}{4}$  P.  
5700 Leave marsh  
8270 fell 2.08 S of corner which I set from  
both org B.T.

Went W + set  $\frac{1}{8}$  P. at  $620\frac{1}{2}$  and  $156$  N of Rand

Hem 12 N 22 W 32  
Fir 11 S 58 E 8

went west and set  $\frac{1}{4}$  P. at 4135 and  $194$  N of Rand

Dead cedar 8 N  $47\frac{1}{2}$  E  $87\frac{1}{4}$   
no other trees

went west and set  $\frac{1}{8}$  P. at  $2067\frac{1}{2}$  +  $52$  N of Rand

Stems 8 N 43 W 32  
no other trees

North from SE corner Var  $3\frac{1}{2}$  E

4000 could not find  $\frac{1}{4}$  Post

8002 fell  $34\frac{1}{2}$  East of corner

Went S and set  $\frac{1}{4}$  P. at 4001 and  $17\frac{1}{4}$  W of Rand

Sugar 10 S  $77\frac{1}{2}$  W  $193\frac{3}{4}$   
Birch 8 S 25 E  $18\frac{1}{2}$

West from E  $\frac{1}{4}$  P. Var  $2\frac{1}{2}$  E

8063 fell 90 N of  $\frac{1}{4}$  P. Set Post from org B.T. SW  
connected East to  $\frac{1}{4}$  P.

North from West  $\frac{1}{4}$  P. Var  $2\frac{1}{2}$  E

4072 fell  $42\frac{1}{2}$  E of corner  
connected S to  $\frac{1}{4}$  P.

South from West  $\frac{1}{4}$  P. Var  $3\frac{1}{2}$  E

4110 fell 35 E of corner connected N to  $\frac{1}{4}$  P.

East from NW cor 406

1600 Enter open Swamp

2672 creek 30 links wide runs SW

SEC 12-37-13 cont" DEC 14 - 1905 37

4128 fell 16 South  $\frac{1}{4}$  P. found SW org BT  
Set Post in old hole. and made new beam  
Stems 3 N 75 W 28  
" 3 S 49 E 36

connected West to corner

As there was no timber along the lines  
& cut out the SE SW and SEE with P.C.

SEC 15-37-13-E DEC 17-1905

Went to NW corner. Set Post from E B.T.  
The distance to the Hemlock is 21 links found  
The hole where org Post stood. Run S Var  $4\frac{1}{2}$  E  
1000 leave Swamp

2400 Enter "

2700 Prestigo River 100 links wide runs SE

4023 fell 29 links E of  $\frac{1}{4}$  P. which I set from  
The SW B.T. The other is gone

Went N and set  $\frac{1}{8}$  P. at  $2011\frac{1}{2}$  +  $14\frac{1}{2}$  W of Rank

As there was no timber of much value  
along the lines of the SW NW + NW S W  
I did not run the  $\frac{1}{4}$  lines. But Run E from  
from N  $\frac{1}{8}$  P. on West line Var  $6^{\circ}$  E

1900 Set Temp  $\frac{1}{16}$  Post no BT

Run South Var  $4^{\circ} 45'$  E

3560 Prestigo River 100 wide Run E of SE

4000 set Temp  $\frac{1}{16}$  Post and run west to  
to  $\frac{1}{8}$  P. S of W  $\frac{1}{4}$  Post

This is all in 15

Went to S 1/4 P found W B.T. OK but dead  
Could not find E B.T. on account of flowage  
Set new post and run N Var 3 1/2 E

700 Needle Shows a Var of 5 1/2 E

7940 Needle Shows a Var of 7 1/2 E. Fell 4 1/8 ch W of 1/4 P  
Which I set from N.B.T. it is a stub 40 feet  
high badly burned but marks as plain

Went South and at 4000 ch corrected line South  
to 2000 chains. Change course 2.53. DEC 5.15

Went to S 1/4 P again + run west Var 00  
650 over River

4042 fell 291 S of corner Which I set in 1899  
by proportional measurement between 1/4 P  
South and one North this Post had been  
moved. I located same by going S to my 1/8 P  
and measuring N on old Random found  
The hole where Post stood made new being

W Pine (road) 22 S 89 3/4 E 51 1/2

NO other

Went E from this corner + set 1/8 P  
no Bearings

North from SW corner Var 10 E

410 intersect flowage of River about 300 wide W

960 intersect Lake I could not find one as

There is a canal cut from River to Lake

me is gone located same as near as possible

3667 on shore of Lake as near as I can fit it.

8727 corner Lake and flowage. me gone

offset W 207 to old Random and run

North an 2 1/2° more E Var (change course 2 1/2)

7670 fell 333 West of corner Set Post from the  
W Pine B.T. other on gone. Went South

and located me as near as possible on

arg. shore of Lake found a Shortage between

measures of 3.37 proportional this Shortage

and set 1/4 P on ice 44 3/4 links S of me

1/4 P. { W Pine Stump 12 S 87 1/2 E 213

NO other

Went South and set 1/8 P at 1805 N of corner and  
16 links W of Random this Post is on ice  
NO trees near

East from W 1/4 P. Var 40 E

500 over Lake

1000 Found columnations of telescope were off  
about 5 links in 1000 ch adjusted same.

I do not know just when this happened and  
Some or all of the lines may be wrong but  
as there is nothing very particular the way the  
Timber is located I will finish as it is

7761 fell 142 North of 1/4 P B.T. gone Post set by  
Oneil. corrected line West and set center

W Pine 8 N 1/4 E 57

W " 12 S 9 E 55

Distance to N 1/4 Post 3950

" " S " " 3987

" " E " " 3786

" " W " " 3975

Went South + set 1/8 P W Pine 8 N 62 E 25

W " 12 S 13 E 38

West from 1/8 P S of center Var 30 E

2008 fell 90 S of 1/8 Post on ice

Corrected line East to 1/8 P

The NW SW is cut so I did not have  
to run the 1/8 line in SW 1/4

Finished DEC 23 1904

WENT E and S to 1/8 P. NO B.T.

NO B.T.



SEC 34-36-6-E DEC 21-22-1905

By Lynn Vaughan

- West from SE corner (+ iron pins) Var 4<sup>00</sup> E  
 1500 Enter Tam<sup>2</sup> + Spur Swamp  
 2700 Leave  
 4500 Enter bottom of Big Rice River  
 4800 Rice Run 400 wide runs SW  
 8000 could not find corner NO Sect-BT  
 9600 Leave bottom of Rice River  
 10200 Enter bottom of Tamahawk River  
 11220 Tamahawk River  
 11350 over "  
 11700 Leave River bottom  
 11998 Fall 115th N. of 1/4 P. org BT  
 Went East + set 1/4 P. BET 4+333+34  
 at 3999 1/3 West of SE cor and 38 1/2 S of Rand  
 B. Pin 10 N 41 W 19 1/2  
 W " 7 S 61 E 45 1/2

West from East 1/4 P. Set by D.H.U. - 1901 1/4 W 4 1/2  
 8206. Fall 1 link S of 1/4 Post

- South from N 1/4 Post Var 4<sup>00</sup> E  
 4200 River bottom  
 5000 Rice River and flowage  
 6200 over "  
 8200 Fall 35 E of 1/4 P.

Went N + set center B. Pin 8 N 2 1/2 W 4 1/4  
 " " 12 S 24 E 23

Dist to N 1/4 P. 4067

" " S " " 4133

" " E " " 4022

" " W " " 4184

Went E + set 1/8 P. at 2011 + 1/4 link N. of Rand  
 B. Pin 8 N 25 1/2 W 14  
 " " 8 S 16 E 14 1/2

Finish ~~DEC 22~~

copied on  
 Page 46  
 county  
 Record

SEC. 5-38-10-E DEC 27 " 1905 41

Went to N 1/4 P. Found both<sup>2</sup> org B.T. Birch  
 is dead Set new Post + runs S Var 3 1/2 E  
 600 Enter Tam Swamp Found columnations of  
 Telescope was a little off. adjusted Lens  
 5000 Leave Swamp  
 5500 Enter " DEC 28  
 6000 Leave " Copied on Page 338  
 6500 Enter " County Record  
 7450 Fall 218 West of 1/4 P. Found Post Set 2 OK  
 cedar is a stump marks OK Tam OK  
 Die for examination 293 Change corner 11,40  
 Connected line N to 1/4 Post  
 This is all in in SEC 5

SEC 32.39-10 E DEC 28 " 1905

East from S 1/4 P. Var 4<sup>00</sup> E

700 Enter Tam Swamp  
 3000 Leave Swamp copied on Page 350  
 3924 Fall 165 N of corner Set Post from sled of  
 N 6 Birch which found at roots of stump  
 The other 3 trees are down and rather no  
 marks. Made new bearings  
 17 Birch 14 N 75 E 39  
 Sugar 16 S 50 W 72 3/4  
 connected line W + set 1/8 P. at 1987  
 Spruce 10 N 42 E 37 1/2  
 Tam 16 S 41 1/2 W 25

North from SE corner Var 3 1/2 E. DEC 29, 1905  
 4035 Fall 126 E of 1/4 P. which I set from

2 org B.T. The goat notes does not give  
 any 1/4 P. but I am satisfied these trees  
 were marked by the US surveyor. I am  
 sure I found the hole where org<sup>2</sup> Post stood  
 B.T. are: Birch 10 N 27 W 35 } var 3 1/2 E  
 Hem 14 S 1 1/2 W 13

Went South and set 1/8 Post

county Hem 8 N 82 1/2 E 39  
 10 S 89 1/2 W 56 record

cut out SESE but did not set Post at NW corner



44 SEC 12-4277 & January 11 1906

Went to S 1/4 P. Which is in flowage. Post gone. Found org B.T. Bitch & N 89 W 603

Set new Post and run N Var 2 1/2 E

3250 leave Swamp & flowage

4650 Enter " " "

5200 Leave " " "

7840 Fall 881 West of 1/4 Post Found both org B.T. Set new Post. found hole where org Post stood

D&C for connection 1117

change course 6° 20' east Var 2 1/2 W

connected line South from 6000 ch

to 3300 ch bal. of line is Swamp

Went to S 1/4 P again & run E Var 2 1/2 E

850 Stream 60 rms NW

1850 leave Swamp & flowage

4035. fell 88 S of corner of corner where

I found Dors Post set from org B.T.

connected line West & set 1/8 Post

B. Pine 7 N 64 1/2 E 45

Do 12 S 83 W 10

Run a line S from this 1/8 P to Swamp

Var 3 1/2 E Dist 2600

This is see they want done

SEC 4. 37-8-E January 16-1906

Went to NW corner Post sets in road found N.B.T. Stump set Turn Post and run E Var 4° E

1050 Stream 40 Run NW

2800 " 30 " W.S.W

3350 " 25 " NW

5350 Enter Swamp

5560 Stream 40 rms S

6000 Enter open Swamp. old bearing

7600 Leave " " "

7971 Fall 129 N of corner. Found SE B.T. with marks plain. is down feet NE Found stump of NE B.T. no marks. made & set new Post and made new bearings

Tam 10 S 23 1/4 W 54

" 6 S 86 1/2 E 75

Went West and set 1/4 P. at 3985 1/2 and 64 1/2

S of Road W.P.S. 18 N 56 W 72 1/2

" " 30 S 70 3/4 E 62

Went West and set 1/8 P. at 1992 3/4 and 32 1/4

S of Road W.P. Stub 10 S 64 E 50

maple 12 S 32 1/2 W 108

copied on Page 132 County Record  
Went to SE corner. found Post & set last fence OK as they have remained the stump of NE B.T. Made new bearing W.P. Stump 40 N 79 1/2 W 18 1/2

Run West Var 5° no other

2400 Enter Swamp

2633 fell 135 S of 1/4 P. Set Post from both org B.T.

I had run S from N 1/4 P. on 7° W Var as I had been told the Shortage was on ~~side~~ West of 1/4 P. I packed up this line and found at 7599 I was 1102 West of 1/4 P. as Shortage was S of 1/4 P.

D&C for connection 1450. change course 8.30  
connect. Var 1.30 E. Dist from 1/4 P. to 1/4 P. 7681

Went to West 1/4 P. which I set last fence, & Run West Var 8° 30 E

2850 End of Road

5900 I missed Lake



## SEC 4-37-8 E cont January 19-1906

6700 Set line stake and went to S me and set flag at N me. & set both of these me. in June 1905. Chained N from S me. Var 140° found distance between me comes 2616 US Surveyors note says 2293. makes an overrun of 323. Govt note say 1/4 P is 678 N of S me. & proportioned the overrun and set 1/4 P on it. 7.73 1/2 N of S me

Commenced on E + W 1/4 P. when I set line stake. 6738 feet 100 N of 1/4 P. D&C for correction 148 change course 50'

Went west + set center W Pin S. 30 N 58 W 37 1/2

Dist to N 1/4 P 3639

" " S " " 3930

" " E " " 2703

" " W " " 4235

Went East and set 1/4 P. Tarn 8 S 24 E 23 1/2 at 13.50'

South from 1/8 P. E of center Var 1° a mistake 4106 feet 134 W of 1/8 P. Connected line to 1/8 P from 1500 ch.

Went to me on N Side of Lake and run North Var 40°.00' west 1

600 leave Swamp copied on Page 133

1500 Enter " Count 1660'

2154 Feet 52 1/2 East of corner. Found a shortage of 96 links. Proportioned shortage and set 1/8 P at 237 N of me and 7 links W of Random

Shore 7 N 3 1/2 E 35

Tarn 10 N 42 1/2 E 56 1/2

From 1/8 P. East of 1/4 P. Var 29° W

3642 feet 532 West of 1/4 P.

connected north through timber This connected touches Lake at outlet

## SEC 34-38-8 E January 20-1906

Went to SW corner which I set the 16" mat and run East Var 3 1/2 E

3300 Enter Swamp

4000 Hasty feet 28 links S of 1/4 Past which I set from NE BT. Spence is gone set new Post and made new bearing: Tarn 7 S 2° E. 23

Connected line West + set 1/8 Post

Edar 10 N 22 W 8 1/2

Horn 16 S 71 1/2 E 61 3/4

copied on Page 176

Went to S 1/4 P and run N Var 8 1/2 E

1100 Doyles Logging Road

1400 leave Swamp January 23-1906

2800 Branch of Logging road

5000 Enter Swamp cut over

7900 Fell 85 W of 1/4 P. Set new Post from both ang BT. They are both green

D&C for correction

change course 36'

Went to S 1/4 P. and run E Var 3 1/2

2000 needle Shows 4° E

4000 " " 5° 30' E counts recall

4007 feet 65 1/2 N of corner set Post from NW and SE BT. found NE tree down marks are under side did not cut it off.

Went west and set 1/8 P

Tarn 9 N 5 W 6 1/2

" " 9 S 54 1/2 E 16

Went to SE corner and run N Var 27 1/2 E

1500 leave Swamp

2000 needle Shows 4 1/2° E

3913 Feet. 95 S of S of 1/4 P. Set Post from SE BT. and Stump SW BT. no marks

Made new bearing: Edar 13. N 63 W 24

X++ See Page 48

Run West from S 1/4 P. Var 3° E

2000 needle Shows 4° E

4000 " " 5 1/2° E and held this course through the section. See page 49

48  
S&C 32-38-8. January 21-1906

Went to  $\frac{3}{4}$  Post. Set Temp Post in "road" from  
Stump of East org B.T. and run N Var  $40^{\circ}$ E  
3972 feet  $2\frac{1}{2}$  links West of cor (an iron pin  
Went S and set  $\frac{1}{8}$ P. notices on stumps near  
copied on Page 174

Went from NB corner Var  $40^{\circ}$ E  
(Before leaving this corner I turned telescope  
on to SE corner. found course of line to  $50^{\circ}$ E  
3700 Enter Swamp

4000 could not find  $\frac{1}{4}$ P. found where others  
had looked for it Henry Wubker was  
there and claimed it was at 3700 ch

7942 feet 149 N of corner which I set from SW  
B.T.  $2\frac{1}{2}$  years ago

Went E and set  $\frac{1}{4}$ P. at 3971 and 74  $\frac{1}{2}$   
links S of Randz

Tam 9 N 68 E 13

" 10 S 85  $\frac{1}{2}$  W 32  $\frac{1}{2}$

Went E and set  $\frac{1}{8}$ P. at 1985  $\frac{1}{2}$  and 37  $\frac{1}{4}$  S of  
Random

W. Pine S. 16 N 59 W 22

no others near

Went to N  $\frac{1}{4}$ P. and as had run the west  
line of this Sic  $2\frac{1}{2}$  years ago + found its course  
to be  $40^{\circ}$ E and as course of E line is  $50^{\circ}$ E I run  
South on an intermediate course of  $4\frac{1}{2}^{\circ}$ E

900 found where Wubker had trespassed on  
NW NE which belongs to Antons ..... ski

1986 Set  $\frac{1}{8}$  Post  
3972 .. center of bee

no trees near

Dead Tam 14 N 49  $\frac{1}{2}$  W 42

Tam Stump 10 S 6 E 8  $\frac{1}{2}$

count 7 & record

Run E from center Var  $50^{\circ}$ E  
3986. feet 36 N of  $\frac{1}{4}$ P.

consecrated line W + set  $\frac{1}{8}$  Post

$\frac{1}{4}$  Pine Stump 17 N 37  $\frac{1}{2}$  W 31

W " " 12 S 14  $\frac{1}{2}$  W 22

Antons wanted  $\frac{1}{16}$ P. in center of B/E  $\frac{1}{4}$  as I did  
not have time to run  $\frac{1}{8}$  lines I run west from  
N  $\frac{1}{8}$ P. on E section on  $50^{\circ}$ E and measured W 3979 ch  
and set Post.

January 25-1906

49  
Section 34. 38. 8 - cont - from Page 47

Went S and set  $\frac{1}{8}$ P. at 1956  $\frac{1}{2}$  and 47  $\frac{1}{2}$   
Birch 10 N 82  $\frac{1}{2}$  E 41  $\frac{1}{2}$   
" 10 S 69 W 40  $\frac{1}{2}$

8684 Full 396. S of  $\frac{1}{4}$ P. set new Post and  
made new bearings

W. Pine Stump 16 N 10  $\frac{1}{2}$  W 80

" " " 16 S 5 W 28  $\frac{1}{2}$

This  $\frac{1}{4}$ P. has been burned out but I found  
sufficient evidence of its exact location to warrant  
me in locating it. old lines running S + W  
and N + S from it. also its proximity to the  
Swamp. and from other evidence I am sure  
it is ok. copied on Page 176

Went East and set center of Section at  
intersection of consecrated  $\frac{1}{4}$  lines

W. Pine Stump 18 N 20  $\frac{1}{2}$  W 74

W " Stump 8 S 36 W 15  $\frac{3}{4}$

Dist to N  $\frac{1}{4}$  Post 3929  
" " S " " 3929 3971  
" " E " " 3971 3856  
" " W " " 3856 4824 (long to W  $\frac{1}{4}$ P.)

Set  $\frac{1}{8}$  Post E of Center at 1928  
Tam 8 N 62 E 7  
" " 29 S 61 W 23

"  $\frac{1}{8}$  Post S " " " 1985  $\frac{1}{2}$   
and 21  $\frac{1}{2}$  E of Random Tam 10 N 12  $\frac{1}{2}$  W 33  $\frac{3}{4}$   
" " " 10 S 83  $\frac{1}{2}$  E 53

Run East from  $\frac{1}{8}$  Post S of center Var  $2\frac{1}{4}$  E  
175 Doyle's Logging Road N. NE, SSW  
700 " " " NE + SW

3875 Leave Swamp

3933 Full 20 S of  $\frac{1}{8}$  Post

center Record

Went to E  $\frac{1}{8}$ P. on South line and run  
North Var  $40^{\circ}$ E

400 Road (Logging)

3200 " " "

3850 " " "

3944 feet 28  $\frac{1}{2}$  W of  $\frac{1}{8}$ P.  
over =





SEC. 30-42-8-E. February 12 1906

Found old line kept same course Var 40° E  
my Random " 3.00 E

3592 offset N 156 1/2 to where old line  
intersects Lake + set mc. Tam 4 N 59 1/2 E 12 1/4  
" 6 S 25 1/2 W 15 1/4

corrected line E to Corner

Prolonged line meet from an course of old line  
4510 West of mc set line stakes and went to  
mc on South side of Lake BEL 25 + 30

Found 3 Pairs BT OK but dead.  
Set Post. from this B.T. and run South Var 30° E

2627. fell 24 W of 1/4 which I set from S & B.T.

xxx Went N + set 1/8 P. at 516 S of mc.  
Went to mc + adjusted instrument on to  
true line and run N across Lake. Var 3.20° E

1487 Set Temp corner

3372 found old line exactly on line set mc  
no bearings no green timber

1/8 P. S { W Pine 16 S 4 1/2 E 41 1/2 } omitted  
of Lake { " " 9 S 67 W 7 }

Found a Shortage of 27 links. Proportioned this  
Shortage and set corner on ice at 1475 N of S mc  
and 1837 S. of N mc picked E + W line and at

3315. fell 59 N of corner on line on ice.  
Gout distance. from mc to corner is 4370  
leaves a Shortage of 1055. Proportioned this  
Shortage and set 1/4 P. on ice 380 West of E mc.  
No timber for bearings.

The distance from NW corner to 1/8 P. S of  
Lake is 1991. The distance from NE corner to  
N 1/8 Post is 1992 The distance from N 1/4 P to  
1/8 " South ~~is~~ should be 194 1/2. but as there  
is 59 links of a departure from mc to NW  
I am S from N 1/4 P on ice on an instrument  
which is 2-5 20 16 1/2 links + set Temp 1/8 P  
no bearings. Run. Run E from this 1/8 P.  
Var 1.15° E.

38 - Fell S of 1/8 P. corrected line W to 1/8 P  
and from NE corner went to mc  
Finished Feb 14 - 1906

SEC 31-42-8-E February 14 - 1906

Went to East 1/4 P. Dams Post + 2 org B.T.

Run West Var. 2.15° E.

3899 fell 58 S of center set James Omeil

Went E + set 1/8 P. at 1949 1/2 and 29 North of Ram  
Bich 9 N 72 W 14 1/2  
W Pine 26 S 4 W 34

= February 15 - 1906

South from center set by Omeil Var 6° E

3985 fell 1 1/2 links west of 1/4 Found Post and  
Parts of org B.T. corrected line N 2000 + set  
1/8 Post at 1992 1/2 W Pine 15 N 15 E 8 1/2  
" " 14 S 80 W 22

East from 1/8 P. S. of center Var 2° E

3954. fell 47 1/4 S of 1/8 P. which I set a week ago  
When working in SEC 32. corrected line  
West 2000 ch = February 16 1906

Went to SE corner + run West Var 3 1/2° E

4005 fell 34 N of 1/4 P. corrected line E 2002 1/2  
and set 1/8 P. Tam 45 S 39 W 84 1/2

W Pine 14 N 5 W 29 5

Run N from this 1/8 P. Var 7° E

600 needle Shows Var 6 1/2° E crossed Stream at 300  
and left creek pattern at 500. This bottom is on  
Lake the bottom of a lake made so by  
beaver dams which drove the outlet out of  
West end of lake original outlet was at NE  
end of lake

3920 fell 47 E of 1/8 P. Went S and set 1/16 P in  
center of SE 1/4 W Pine 18 N 79 E 12 1/2  
" " 14 S 74 W 24 1/2

West from center set by Omeil Var 1.40° E can see slashings  
3824. Fell 70 links N of 1/4 Post which I set from  
Stumps of both org B.T. Found a Shortage  
Gout distance is 3493 my measurement  
is 3824. makes Shortage of 169 Proportioned  
this Shortage + set 1/8 P. 1915 West of center  
and 1909 E of W 1/4 Post. + 30 links South  
of Random W Pine Stump 22 N 16 E 44  
" " " " 16 S 89 1/2 E 37 3/4



SEC 28-38-88 cont. May 5<sup>th</sup> 1906

Went to S  $\frac{1}{4}$  P. found Post I set 2 years ago from 1 org. B.T.  
 Run N var  $8\frac{1}{2}$  E  
 4600 Slough 125 bears N & S W to lake  
 7957 hill 76 East of  $\frac{1}{4}$  P. Stumps to 2 org. B.T. ok

Went to W  $\frac{1}{4}$  P. found Post sitting beside road. B.T.  
 both gone. got course of road turned angle west to  
 Post + draw a hardwood Post in Road

W Pin STP 14 S 68 E 28  $\frac{1}{2}$

no other

Run East var  $4\frac{1}{2}$  E

932 Top of hill

1250 fence at wet marsh around shore of Lake

2150 over lake + wet marsh

9287 hill 142 S of  $\frac{1}{4}$  Post

Went west + set center W Pin STP 18 S 36 W 3  $\frac{1}{4}$

" " " " 18 S 2  $\frac{1}{2}$  E 49  $\frac{1}{2}$

~~Set~~ copied on Page 169

Distance to N  $\frac{1}{4}$  Post 3982 County

" " S " " 3975

" " E " " 4121  $\frac{1}{2}$  Record

" " W " " 4165  $\frac{1}{2}$

1991 North of center set  $\frac{1}{8}$  P. W Pin STP 14 N 2 W 19  $\frac{3}{4}$

" " " " 14 S 47 E 23  $\frac{3}{4}$

1997  $\frac{1}{2}$  South of center set  $\frac{1}{8}$  P. W Pin STP 14 N 85 W 25

" " " " 12 N 86  $\frac{1}{2}$  E 11  $\frac{3}{4}$

concocted line N from center to  $\frac{1}{4}$  P

" " S " " "  $\frac{1}{8}$  P.

East from  $\frac{1}{8}$  P. South from center var  $4\frac{1}{2}$  E

2700 Stream 25 across South

3731 hill 134 S of  $\frac{1}{8}$  Post concocted line west

To  $\frac{1}{4}$  Post

SEE Page 118 for work done in June 1907

SEC. 7. TOWN 27. N. R. 26. E May 10<sup>th</sup> 1906

Went to Sec. 7. found old Post but no B.T.

" " S  $\frac{1}{4}$  Post " " " " " "

" " Court house at Sturgeon Bay and made  
 copy of Govt. field notes. Found Survey was  
 Made by Sylvester Sibley in 1835

May 11

Found the center of Sec had been set 25 years  
 ago also, East  $\frac{1}{8}$  P. on South line and  $\frac{1}{8}$  P. East  
 of center and iron monuments established  
 and I used them they were made by an old  
 Surveyor named Gunter.

I began at  $\frac{1}{8}$  P. East of center and run South  
 var  $1.45$  E

2015 hill  $8\frac{1}{2}$  links W of  $\frac{1}{8}$  P. Set by Gunter.

concocted west and set  $\frac{1}{8}$  Post. an iron  
 Pin 1 in dia 1 foot long. The SE corner of  
 stone wall under the north Post of School  
 house bears  $389\frac{1}{4}$  W  $91\frac{3}{4}$  links

Went to center of Sec + Run South var  $2\frac{1}{2}$  E

4006 hill 20 links East of  $\frac{1}{4}$  Post

concocted line west and set an iron pin  
 for  $\frac{1}{8}$  P. no B.T. no timber near

Run East from  $\frac{1}{8}$  P. S. of center var  $2\frac{1}{2}$  E

2008 hill 3 links N of  $\frac{1}{16}$  Post

concocted line west

Platted the NW SE as Sorenson's addition to  
 the city of ~~Sturgeon~~ Sturgeon Bay



See 7-8-17-18-19-20-29-30-31-32-38-8 E May 29. 06

went to corner 29-30-31-32. found Post and Stump of both org B.T. marks Plain. made new bearings

Y Pin 10 S 52 W 145 1/2  
no other copied on Page  
Run N Var 5°E 171

1800 Leau Swamp marsh

3700 Eula "

3985 fell 2 1/2 links East of 1/4 Post found marks on Stump of West B.T. and Stump of East one Continued north on same line + corner but chained from 1/4 P.

1850 Leau Marsh

3983 fell 4 1/2 links west corner. which I set from Stumps of org B.T. these made new bearings: W Pin Blump 30 N 23 E 73

30 S 71 1/2 W 22 3/4

Had I corrected onto 1/4 P. and prolonged line I would have been 6 1/2 links west of corner Still north from this corner var 4° E May 25. 1906

H044 fell 13 links east of 1/4 P. which I set from West BT which is ok

Run north from this 1/4 Post Var 4°E

2918 fell 58 1/2 west of me which I set from both org B.T. Pins is down and lies in Lake. the maple is broken off 2 feet high marks of Post sets in Lake 10 feet from shore

went across Lake + set made new bearings  
Y Pin 12 S 16 1/2 W 92 1/2  
no other

went across Lake + set me from both org B.T. both dead made new bearings

Y Pin 12 S 8 5 W 5  
no other near

Run N Var 4°E County Record

429 fell 23 west which I set from 3 Stumps of both org B.T. made new bearings: Hem 14 N 2 W 84 1/2  
corrected line South. to 1/4 P no other

" " " + set 1/8 P. WP Sp 30 S 21 E 44 1/2  
no other

Continued

Run E from this 1/8 P. Var 2°E  
1260 center of Road to Summer resort  
2000 set Temp 1/16 P. W Pin 8 N. 60 1/2 E 44 1/2 70

Run N. Var 3 1/2  
415 fenced Lake and set me Y Pin 15 N 70 W 20 1/2  
Copied on Page 171

Went to 1/4 P. and run East Var 2°E  
1534 fenced Lake + set me W Pin 14 S 18 W 8

North from car to 17-18-19-20 Var 3 1/2 E  
1115 fenced. Bay of Lake made Shaws 7°E  
1700 " " " " " " 6°E  
4000 could not find 1/4 P

7936 fell 108 west of corner which I set as follows org B.T. gone Mansell had located this corner by Proportional measurement.

and had set me on left bank of river also 1/4 P. But 8 + 17 and 1/8 P east of this 1/4 P. So I began at 1/4 P. and run E Var 3°E

1934 1/2 found 1/8 P on line  
3869 set corner notes. Put rock around Post

West from NE corner of 31 Var 3°E  
4000 found an old post 200 N no B.T.

4372 offset N 4 55

4625 Board in River

5221 " " "

5571 fell 43 N of me set from NE B.T. Post 10 feet in River  
line reads 5571 fell 412 South of me

Went East and set 1/4 P. at 3990 1/2 and 295 1/4  
North of Random: WP Sp 14 N 89 1/2 E 54  
" " " " " " 16 S 65 W 43 3/4

corrected line East to corner

Went to SW corner of Sec 20 and run  
N 32 1/2 E Var 4°E 2169 ch  
Thru N 12 1/2 E " " " 198 to 1/8 line on N  
Side of SW 8 W. and 1260 East of 1/8 P

County Record

SEC 17 12-36-9E June 5 1906

went W 1/8 P East of corner to 1-2-11-12 and  
 run East Var 2 10 E  
 1100 needle Says course is so needle  
 1785 Fell 68 1/2 S. of 1/4 P

conected onto this 1/4 P. and run East  
 copied Var 40 E on Page 191

500 Enter Swamp  
 3571 Set 48 links N of corner all the  
 org BT are down. Made new bearings  
 county TAMM N 57 1/2 E 56  
 no other near RECORD

East from corner to 1-7-11-12-36 NR 9+10  
 Var 40 E

350 Leave Swamp copied on

550 Enter "

4329 fell 107 3/4 S. of 1/4 P said to have been  
 set by Williams Allen. Found Post was  
 scribbled. BT marked 1/4 S conected onto  
 this 1/4 P. and prolonged true line from  
 the corner out 1/4 P

500 Leave Swamp Var 60 E Page 310

1700 needle Says 5 1/2 E

2700 Enter Swamp 400

4200 could not find corner. Last corner as  
 me never have been found

4300 Leave Swamp

5000 went to Schellers at 4.35 P.M

16988 fell 1186 1/2 South of corner to 4-5-8-9

The org B.T. an entirely gone. W Allen had  
 set this Post from org B.T. and made new  
 bearings and this was down. Made new org

Bick 12 N 13 W 42

no other county record

Found distance 864 ch larger than returned by US  
 Surveyor - proportioned Proportioned whole distance  
 and set conected line west and set 1/4 P  
 Bet 5+8 at 42 14/4 west of corner map 10 N 7 W 40 1/4  
 conected line west and set corner 10 S 5 W 38 1/2  
 to 5-6-7-8 at 84 28 1/2 see next Page

continued June 7-1906

corner to map 6 N 6 E 47  
 5-6-7-8 Bick S 6 W 39 1/4  
 conected west and set 1/4 P Bet 6+7

Tamm S N 50 W 27 1/2 Pocket compass  
 S S 40 E 17 For course

Then conected line west to corner of 1-12-6-7 For  
 road for Town of Pelican

These corners were set temporary as I  
 did not run N+S to set corner to 5-6-7-8  
 by Proportional measurement N+S but I think  
 the distance is about right, as I found allens B.T.  
 for his corner which is set by Proportional  
 measurement and they are so close to my  
 corner I used them. The line as conected, which  
 is a true line Bet corner Range line and corner  
 to 4-5-8-9 is 10 rods South of lake at nearest  
 Point

= June 9 1906 =

conected line Bet 1+12-36 West to corner  
 and then west to Road at Schellers

This Page is copied on Page 310

county record

62 SEE 27-37-6E June 12-1906

went to N 1/4 P. Set Post from stump of East BT  
marks plain. found stump SW BT marks gone  
Run E Var 4° E

40.54 fell 68 N of corner which I set from both  
orig BT. The east one did not hook up for  
distance but course was ok. canceled line

Went to 1/4 P. for Road  
copied on page 51 County Record

South from NE cor Var 3 1/2 E

3976 fell 67 3/4 W of 1/4 P which I set from the stump of  
East BT marks plain The west one is down and  
marks are gone. canceled line to cor Road  
For Town of Cassian

Survey of Road for Town Cassian June 12-13

Beginning at 1/4 P. bet: SSec 22 + 27. T 36 N. R 6 E

Thence East on Sec line to corner of 22-23-26+27. 4054

" South " " " " 1/4 P. bet 26+27. 4054 3976

" East. Instrument adjusted on 4° E - - - - 4426 ch

" South 53° East # 824 "

" North 64° " 1096 "

" South 56° " 1645 "

" " 43 " 1779 "

To Cassian + Harshaw Road as surveyed and recorded  
June 1904. Set Post 13 Pine Stump SSec 16 S 85 East 55

This survey of new road crosses SSec line

BET 25+26. No of cor to 25+26-35+36 on the  
course. South 43° E. crossed line between 25+26  
ch North of intersection with Harshaw and  
Cassian Road

copied on Page 392

COUNTY RECORD

BET Towns 36+37. R 6 E + between SSec 3 + 34 June 14, 1906

went to me on west bank of Tannahawk River  
and run west Var 40 E

3793 (405) fell 19 links N. of 1/4 P. which I set from  
orig BT. This tree is down and rotten but the  
marks are quite plain made new bearings

B Pine N B Pine 12 N 9 1/2 W 47 1/2  
S " 8 S 11 W 28 1/2

canceled line onto 1/4 and prolonged it west  
4013 fell 8 links South of corner which I set from  
Stumps of 3 orig BT. all nearby gone made new bearings  
B Pine 153 10 3/4 East 205. make it T. W. NR 6 E  
no other

canceled line East to MC for Road for town  
Cassian

went to me ~~at~~ in corner to 2.3.34-35 and  
run East Var 4 1/2 E from 111 1906 and  
canceled my old Random East to 1/4 P bet 2+35

Survey of Road for Town of Cassian June 15, 1906  
Beginning at 1/4 P. between 2 + 35 and between Towns

36 + 37 N Range 6 E. Thence with town line 1256 ch

copied on Page 392 S 58 1/2° W 721

392 county " S 73° W 732

Record " N 89° W 775

" N 82° W 217.

" N 73° W 413

To SSec corner on East Bank of Tannahawk River

Beginning at 1/4 P. between <sup>2+11</sup> Towns 36 <sup>NR 6</sup> + 37 R 6 E June 16, 1906

Thence west on Sec line 4.04 to stake which stands 50 W of R of Way  
of the C. M. & ST P. RR

Thence N 13° E Parallel with said right of way 694 ch

" N 11 W 438 "

" N 43 1/2 E To a stake which stands 50 W of R of W 485 "

" N 17 1/2 E Parallel with Right of way 3863 "

" N 30 1/2 W 456 "

" N 87 W over Bearskin Creek 384 "

" N 46 W To old survey of Harshaw Road 203



SEC 11-12-36-6 June 16 1906

Went SW cor of Sec 1 found Post & set from orig BT June 1902  
Run East Var 40°

4000 Could not find 1/4 P.

8177 Fell 275 N of corner which I set from the two  
W Pine BT, others are gone both pins are down. made  
new bearings W Pine Stub 20 S 39 3/4 E 69  
Aspen 65 78 W 11 1/2

Went West and set 1/4 P. W Pine Stub 24 N 15 E 28 1/4

no others near

Went West + set 1/8 Post W Pine Stub 14 S 51 3/4 E 13

no others near

Town of Cassin

SEC LINE Bet 16 + 17 - 36 - 6 June 16. 1906

Went to corner of 16-17-20-21 found Post & set in 1903  
also bearings made at that time. Run N Var 3 1/2 E

4000 could not find 1/4 P

7000 Enter Swamp

7980 Fell 14 links E of corner Found Post Set by George  
Smiths also found stumps of both orig B.T.

Went S + set 1/8 Post B Pine 8 N 23 W 32

no others near

Went S. + " 1/4 " B Pine 7 N 7 1/2 W 21 3/4

" " 12 S 67 E 27

Went S + set 1/8 Post B Pine 10 S 76 1/2 E 31

" " 10 S 81 W 30

connected line South to corner for Road

SEC 21. 36. 6. June 16 1905

Went to SW corner Found Post + BT & set + made  
in 1904. as my notes gave the distance to MC  
on Right bank of River. I found a shortage of 1.04  
Proportioned this shortage and run East on true line1924 1/2 and set 1/8 P. W Pine Stub 18 N 64 1/2 E 149  
Var 47 15 E B Pine 65 54 1/4 W 86 1/4

Went NW corner and run E Var 3 1/2 E

1881 Fell 124 1/2 N of MC which I set on a line to E  
MC The B.T. to which are both stumps are  
still ok. found an over run of 19 links  
I could not set 1/8 P. as it came in straightPosted on Page 16  
County recordCopied on Page 28  
County recordCopied on Page 32, 50, 51  
County record

SEC 21-36-6 continued June 16-1906 65

The 1/8 P E of NW corner is 2025 1/2 E of cor - and in Run  
" " " " S " " 99 24 1/2 " " "  
2025 1/2 + 1924 1/2 = 3950 ÷ 2 = 1975 which 1/8 P. would  
be East of west 1/4 P. The recent line of this Sec is straight  
I run it 3 years ago + set 1/4 Post.Went to W 1/4 P. found Post and B.T. ok as the course of  
South Sec line is 41 1/2 E. and N Sec line runs on 45 W an  
intermediate course is 1:50 E So I am E on this course  
1975 and set 1/8 P. W Pine 16 S 53 1/2 E 420.3/4  
no others nearRun South from this 1/8 P. Var 3° E intended to run on 1:50  
3988 fell 122 E of 1/8 P. connected line N for Road

Run line North from this 1/8 P. (East of W 1/4 P.)

on same course as connected line going South  
1996 set 1/16 Post W Pine 18 N 32 1/4 E 349.

no others near

Thence N on same course 499

" " 8° West 210

" " 47° " this page is copied 684

" " 37 1/2 " on page 32 583

" " 65 " County record 584

" North 249 to Sec line

Bet 16 + 21

Thence West on Sec Line 460 to Sec. corner

for Road. This makes Road line as follows

Beginning at 1/8 P. E of SW corner Thence

N on 1/8 line to 1/16 P in center of NW 1/4. (21)

Thence N on 1/8 line 499 ch

" " 8° W 210 "

" " 47 " 684 "

" " 37 1/2 " 583 "

" " 65 " 584 "

" North 249 " to Sec line bet 16 + 21

" West on Sec " line 460 " " corner of 16-17.

20 + 21 - 36 - 6 - E completed June 17 1906

Went to SW corner found stake set by Dornok  
I then began the survey of a piece of lands as  
follows.

Beginning (with instrument adjusted on 0000)  
at a point on mud Lake 440 chains N 20° E from the  
SW corner. Then east to a stake which stands on  
shore of Lake creek. There

N 22° W	240 chains	along shore of Lake creek
N 20½ E	6.64	" " " " " "
N 51° E	2.59	" " " " " "
N 64 E	4.37	" " " " " "
N 50 E	1.12	" " " " " "
N 16 E	2.18	" " " " " "
N 7½ E	2.29	" " " " " "
N 12 E	.87	" " " " " "

To a stake which stands on shore of Lake creek

N 35¼ W	75	" To county Road
N 13 W	3.00	" " Right of way of Robbins R.R.

And along South side of Town Road

S 56 W	4.29	" along Right of way of Robbins R.R.
S 65 W	5.17	" " " " " "
S 79 W	4.00	" " " " " "
N 80 W	1.73	" " " " " "

To a stake which stands on shore of mud Lake

S 5° W	1.09	" along shore of " "
S 19 E	1.89	" " " " " "
S 37½ W	7.80	" " " " " "
S 40 W	9.55	to place of beginning

This page is copied on page 228 in  
county record of field notes

Went to SW corner of 26 found corner at  
Run East on old Random from a stake 15 links N of  
corner Van 3½ E Copied on Page 260  
2776 found on Past on line

Went West and set ¼ Post at proportional  
distance on iron pin 20 inch long  
which is 694 W of MC. and 2082 East of cor.  
Went West and set Post ½ way between  
¼ P. and the corner. WP. Stump S 12 E 13¾  
no other

I then made a survey as follows

Beginning at the ¼ Post.  
Thence N at right angles with Sec. line 3.25 ch  
" S 41½° E 4.32 "  
" West on Sec line to Place of beginning 2.86 "

Beginning again at a stake which stands on Sec  
line 2.86 ch east of ¼ Post

Thence S 58° E. 3.64 ch to a stake which stands on  
shore of Lake county record  
Thence along shore of Lake to Sec line at MC  
" West on Sec line 4.08 ch to Place of  
beginning

SEC 19-42-4 E June 25-1906

Went to Manitowish River. found B.T. for N 1/4 Post. Set instrument on East side of River. doped same on a line of 3 1/2 E. and set it where the B.T. for 1/4 P was north 75 West measured the distance to tree by use of Stadio wires found instrument was 7.67 ch distance given in Gout notes to 1/4 P. is 4.50 ch from B.T. this distance brought 1/4 P in River Gout notes say it is 100 ch West of River. Found that River had changed its bed indications show plainly that the River at time the Gout survey was made was 550 ch East of B.T. 1/4 Post no comes in Stream 3.17 ch West of instrument. turned a right angle South to a point due east from where I located 1/4 P in Stream. 450 ch from B.T. and on Sec line I then run South Var 7 E

1000 offset West 3.17 ch to line & continued South I had crossed River at 4.30 ch

77.57 Fell 2.32 ch East of 1/4 P. both org B.T. & Post  
Went north and canceled line from 4000 ch north to where canceled 1/4 line intersects Manitowish River

SEC 32-41-8 June 26 1905

Went to me on East side of Lake and set Post from bolts org B.T. and run E Var 3.20 E 2182 feet 42 E of 1/4 P org B.T. ok set Post.

Went next and set 1/8 P by proportional distance 20.32 2/3 West of 1/4 Post and 149 1/2 East of m.e. Y Pin 20 N 53 W 24 1/2  
no others

Run a line and canceled same South from 1/8 P to 1/8 Post on the 1/4 line  
IT □ □

SEC 10-40-8 June 27 1906

Found Graham had set W 1/8 P on South line. Gave to cut 10 acres of E side of lot 6.

Found Graham had run a line from 1/8 P to Lake

.. distance from 1/8 P to Lake is 1127 ch

.. I must take off 6.75 ch on East side

.. distance on West line of the 10 acres to Lake is 1450 ch. set Posts and at corners used line stake

□ □ □

SEC 28-41-8- June 29 - 1906

Went to me on E side of Plum Lake and chained SW along shore of Lake. 2067 ch & set cedar Post

Y Pin 14 S 68 E 33

Hem 12 E 27 1/2 W 24 Thence S 25 1/2 E to Lake & set Post

W Binds 8 N 11 E 9

W Pin 20 S 62 W 16 I then began at the stake 2067 from me and run SW along shore of Lake 5.27 ch and set Post

Hem 10 N 45 E 8

Binds 14 N 75 W 10 1/2

Thence S 25 1/2 E 2.73 to Lake & set Post

Y Pin 12 N 72 E 15

.. " 10 N 87 W 7



See 22-36-7 July 6-1906

Went to S  $\frac{1}{4}$  P on East line which I set last Fall and run west Var  $3^{\circ}E$

3525 Intersect wet Marsh, as this was for a road we quit and went to E  $\frac{1}{4}$  P.

and run west started on  $3^{\circ}E$  Var.

When I gone 10<sup>th</sup> I found I was running on  $5^{\circ}E$ . muddy had changed its course  $2^{\circ}$

1204 Top of Hill east of Swamp 280 ch East of Swamp. Set flag on hill west of Swamp. dist from instrument is 2370

3574 over Swamp (Very wet)

8022 Fell 486 South of  $\frac{1}{4}$  P. Set Post from Stump of W Pine B.T. Fir is gone. Made new bearing W Pine Stump  $18 S 30^{\circ} 1/4 E 23^{\circ} 3/4$

Found Point of old Post

S&E for correction:  $6.06$

change course  $3.24$

Cancelled line East 4011 for Road

Went S  $\frac{1}{8}$  P on East line again. adjusted instrument on a Var of  $4^{\circ}E$  and run

North  $86^{\circ} 1/2^{\circ}$  West 1430 about an  $\frac{1}{8}$  line

There " 52 " " 1344

" " 71 " " 779

" " 41 " " 665 all Swamp & Lake

" " " " 539 up gradual rise

" "  $\frac{1}{2}$  " East 279 to a stake which stands

on E & W  $\frac{1}{4}$  line 4011 ch from each  $\frac{1}{4}$  Post

Then as west an  $\frac{1}{2}$  line to west 14

Came here near S  $\frac{1}{4}$  P. and set a good cedar Post from both org B.T. remarked the Stumps of W. Pine as marks were nearly buried off Marks on cedar are plain tree is dead.

Finished at 4 P.M. July 8

copied on page 38. count Record

See 4-42-6-E July 9 1906

Went to S.E. corner. Found both org B.T. The Spere is down Stak 2 feet high with B.T. Plain " Trunk is broken off 3 feet from Stump Marks are plain. The Tamame is down has feller S.E. Marks of iron are on Top and are plain Set Post and made new bearing W Pine  $12 N 78^{\circ} E 74$   
No others

Run west Var  $4^{\circ}E$

1100 Leave Swamp and head of creek

4200 Stream 50 links west runs S.E.

4213 Fell ~~218~~ 218 North of  $\frac{1}{4}$  Post. The bearings for this  $\frac{1}{4}$  P. were grabbed out of a logging road. which runs south along Shore of Stream Found the South B.T. beside road. I am sure it was South B.T. as it is only 8 in - in dia now. The north tree is said to 11 in in dia after a long search I found what I believe to have been the Place where both trees originally stood. Placed the South tree (which is about 5 feet high) in its original position Marked the Place where I found it by a cedar Post. also marked Place where north tree stood with cedar Post. Set new Post. and made new bearing W Pine Stump  $18 N 3^{\circ} 1/2 W 12^{\circ} 3/4$   
No others

Found where runs are had set a Post for  $\frac{1}{4}$  P.

1225 South of  $\frac{1}{4}$  P. but there is no evidence of a  $\frac{1}{4}$  P. there. Found an old line made at time of "gout" survey was made running west from S.E. corner. also to the same kind of a line running East from SW corner This line runs on about  $3^{\circ} 1/2^{\circ} E$  while the one from S.E. corner runs on  $7^{\circ} E$  I am west from  $\frac{1}{4}$  P. Var  $19^{\circ} 1/2^{\circ} E$

4267 Fall 19 links N of corner. 2 org B.T.

Went East and set  $\frac{1}{8}$  P. at  $2138^{\circ} 1/2$  and  $9^{\circ} 1/2$  South of Random W Pine  $15 N 83^{\circ} 3/4 W 6^{\circ} 1/4$

14 S  $70^{\circ} 3/4 E 27^{\circ} 3/4$

Cancelled line East to  $\frac{1}{4}$  P.

SEC. 4. 42-6. E July 11 1906

I measured S. from W 1/4 P. on South line

448 found a stake Samson had set for an 1/8 P

I prolonged my offset line South to where Samson claims the South line to be. (This offset line is 42.49 west of S.E. corner and 36 links west of 1/4 P.) Found distance from 1/4 P. to be

1225 to Samson's South line. This Part is 4000 ch East of SW corner and course of line is about 3 1/2 E. Had this <sup>line</sup> been Prolonged East they would have fell 1500 ch South of corner

The line from S.E. corner Prolonged West from 1/4 P. would intersect west sec. line 8.75 N of SW corner. FINISHED at 10. am

36	6	2	4
14	7	4	5
	7	8	9

SEC. 5. 43-5. JULY 17-1906

Went to SE corner. found both arg B.T. OK. The course to both is correct, and distance to Hemlock correct, but distance to cedar is 18. instead of 8 links

Went West to Lake. found both arg B.T. north one is a stump and does not agree with field notes for either course distance. I set Post from South line. The N. B.T. is N16 E 30 1/2

Placed instrument in line between SE cor<sup>n</sup> and me. Found distance to be 551 and course of line 1.20 E var.

Went to West side of Lake &amp; set m.c. from cedar B.T. Hemlock is gone. Set instrument at this m.c. and Flag at E. m.c. found course of line 2.15 E var and distance 1425. So my notes reads from SE cor

551 feet to Lake set m.c. var 1.20 E

1976 over " " " " 2.15 E

West from West m.c. var 3.0 E

315 into Swamp

1025 over "

2027 1/2 Right bank of Turtle River	The line run by Govt Surveyor is 75 north on E side of River and 15 on W side of R.
2310 Left " " " "	
5332 - 18 links from left bank of Turtle River	

5582 - 15 " " Right " " " "

" " The line run by U.S. Surveyor is 100 north

" " Fell 86 links N. and 56 W of Witness corner set Post from cedar B.T. Hemlock is gone made new bearing

cedar 14 S 11 E 27 L

... other ...

The notes of U.S. Surveyor say Witness corner is 50 Lks East of tree corner in Stream. they should say 50 Lks W. They say River runs SW. but it does Run SE.

Found my departure at tree corner in Stream is 4.37/100 and the dist<sup>n</sup> from west m.c. is 5419.Went East and at 2823 west of W. m.c. set 1/4 Post from arg B.T. That is I am sure I found what they so left of the B.T. there is no Hemlock or Fir standing with the marks on. There are only 2 Hemlock down anywhere near 1/4 P. Should be one of the was much to large the other the right size. It was rotten but I found enough of the original mark of iron to satisfy me it was the arg<sup>n</sup> B.T. Set instrument at the roots of this Hemlock measured the distance on

SEC 5-43-5- JULY 19 - 1906 cont.

the corner given in field notes and set instrument at this point measured the distance and an course given in field notes and found the stump of a Fir of the right size to rotter to find any marks, nothing but the roots are left. as the course and distance agrees with the goal. Field notes, the size and kind of tree also. and as the Post sets on the line marked U.S. Surveyor and for numerous other reasons I am satisfied I have placed this 1/4 P. in its original position

North from S 1/4 P. Var 1° E

300 Left bank of turtle River just west of large pine Springs  
925 C + NW. RR.

1200 Enter Swamp

3000 leave "

4500 Enter "

5400 leave "

7400 Enter "

7989 Fall 510 West of 1/4 P. found 2 org B.T. + Post

Set new Post and went to NE corner found  
4 org B.T. Set Post + run west Var 3° E

2300 found I had made a mistake in setting Vernier  
of 6°. I offset south 240 ch and changed course 6°

2450 needle changed to 2 1/2 E

3947 Fall 32 links N of 1/4 P

7929 " 31 " " " corner found 3 org B.T. and Post

Set new Post and went to W.C. for SW cor  
looked carefully all the way south for line  
also looked careful for 1/4 P but neither could  
be found

Began + witness cor = run west 250 ch

Thence North 6° E

788 Bend in River

1500 over bend in River

4000 offset East 300 ch to line

8056 Fall 124 West of corner

Went South + set 1/4 P. at 4028 and 62 E of Random

1/2 Birch 26580 W 7

1/2 Birch 20574 1/2 E 35 1/2

East from west 1/4 P Var 3.16 E on an intermediate  
course between south line and North line

SEC 5-43-5 JULY 22 - 1906

3406 Intersect N + S corner 1/4 line and find I am  
11 links S of an intermediate course between Sec.  
lines when made straight from corner to corner  
Set center of Sec 11 west of line 1/2 Birch 14 N 69 W 26"

10 S 19 E 26"

Distance to S 1/4 P. 3971 1/2 Birch 12 S 71 1/2 W 21 1/4

" N " 4018 1/2 Hem 12 S 57 E 28

Went South and set 1/8 P. at 1985 1/2 and an corner 1/4 line

1/2 cedar 10 N 58 E 71 1/2 1/2 Birch 14 N 69 W 26

1/2 Birch 18 S 36 E 71 " 10 S 19 E 26

East from this 1/8 P Var 32° E an intermediate course  
between E + W 1/4 line and S. Sec. line

3100 Intersect north Lake set MC

1/2 cedar 10 N 58 E 11 1/2

1/2

1/2 Birch 18 S 36 E 21

cut 2 acres off the west side of lot 6 - 4. 43-5

It is 490 from SW cor of 4. to MC between 4 + 5 as the  
South shore of lake bears a little north of look of a strip  
400 ch wide cut Post on Sec line 400 ch of corner in

Right of way of C + NW RR

Set Post on shore of Lake 400 ch east of MC

1/2 cedar 10 N 5 E 3

" 8 N 54 W 5

Set new Post at mc Between 4 + 5

1/2 I cornered the Sec line from S 1/4 P to E to MC

" " " N + S 1/4 " " " " " 1/8 Post South of  
center and marked the N line of lot 5 from mc west  
to 1/8 P south of center



SEC 23. 42-5 JULY 31-1906

Went to NE corner found Post & set from NW  
B.T. in 1902. which is now a stump

Run south on my old Random var  $43\frac{1}{4}^{\circ}$   
3982 fell  $141\frac{1}{2}$  East of  $\frac{1}{4}$  P. the orig. B.T. and Post &  
Set in 1902 the new bearing & made at that time  
has been est. by Pin 16  $384\frac{1}{2}$  W 95  
canceled line North to corner

SEC 14. 36-6. August 2 1906

Went to center of SEC. which I set in DEC 1903

Run South var  $1\frac{1}{2}^{\circ}$  E

3902  $\frac{1}{2}$  fell  $7\frac{1}{4}$  W of  $\frac{1}{4}$  P. which I set in 1902  
Went North & set  $\frac{1}{8}$  Post at  $195\frac{1}{4}$  and  $3\frac{1}{8}$  links  
East of Random. The Post is a piece of Railroad  
Rail 3 feet long TAM: 12 N 77 W 20  
12 S 66  $\frac{1}{2}$  E 203  $\frac{1}{4}$

 Copied on Page  
25 COUNTY RECORD

SEC-10-36-6 August 3" 1906

Went to SE. corner. Set instrument at Post turned  
Telescope onto  $\frac{1}{4}$  Post between 10 & 11 found corner  
of this line to be  $3\frac{1}{2}^{\circ}$  E var.

Turned off  $90^{\circ} 20'$  West. and run west

2750 Enter Swamp copied on Page 19

3850 Leave "

4058 fell  $18\frac{1}{2}$  links N of  $\frac{1}{4}$  P. which I set from Stumps  
of orig. B.T. in 1901. found angle of this line  
10  $90^{\circ} 35'$ . Turned off  $90^{\circ}$  an angle of  $90^{\circ}$  to the  
North. Then turned off  $35^{\circ}$  East which gives the  
same corner as East line of section

Run north on this corner var  $3\frac{1}{2}^{\circ}$  E

100 Enter Swamp

3600 Leave "

3800 Enter " County Record

3975 Leave "

4050 Enter " and River bottom

4078 Left Bank of Hannawalk River & set Meander Post

B Pin 12 South 176  
no other

SEC. 21-37-9-E August 15 1906 77

Went to NE corner identified by B.T. & A  
Marked in 1901. W Pin 12 N  $57\frac{1}{2}$  W 94  
no other

Surveyed School grounds as follows  
Beginning at a point 33 feet West of NE corner  
Then Southeasterly Parallel with Town Road 264 ft  
" West Parallel with Sec line 165 feet  
" northeasterly Parallel with Town Road 264 ft  
" East on Sec. line 165 feet to Place of beginning  
containing on a c.  $\square$   $\square$

county record

SEC 29-37-9-E Aug 14-1906

As there was some dispute about a stake  
which is said to be the SW corner. I set flag  
at this stake and at S  $\frac{1}{4}$  P. Placed instrument  
in line between flags. found a stake said to  
have been set by them to be in line. So I  
drew a Pump point 3 feet long filled with  
Charcoal when Post stood for SW corner and  
drew it 4 inches below surface and placed  
a rock  $15 \times 18$  inches  $\times$  8 inches on top of  
Pump Point. as I am satisfied it is where  
orig corner stood. found old fences all  
agree with this location

copied on Page 180

SEC 3+10 &amp; 49-39-8- Aug 1906

Work done with Pocket compass

Set new Post at corner to 3-4-9-10 from  
both orig. B.T. used as is a stump 3 feet high.

Remarked it with Scribbling iron. The east  
corner is down marks Plain Set Post at roots of  
Same and mark it O.B.T. Went N and found  
 $\frac{1}{4}$  P. old B.T. gone Set Post in where old Post  
stood & marked a what Pin 10 N 108 26

Found  $\frac{1}{4}$  P. between 9+10 Set new Post

" corner to 2-3-9-10 & set Post

county Record

Went to S 1/4 P. which I set from west BT Jan 1904

Run East Var 5° W

531 center of R.R. track

4035 Fall 473 South of corner which I set from Y Pin

It is now a stump cut very low remarked  
it went West 2 dot 1/2 dot Birch N 1 E 11

8 273 E 15

Went again to S 1/4 P. and run north Var 5° E

new bearing for 1/4 P. W. Pin 1092 1/2 33

no other

1482 Jan 50 links South of Swamp

2764 .. .. 75# " North .. .. and lake

4088 Fall 6 links E of center set by oneil

5874 Top of hill South of Swamp &amp; Lake

6347 over lake

7600 " Swamp

4170 Fall 58 1/2 W of 1/4 P. Set Post from Birch

Aspen gone, made new bearing

W Pin Stump 10 S 31 E 24

Dec for correction 716 Change course 40'

Went to E 1/4 P. found Post &amp; 1095 BT in place

Run west on old random on oneil's cornered line

Var 30° E

700 Leave Swamp &amp; Flaway

1150 offset N 2 links to miss Y Pin

2625 into Swamp

3920 Fall 4 links South of Oneil's center

4800 Leave Swamp

6400 into "

6800 leave "

7200 into "

7927 Fall 185 N of 1/4 Post org Post made new

bearing Tam 6 S 16 E 9

Went East and set center

Dead W Pin 14511 E 46 1/2

DEC for correction 231 change course 1.20

Distance to N 1/4 Post 4169 1/2

" " S " " 3889 1/2

" " E " " 3879 1/2

" " W " " 4041 1/2

Oneil set his center about 1/2 way between the N & S 1/4 P  
and then run E + west from it to E + W 1/4 Post  
His center is 96 links North + 41 West of mine  
Went East and set 1/8 P

Birch 10 N 77 E 30

10 S 25 3/4 W 29

= August 27<sup>th</sup> 1906 =

South from 1/8 Post E of center Var 52°

3977 Fall 7 E of 1/8 Post

Went North to 2000 chains and cornered

line N to 1/8 P. and scaled 12550 feet of

Tape on N.E. 32-23-42-7

Finished at 4 P.M

□

SEC. 36. 37-9 E August 29<sup>th</sup> 1906

Went to mc. near 1/4 on East line found mc

Post &amp; set from org 1/4 BT. in June 1906 BT OK

Run west Var 5-30 E copied on Page 236

191 offset North 65 LINKS to 1/4 line

7990 Fall 143 S of 1/4 P. I set in June 1903

- DEC for correction 179 change course 1° 02'

Went to S 1/4 P. which I set from org BT

in June 1903. Run N on my old line

which is an intermediate course.

4178 I intersect cornered E + W 1/4 line and set

Post for center of Sec Y Pin = 10 S 78 W 50 1/2

W " S. 10 S 61 E 23

Prolonged N &amp; S 1/4 line North

1463 Intersect Lake and set mc.

Cant's record

Y Pin 10 S 71 E 20

of field notes W " 10 N 80 W 51

Came back to center and cornered line East at

1994 Set 1/8 P. 35 3/4 N of Rand W.P.S. 16 N 56 W 22 1/2

" " 10 S 60 E 27 1/4

Cornered line East to Lake and set

M.C. over

SEC 36-37-9-E continued Aug 30 1906

Went to S  $\frac{1}{8}$  P. on East Line which I set in June 1903. run W Var  $4\frac{1}{2}$  E

4018 fell 42 S of  $\frac{1}{8}$  P Set in June 1903. corrected Line E + set  $\frac{1}{4}$  P. W Pine Stump 16 S  $88\frac{1}{2}$  E 31  
No others near

Went to  $\frac{1}{8}$  P. E of center and run S Var  $5\frac{1}{2}$  E  
2142 fell 18 E of  $\frac{1}{4}$  P. corrected line east to  $\frac{1}{8}$  P.  
copied on Page 236 county record of

North from  $\frac{1}{8}$  P. E of center on corrected Line from  $\frac{1}{4}$  P. in center of SE  $\frac{1}{4}$

2847 Intersect Lake and set me  
fired mark W Pine Stump 20 S  $47\frac{1}{2}$  W 26  
No others near

Finished August 31<sup>st</sup> 1906

SEC: 3-36-10 E September 3<sup>rd</sup> 1906.

went to SW corner. found Post set by William Allen, and Stumps of both original B.T. cut 4 ft high with all the original marks plain  
Run East Var  $75\frac{1}{2}$  West

6650 Enter wet Swamp Copied on Page

7372 fell 50  $\frac{1}{2}$  links North of corner set by Don  
SEC for correction 782 change corner 21

corrected line west + set  $\frac{1}{8}$  P. at 1843 west of SE corner  
and 39 links S of Random B. Pine 10 N  $42$  W  $9\frac{1}{2}$

309  
corrected west and set  $\frac{1}{4}$  P. at 3686 and 26  $\frac{1}{4}$  South  
of Random B. Pine 9 N  $69$  W  $2\frac{1}{4}$

county record  
corrected line west and at 1843 East of SW corner set

$\frac{1}{8}$  Post 12  $\frac{1}{2}$  East of Random B. Pine 11 N  $75$  W  $20\frac{1}{4}$   
" " 10 S  $59$  E  $29$   
" " 10 S  $57\frac{1}{2}$  W  $16$

Went East to  $\frac{1}{4}$  P. and Run North Var  $26$  East

100 Enter Swamp  
700 Lake

September 1906

SEC: 3-36-10-E. continued Sept 4 - 1906

Went to SW corner and run N Var  $30$  E

4197 fell 113 East of  $\frac{1}{4}$  P. which I set from the stump of the org B.T. N  $86$  W  $317$ . Someone has tried to obliterate this monument by cutting the marks off and burning the stump on the side which bears the marks. remarked this stump and made new bearing W Pine 20 N  $84$  E  $269$   
No others near

The Parties who obliterated marks on stump removed the  $\frac{1}{4}$  Post it was ok 1  $\frac{1}{2}$  years ago  
Went South + corrected line 2098 ch and set  $\frac{1}{8}$  P

copied on Page Tamm 14 N  $31$  E  $20\frac{1}{4}$   
cedar 6 N  $52$  W  $16$

309  
East from W  $\frac{1}{4}$  Post Var  $19$  East West  
6605 intersect East Sec line and set line stakes

Went To NE corner and set Post from 4 org B.T. The Birch and Spruce are stubs marks ok The pine on sk. found down old Random corner cut 4 links East of Post run South Var  $13$  E

7615 SE corner set by Don. a shantay of 445  
Went N + set  $\frac{1}{4}$  P at 3879

W Birch 8 N  $44$  W  $32$

Aspen 10 N  $78$  E  $23$

Went N and set  $\frac{1}{8}$  P at W Pine 18 N  $54\frac{1}{2}$  W  $20$

1918 S of NE corner Birch 16 N  $34\frac{1}{2}$  E  $10$

county record

picked up E + W  $\frac{1}{4}$  line and at

6884 fell 472 N of  $\frac{1}{4}$  Post.

See for correction 683. change corner 40

corrected Var  $23$  West

= Sept 6 - 1903 =

Went to South  $\frac{1}{4}$  P and run N Var  $17$  E

6605 fell 386 East of  $\frac{1}{4}$  P. set from both org B.T. Went South and set center of Sec at the intersection of corrected  $\frac{1}{4}$  lines

Y Pine 20 N  $87\frac{1}{2}$  E  $46\frac{1}{2}$

run W .. 8 S  $45\frac{1}{2}$  W  $14$





Sec 29. 37-11 Sept 24<sup>th</sup> 1906

Went NE cor. found Post Set by Dorr. no bearings. no timber near Run S 15° E. Mustola in setting. Service intended to run on S° E  
3793 1131 E of 1/4 P. NW BT OK + Dorr Post. Went north end Set 1/4 P

Copied on Page 370

Went again to NE cor. Run W Var 3 1/2° E  
371720 NW RR

2250 leave Swamp

4195 S 11 125 S of 1/4 P. Found an old Post marked 1/4 S. Found Stump of org BT. Marks gone made new bearing Hem 11 N 82 1/2 W 13

no other

Went from E 1/4 P Var 3 1/2° E

1620 NW RR.

2000 middle Shows 320

4000

4076 Sell 4 1/4 links S of 1/4 P. both org BT

SW one down and Marks nearly gone made new bearing Hem 10 S 75 1/4 W 67

no other

Went to N 1/4 P. Run South Var 9° E. Sept 25

8094 Sell 289 W of 1/4 P. could not find org BTs but found post set by someone who had run the south line from corner to corner but do not think he found org BT.

Went North and set center of Sec

cedar 14 N 11 E 62

Hem 10 S 33 1/2 W 44

Intended to cut up NE 1/4 but the town board changed their mind in regard to location of road. canceled E & W 1/4 line from W 1/4 P. E to right of way of C & NW RR.

Dist to N 1/4 P. 4061

county " " S " " 40.33

read " " E " " 38.74

" " W " " 42.17

Did not set any 1/4 posts in this

section

Sec 30. 37-11 Sept 26<sup>th</sup> 1906

copied on Page 371  
Went from E 1/4 P Var 1/2 W county  
9710 Sell 540 554 South of 1/4 Post Set new Post where I set this 1/4 P 8 years ago from org. B.T. The post I set at that time is still there but rotten. I found the SW BT down but marks plain. Made new bearings  
change course 3° 10' Hem 10 N 75 1/2 W 36  
cancel Var 3.40 W " " 10 S 13 1/2 E 31

cancelled line E line East to 1/4 P. for Road

This line as canceled crosses Streams twice, one about 200 ch east of W 1/4 P. and again at about 800 ch east of west 1/4 Post Read

Finished at 5 PM Sept 27<sup>th</sup> 1906

Copied on Page 366

Section 33-36-11-E. Sept 28, 1906

Went to SE corner found Post set by Dorr from org. B.T. which are all gone but the Sugar which stands NW which is OK. Run West Var 3 1/2 East.

850 Enter Swamp

There was a road cut out

2000 leave "

in this line about 25 years

4800 Enter "

ago, 305 set wid. bearings at

1/4 P. use of later 60

8158 Sell 290 South of corner, org B.T. and Post set by Dorr West East and set 1/4 P. at 4079 + 145° N of Random

Sugar 94 N 4 W 63

" " 10 S 45 W 21

cancelled line East and set 1/8 Post

Hem 9 N 42 E 16

Birch 16 S 19 1/2 E 25 1/2

Went to North 1/4 P. Found Birch OK maple down but marks on plain. Run S Var 3 1/2 E

8395 Sell 521 E of corner org BT 1/4 Post

cancelled line North to 1/4 P.

county road

S&amp;C 33.39.9. Oct. 3-1906 2.30 P.M.

Went to E 1/4 P. found Dorrs Post and 2 B.T.  
 One B.T. gone if they can live even there as Dorrs  
 bearings are both dead and South one is down. &  
 made new bearing W.P. Pine Stump 30 S 72 W 82

Dorrs B.T. Standing 1 Hem 7. N 14 E 24

Run N. Var 1.10 E copied on Page 297

2359. off set W. 23/4 county record

3667 Sill 238 E of corner including off set

Found the Tam: down and 15 links from

Stump. Found Stump of same and old Post

Placed Tam: on Stump and braced it up

made new bearing cedar 85.62 1/2 E 26 1/2

Went South + Set 1/4 P at 1833 1/2 and 1/4 W of Rank

W.P. Pine Stump 30 S 26 E 37

No. other trees. Post 1/2 W of cut in

Road 1.20 ch. canceled line S + set Post 1/2 distance

Bot: 1/8 P. and 1/4 P Hem 10 S 57. E 93

South from E 1/4 P. Var 550 E

3667 Sill 17 1/2 W of corner found 3 org: B.T.

all down found Stump of SW. B.T.

made new Post no green timber near

Post stands in Swamp 20 E of Road

West from SE Corner Var 30 E

4063. Sill 219. N of Post. found both org B.T.

down marks plain. made new bearing

W.P. Stump 30. S 87 1/2 W 12 1/2

of feed notes

West from S 1/4 P. Var 60 E

2175 Sill 25 links runs north

4096. Sill. 121 1/2 S of corner. found 3 org. trees

They are all dead 5 in is nearly gone made new

bearing W.P. Birch 10 N 3 1/2 W 50

Went E &amp; Set 1/8 P between SW cor + S 1/4 P

Post 20 in burned Tam 14 S 1 E 53

Swamp

No other timber dead + down

Set 1/8 P. East of S 1/4 P W.P. Stump 14 S 84 1/2 E 38

No other timbers gone. -

Set 1/8 P. ~~1/8 P~~ 10 S E 1/4 P See Page 87

SEC 33.39-9 cant Oct 5-1906

North from SW Cor Var 50 E

1650 9 miles at Sugar camp creek

2117 over creek and 6000 m copied on Page

3000 same creek is 75 E of line 297

3507 High bank of Echo Lake

6287 Sill 100 West of me on north shore of Lake

Found the stump of W.P. Pine B.T. Finger

Went to S side of Lake + set MC at 3539 N

of SW cor: and on shore of Lake

W.P. Stump 16 S 83 W 25 1/2

12 N 87 1/2 E 36

canceled line S and set Post on S bank of Stream

at 1645 canceled line S. to SW corner

canceled line from SW. East to SE corner and

N from SE corner to E 1/4 P Set 1/8 P S of East

1/4 P. W.P. Pine Stump 18 S 73 E 40

no other

as MC. on N side is said to be even 20.00 ch South

of NW corner. and as I wanted the N 1/8 line

I run E from this MC. Var 80 E + + +

8 51.50 Run N from MC. on north side of Lake

Var 40 E. county record of

2100 Sill 178 E of corner. Set Cedar Post 5x5 inches

and 3 feet long 50th W.P. Pine down and marks

nearly gone. set a part of trunk in hole

near Stump from which it came. and

re-marked the Stump. the Hemlock is all gone

but the Stump 8 in high marks gone, re-marked

it no timber near for new bearing

Change corner 5.50 = 8.50

+ + + over Lake

feed notes

3434 over Lake 150 south of inlet

7949 Sill 79 1/2 S of 1/8 Post cancel Var 35 East

Dec. 100. canceled line West to Lake and

Set MC W.P. Pine Stump 14 S 78 1/2 E 446

no other



Sec 32, 36.9. E Oct 12" 1906

Sound Don had established the NE and NW corners by proportional measurement and had set the West and North  $\frac{1}{4}$  Posts. Had also set N  $\frac{1}{8}$  P. on E line and the  $\frac{1}{8}$  P. North of center. So I begin at N  $\frac{1}{8}$  P. on E line and run West Var  $2\frac{1}{2}$  E.

2057 found where they say Don set  $\frac{1}{16}$  P. 115 gams  
4107 fell 13  $\frac{1}{2}$  links N of Dons  $\frac{1}{8}$  P.

Posted on Page 207

Went to N  $\frac{1}{4}$  P. Set flag at NE corner placed instrument in line near  $\frac{1}{8}$  P. found distance 4118  $\frac{1}{2}$  so set  $\frac{1}{8}$  P. at 2059  $\frac{1}{4}$  a large rock in center of road with + cut an it. with stars hammer

Run South from this  $\frac{1}{8}$  P. Var  $1^{\circ}$  E

2038 fell 14  $\frac{1}{2}$  west of  $\frac{1}{16}$  P. which I set at equal distance between Dons  $\frac{1}{8}$  Posts

County Record { Linden 20 N 17. E 2

corrected line onto this  $\frac{1}{16}$  P. and prolonged the line 2038 = 4076 South of  $\frac{1}{8}$  P.

corrected line N from  $\frac{1}{16}$  P. to  $\frac{1}{8}$  P.

SEC 7-36.11 E. Oct 18 1906. cont- from Page 30

Run West from  $\frac{1}{8}$  P. N of center Var  $1^{\circ}$  E

5300 fell 8 links S of Dons  $\frac{1}{8}$  Post

Went East and set  $\frac{1}{16}$  P. in center

of NW  $\frac{1}{4}$

as per on Page 1360 County record

corrected line N to  $\frac{1}{8}$  P. and East to  $\frac{1}{8}$  P.

XXX Picked up  $\frac{1}{8}$  Line and at 5100 fell 8 links  
253 South of

SEC 6. 36.11 Oct 20" 1906

Went to center set by Dorr. found Post and both of his B.T. copied on Page 360

Run North Var  $4^{\circ}$  E

1370 Someones  $\frac{1}{8}$  Post 13 links E. no bearings

= OCT 22 =

3385 feet 18 links West of  $\frac{1}{4}$  P. set new Post from South B.T. now a stump. found a shortage of 43  $\frac{1}{2}$  ch. proportioned this shortage and set  $\frac{1}{8}$  Post at 17.73  $\frac{1}{2}$  North of center.

Hem 10 N 53  $\frac{1}{4}$  E 10  $\frac{1}{2}$

" 12 S 71 W 37  $\frac{1}{2}$

Corrected line to center

West from  $\frac{1}{8}$  P. N. of center, Var  $3^{\circ}$  E

1500 Enter tam = Swamp

3017 .. Wet marsh and sluggish stream

3189 over .. .. .

4400 Leave Swamp

5100 fell 253 South of  $\frac{1}{8}$  P. found which

I set as follows. Went to NW corner found the stumps of the 4 Pine also the Birch which is dead Spruce is gone & steep stump the course and distance to Pine is ok, but the distance to Birch & stump of Spruce should be reversed set new Post and run S. Var  $3^{\circ}$  W

500 Enter Swamp

2467 fell 216 West of  $\frac{1}{4}$  Post found both org. B.T.

Set new Post. found a shortage of 43  $\frac{1}{2}$  ch. Proportioned shortage & set  $\frac{1}{8}$  P. at 14.74.85  $\frac{1}{10}$  from NW cor. and 15.32.15 N. of  $\frac{1}{4}$  P.

XXX set opposite Page at; W Pine 18 S 60  $\frac{1}{2}$  W 155

near bottom Spruce 4 N 48 E 38

corrected line East to 20.00 ch

Went to center Took Dorr's B.T.

Tam 10 S 23 W 20

W. Pine 12 S 41 E 8  $\frac{1}{2}$

Run West Var  $1^{\circ}$  W. County

2500 RR track

3250 Enter Wet marsh and stream

## Section 6-36-11-E Oct 27. 1906

Copied on Page 360

3657. over wet marsh + stream

5190 fell 11 links S of  $\frac{1}{4}$  P. corrected line East and  
Set  $\frac{1}{8}$  P. at 2056  $\frac{1}{3}$  ch. of centerPost sets on S. side of W. Pine 15 S 41 E 66  $\frac{1}{2}$   
RR in edge of cut Ino. othersRun North from  $\frac{1}{8}$  P. west of center Var 2° E

1400 entz. Wet marsh. some tamarac

3200 Set line stake. could not find  $\frac{1}{8}$  P or town  
line. I found it would not be possible to run  
the town line as it is wet boggy marsh water  
2 feet deep. So I set  $\frac{1}{16}$  P. at proportional  
distance between  $\frac{1}{8}$  Posts. which is 2054  
corrected my N + S Rand. on to this  $\frac{1}{16}$  P  
and at 1680 fell 44 E of  $\frac{1}{16}$  P corrected  
line South of to  $\frac{1}{8}$  P.

= Oct 26 =

Went to center and <sup>run</sup> east Var 1  $\frac{1}{2}$  <sup>west</sup> East  
4237 fell 2 links N of  $\frac{1}{4}$  P. found one B.T. Set new W Post  
and made new bearing Cedar 7 N 45 W 48  $\frac{1}{2}$   
Went West and set  $\frac{1}{8}$  P. did not set this PostNorth from E  $\frac{1}{4}$  P Var 5 E

2200 Stream 10 links wide runs SW

= Oct 17 =

3550 fell 102 West of corner found 3 BT's spruce  
is all but stump no marks on it set Post and  
went South and set  $\frac{1}{8}$  P. at 1888. as there is a  
shortage of 2100 ch. Cedar 12 N  $\frac{1}{2}$  W 51  $\frac{1}{2}$ : " 12 E 37 W 24  $\frac{1}{2}$ West from N  $\frac{1}{8}$  P on East line Var 004228 fell 222 links N of  $\frac{1}{8}$  P corrected line  
East 2114 found an old line at 2114 so I  
did not run N + S  $\frac{1}{8}$  line

county = Oct 28 = read

South from center Var 34  $\frac{1}{2}$  E3941 fell  $\frac{1}{2}$  links East of Dorrs  $\frac{1}{4}$  P. went North  
and set  $\frac{1}{8}$  P Cedar 10 N 79  $\frac{1}{2}$  W 48  
Spruce 10 N 51  $\frac{1}{2}$  E 27

## Section 6-36-10-E Oct. 30-1906

Copied on Page 360

Went to SW corner again Run N. Var 2° E

4045 fell 136  $\frac{1}{2}$  West of  $\frac{1}{4}$  P. went South and  
Set  $\frac{1}{8}$  P at 2022  $\frac{1}{2}$  W Pine 18 N 11 W 15and 68  $\frac{1}{4}$  East of Rand. Birch 10 S 8  $\frac{1}{2}$  W 49  $\frac{1}{4}$ 

Corrected line South to open swamp

West from  $\frac{1}{8}$  P. S. of center Var 4  $\frac{1}{2}$  E

3000 Leave swamp

5150 Stream 20 runs South

5297 fell 115 South of  $\frac{1}{8}$  P. corrected line East  
2150 to about where  $\frac{1}{4}$  Post will be  
= Oct 31. 1906 =South from  $\frac{1}{8}$  P. West of center Var 2° East3975 fell 30 links E of  $\frac{1}{8}$  Post. went N + S set  $\frac{1}{16}$  P in  
center of SW  $\frac{1}{4}$ . W Birch 10 N 78 W 20  $\frac{1}{2}$ county Pine 18 S 47  $\frac{1}{2}$  E 26  $\frac{1}{2}$ corrected line N to  $\frac{1}{8}$  P and W to  $\frac{1}{8}$  P.  
finished Oct 31. 1906 readSurvey of school Ground on Gout Lot 5  
Sec. 13-36-8 E. (1906)

Commencing at a Point on  $\frac{1}{4}$  line 450 ch  
North of SE. of Gout Lot 5.  
Thence West 235  $\frac{1}{2}$  ch. Thence at right angles with  
 $\frac{1}{4}$  line. Thence North parallel with  $\frac{1}{4}$  line  
350 ch. Thence East at right angles with  $\frac{1}{4}$   
line 235  $\frac{1}{2}$  ch. Thence South on  $\frac{1}{4}$  line  
350 ch to place of beginning containing one  
acre. all in Gout Lot 5 township 36 N. Range  
8. East Omeida co Wis  
NOV 3. 1906

Posted on Page 360  
 117 county records

5190

2054

3134

Section 3-42-5-E NOV-8<sup>th</sup> 1906

Went to S<sup>1</sup>/<sub>4</sub>P. Which I set last winter  
 Run N. Var  $1/2^{\circ}$  E on some ones picket line  
 2000 offset W 4 Links

3000 " " 3 " Picket line bends west

3500 could not follow picket line

7800 Stream 40 links wide runs west

7952 fell 315 E of <sup>1</sup>/<sub>4</sub>P. OK set it 5 years ago

correct Var  $2.45^{\circ}$  DEC. 3.96

Went S. and set 3 line stakes on true line

Went to S<sup>1</sup>/<sub>4</sub>P. and run East Var  $3/2^{\circ}$  E

4000 could not find corner it is burned out

81.18 fell 69-5 N of <sup>1</sup>/<sub>4</sub>P. Which I set from org BT  
 in 1901. both trees are down no timber near

Went West and set Temp<sup>2</sup> cor<sup>2</sup> at 40.59 and

34.3/8 S of Random

Went East <sup>1</sup>/<sub>4</sub>P. found Post but think it has

been moved. Went to E BT which is N  $6^{\circ}$  E 840

found stump with Bt. OK RS  $6^{\circ}$  W 840 ~~Var~~ Var  $4^{\circ}$  E

and set Post made new bearing

W. Pine 12 N 38 E 108

No others

Went to E+W <sup>1</sup>/<sub>4</sub> line at 39.76 ch and run E on  
 Someones picket " Var  $1/2^{\circ}$  E

39.29 fell 238 S. of <sup>1</sup>/<sub>4</sub>P. Went West + set Temp

<sup>1</sup>/<sub>8</sub>P. at 196  $4/2$ . 1 Link E of Someones <sup>1</sup>/<sub>8</sub>P

1 Run South Var  $2/2^{\circ}$  E

40485-LL 17  $1/2$  W of Temp <sup>1</sup>/<sub>8</sub>P which is an true  
 line between S<sup>1</sup>/<sub>4</sub>P. and Temp S.E. corner  
 connected line N

finished NOV 9. 1906

## SEC. 36.37-10 East NOV-10-1906 1.P.M.

Went to SW corner found 4 ora. Bt. West birch  
 is broken off 3 feet high. Run East var  $2/2^{\circ}$  East  
 4021 fell 218 ch North of <sup>1</sup>/<sub>4</sub>P. found stub of East BT and  
 Stump of W BT. made new bearings

copied on W Pine 12 N  $12/2$  W  $39/2$

Page 335 " " 12.5 72 E 24  $1/2$

Went Wand set <sup>1</sup>/<sub>8</sub>P at 20.10  $1/2$  and 1.09 South of Random

W Pine 12 N  $40/2$  E  $8/2$

" " 14.5 51 W 17

Went to SW corner and run North Var  $4^{\circ}$  E. NOV 11

450 cross Railroad track

950 " " " No 2

3700 Enter Swamp

4000 could not find <sup>1</sup>/<sub>4</sub>P no Gout<sup>2</sup> line bet<sup>2</sup> 35+36

7700 found + line NO corner

= NOV 12 =

9005 Stream 40 links wide R.S.W

10000 Enter Swamp

13000 Leave "

162.42 fell 307 West of corner to 23-24-25-26

found both ora. Bt. down marks OK. Set new

Post and made new bearings

W Pine 19 N  $6/2$  E 35

" " 54. 12.5 24 E 27  $1/2$

Went south and set Temp<sup>2</sup> corner at

8121 and 153 ch East of Random

= NOV. 13 =

Went from Temp<sup>2</sup> corner var  $2^{\circ}$  E

8000 could not find. " have been ordered to quit

until farther orders came home at 920 A.M. NOV 14

= DEC 11-1906 =

found corner to 26-27. 34.35 ash gone spruce nearly

gone. set Post and mad new bearings

W. Pine 18 S 83 E 14

" do 18 S 10 W 10

Picked up line I left NOV. 14 and at

81.12 fell 55 South of corner to 26.27.34.35

continued on Page 101

can'ty record



Sec 21-41-6 NOV 16 1906

Went to N 1/4 P. found NE BT marks nearly gone set Post and made new bearing

W. Pine stump 8 N 1 W 20 1/2  
 Y. Pine 14 S 65 E 47 1/2

Run South var 3 1/2 E

816 1/2 High bank of trout River runs SW 150 wide  
 1085 to high bank on S side of River

7787. fell 144 W of 1/4 P. found 8 BT. a stub 75 ft high  
 marks plain, set new Post and made new  
 bearing

Y. Pine 15 N 87 E 47  
 no other

Went to SW corner. found Post and BT ok WEST  
 B. down marsok. Run N var 4 1/2 E

4000 could not find 1/4 P.

4175 small creek runs west

5518 High bank of trout River

5720 over

7831 fell 4 1/2 links East of corner. field notes

call for 2 W. Pine 6 in. found oypine marked  
 for corner and must have stood SE of corner  
 as it is marked sec 20. Some one has set Post  
 and run Lines N & East from set new Post +  
 Went South + set 1/8 P at 5873 1/4 and 3 1/4 West  
 of Randam

cedar 7 N 42 E 8 1/2  
 " " 7 S 56 E 33

Went South + set 1/4 P at 3915 1/2 and 2 1/4 W  
 of Randam

Tam 10 N 86 W 28  
 " " 8 S 20 E 14

East from West 1/4 P var 40 E. NOV 16 - 1906

7863 fell 28 links South of 1/4 P found Post but no  
 bearings. this Post was set by whoever run  
 the line for Wright Lumber co 809 -  
 it made new bearing

W Pine stub org 18 N 88 E 52  
 no others

Went West & set center W Pine 12 N 47 1/2 E 76

" " stub 108 84 W 13 1/2

SEC 21-41-6 NOV 17 - 1906 continued

Distance to N 1/4 Post 3833

" " S " " 3954

" " W " " 3968

3895

1984 WEAT at center S-C 1/8 P W Pine 14 N 47 E 223

no others

1916 1/2 North of center S-C 1/8 P

East from North <sup>1/8 P</sup> on West line var 4 1/2 E

375 trout River

526 High bank over river

3959 fell 85 North of 1/8 P. corrected line West to  
 1/8 P and from center South 20,000 and  
 north to 1/8 P.

Set temporary 1/8 P in center of NW 1/4 and run  
 South var 4 1/2 E NOV 18, 1906 - 19 - 1906

1939 fell blink 8 of 1/8 P corrected line north  
 to 1/8 Post

finished Nov 17 at 11 AM

Sec. 29. 35-11 NOV 21-1906

As I could not find SW corner as it has been  
beaten out I went to 1/4 P betw 31+32. Set  
Post from W B.T. and run N var 20  
40.00 off set W 22 7/8 ch. to old line and run N var 3 1/2  
East which is true course of line from 1/4 P

copied on = Nov 22 = Page 357

7954 fall 7.20 W of corner found S E B.T. and stump  
of SW B.T. and Post marks are plain on S E Tree  
Set a cedar Post at stump of SW B.T. mark O.B.T  
found a shortage of 42 Links = NOV 23

Went south and set Temp. corner at 3986  
N of 1/4 P betw 31+32 and run W var 1/2° E

2874 fall 101 N of 1/4 P. in road, which I set in 1901.  
Went E & H to Temp. cor. and run E on true  
line from 1/4 P. W of Temp. cor. to Temp. cor.  
which is 237 East

4054 fall 7 1/2 N of 1/4 P. set new post from both Org. B.T.  
Went back to Temp. cor. and again made diligent  
search for org. cor. which I believe once  
stood near temp. cor., as the org. line N. from  
this point and East from this point come together  
here. no line can be found running South or West.  
As I cannot find any further evidence of org. cor. I  
proceed to set Cor. by Proportional measurement  
Dist. E + W betw 1/4 Posts. is 6928. So I Spring  
Temp. cor East 58 7/2 Leaving dist. to 1/4 P bet 30+31  
346 1/2 and to S 1/4 P. of Sec 29. 346 1/2

W Birch 10 N 83 E 51

" " 10 S 86 W 43 1/2

This cor. now stands at Proportional distance bet  
the 1/4 P. betw 31+32 and the cor. to 19.20. 29. + 30  
Also betw 1/4 P. bet 30+31 and 1/4 P. bet 29+32.

Corrected line North + set 1/8 P. Hem 10 S 76 1/2 W 20  
Maple 12 S 62 E 28

The W 1/8 P on S line I did not have daylight to set but  
it should stand at 1733 1/4 and 32 1/2 links S of Rand & Put a  
Stake as near right as possible by moonlight no bearings

W. Rice said he could not afford to have  
any more done at present record  
County NOV 24 1906

Section 22. 36-10-E NOV 29 1906 Thanksgiving

Went to SW corner found SW B.T. OK. No tree down and  
rotten, set new Post and made new bearing

Copied on Spruce 8 N 69 E about 65  
no other far get to measure

Run north var 3.30 East

4048 fall 118 West of 1/4 P. set Post from both org. B.T.

Doc 2.93 corrected var 7.50 E

Corrected line South and set 1/8 P at 2024 and 59  
East of Rand Cedar 10 S 83 E 25 1/2

" " 10 S 83 W 9 1/2

Went to SW corner again and run East var 40 E

200 Leave Swamp

2250 to E. Road to camp Page 315

2600 Enter Swamp

2600 fall 250 N of 1/4 P set new post from both org. B.T. Birch  
ok. fir is down. Dec. 6. 23. correct var 25 East  
Corrected line West and set 1/8 Post at 1997 + 125 South  
of Rand W. Pine stump 22 N 27 1/2 W 19

" Spruce 6 S 41 1/2 W 9 1/2

East from South 1/4 Post var 30° East

4145 fall 14 Links South of cor. I set this cor 6 years ago

From org. B.T. Went West + set 1/8 P. at 2072 1/2

and 7 Links N. of Rand Fir 10. N 39 E 30 1/2

Went West + set 1/8 P at 2072 1/2 " 12 N 89 E 21

North from S E corner var 7.15 East

300 Leave Swamp

950 creek 20 runs SW

County

3000 Enter Swamp. Wet. no frost. 1 foot or more snow

3 = December 1st 1906 =

4500 Leave Swamp NE cor of 22 NOV 26

7200 Enter Tam 12 S 4 1/2 E 13 1900

7596 fall 132 East of 1/4 P. set by Proportional measurement

in 1900. Went South and set 1/4 P at 3798 and 66 links

West of Rand Tam 10 N 39 E 1

Correct var 8.15 " 10 S 45 W 33

Went South + set 1/8 P. fir 15 N 35 W 28 1/2

Tam 15 S 57 E 16

Went to S 1/4 + Run N var 50° E. 150 + 810 = 1000 ÷ 2 = 500

400 Leave Swamp. Record

7500 Enter Swamp

Section 22-36-10-E. cont. DEC 2<sup>nd</sup> 1906

copied on Page 315

7710 fell 164 West of 1/4 Post. I set this Post in 1906 by proportional measurement E+W also NE cor I had to Spring NE cor<sup>u</sup> South 88 Links So Spring this Post South 44 Links and made new bearings with Pocket Compass as water is too deep to set transit at Post. No var. Tam 8 45 W 7 1/2  
Dec 213. correct var 3.45 W Pine 12 East 29

Went to West 1/4 Post and run East var 7.15 West  
400 Leave Swamp

6700 Enter "

7800 fall 18 1/2 South of 1/4 Post

Went West and set center Birch 8 N 31 E 14 1/2 9.6  
" 8 N 46 W 19 1/2 32.7

Distance to North 1/4 Post 3760

" " South " " 3950

" " East " " 3946

" " West " " 3844

1885 N of center set 1/8 Post Tam 8 N 6 1/2 W 24

Spruce 6 S 70 E 3 1/2

1975 S " " " " Tam 10 N 24 E 17 11.7

1922 " " " " " 10 S 9 W 12 7.9

1922 W " " " " Fir 8 N 45 E 10

Spruce 8 S 26 E 5

East from 1/8 Post South of center var 35 W

4053 fell 58 South of 1/8 Post. went West and set temp 1/16 and run South var 6 E 1936 fell 20 Links E of 1/8 Post

corrected Line North to Temp 1/16 Post

" " S from center + N. from center to 1/8 Posts

" " W " " To 1/8 P

Run Line with P.C. on N and W sides of S E N W

" " " " " N " E " " S W S W

finished Dec 4 1906

county record

Section 7-36-7 East December 5<sup>th</sup> 1906

Went to me on South Side of Lake on West Line found stumps of both org = BT, marks plain. Set Post and went to me on north shore of Lake. found both org = BT with marks. E one is low stump. W one is a stub 4 feet high. set Post and chained South on ice. var 4 E. 1670 to S me. US notes say the distance is 1634. an overplus of 36 Links. Proportioned the overplus and set 1/4 P. on ice 147 N of South me Run East var 3.30 E  
2685 over Lake on ice.

8000 could not find 1/4 P. set Line stake and went to SE corner. found East BT marks nearly gone. W BT gone set new Post 20 Links South and 6 Links W of new Post with painted top. Run north on old Random var 4.40 E. started 6 Links E of my Post

4000 could not find 1/4 P.

5000 old gouge Line is 43 Links West of Rand

6000 " " " " 47 " " " "

7010 fell 50 East of where org = Line intersects Lake and set witness corner

W Pine stump 108 77 W 81

Aspen 89 127 W 112

Went South and set 1/8 P. at 5856 N of SE corner and 42 3/4 Links W of Random Birch 18 N 26 E 14

Hem 18 S 55 1/2 W 37

Went South and set 1/4 at 3904 North of SE corner and 31 Links W of Random Birch 8 N 54 E 15 1/2

" 8 S 41 W 21

Picked up E+W Random Line and at

8020 fell 406 South of 1/4 Post

= DEC. 6<sup>th</sup> 1906 =

Dec for correction 506 correct var 3.30 E

Went to South 1/4 P. found org = BT. set new Post and made new bearing Aspen 7 N 15 W 17 1/2

W Pine 8 S 66 E 27

Run North var 4.30 E.

400 25 RR track Posted on Page 38

500 Enter marsh county Record



## Section 7-367-E cont. Dec 6 1906

1000 over marsh

2900 Enter "

3700 over "

7800 could not find  $\frac{1}{4}$ P set Line stake + went to NW corner found Post set from org. B.T. June 1906  
Run South East var =  $3\frac{1}{2}$ E. Want to miss Windfall  
= Dec 7" 1906 =

7250 intersect Lake

7984 fall 325 ch South of corner in Lake. which I set on ice by prolonging sec. Line between 748 N from W. e. 818 ch. Went West + set  $\frac{1}{4}$ P. Post at

3994. East of NW cor. and 3992 W of NE corner

Picked up my N+S Random  $\frac{1}{4}$  Line and at7674 fall 194 East of  $\frac{1}{4}$ P. fir 6 N 17 W 25

" 6 S 80 E 26

Went south and set Center B. Pine 8 N 28 E 47

Tann. 10 S 31 W 27

Distance to N  $\frac{1}{4}$  Post 3959

" " S " " 3715 ( 7674

" " E " " 3928

" " W " " 4092 ( 8020

Went south and set  $\frac{1}{8}$ P South of center at 1857  $\frac{1}{2}$  and

' Red oak 10 S 47 E 35

' W. Pine 10 S 43 W 67

6  $\frac{1}{8}$  Post East of center should be at 1964 and 3068 Nof Random. move valley 6000 ch East 56 Links and N 306  $\frac{1}{2}$ 

Did not have time to set this  $\frac{1}{8}$ P and get home today. Dec 8" 1906

copied on Page 38 county Record

## Section 36-37-10 continued from Page 93. Dec 12/06

Went to NW (Temp) Cor again and run East var 1 W

18.00 Enter SW Wind fall which extends South 600

40.00 needle Shows 2° W

6000 " " " 00 VAR copied on

7500 Wind fall extends South 2000

8285 fall = Dec 13 = 1906 =

3  $\frac{1}{2}$  Links N. of cor. found NE BT ok

but dead balance of B.T. down found them all

and org. Post lay under NW BT. Set new Post and

Went West and set Post cor. to sec. 25-26-35-36

found Page

W Pine 28 N 5 E 32  $\frac{1}{2}$ 

Do. 16 N 32 W 47. . .

My Line running East was 7 Link south

after I had sprung Temp. Cor. East 82 Links

The whole dist. of Temp. cor. East is 8285 to cor.

West 8112 =  $16397 \div 2 = 8198\frac{1}{2}$ , dist. given by U.S.

surveyor to East cor. 7974. to cor. West is 7964

I divided the actual dist. then gave East Line

10 Links more than West one

Distance NE cor. of 36-8203 335

" to NW " " 35 8193

" SW " " 36 8121

" NW " " 35 8121

as true cor. is 7 Links N of line going East and

8 fall 3  $\frac{1}{2}$  N of cor. I went East and set  $\frac{1}{4}$ Pat 4101  $\frac{1}{2}$  and 5  $\frac{1}{4}$  of Rand. 1 aspen 41 W about 40 Links

1 no others are on all down

I then set West  $\frac{1}{4}$ P. as my line going north fromSW cor. at 8121 is 153  $\frac{1}{2}$  W of Temp. cor. and as

I sprung Temp. cor. 82 Link my departure at this point

is 153  $\frac{1}{2}$  + 82 = 235  $\frac{1}{2}$ . So I set  $\frac{1}{4}$  Post at 4060  $\frac{1}{2}$  and117  $\frac{1}{4}$  East of Rand. 1 cedar 7 N 79 E 31  $\frac{1}{2}$ Tann. 15 S 73  $\frac{1}{2}$  W 35  $\frac{1}{2}$ East from West  $\frac{1}{4}$  Post var 30' W

400 Leave Swamp

750 Railroad grade County record

2200 Enter Swamp

3200 Leave " Dec 14 - 1906

7800 Enter Swamp

## Section 36.37.10-E Nov. 14 1906 continued

8219 fell 66 South of  $1/4$  Post. found both org BT down  
marks Plain sec Post and made new bearings  
Dec for correction 80 White Birch 16N 53W 26  
Change course 28' Hemlock 8N 51W 23

copied on Page 335

Went to  $3/4$  Post and run North var 130° E

1500 Railroad Grade  
7000 Enter Windfall and Swamp  
8081 fell 52 Links West of  $1/4$  Post

Dec for correction 64. Change course 20' corrected var. 10

Went South and set center of sec. Birch 8N 62 1/2 W 41  
Do. 12S 71 E 30

Distance to North  $1/4$  Post 4112 yds. Birch 8N 63 3/4 E 14 1/2  
" " South " " 4069 " " 12S 19 W 26  
" " East " " 4105 8219  
" " West " " 4114

2034 1/2 South of center sec  $1/8$  P. Birch 10N 62 1/2 W 41  
Do. 10S 71 E 30

2057 West of center sec  $1/8$  Post Hem 12N 2W 37 29 1/2  
Hem 14N 67 1/2 E 16 WP 20S 20 W 35  
W Pine 26S 60 1/2 E 29 1/2

West from  $1/8$  Post South of center var 15° W  
4069 fell 32 Links South of  $1/8$  Post which set at 2061 1/2  
and 17-6 58 3/8 East of Rand. Hem 12N 2W 37

WPine 26S 60 1/2 E 29 1/2

North from W  $1/8$  Post on South Line var 130° East

800 main Line of Johnson and Kellys Railroad  
2600 spur of " " " "

4069 fell 9 Links East of  $1/8$  Post. went South and set  
H.P.  $1/16$  Post to W 44 W Pine 14S 42 W 67 1/2  
Birch 18S 62 1/2 E 41

Corrected Lines from Center East to  $1/4$  Post and  
from Center South to  $1/8$  Post. and then West to  $1/16$  P.  
in center of SW  $1/4$  and from this  $1/16$  Post South to  
to  $1/8$  P on South Line at Sunday Dec. 16 1906

county = Dec. 17 1906 = record

Went to S.E. Cor. Run N. var 10° E. Tamarac 8N 67 W 17

3984 fell 35 1/2 E. of  $1/4$  P. went S. + set  $1/8$  P. Spruce 10N 72 E 24

Run West var 112° East 440 fell 34 S of  $1/8$  P. corrected E. to 14°  
fall of  $1/8$  P. corrected Line East to  $1/8$  P.

Finished Dec 18 1906

## Sec. 5. 36. 11. East. Dec. 19. 1906

copied on Page 359 county record  
Went to S  $1/4$  Post. found Post & set in 1904. from org BT  
Run East var 5° E  
4150 fell 230 S of  $1/4$  P. corrected W to  $1/4$  Post

## SEC. 8. 36. 11 January 3 - 1907

Went to N  $1/4$  Post found post & set in 1904. from  
org BT Run West var 40° E copied on Page 561  
4049 fell 42 1/2 ch South of cor. org BLS  
Went East and set  $1/8$  Post. Tam 10S 80 1/2 E 16 3/4  
county Hem 8S 59 W 13

Corrected Line to  $1/4$  Post

South from  $1/8$  West  $1/8$  Post on N Line var 6 1/2° W  
3504 fell 47 West of  $1/8$  Post. set Dec. 1904

Corrected Line North and at 1752 set Temp.  $1/16$  Post  
" " " " to  $1/8$  Post record

copied on Page 359

## SEC. 4-36-11-E January 4 - 1906

Went to SW cor. which set in Dec. 1904 by proportional  
measurement, run var 133° E. I did not have my old  
notes but remembered I had run on 5° from SE cor. of  
8. and missed cor. on town line over 800 ch and as I  
had to spring Temp. cor. on my rand. line over 200  
ch it figured 13 1/2°. but I found after crossing my old  
Rand. I had run it on 5° W. set at

4500 8055 set East 781 ch. and changed course to  
6832 fell 33 3/4, East of cor. found Post and 309 Post  
found a shortage 9.2 ch proportioned the shortage  
and set  $1/4$  Post at 3534 1/2

county

Set N  $1/8$  Post at 5283 5301

sugar 10 1/2 43 7/2 E 28  
" 12 5 9 4 W 25

Telegraph Pole 10S 77 1/2 W 34

W Pine 5N 18 E 30

" S  $1/8$  " " 17 67

" 11S 42 E 14

Post sets in alder Swamp

Sir 10S W W 67

Corrected Line N from  $1/4$  P. to  $1/8$  Post

" " " " SW cor. to  $1/8$  Post

record

SEC 4-36-11-E. Cont January 5" 1907

Went to SW COR again and east var 3.10' W  
1775 CENTER of C+N.W. R.R. Track

3750 LEAVE SWAMP *copy on page 359*

4150 found Someone's 1/4 P. 40 Links South of Line

4600 Enter SWAMP

5000 Leave "

8200 Enter "

8361 FELL 135 South of corner this is a post cor. I set a post here Dec 1904 found marks on <sup>SW</sup> BE. also stamp of the old B.T. today Jan 6 found post gone SET NEW one from B.T. I made in 1904. Went WEST and set 1/4 Post at 4180 1/2 and 67 1/2 North of Rand

Fir 14 N 21 1/2 W 11 1/2

Tamarac S 2 1/2 W 32 1/4

Corrected Line WEST to R.R. Track, correct var 2° W

= Jan 6" P.M. =

Went to W. 1/4 P. and run East var 30' E Made 45,000 ch

= Jan 7 - A.M. =

8264 SET Line Staks and went to SE. Cor. and run north var 6° E

200 LEAVE SWAMP *county*

1700 Enter "

2900 LEAVE "

3200 Enter "

3450 found a cedar marked 1/4 S, think it was marked by US surveyor, but as US notes call for two Tamarac, and as this tree stood so far from where it belongs I ignored it and kept on north

4015 crossed E+W Random could not find 1/4 P.

7567 FELL 502 WEST of corner, SET Post from NW B.T. others are gone. found a post 25 Links East of true corner

found a shortage of 133 proportioned short cage and

SET N 1/8 Post at 5884 and Spruce 8 N 33 1/2 E 17 1/2 6 1/2

390 1/4 East of Random Jan 14 S 35 1/2 W 11

Corrected Line South and set 1/4 Post at 3938 1/2 and

262 1/2 East of Random Birch 8 N 68 1/2 E 29

*cedar*

Corrected Line South + set S. 1/8 Post at 1568 and 131 East of Random

Corrected var 2 1/5' East

Cedar 8 N 58 1/2 W 27 1/4

H.M. 8 S 82 1/2 E 19

Fir 8 S 69 W 18

SEC 4 36-11-East continued January 8" 1906

*copy*

I found a 1/4 Post SET by someone about 6 Links of mine They are both about 500 ch north of cedar and 1500 ch East.

Went to south 1/4 Post and run north var 3.30 East

7270 FELL 2 1/2 Links of 1/4 Post SET Post from 2 BT made by <sup>SW</sup> <sub>SW</sub>

This line is ALL SWAMP E+W 600 ch on South End and 1500 ch on North end

Picked up my E+W Random where I had set line stake and at 8410 FELL 56 N. of 1/4 Post. corrected var 10' E

I then set center at intersection of corrected 1/4 Lines

on Page 359

Tamarac 14 N 33 1/2 E 14 1/2

DO 14 S 19 1/2 W 40 3/4

Distance to North 1/4 Post 3504

" South .. .. 3766

" East .. .. 4207

" West .. .. 4203

1883 South of center SEC 1/8 Post Birch 10 N 21 1/2 E 13 3/4

Cedar 6 N 87 W 2 1/4

1974 North .. .. Fir 10 N 62 1/2 E 16 3/4

2803 1/2 Sugar 8 S 54 W 12

2103 1/2 East .. .. Cedar 14 N 43 E 10 1/2

Spruce 6 S 50 W 6

East from 1/8 Post South of center var 1° W

4232 FELL 2 Links North of 1/8 Post corrected Line West

January 10

East from 1/8 Post north of center var 1.15 East

4226 FELL 22 1/2 South of 1/8 Post

West from 1/8 Post north of center var 1.45 East

4246 FELL 29 South of 1/8 Post

West from 1/8 Post South of center var 1° W

4226 FELL 7 Links North of 1/8 Post

Corrected all the Lines, thus. West sec Line from 1/4 Post

N + S to 1/8 Posts. South sec Line from 1/4 Post ~~Post~~ to SW Cor

North 7 from SE Cor. of sec to North 1/8 Post. from South 1/4

Post north to center of sec. Both E+W 1/8 Lines

from 1/8 Post to 1/8 Post through sec

finished January 12" 1906

*county road*



SEC 9. 42-5 January 17<sup>th</sup> 1906

Went to meander cor<sup>n</sup> on east side of Lake bet<sup>w</sup> 4 & 9 found stub of south BT marks plain N BT gone. drove a iron pipe 5 feet long + 1 inch in dia<sup>m</sup> 4 feet in ground and in edge of Lake for meander post. Run east var<sup>s</sup> 230 W to miss buildings. wood pile &c.

13.16 fell 137 1/2 South of cor<sup>n</sup> identified by south east BT. this is a W Pine 15 in dia<sup>m</sup> 5. 8° E 20 When I first saw this tree 6 years ago the about marks were plain upon it. It has been somewhat disaced since that by use of at and fire. I set a Post for this corner in DEC<sup>r</sup> 1905. Someone has removed Post and built a fence nearly where Post stood. I drove an iron pipe. 6 feet + 3/4 inch 5 feet in ground where Post set by U.S. Surveyor stood. corrected line west to meander Post

Run South from NE Cor<sup>n</sup> var 1° E

3750 intersect Lake

3974 fell 193 West of 1/4 P. in Lake I located this 1/4 P. in Dec<sup>r</sup> 1905 and made bearings for same. Located it today from same bearings. Dec<sup>r</sup> for correction 486. change course E. 245 corrected var 3.45 corrected north at 38° set an iron an iron pipe on line 5 feet + 3/4 inch 45 feet in ground corrected line north 974 ch when it was dark. gave for the figures for correcting bal<sup>ance</sup> of line. and census Home.

Course of line from NE cor. west to Lake is 3/2 E

" " " " " " South " " " 3.45 E

SEC 1. 36-10. E. February 20<sup>th</sup> 1906 1. P.M.

Went to N. 1/4 Post which I made new bearings to in Oct<sup>r</sup> 1906 when I cut up 36-37-10. Run South var 4° E 7136 set line stake. found two posts which had been set for 1/4 Post. They were about 400 west of road and about 400 apart one was at 6700 ch the other at 7136. found woodcock had run a line from SE cor<sup>n</sup> and tied onto the south one of the posts. I took his rand<sup>om</sup> and continued it west var 3° E

7270 fell 35 1/2 South of Dorrs corner, found stub of old Post and his SE BT. a Birch stub. set new Post. and made new bearings | Birch 15 S 23 1/2 W 54 1/2  
maple 10 S 52 1/2 E 42 1/2

Went east and set 1/4 Post at 3635 and 173/4 N of R.

Picked up N + S 1/4 line at 7174 fell 13 hinks | Birch 14 N 17 1/4 E 36 1/2  
W of 1/4 Post " " 14 S 59 1/2 E 20 3/4

Went North to Lally 8 (4000 ch) and corrected line to 1/4 P. Feb<sup>r</sup> 23.

Went to East 1/4 Post set by Dorrs took his bearings  
2.092 BT. set Post Oct. 1906 | Cannon 44 1/2 W 17 1/2  
| Birch 8 S 15 1/2 W 20 1/2

Run west var 5° E copied on Page 308

3400 LEAVE SWAMP

3930 CROSS N + S Ranges

4100 ENTER SWAMP

7300 LEAVE "

7751 fell 20 1/2 South of 1/4 P. which I set 10 years ago I set

Went east and set center | Cannon 10 N 48 W 17 1/2  
| Birch 8 S 15 1/2 W 20 1/2

Distance to N 1/4 Post 3302

" " S " " 3961 EQUITY RECORD

" " E " " 3924 OF FIELD NOTES

" " W " " 3827

Went North and set 1/8 Post N of center | Pine 8 N 45 E 23

East from 1/8 Post N of center var 2° E " 12 S 55 W 16

4012 fell 135 South of 1/8 Post I set last Oct

Went west to 2000 ch and corrected line west  
to 1/8 Post finished Sunday Feb 24<sup>th</sup> at 6 P.M.  
SEE Page 112

SEC. 10-38-9-E March 8<sup>th</sup> 1907

copied on Page 246

Went to North 1/4 Post. SET Post from both org Bt

and run South var 5.16 E County record

3740 FELL 88 WEST of center SET by Dorr

Went north and set 1/4 Post at 1870 and 400 East

of random Sugar 12 N 35 W 30

in road " 12 S 66 E 23 1/2

Went to where West 1/4 Post was. in road found Dorr's rail

going East fixed a point as near as possible to where 1/4 P

stood. measured north on road var about 5 1/2 E

3730 SEC. COR. went South and set temp. 1/8 P. no Bt

Went to 1/8 P. N. of center, run var 2 1/2 W

4070 FELL 539 North of temp 1/8 P. Went East to 2000

SET temp. 1/16 P. and corrected line East to

1/8 Post &amp; also set a stake in line on N + S 1/4

Line 10.00 ch South of N 1/4 Post

finished March 9. 1907 of field notes

SEC. 3.34.11.E. March 22<sup>nd</sup> 1907

AS the me. bet 2+3. on S. side of Post Lake is gone.

also the 1/4 P. and cor. to 2.3.10.11. and 1/4 P. bet 7

10 + 11 and me. on N. side of Post Lake bet 10 and 11

I went to me. on East side of Lake bet 11 + 14 found

the org Bt. now a stub 4 1/2 feet high. SET Post and

Placed flag at same. Went West and found me SET by

Dorr. HE had went to SW cor. 10 and run East to 1/4 P

corrected onto same. and prolonged line East to

Lake. and set me. I placed instrument in line

bet me corners found course of line 3 1/2 W.

found dist. bet meanders 14.04. good dist. is

7.55. an over run of 6.49 ch Proportioned the over-

run and set temp. cor. on ice 316. East of West

me. and 1088 West of East me.

Distance to from temp. To South me. is 1050 ch

and course is 5 1/2 W.

Ran North from temp cor. on ice var ee

683 Leave Lake where Dorr had set Temp me.

1000. SET Line stake with nail in Cop. also drove nail

in top of fence Post which is Dorr's me.

I did not have good dist. to me. bet 14 + 15

SEC. 7-38-8 April 11<sup>th</sup> 1907

copied

AS the corners on Range Line are said to

be all gone I went to me. bet 13 and on S

side of River found both Bt. ok. SET Post and

run N var 3 1/2 E on Page 161

206 over River found stumps of 2 org Bt. for N

me. + set Post and run N var 3 1/2 E

3144 SET temp cor. to 7-12-13-14 and began

Chaining from this Post

4000 SET temp. 1/4 Post

8000 " " corner to 1-6-7-12 began to chain

4092 FELL 85 East of 1/4 P. bet 1 + 6 and set Post

from stumps of both org Bt. remade them

and made new bearing VAR 30 5/8 E

W Pine Stump 20 S 30 1/4 W 12

found an over plus of 92 Links

Proportioned the over run and set corner to 7.12.13.14

at 3144 + 19 = 3163. and 16.86/100 W of random

W Pine Stump 16 N 24 W 10 1/2

" " " " 20 N 24 E 20 6

✓ SET 1/4 Post bet 7 + 12 at 3163 + 40 24 1/3 = 7167 1/3

and 40 1/2 S of Rand W Pine Stump 8 S 42 1/2 E 74

" " " " 8 N 42 1/2 W 41 1/2

SET cor. to 1-6-7-12 at 7167 1/3 + 40 24 1/3 = 11151 and

63 1/4 W. of Random W Pine Stump 18 N 62 E 34 1/2

" " " " 20 S 21 1/2 W 64 1/2

SET N 1/8 P. bet 7 + 12 W Pine Stump 7 N 12 1/2 W 20 1/2

" " " " 10 S 35 E 11

SET S " " " " W Pine Stump 8 S 11 1/2 E 35

" " " " 8 S 9 1/2 W 70

East from NW cor var 3° W

5181 to Wis. River no me. County

5649 " me on E side of river fell 251 North of Post

5649 WENT WEST and set 1/4 Post at proportional

MEASUREMENT B. Pine 8 N 27 1/2 E 8 1/2

W " " " 8 S 10 1/2 W 29 1/2

went west and set 1/8 Post in like manner

Record W Pine 8 S 5 1/2 W 42

W Pine 8 S 5 E W 11

COURSE. of this is 5.33 W Continued on next Page

Section 7. 38. 8. E April 15 1907

WENT SW corner which I set by proportional measurement  
 AS I only wanted the course of this of the course of this  
 this line I set flag to m.c. bet<sup>n</sup> 7+18 on E bank of WIS-  
 River as yr m.c. is gone. With instrument at cor.  
 found course of line is 12<sup>W</sup> 12<sup>W</sup> + 530 = 1730 ÷ 2  
 = 845 W. which is course of E+W 1/4 Line

Went to W 1/4 Post. and run East Var<sup>n</sup> YHSW  
 3820 to high bank 75 Links W of River and set m.c.

Y Pine 14 N 41 E 25 1/2

18 S 21 W 42

copied on  
 Page 161  
 County Record

this is all at present

copied on Page 240 County record

SECTION 4 38. 9. E. April 30. 1907

commenced at East 1/4 Post in cent of road  
 both BT. gone. but the post was set by Dorr  
 when the BTs were OK I found stump of west  
 one. Run north var 11 45 E

4724 fell 15 Links East of corner which I  
 set Oct 4 1906. corrected line South  
 to 1/4 Post corrected var 11.55 E. Dec 30 2  
 = MAY 15 1907 =

west from East 1/4 Post var 6 1/2 East  
 6660 stream 30. runs South

7531 Same stream but large 50 wide runs NW  
 as 1/4 Post is said to be east of this stream  
 I set line stake and searched for 1/4 P. but  
 did not find it. went South and looked  
 for S.W. corner

= MAY 2nd 1907 =

found SW cor<sup>n</sup> Post set by Dorr OK  
 The Tamarack is ok, Spruce is broken  
 down marks near gone made new  
 Bearing i Tamarack 8 S 65 W about 20  
 as Snyder did not want to go to the  
 expense of running this line. to get west  
 Post I quit

of field notes  
 SEE Page 120

□ □

SEC 3. 38. 9. E May 2 1907 1. P.M.

East from W 1/4 Post var 6 1/2 East  
 4264 fell 1 inch N of 1/4 Post which I set from  
 stump of SE BT. the SW one has been grubbed  
 out, this line is in and near road.

copied on Page 239 County record  
 Went to North 1/4 Post. found both 9 BT  
 run south var 10 E

4509 cross E + W 1/4 Line needle show 9 1/4  
 4577 fell 31 1/4 East of 1/4 Post 2 or 3 trees

Went North and set center in road

Sugar 16 N 73 1/2 E 11 1/2

no other

corrected line North from center to N 1/4 Post

Distance to E 1/4 Post 4372 = 8164 ch

" " W " " 3892

" " N " " 4509 = 4577

" " S " " 4068

Set 1/8 Post East of center at 2186 Sugar 9 S. 11 W. 41

of field notes

" " west of " " 1946 W Pine Stump 30 N 5 1/2 W 50 1/2

no other

finished May 3 1907 at 8.30 am.

L = 105-30

Lot 6. SEC 1-36-8-E

Damages assessed assessed by D.H. Vaughan  
 Carl Kreuger. and James Tubbs to be  
 paid to Union Electric Co. by Rhineclunch  
 Power Co. for overflow of said Lot 6.  
 is fixed at \$175.00

Established a B.M. at cut on top  
 of Boulder. 6 feet in diameter  
 near water line East of house, and  
 is 14/100 feet above flowage line

Posted on Page 114 County record



## Section 1.36.108. March 26" 1907

Begin at W 1/8 P. on N Line, which I set  
Nov 10" 1906 Run S. Var = 5° E  
35.05 fell 33 Links East of 1/8 P. which I set  
from tally stake on Random which I run  
Feb 23" 1907. Set 1/8 P. at 190 1/2 W. of center.  
and 15 1/4 N of Rand. cedar 10 N 40 1/2 E 8 1/4  
Copied on Page 308 <sup>town</sup> 14 S 10 1/2 W 2 1/2  
went north and set temp 1/16 P. at 175 1/2  
corrected line N to 1/8 P. <sup>county record</sup>  
WILL have to do some work in this  
SEC. When snow is gone.  $\Delta$   $\Delta$

## SECTION 21.40.8 MAY 14. 1907

Went to East 1/4 Post found the Birch, with marks  
enough left to thoroughly identify it found  
stump of Aspen marks gone. Set new post  
and made new bearing a large W Pine stub  
originally 30 inches. S 6 1/2 W 15 3/4. made it  
near roots also about 6 feet high and run  
north Var 3.45 E

1200 needle shows T. 30 + 345 = 515

39.09 fell 112 West of corner which I set from  
stumps of org. BT has no marks but the  
lines made by Deputy U.S. Surveyor cross  
where corner is set and these two stumps  
hook up for course and distance. ~~then~~  
corrected line south and set 1/8 Post at  
19.54 1/2 and 56 West of Random

Birch 16 N 72 1/4 E. 28

No other

Made new bearings for N.E. Corner

Birch 12 N 13 1/2 W 51 1/2

Sugar 12 S 35 E 62

Run West from NE corner on old line run  
by Deputy U.S. Surveyor. Var 2° E  
23.31 set line stakes and went to N 1/8 P on E  
line and run West Var 2° E  
26.72 intersect St Germain Lake no trees  
for meander corner set Post  
SEE next Page B

## SEC-13.40-6. E March 28" 1907 113

this is a survey of island in NW NW 1/4  
could not find N me bet 11+12 but found west  
one bet 11+14. there is only the stump of N  
BT left and that is broken off marks ok. found  
course of line West bet 11+14 is 00 set transic  
at me and line bet 11+14. Placed flag on island  
at SW Point flag bears 71° E. Chained across lake  
to island on ice. Distance 2778 to flag.  
Set a Linn post in place of flag and begin  
meander of island and run Var

Then N 17 W 300 Low wet ground thick undergrowth

" N 33 E 400

" S 62 E 250 <sup>dist to N shore of Lake 700' off water</sup>

" S 6 1/2 W 750

" N 58 1/4 W 275

to me. ~~xxx~~ W.P. 22 N 23 E 53 1/2

town 8 S 83 1/2 E 50

Distance from South Point of Island to S Shore of  
Lake is 5.50 water 10 feet deep  
improvements on island <sup>Rough beam</sup> House 12x16  
value \$50.00 built by me farland

22

## B. SEC. 21.40-8 continued May 16" 1907

Could not finish the Nor line of 21 until  
this date picked up same end and prolonged  
it West ~~at~~ and at  
31.13 intersect St Germain Lake & set Post  
Went East and set 1/8 Post at 19.46 West  
of corner. Run W Pine stump 18 N 45 E 47 3/4  
no others

Run South 4° E

39.75 fell 8 Links W of where 1/16 Post should be  
but it now stands 100 to far West ~~xxx~~  
Some random is only 8 Links to far W  
Run a temporary line around Lot 1 in 16

xxx an error in setting 1/16 Post of 100  
corrected same

SEC: 15. 40-8 May 18<sup>th</sup> 1907

Went to NE corner found Stumps of original  
B. Trees. Set new Post and run south var 3 1/2 E  
4000 could not find 1/4 Post  
5650 open marsh  
6000 over

= May 18. =

78.77 fell 92 West of corner & identified by  
Stub of NW Birch and Stump NE Birch  
both are nearly gone made rebearing  
White Pine Stump 24 S 66 W 120

Placed a stone 12 x 4 x 8 with pointed  
top. corrected Line North and set 1/4 Post  
at 3938 1/2 and 46 E. of Random Sugar 14 N 61 W 62 1/4  
W. Pine Stump 30 N 33 1/2 E 67 1/4

This is all in 15 at Present = Set Page ~~114~~ H6

LEVELS taken of found Lake creek  
Lake May 18. 1907

LEVEL		decline
4164	6445	2301
5330	6864	1534
7332	9475	2143
5544	7026	1482
8466	9100	634

8.094 To the last high banks,  
which are 9 1/2 feet  
above water level

A piece of Land Surveyed for O. W. Sawyer  
in Lot Sec: 29. 41-8. May 19<sup>th</sup> 1907

commencing at m.c. on <sup>East</sup> South side of  
Plum Lake. thence East on sec: Line between  
29 & 32 450 feet. Thence north at right  
angles to sec: Line 29-7 feet. Thence north  
West (# instrument adjusted on  
a var of 4° E.) 3.32 feet to shore of Plum  
Lake. Thence Southwesterly along shore of  
Lake 239 feet to place of beginning

SEC: 14-40-8. May 21 1907

Went to NW corner which I set from  
ORA - B.T. a few days ago. Run E. var 4° E  
2900 center of <sup>found</sup> creek  
2954 fell 3 Links South of 1/4 P. SE BT OK  
also m.c. just East of E 1/4 Post  
Went West and set 1/8 P. at 1977

WR 10 N 68 1/4 W 31

DS 43 1/2 E 21 1/4

I then run South var 4 1/2 E which is the  
course of West sec: Line which I run last  
week. the distance to N. 1/4 Post on Line  
between 14 & 15 is 1969 1/4 ch so at  
1969 1/4 I set 1/16 Post Birch 14 N 31 1/4 W 37  
W. Pine 10 S 85 1/4 E 38 1/4

I then run East on course of North Line  
which is 4° E. at  
250 ch I intersect Lake & set Post N. B. T.  
The courses above given we obtained  
by angle taken with Vernier to limb  
as I wanted to cut out 2 acres on S.  
side of Lot 2, I took angle of shore of Lake  
where the South Line of Lot intersects the  
Lake. angle taken from South line of Lot  
and is N 40° East. I then measured north  
from 1/16 Post on West Line 500 ch then  
run East parallel with South Line of Lot  
to Lake 575 ch to Lake and set m.c. No B T

Description of 2 acres is as follows  
A piece or parcel of Land in Lot 2 in  
Sec: 14, Township 40 N. R. 4. E and more  
particular described as follows: commencing  
at a point where South  
line of said Lot intersects found Lake,  
thence West on South 250 ch to 1/16 Post or SW  
corn of Lot. Thence North on West line of  
said Lot 500 ch Thence East parallel with  
South line of said Lot 575 ch to Lake,  
thence Southwesterly along shore of Lake  
to place of beginning

SEC 2<sup>2</sup> 3<sup>4</sup> 11 May 27, 1907 cont<sup>d</sup> from Page 108

As the whole line bet<sup>n</sup> 2 + 3 was all gone also SW cor of 2 I believe at me. bet<sup>n</sup> 10 + 11 which was set by Dorr and run north var 2.50<sup>0</sup> E 1/4 W

3358 fell 14 links East of 1/4 SEC by Bishop from org BT. The Hemlock is down and rotten marks gone Birch is all gone, but a Mr WENZEL and Tom Irvin both swear the marks were plain on the Hem when Bishop set Post (a stone) 10 years ago so I used it found an overrun of 408 between me + 1/4 P. Proportioned same and set 1/8 P

2227 South of 1/4 P. and 1081 N. of me  
no bearings

North from 1/4 P. bet<sup>n</sup> 30 + 11 var 4° E on road 4000 SEC line stakes. found line bet<sup>n</sup> 2 + 11 and followed it East to Post Lake, found stump of org<sup>n</sup> BT the pine, as the Lake is high Post came in Lake remarked old stump and run West 4° E

Before starting from shore of Lake I looked East through telescope and could see stump of me. The me on W side was nearly in line with one on E side.

2200 SEC stake for temp cor this is the distance given in good notes from me to SEC. cor as no corner could be found, I continued line west on same course old line is 126 ch South.

4000 could not find 1/4 P.

8000 could " SEC corner set temp post and continued line west on same course

14708 4508 fell 180 South of 1/4 Post, set cedar Post from Hemlock BT. Birch is down and rotten no marks on it Hem ok made new bearing; cedar 85 24 W 9 1/4

At me on South 1/8 line in SEC 2 | no bearings  
bis to Lake is 1025

SEC 2" 34.11.E. continued May 29 1907

Whole dist<sup>n</sup> from me 14708  
U.S. Surveyors returned dist<sup>n</sup> 14210 making an overrun of 498 ch Proportioned this overrun and set temp corner at 2277 W of me. picked up line from 1/4 P. bet<sup>n</sup> 10 + 11 and prolonged it north on same course, and at 8639. fell 186 1/2 East of me which I set as follows: I found on high bank of Lake a W Pine tree lying down near stump which has the line run by dept<sup>y</sup> U.S. Surveyor plainly marked upon it. I cut into this tree and found the tree had grown for 36 years after being so marked, and tree has been dead and down for a number of years. So I feel confident that this is the point where the line run by U.S. dept<sup>y</sup> Surveyor came to Lake. I also found what I believe to be the SW org<sup>n</sup> BT. now a stump, showing quite plainly where the BT was placed, found an overrun of 327 ch. Proportioned same and set temp cor at 4157 1/2 Sprung this temp corner West 77 links at right angles with random, Sprung temp<sup>2</sup> corner on E + W random South to the true line and to the temp<sup>2</sup> cor of N + S line and set Post for corner to 2-3-10-11

W Pine 55 1/2 W 25  
Aspen 7 N 51 E 52 1/4

Run north var 2.45 E  
1000 found needle shows a var of 4 1/4 E and held this course to end of line  
4488 fell 129 1/2 W of me. DEC 290  
Corrected line South and set stake for 1/4 P at 2105 1/2 for 1/4 P no trees near  
Corrected line South and set 1/4 P. at 2052 3/4 and 59 1/2 E of Rand<sup>n</sup> 14 N 39 1/4 E 49 1/4

Run East to Lake from this 1/4 P parallel with South line of SEC and set me on shore of Post Lake, see Page 116



SEC 33. 37. 9 E. May 31 1907

began at SW corner which is OK but B. trees are gone. It is large Post and I know it is correct

Run EAST var 3 1/2° E NEW bearing Spruce St. 12 N 39 W 41  
4054 fell 35 1/2 Links N of 1/4 P. OK

Went WEST and SET 1/8 P. W. Pine Stump 30 S 43 W 5 1/2

copied on Page 233 county record

Run north from W 1/8 P. on South Line var 4 1/2 W

3623 fell 98 Links W of 1/8 P. which I set in 1901

corrected Line south to 1/8 Post DEC 275

north from south 1/4 Post var 14 1/2 W

33.69 fell 24 Links East of center which I

set in 1901. Went south and set 1/8 P.

at 168 4/2 W. Pine Stump 14 N 33 3/4 E 62

16 S 49 1/2 W 47

of field note

East from S 1/8 P. on West Line var 1° W. Post set in 1903

3980 fell 68 South of 1/8 Post. Went WEST and

SET 1/6 Post W. Pine Stump 36 N 108 67 1/2

corrected Line W to 1/8 P. no others

finished June 1. SE 1907.

SEC 28. 38-8. E June 5 1905

East from 1/8 P. N of center on line cut out for road var 4 1/2 S

1800 needles Shows 6 1/2 E posted on Page 169

2150 Strain 20 turns SE. county record

4129 fell 138 N of 1/8 Post corrected line west

and SET Temp 1/6 P. W. Pine Stump 16 S 18 W 37 1/2

no other

Run N var 4° E

2010 to SEC Line 35 links E of MC.

corrected Line from 1/16 P. W to 1/8 P

SEE Page 55 for work done in May 1906

21-38-8 June 4 1907

Went N 1/4 R. found Post. also South BT (Stump)

Run south var 4° E copied on

3882 fell 68 1/2 East of center set by Dorr

found 1 org. BT. W. Pine Stump 16 N 33 3/4 E 14

Made NEW bearing " " " " 12 S 47 E 31 3/4

Went North + SET 1/8 Post W. Pine Stump #12 N 71 1/2 W 5 1/2

WEST from 1/8 P. North of center var 2° E

3996 fell 54 N of 1/8 Post set by Monseal

corrected Line East and SET Temp 1/16 Post

Birch 10 N 5 W 38 1/2

Hem 15 S 58 1/2 W 37

Went to N 1/8 Post on East Line which I set in 1903

~~K~~ bearing is W. Pine Stump 16 N 16 1/2 W 23

Run WEST in road var 4° E

4021 fell 68 South of 1/8 Post went East and SET

Temp 1/16 Post 1/16 Post W. Pine Stump 22 S 9 E 45

Page 163

No others

Went to NW corner on shore of Black's Lake. found

Post set by Monseal. The bearing trees called

for in field notes are gone. but there is a Pine

10 South West about 25 Links that was marked by

U.S. Surveyor and a Birch standing S.E. also

marked by him but neither are called for in his

notes. I believe the Post is right and used it

and run East var 3 1/2 E

1925 Wet marsh county record

2008 a Post set by someone is 12 1/2 South of Line

2400 Lake marsh

4015 fell 24 1/2 N of 1/4 Post called 1/8 Pin marsh

OK. and run East from N 1/4 P. var 3.15 E

3750. Wet marsh

4009 fell 37 South of org. corner on N. Shore

of Lake. corrected Line WEST and SET 1/8 P

at 2004 1/2 W. Pine 14 S 31 W 73

No others near.

Corrected Line W to 1/4 P.

North from 1/16 P. in center of NW 1/4 var var 3 1/2 E

1965 fell 1/2 East of 1/8 P. corrected Line South to 1/16 P

North from 1/16 P. in center of NE 1/4 var E

1920 fell 4 Links W of 1/8 P. corrected Line SE to 1/8 P

SEC- 4.38-9 E June 18<sup>th</sup> 1907

Went to where ~~9<sup>th</sup> 1/4~~ on E + W 1/4 ~~Line~~ <sup>may 2nd</sup> ~~2nd~~  
and began at 7531 and run West Var 6 1/2 E  
7402 set line stakes and searched 3 hours for  
1/4 Post without success.

= June 18- 1907 =

Went to SW corner (OK) and run north var 10 E  
500 Leave Swamp

1800 Enter .. copied on Page 240

2500 STRAIN 10 runs NE

3000 Leave Swamp

3850 Enter ..

4000 Searched 3 hours for 1/4 P could not find it

5500 Enter Swamp

7450 Leave .. COUNTY RECORD

8673 fell 226 W of corner OK

found an overrun of 1763. Proportioned  
same + set 1/4 Post at 5020 1/2 ch N of cor

! W Pine Stump 48.574 E 60 1/2

! No others near.

Picked up E + W Rand and at

8476 1/2 intersected corrected sec Line 1217 1/2 S  
of 1/4 P. corrected var of W sec Line is 8.30 E  
course of E + W rand is 6 1/2 E difference  
in angle 2°. 2° in going 1217 1/2 ch is  
43 1/2 Links which must be added to 8433

Hence at of field notes

8476 1/2 fell 1217 1/2 S. of 1/4 Post

I also searched for 1/4 P. at 2910 South  
of N.W. corner, but did not find it  
corrected var of E + W 1/4 line is 1.45 W  
SEC for correction 14.36. change course 8 1/2

= June 19- 1907 =

Went to S. 1/4 P. found Post and SW. B.T. OK

the Hem. is gone. run N. var 9 0 E

8554 fell 32 W of 1/4 P. which I set last Oct

from both org B.T. see Page 86

corrected Line South and set center of sec

SEC for correction 373

Change course 15'

SEC 4.38-9 E cont. June 20. 1907

! Cedar Stump 15 N 47 W 16 1/2

! " " " 12 S 27 1/2 E 29 1/2

copied on Page 240

Distance to E. 1/4 P. 4294 = 8476

" " W 4182

" " N " 4094 = 8554

" " S " 4460

corrected Line South and set 1/8 Post

! W Pine Stump 24 S 59 W 24 1/4

! " " " 30 S 76 1/2 E 51

corrected Line East from center and set 1/4 P

! Birch 18 N 44 E 15

! Sugar 15 S 23 W 53

corrected Line East to 1/4 Post and set Post  
1000 ch W of 1/4 Post! Hem. Stump 16 N 31 W 10 1/4

county record

Made new bearing for 1/4 P. W Pine Stump 28 N 46 E 64

North from S.E. cor var 5.10 E SW rec ok

3992 fell 132 E of 1/4 P. corrected Line South and

set 1/8 Post! Hem 24 S 27 W 20 1/2

! No other

Finished June 20, 1907 of field notes

SEC 1-36 10. E JULY 6<sup>th</sup> 1907

Went to N. 1/8 P. on W. Line and run E var 4° E

700 Enter Swamp copied on Page 308

1100 Leave ..

3925 fell 179 N of 1/8 Post 9 set last winter

corrected Line W. and set 1/16 Post

! Y Pine 10 N 28 1/2 W 35

! Tam 10 S 41 1/2 E 9 1/2

for other work done in this sec. see pages

89. 107. 112. 121 This book

County record

Copied on Page 142  
Road Town of NEWBOLD June 1 1907

Beginning at  $\frac{1}{4}$  Post bet<sup>n</sup> 15+16 37-8  
Thence N var<sup>n</sup> 40° 300 feet  
" W " " 300 "  
" N 63° W " 436 "

to road at ~~top~~ top of hill N of CREE in  
sec<sup>n</sup> 16. course and distance above given  
are center and line of road  
county record

SEC<sup>n</sup> 15-37-8-E June 12<sup>n</sup> 1907

I have run the South Line 6 years  
ago. set  $\frac{1}{4}$  P. East  $\frac{1}{8}$  P. and me on  
West Side of Lak Town<sup>n</sup>!!  
copied on page 140

MC.

$\frac{1}{8}$  P Spruce 6 S 78° W 41/2  
" " 7 N 6 E 16  
 $\frac{1}{4}$  P. W Pine 8 to S 28 1/2 W 16  
Spruce 7 N 45 W 30

Course of line as taken at MC is 3° E

So I begin at  $\frac{1}{4}$  P. run W var<sup>n</sup> 30°

I found the magnetic course was changing  
as I run WEST county Record

4100 fELL 583 ch N of Cor<sup>n</sup> mag<sup>n</sup> course 3° W  
Set new post. found stub of one I set 6  
years ago. also stump of NW B 7. and  
made new bearing. W Pine stump 14 N 70 1/2 E 13 1/2.  
remarked on bearing No other

Went East and set  $\frac{1}{8}$  P W Pine stump 12 S 73 E 20  
change course 8.15 " " 10 S 9 W 29 1/2

Corrected line East to  $\frac{1}{4}$  P

Went to W  $\frac{1}{8}$  P on S line and run N at right angles  
with South line. I done this because the flowage  
is so I cannot run W line and there is no corners  
of  $\frac{1}{4}$  P. Left on East line. also mag<sup>n</sup> courses are  
cannot be depended on, as they change 10° in  
that many chains. Run North 20.00 ch and  
was in flowage. set temp  $\frac{1}{16}$  Post and  
turned a right angle East and run 4100 ch

SEC<sup>n</sup> 15-37-8-E. cont<sup>n</sup> June 13<sup>n</sup> 1907

The NEEDLE is shifting, drawing WEST  
4100 SET TEMP<sup>n</sup>  $\frac{1}{16}$  P in SE  $\frac{1}{4}$  and run  
South at right angles. Copied on Page 140  
1973 1/2 fELL 31 W of  $\frac{1}{8}$  Post which set 6 years ago  
Corrected line N. and moved Temp  $\frac{1}{16}$  P  
north 26 1/2 links. Corrected WEST to Temp  
 $\frac{1}{16}$  Post County Record

SEC 14 37-8 June 13 1907

Survey of a piece of Land in Lot 7  
commencing at a stake which stands on

shore of Wis. River; W Pine stump 18 S 77 W 49 1/2

Thence South 55 E 269 ch 177.5'

" " 43 W 185 " e 122.1 " 118.8

" North 71 W 180 " copied on Page 139

" " 50 W 118 " to shore of river + SET Post

" " 77.9' W Pine stump 18 S 31 E 32

County Record. no other

" " 48 E 229 along shore of RIVER to the  
Place of beginning containing 49/100 of an acre





SEC 33-41-7 June 27-1907

Went to N  $\frac{1}{4}$  Post W Pine OK Birch gone  
runs south var  $3\frac{1}{2}$  E.

904 WET marsh

1564 over "

4113 fell 42 W of center set by POWELL

I found he had run both  $\frac{1}{4}$  lines and as  
his work looked right I used it

" bearings are: Y Pine 10 N 33 E 01

" " 14 S  $4\frac{1}{2}$  W  $15\frac{1}{2}$

East from center var  $3^{\circ}$  E

614 to Lake

1927 over Lake

2366 arm of Lake

2666 over arm of Lake

4019 fell 32 South of  $\frac{1}{4}$  P OK  $\frac{1}{8}$  P

corrected line west + set temp  $\frac{1}{8}$  P.

on shore of Lake, the Lake extends N about  
2500 ft Y Pine 8 N 34 W 12

$\frac{1}{8}$  P. E of center 1 W " 8 S 62 W 22  $\frac{1}{2}$

South from this  $\frac{1}{8}$  P. var  $3\frac{1}{2}$  E

3320 to WET marsh of set East 374

3993 fell 371 East of  $\frac{1}{8}$  Post in Lake,

Went N + set temp  $\frac{1}{16}$  P. NO BE.

corrected line N to  $\frac{1}{8}$  P.

East from this  $\frac{1}{16}$  Post. var  $3\frac{1}{2}$  E

4070 fell 4 links N of  $\frac{1}{8}$  P. set by PORTER WRIGHT

West from center on old road S 35 of center var  $3\frac{1}{2}$  E

4602 to  $\frac{1}{4}$  P. came east and set  $\frac{1}{8}$  P

Sugar 10 N 38 W 27

Oak 14 S 8 W 18

Run North var 320 E

2747 shore of Lake

3856 over " to top of hill.

4043 fell 72 E of  $\frac{1}{8}$  Post which I set by

Proportional measurement between N

$\frac{1}{4}$  Post and M.C. An overrun of 24 links

$\frac{1}{8}$  Post is at 2020 W of  $\frac{1}{4}$  P.

SEC 33-41-7E cont JULY 2<sup>nd</sup> 1907<sup>125</sup>

Went south and set temp  $\frac{1}{16}$  Post on East  
Side of Lake cannot run the E+W  $\frac{1}{8}$   $\frac{1}{8}$  Line  
on account of overflow.

corrected line south to  $\frac{1}{8}$  Post

East from  $\frac{1}{16}$  Post in NW  $\frac{1}{4}$  var 2458

4038 fell 39 South of  $\frac{1}{8}$  Post which I

set just now W Pine 8 in for  $\frac{1}{8}$  Post

" " 9 S 80 W 14

corrected line West. to  $\frac{1}{16}$  Post. broke Lake

East from  $\frac{1}{8}$  P north of center var 2458

1420 intersect Lake. could see line across

Lake as NENE has been cut, found my

line is correct

finished July 2<sup>nd</sup> 1907

SEC-28-41-7 June 25. 1907

Went to where E. 1/4 P. should be, both BT  
gone. Went to me S of 1/4 P. found both BT  
run N to Lake. Proportioned dist. + SET 1/4 P

W. Pine 10 N 84 W 16 1/2  
10 S

W. Pine 16 N 23 1/2 W 35 1/2  
10 S 84 W 16 1/2

Run WEST Var 3 1/2 E

7964 FELL 8.39 N of 1/4 P W Pine ok. Y Pine a stub

South from W 1/4 P. Var 3 1/2 E

4000 No corner. Still S 3 1/2 E

5501 FELL 8 1/2 W of me. found an overrun of  
83 Links. proportioned same + SET Temp  
corner at 4062.

Went East to me. BT ok run W Var 3 1/2 E

562 SET Temp Cor. Spungy Temp Cor on  
N + S line WEST 30 Links to conform to the  
Govt notes + SET corner to 28.29. 32 + 33

W. Pine 14 N 48 E 19

14 N 33 W 78

Corrected Line N + SET 1/8 P at 20 31

W. Pine 18 S 24 E 57

10 S 84 W 16 1/2

Run East to Lake about 5 chains

= JUNE 26, 1907 =

Went to S.E. Cor. found stumps of both org BT  
Post sees in Swamp 2 FEET of WATER. Went to W side  
of Swamp. took distance to cor. with stadia wires

700 Leave Swamp Var 2 1/2 E

1124 top of hill East of wet hole

1646 " " " " " " stadia wires

1743

2207 over

4134 FELL 67 S. of 1/4. found W Pine ok Birch gone

WEST from S 1/4 P. Var 3 1/2 E

475 wet hole

820 top of hill WEST of hole

3004 FELL 19. N of M.C. both BT SET new Post

SEC-28 cont June 26 - 1907

found the distance from S 1/4 P to SE cor  
is 4134 and to SW cor 3971 difference 163  
corrected line from S 1/4 P. to SW cor

North from S 1/4 P. Var 3 1/2 E

3951 FELL 23 W of wher I set center.

W. Pine 10 N 41 W 22 1/4

9 S 71 E 30

Dist to E 1/4 P 4085

" " W " " 3879

" " S " " 3951

" " " " " "

N + S 1/4 Line is on an  
intermediate course  
in Lake! BEC = E + W SEC line

Went to me: S. of E 1/4 P. bear 27 Links N and  
run west at right angles with E. SEC line

868 run South parallel with " " "

2123 " East at right angles " " "

868 ~~from~~ Parallel to East " "

57 Links S of me ok. This makes the  
Lake 2039 gout 1965 overrun 74 Links

Proportioned overrun and SET Temp 1/8 P

on offset line 467 N of south me and 868  
WEST of E SEC line. and run WEST Var 2 1/2 E

4103 WEST 1/8 P. in Lake to N + S SEC line FELL

14 South of 1/8 P. corrected line S 20 51 1/2  
to top 116 P.

North from E 1/8 P. on South line Var 2 1/2 E

This 1/8 Post is in a wet Swamp 3 1/2 feet

of water. so I began at a point 2207 W

" SEC cor. run N at right angles to SEC

line. hence 140 to line hence north

1957 FELL 79 W of 1/16 P. correct Line S. to

WET hole. also corrected line from S 1/4 P

N to 1/8 P which I set at 1975 1/2 S. of center

W. Pine 18 N 61 1/2 W 30 1/2

9 S 18 W 16 1/2

corrected line from SW cor East to Lake

SEC. 2. 36-10-E JULY 6-1907

Went to E 1/4 P. which I SET in 1899 found both BY  
 copied on W Pine 18 N 49 E 22 1/4  
 P 46 308 fir 10 S 61 W 15

Run WEST Var 00

3824 FELL 2 Links N of 1/8 P. set in 1899 by myself  
 Run South Var 9° E

3938 FELL 14 Links East of 1/8 P. I SET in 1898

Went to # South 1/8 P on East Line, <sup>set by Dorr</sup> and run  
 WEST Var 00

3750 FELL 18 Links South of <sup>1/8</sup> corner set in 1899  
 Went East and SET 1/6 Post in center of SE 1/4  
 county Cedar N 86 1/2 W 10

read " " " S 17 E 14

Corrected Line East to 1/8 Post, and South to 1/8 P.

SEC. 14. 36.9. E JULY 8" 1907

Went m.c. on E side of LAKE BETWEEN 11 + 14  
 found The Birch ok, and Stump of Pine there  
 are no marks left on it, found course and  
 distance does agree with goul notes exactly  
 I think the dist. to birch is correct but course  
 is 10° off and distance to pine should 28  
 instead of 18. found where org. Post stood  
 Pine is S 29 E. 28. Birch. is N 16  
 Set Cedar Post and made new bearing  
 Copied on Page 198 W Pine 12 N 60 W 7

Run East Var 40° E county read

2370 FELL 90 Links South of SET ne Post and  
 made new bearings W Pine Stump 36 N 65 W 33  
 " " " 16 S 11 E 14

Corrected Line WEST to m.c.

measured East on corrected Line 150 feet  
 turned a right angle South Var 6.10° E  
 SET STAKES EVERY 60 FEET for 420 FEET. turned on  
 S 24° W and measured off 5 Lots 75 FEET each  
 came back and run Lines to Lake PARALLEL with  
 North See Line □ □ □

SEC 17. 38-10 JULY 11" 1907

Went to center set by Dorr Post + BT ok  
 Run South Var 40° E

3949 FELL 2.05 East of 1/4 P. South BT stub ok  
 Went N. and set 1/8 P. Birch 12 N 23 W 19  
 Copied on Page " " S 12 E 13 1/2

Went to SE corner found Stump of Birch ok  
 Ironwood gone I SET this cor. 6 years ago but  
 Post has been moved set 2 rods found hole  
 where it stood, set new Post and run N Var 3 1/2 E  
 4670 found Dorr's Post on line in open marsh  
 went South + set 1/8 Post at 23.35; Cedar 12 N 53 1/2 E 7 3/4  
 " " " " N 42 W 10 1/2

East from 1/8 P South of center Var 8 1/2 E  
 4222 FELL 171 N of 1/8 P. = fearing Dorr's 1/4 P had  
 been moved. I went to it again and  
 run on same course Var 3 1/2 E

3111 FELL 35 1/2 W of cor both org BT. ok  
 I had taken an offset of 2 Links to the West  
 so I FELL 37 1/2 West of corner.  
 Went South + set 1/4 P. at 3891 + 183/4 <sup>East</sup> of Rand  
 on offset line Hem 12 N 52 1/2 W 52  
 Birch 15 S 51 E 39  
 - 343

Went South and set 1/8 P at 1945 1/2 and 83/4 East  
 of Rand on true Rand Birch 8 S 87 W 43 1/2  
 " " " 10 S 67 1/2 E 12

picked up E + W Rand and at 4187 FELL 561  
 Not true 1/8 P. (obliterate the other one)  
 corrected 1/8 Line W to 1/8 P. set temp 1/6 Post  
 at 2097 1/2 and 280 1/2 South of Rand

DEC for correction 13.40 change course 74 1/2  
 surveyed school ground as per deed  
 commencing 250 ch. W of NE cor. of SWSE  
 thence S 7 3/4 W ch thence W 3/5 ch thence  
 3/5 ch thence East on line to place of beginning  
 finished July 13. 1907

this 1/8 Line passes through Porch to Scholl  
 house county read



SEC = 20-43.5. JULY 16<sup>th</sup> 1905

Went to SE Cor<sup>r</sup>: found both org<sup>s</sup> B.T. OK. The Course to SE tree is S 1/2 E and distance is 220

Run north Var<sup>s</sup> 3.45 E

1050 Leave Swamp

4048 FELL 73 1/2 W. of 1/4 Post. SEC Post from both org<sup>s</sup> = B.T.

The Hem is down. Birch is a stub 6 feet high.

60<sup>r</sup> Went South + SEC 1/8 P. at 2024 + 36 3/4 East of Road

Sugar 12 S 84 W 11 1/2

14 S 64 E 28

Corrected Line S. to Corner. Dec 180. Corrected course 235

Went to SE Corner again and run WEST Var 2 1/2 E

1300 Enter Swamp

2800 LEAVE "

3800 Enter "

4036 fell 34 N. of 1/4 Post SEC Post from S B.T. The

N one is down marks OK. Small windfall HERE

Corrected Line East and set 1/8 P. Cedar 9 N 22 E 26

W. Pine 24 S 72 E 13 1/2

North from S. 1/4 P. Var 3 1/2 E

3400 Leave Swamp

3475 Railroad

8113 fell 293 West 1/4 P. SEC Post from both org<sup>s</sup> B.T. The

Cam is OK Spruce is broken down marks nearly gone

Made new bearing Ash 8 N 17 E 26 1/4

WEST from N. 1/4 P. Var 3 1/2 E

800 LEAVE Swamp

3200 Enter "

3600 Leave "

4206 FELL 14 1/2 North of Cor<sup>r</sup>: SEC Post from both original B.T. corrected Line East and

SEC 1/8 P. at 2103 Linden 10 N 58 W 11 1/2

Fir 12 S 31 W 15 1/2

South from NW Cor<sup>r</sup>: Var 3 0 E

~~4300~~ Leave Swamp

~~4300~~ Railroad Enter Swamp

~~4400~~ Enter Swamp

42.68 FELL 21 W of 1/4 Post SEC Post from both org<sup>s</sup> B.T.

Went N and SEC 1/8 P. at 2134 and 10 1/2 E of Road

SEC 20-43.5. COND<sup>r</sup> JULY 18<sup>th</sup> 1907

N 1/8 P. on W Line Hem 8 N 76 W 23 1/2  
Cedar 10 S 43 E 21

South from W 1/4 P. Var 3 1/2 E

850 Leave Swamp

975 Railroad

1400 Enter Swamp

1500 LEAVE "

3682 FELL 30 East of Cor<sup>r</sup>: SEC Post from both org<sup>s</sup> = B.T.

the courses is ok dist. to SE tree 25. to west tree is 36

Went North + SEC 1/8 P. at 1841 + 15 W of Road

W. Pine 20 N 53 W 26

" " 16 S 67 E 12

East from SW Corner Var 3 0 E. this is the course of Line from SE corner to South 1/4 P.

2200 Enter Swamp

3300 LEAVE "

4092 FELL 2.68 N. of 1/4 P

Went to WEST 1/4 P. and turn East Var 2.15 E

8040 FELL 2.19 South of 1/4 Post made new bearing

Birch 18 S 55 E 15

Went WEST and SEC Center at intersection of corrected

1/4 Lines Pine 20 S 57 W 20 1/2

" " 18 S 45 E 22 1/2

DIST to North 1/4 Post 40.89

" " South " " 40.14 } 8103

" " East " " 39.02 } 8040

" " WEST " " 41.38 } 8040

Went WEST and SEC 1/8 Post Tam 14 N 9 W 20

" " 14 S 17 W 18

South from 1/8 Post W of center Var 3 0 E

540 to Railroad

1000 Enter Swamp

3849 FELL .66 East of 1/8 Post

East from South 1/8 P. on West SEC Line Var 2.10 E

250 Enter Swamp

1200 LEAVE "

4110 FELL 22 N of 1/8 P. for this 1/8 P. see next page



## SEC 29. 43-5.E. Cont. October

West from East  $\frac{1}{4}$  Post Var.  $3\frac{1}{2}$  East

500 LEAVE Swamp

1000 Enter "

1100 Cross Railroad

1500 LEAVE Swamp

2000 Enter "

8186 FELL 31 north of  $\frac{1}{4}$  Post see Page 148"South from N  $\frac{1}{4}$  Post Var 220 E. See Page 130

700 LEAVE Swamp

2000 Enter "

3790 intersect E+W corrected  $\frac{1}{4}$  Line

5700 LEAVE Swamp

6500 Enter "

7500 LEAVE "

7849 FELL  $6\frac{1}{2}$  East of  $\frac{1}{4}$  Post

Corrected Line north + SEC Center of sec

Cedar 10 N 66 W 32  $\frac{1}{2}$ Do 12 N 75 E 25  $\frac{3}{4}$ Distance to N  $\frac{1}{4}$  Post is 3790

" " S " " " " 4059

" " E " " " " 4053

" " W " " " " 4133

1495 N of center set  $\frac{1}{8}$  Post Birch 9 S 40 E 9  $\frac{1}{2}$ 2029  $\frac{1}{2}$  S " " " " Cedar 6 North 2  $\frac{1}{2}$ 2026  $\frac{1}{2}$  E " " " " Cedar 10 S 75 W 152026  $\frac{1}{2}$  E " " " " Hemlock 14 N 10  $\frac{1}{2}$  W2066  $\frac{1}{2}$  W " " " " Spruce 15 S 12 W2066  $\frac{1}{2}$  W " " " " Cedar 8 N 54 W 18  $\frac{3}{4}$ 

Tam 12 S 21 E 25

South from  $\frac{1}{8}$  Post West of center Var. 247 East

1200 LEAVE Swamp

1700 Enter Swamp

1800 LEAVE "

3000 Enter "

4095 FELL 3 Links East of  $\frac{1}{8}$  PostCorrected Line north to  $\frac{1}{8}$  Post

## SEC 29. 43-5. E Cont. Oct 2" 1907

West from  $\frac{1}{8}$  Post South of center

300 Enter Swamp

1000 LEAVE "

2950 Enter "

4097 FELL 16 N of  $\frac{1}{8}$  P. corrected Line Eastand set  $\frac{1}{16}$  Post Birch 20 N 46 W 43" " " " 18 S 59 E 34  $\frac{1}{2}$ Corrected Line East to  $\frac{1}{8}$  Post SW  $\frac{1}{4}$  finished" E+W  $\frac{1}{4}$  Line from center West to  $\frac{1}{4}$  PostWest from  $\frac{1}{8}$  Post north of center Var 150 East

200 Enter Swamp

3400 LEAVE "

4122 FELL 13  $\frac{1}{2}$  South of  $\frac{1}{8}$  Post corrected Line East 2000 ftNorth from  $\frac{1}{8}$  Post W of center Var 210 East on Swamp3915 FELL 27 West of  $\frac{1}{8}$  Post corrected Line Southand set  $\frac{1}{16}$  Post Cedar 10 N 77 E 18

Birch 10 S 7 E 32

□ October 5" = 1907 □

East from  $\frac{1}{8}$  Post South of center Var 40 E

700 Enter Swamp

2100 LEAVE "

3000 Enter "

4054 FELL 9 Links South of  $\frac{1}{8}$  P. corrected Line W. to  $\frac{1}{8}$  P.North from  $\frac{1}{8}$  Post East of center Var 150 E

650 Enter Swamp

1300 LEAVE "

3804 FELL 24  $\frac{1}{2}$  East of  $\frac{1}{8}$  PostEast from  $\frac{1}{8}$  Post north of center Var 325 (335)4044 FELL 41  $\frac{1}{2}$  South of  $\frac{1}{8}$  P.Went West and set  $\frac{1}{16}$  Post in center ofN  $\frac{1}{4}$ Cedar 10 N 63 W 11  $\frac{1}{2}$ " " " " 12 S 29  $\frac{1}{2}$  E 30Corrected Lines West and South to  $\frac{1}{8}$  PostsThis finishes sec 29. and I am glad finished  
OCT 5. 1907 at 5 P.M.



SEC 28-43-5 OCT 6, 1907

Went to West  $\frac{1}{4}$  P. which I set July 24<sup>th</sup> 1907. and run  
East Var  $2\frac{1}{2}$  East. as it is only 3811 N to N.W. corner

700 LEAVE SWAMP

1825 intersect telephone line run SE

5500 "

Road to Turtle Lake + Manitowish

6000 NEEDL says 315 E

7775 FELL  $77\frac{3}{4}$  South of  $\frac{1}{4}$  Post which I set from both  
Org: BT. The Linden is nearly gone, but is ok  
for course and distance. found point of org: Post.  
the Birch is S 59 W 29 instead of S 56 W 28. set new  
Post and made new bearing Birch 10 N 75 E 45  $\frac{1}{2}$   
no other

corrected from tally 6000 E. WEST to  $\frac{1}{4}$  Post

= Oct 7 - 1907 =

South from North  $\frac{1}{4}$  Post Var = 300 E,

Set Post from Birch, H.E.M. down, courses are OK.

Dist: to Birch is 29. to H.E.M. 29  $\frac{3}{4}$ . found Point of org:Post, made new bearing Birch 20 S 68  $\frac{1}{2}$  W 19  $\frac{1}{2}$  ---

950 Manitowish Road

1950 Railroad grade

6000 Enter Swamp

6800 Telephone Line

7000 LEAVE SWAMP

8015 FELL 284 East of  $\frac{1}{4}$  P. found the Birch OKSpruce gone. Set new Post & made new  
bearing Birch 10 S 8 W 11.

Went north and set center H.E.M. 8 N 15 W 21

Birch 10 S 78 E 12  $\frac{1}{4}$ Distance to N  $\frac{1}{4}$  Post 3930

" " S " " 4085

" " E " " 3765

" " W " " 4010

1882  $\frac{1}{2}$  East of center set  $\frac{1}{8}$  Post Birch 8 S 68 W 17

DO 10 S 13 E 6

2005 West " " "  $\frac{1}{8}$  " H.E.M. 12 N 53 E 33

DO 14 S 87 W 30

2042  $\frac{1}{2}$  South " " "  $\frac{1}{8}$  " CEDAR 10 N 11  $\frac{1}{2}$  W 26  $\frac{1}{2}$ W. line 18 S 69 E 8  $\frac{3}{4}$ 

Did not set  $\frac{1}{8}$  P. N. of center It should be at 1965  
and 69  $\frac{3}{4}$  W. of road. SEE Page 139 =

SEC 20-43-5 July 27<sup>th</sup> 1907 cont<sup>d</sup> from page 132

East from  $\frac{1}{8}$  Post North of center Var 3.45 E,  
3863 FELL 22  $\frac{1}{2}$  North of  $\frac{1}{8}$  Post. corrected line  
West and set  $\frac{1}{16}$  Post at 1931  $\frac{1}{2}$ .

Aspen 8 N 77  $\frac{1}{2}$  E 01

Sugar 16 N 56 W 03

Corrected Line west to  $\frac{1}{8}$  Post and north from  
 $\frac{1}{8}$  Post to N  $\frac{1}{4}$  Post

I set this  $46\frac{1}{2}$   $\frac{1}{16}$  Post equidistant between  $\frac{1}{8}$   
Posts, as Turtle Lake is where East  $\frac{1}{8}$  Post on ~~west~~  
would come. I have yet to run the N+S  $\frac{1}{8}$  line  
in NE  $\frac{1}{4}$ . The Flambeau Lbr Co and Turtle Lake  
Lbr Co have agreed each to pay its proportional share  
of survey. So I have come into 20 again to cut out  
the T.L. Co. Land from others than f. Lbr Co.

The Pappoose Lbr Co + f. Lbr Co are about to trade  
lands, so as to bunch them & go home to day  
and wait until they have their arrangements  
completed. Sunday Sept 15 - 1907

N from  $\frac{1}{8}$  P. East of center Var 2  $\frac{1}{2}$ . 2088 FELL 17 E of  $\frac{1}{16}$  Post  
corrected on to  $\frac{1}{16}$  P and prolonged line North. See bottom of page

SEC b - 37-8 Aug 5<sup>th</sup> 1907

Went to NW corner found stump of NE BT.  
Others grubbed out set Post in center of road  
Went to N  $\frac{1}{4}$  P. found stumps of org BT.  
Mansell had set posts where the B.T. set new  
Post. placed instrument on top of depot and  
in line between  $\frac{1}{4}$  P. and corner. found  
distance to be 37.21 on overrun of 5 links  
Proportioned same & set  $\frac{1}{8}$  P. 2003 West of  
 $\frac{1}{4}$  Post Tam 5 S 87  $\frac{1}{2}$  W 72 copied on page  
! no other 135. count record

Surveyed a lot in NE NW as follows  
commencing at a point 710 ft West and 33 ft  
South of NE cor. - thence S 200 ft thence west  
100 ft thence N 200 feet thence E 100 feet to  
Place of beginning -

# 1325 intersect Turtle Lake and set meander Post  
corrected line South to CEDAR 10 N 44 W 14  
 $\frac{1}{16}$  Post and f  $\frac{1}{16}$  Post to " " " 8 N 64 E 15  $\frac{1}{2}$   
 $\frac{1}{8}$  P E. of center

SEC 35-36-9 E Aug 6 1907-SEE Page 25

Went to South  $\frac{1}{4}$  P which I set from  $\frac{1}{8}$  P. Nov. 1905  
and run West var 3:30 East  
4131 fell 78 South Post which I set from the 2  
East BT both stubs. Dec. 188 correct var 2:25  
Went & corrected East and set  $\frac{1}{8}$  Post at  
20 6  $\frac{1}{2}$  and 3.9. N of Rand Birch 12 N 6 E 15  
" " 8 S 45 W 8

Corrected East to  $\frac{1}{4}$  Post  
copied on Page 208

East from South  $\frac{1}{4}$  Post var 2  $\frac{1}{2}$  E  
4215 fell 51  $\frac{1}{2}$  South of cor. found <sup>Dorrs</sup> Post. and  
used 10 trees all the but fir, but they do  
not agree with field for course or distance  
corrected course  $\frac{5}{12}$  Dec 123  
corrected Line West and set  $\frac{1}{8}$  Post at 2107  $\frac{1}{2}$   
and 25  $\frac{3}{4}$  N. of Random Cedar 16 S 14 W 34  $\frac{1}{2}$   
No others

Went to NE cor. set by Dorrs Post has been  
moved N 8 feet to N side road set in instrument  
where Post originally stood and took Dorrs bearing  
tree Tam Swamp 7 S 39  $\frac{1}{2}$  E 27. Run South var 6  $\frac{1}{2}$  E  
Aug 8" 1907

450 Leave Swamp  
5200 Enter " county record

6030 Leave "

6800 Enter "

7350 Leave "

8773 fell 173  $\frac{1}{2}$  East of cor explained above  
Went North and set  $\frac{1}{8}$  P. at 2193  $\frac{1}{4}$  N. of SE  
cor. and 1.30 W. of Rand. fir 12 N 10  $\frac{1}{2}$  E 24  $\frac{3}{4}$   
Cedar 10 S 85  $\frac{1}{2}$  W 27  $\frac{3}{4}$

Corrected Line N. and set  $\frac{1}{4}$  P at 43 86  $\frac{1}{2}$   
and 86  $\frac{1}{2}$  W of Rand. Tam 10 S 65  $\frac{1}{2}$  W 23  
Hem 10 S 53 E 30

Went N + set  $\frac{1}{8}$  P. at 2193  $\frac{1}{4}$  S of NE cor.  
and 43  $\frac{1}{4}$  W. of Rand. Y Pine 16 N 45 W 11  $\frac{1}{2}$   
" " 16 S 65  $\frac{1}{2}$  E 12  $\frac{1}{4}$

Corrected Line N to corner  
corrected course 4.20. E Dec 198

SEC 36-36.9 E August 9. 1907

Went to N  $\frac{1}{4}$  P. which I set <sup>8</sup> Post on Page 209  
<sup>7</sup> years ago  
Run South var 3  $\frac{1}{2}$  E  
4550 fell 234 W of  $\frac{1}{4}$  P. which I set from ory  
BT. in June 1899 found Post and my BT ok  
Corrected Line north & set Temp Post  
marked 4275 with scribing iron set  
Line stakes South of Post on corrected Line  
This is all Hardell wants done except  
Correcting Line 2137  $\frac{1}{2}$  South from N  $\frac{1}{4}$  P  
which I did, finished Aug 9" 1907  
county record

SEC 28-43-5 Continued from page 136

= October 8" 1907 =

South from  $\frac{1}{8}$  Post East of center var 1  $\frac{1}{2}$  E  
450 manitowish Road  
4044 fell 44  $\frac{1}{2}$  West of  $\frac{1}{8}$  Post which I set 6 years ago  
corrected Line North to  $\frac{1}{8}$  Post

East from South  $\frac{1}{8}$  Post on West Line var 150' E  
500 Leave Swamp

1700 Enter "

3974 fell 4 Links South of  $\frac{1}{8}$  P. went West and set  
Temp  $\frac{1}{16}$  Post Cedar 8 N 55 W 24  
Do 7 S 50  $\frac{1}{2}$  E 12

Corrected Line West to  $\frac{1}{8}$  Post

South from  $\frac{1}{8}$  Post West of center var 2  $\frac{1}{4}$  E  
2047 fell 22 Links East of  $\frac{1}{16}$  Post  
Corrected Line north to  $\frac{1}{8}$  Post

= This finishes sec 28 =  
Oct. 8-1906

SEC. 5-43-5 - August 18 - SE Page 73

Went Center of sec which I set JULY 21<sup>st</sup> 1906  
and chained north on my random

2009 + SEC  $\frac{1}{8}$  P. 38 1/2 E. of R. Hem 14 N 42 E 31

Sugar 15 N 83 W 35 1/4

Went to N  $\frac{1}{4}$  P. set from org B.T. JULY 1906 and  
chained east on my random

1973 1/2 SEC  $\frac{1}{8}$  P. 16 S of Rand maple 16 N 54 E 11 1/2

" " 8 S 48 1/2 W 11 1/2

Began again at N  $\frac{1}{4}$  P. and chained WEST on  
on my old Random

1990 SEC  $\frac{1}{8}$  P. 31 1/2 S. of rand cedar 12 N 25 E 22 1/4

Birch 16 S 52 W 45

Went to center and chained west on my old Rand

1703 SEC  $\frac{1}{8}$  P. 5 1/2 N of rand cedar 12 N 70 E 24

" " 14 S 32 W 32 1/2

Went to W  $\frac{1}{4}$  P. and chained N on old Random

2018 SEC  $\frac{1}{8}$  P. 93 E of Rand Birch 10 N 74 W 18

Hem 10 S 72 E 18

East from N  $\frac{1}{8}$  P. on W. Line Var 3/2 E

985 intersect Lake

1671 over Lake

3630 FELL 3/8 S of  $\frac{1}{8}$  P. found I had made slip  
in adjusting Vernier of 5°

East from  $\frac{1}{8}$  P. N of center Var 3/2 E

1973 1/2 SEC Temp 1/16 P. and run N Var 2.40 W

1997 FELL 93 W of  $\frac{1}{8}$  P. Thinking something is wrong

I send chainmen and chain 64 W Line over  
again, found it only 1900 S of FELL only 19 1/2 W.

corrected line south and set 1/16 Post at 1973 1/2 E

of  $\frac{1}{8}$  P. and 2009 S of  $\frac{1}{8}$  P. and in center of N  $\frac{1}{4}$

Hem 12 N 27 1/2 E 29

corrected line W to  $\frac{1}{8}$  P. " " 14 S 63 E 19

North from  $\frac{1}{8}$  P. W of center Var 2 1/2 E

4010 FELL 142 1/2 W of  $\frac{1}{8}$  P. went S. and set  $\frac{1}{16}$  P.

This 1/16 P. is 75 links E of lake Tam 12 N 25 W 14 1/2

Lake at this point is 800 wide " " 10 S 9 1/2 W 18

corrected line W to  $\frac{1}{8}$  P. and south to  $\frac{1}{8}$  P.

this is all in SEC 5

SEC. 6-43-5 E. Aug 21<sup>st</sup> 1907

west from E  $\frac{1}{4}$  P. Var 3/2 E

76.14 FELL 28 1/2 South of  $\frac{1}{4}$  P. set Post from  
both org B.T. They are both down marks  
Plain. Mad new bearings

W Pine 18 N 20 3/4 E 52

Spruce 12 N 88 W 38

North from WEST  $\frac{1}{4}$  Post Var 3/2 E

4004 FELL 3 Links WEST of ~~the~~ corner found the  
org Post and 3 B.T. OK TH NW tree is down

Went South + set  $\frac{1}{8}$  Post Spruce 17 N 21 1/2 E 23

Birch 12 S 9 W 24 1/2

corrected line South to  $\frac{1}{4}$  Post and then east  
to center of SEC

Aug 22 1907

Went to N  $\frac{1}{4}$  P. from both BT south one is down  
set new Post and made new Bearing

cedar 7 S 10 W 22 1/2

Run south Var 4° E

8000 set line stakes. as I could not find

South  $\frac{1}{4}$  P. = Aug 23<sup>rd</sup> 1907 =

Went to witness cor for SE cor

and run west Var 3/2 E

1300 Enter Swamp

2500 Turke River 200 South runs from SE + then SW

3200 Leave Swamp

5450 Enter "

6450 Leave "

6900 Enter "

7824 FELL 209 1/2 South of cor set Post  
from 4 org B.T. the 2 N ones are down

Went East + set  $\frac{1}{8}$  P. by proportional  
measure ment at 6216 + 16 1/2 N of Rand

cedar 6 N 71 W 12 1/2

" " 12 S 86 E 13 1/2

corrected line E and set  $\frac{1}{4}$  P at 4141 and  
106 1/4 N of random Hem 14 N 23 1/2 W 19 1/4

" " 14 S 2 1/2 W 26 3/4

Went N + set center Cedar 7 N 19 1/2 W 10

Hem 12 S 5 W 18 1/2

over



SEC 6 43.5-E Cont Aug 24 1907

Dist<sup>n</sup> to N<sup>1</sup>/<sub>4</sub> Post 4009  
 " " S " " 4014  
 " " E " " 4050  
 " " W " " 3564

Went N + SET <sup>1</sup>/<sub>8</sub> Post Birch 14 N 11<sup>1</sup>/<sub>2</sub> W 46  
 " " " " " 16 S 23 E 30

Went WEST + SET <sup>1</sup>/<sub>8</sub> P. CEDAR 11 N 9<sup>3</sup>/<sub>4</sub> W 40  
 " " " " " 12 S 48 W 37<sup>1</sup>/<sub>2</sub>

WEST from <sup>1</sup>/<sub>8</sub> P N of Center Var 3<sup>15</sup>

1500 Enter Swamp

2450 LEAVE "

3514 FELL 19 S of <sup>1</sup>/<sub>8</sub> P. Corrected Line East  
 and SET Camp <sup>1</sup>/<sub>16</sub> P at 2005 W of E <sup>1</sup>/<sub>8</sub> P

Tam 12 N 77 E 22

W Pine 18 S 11 E 25<sup>1</sup>/<sub>2</sub>

South from Camp <sup>1</sup>/<sub>16</sub> P Var Var 402

2003 FELL 17 W of <sup>1</sup>/<sub>8</sub> Post Corrected Line N

South from <sup>1</sup>/<sub>8</sub> Post W of Center Var 3<sup>15</sup>

1996 FELL 35<sup>1</sup>/<sub>2</sub> W <sup>1</sup>/<sub>8</sub> P Corrected Line N

SEC 2-<sup>39-6</sup> 43-E August 30. 1907

Went to mc on west side of Lake 1<sup>1</sup>/<sub>2</sub> W of corner  
 and run west Var 3<sup>15</sup> E

3876 FELL ~~35~~ 84 N of <sup>1</sup>/<sub>4</sub> P. in which is in right of  
 way between side track and main line went east  
 and at 543-5 feet W of mc. set Hub also set  
 an iron pin 100 ft farther west and a Hub  
<sup>1</sup>/<sub>2</sub> way across Bk B

Posted on Page 60 Co. Record

SEC 19-43-5-E SEPT 5 1907

Went to N<sup>1</sup>/<sub>4</sub> P. found the Hemlock BT now a stub  
 marks plain. set Post and made new bearing  
 Post sets on east of Hem 16 N 40 W 11.  
 Railroad, 25 Links The other org<sup>n</sup> BT 189022

Run south var 3<sup>15</sup> E  
 6500 Enter Swamp

7971<sup>1</sup>/<sub>2</sub> FELL centered the south <sup>1</sup>/<sub>4</sub> P. which & SET from  
 both org<sup>n</sup> BT. which are OK. <sup>space</sup> Corrected Line  
 from N<sup>1</sup>/<sub>4</sub> P. South to Hoopch

SEPT 14, 1907 (Have been working in 22.43-5)

Went to SW COR which & SET last JULY run west var 3<sup>15</sup> E  
 3854 FELL 27 N of <sup>1</sup>/<sub>4</sub> Post which & set from org<sup>n</sup> BT. Sept 6 1907

Went E + set <sup>1</sup>/<sub>8</sub> Post Hem 17 N 33 W 13 Cedar 12 N 27 E 24  
 Birch 10 S 50<sup>1</sup>/<sub>2</sub> E 26 Hem 11 S 65 W 21

Went from south <sup>1</sup>/<sub>4</sub> Post Var 3<sup>15</sup> E

1600 offset South 3 Links

1998 " North 3 "

3976 FELL 6 Links South of corner, which & set from 3 org<sup>n</sup>  
 BT in Birch is gone. Cedars both dead. Tam OK  
 Corrected Line East + SET <sup>1</sup>/<sub>8</sub> Post, found an overrun  
 of 2 1/2 inch proportioned overrun + set <sup>1</sup>/<sub>8</sub> Post 2154  
 West of <sup>1</sup>/<sub>4</sub> Post and 1812 East of corner

Hem 12 N 33 W 13

Sugar 10 S 50<sup>1</sup>/<sub>2</sub> E 26

= September 16. 1907 =

Went from East <sup>1</sup>/<sub>4</sub> Post Var 1.30 E

1800 LEAVE Swamp "Very wet" hard rain last night  
 3250 Railroad

3934 N + S CORRECT <sup>1</sup>/<sub>4</sub> Line and enter Swamp

4300 LEAVE Swamp

7892 FELL 17<sup>1</sup>/<sub>2</sub> Links South of <sup>1</sup>/<sub>4</sub> Post. SET Post from  
 Sugar Pine gone, made new bearing

Hem 16 N 74 W 25

Went East and set Center W Pine 9 N 71 W 8<sup>1</sup>/<sub>2</sub>  
 Spruce 8 S 30 E 15

Distance to North <sup>1</sup>/<sub>4</sub> Post 4124

" " South " " 3848

" " East " " 3934

" " West " " 3958

OVER

SEC 19. 43. 5. E cont. SEPT. 16. 1907

Set  $\frac{1}{8}$  Post South of center at 1924. (and on Line)  
 corrected  $\frac{1}{8}$  Post Birch 28 N 70 E 13  $\frac{1}{4}$   
 Do. 15 N 49 W 19  
 Set  $\frac{1}{8}$  Post East of center at 1967 and  $\frac{4}{3}$  Links N. of rand.  
 Birch 9 N 12  $\frac{1}{2}$  W 15  
 Tam 7 S 11  $\frac{1}{2}$  W

I find an over-run between center + west  $\frac{1}{4}$  Post  
 of 294 ch proportioned same and set  $\frac{1}{8}$  Post at 2160  $\frac{1}{2}$   
 west of center. and 1797  $\frac{1}{2}$  East of West  $\frac{1}{4}$  Post

Sugar 8 N 39 E 10

7 S 12 E 29  $\frac{1}{2}$ 

Sept 17 1907

North from west  $\frac{1}{8}$  Post on South Line var 245 E  
 3823 fell 59 E of  $\frac{1}{8}$  Post

South from West  $\frac{1}{4}$  Post var 3  $\frac{1}{2}$  E  
 1250 Enter open swamp  
 2350 over  
 3300 Enter Tam

The South  
 Line of the  
 on North side of SE SW  
 is the correct one

3996 fell 54 East of SW. cor. went N. and set  $\frac{1}{8}$  P  
 in open swamp W. Pine 14 S 9  $\frac{1}{2}$  E 265

no others near

West from  $\frac{1}{8}$  Post South of center var 230 E  
 3960 fell 65 N of  $\frac{1}{8}$  Post. went E + set  $\frac{1}{16}$  Post  
 in center of SW  $\frac{1}{4}$ . W Pine 10 N 43 E 32  
 corrected  $\frac{1}{16}$  P. 15 S 25 W 31  $\frac{1}{2}$   
 corrected East and south to  $\frac{1}{8}$  Posts.

North from East Post on South Line var 2.15 E  
 3765 fell 27 W of  $\frac{1}{8}$  Post

East from  $\frac{1}{8}$  Post South of center var 230 E  
 3892 fell 14 N of  $\frac{1}{8}$  Post. went West and set  
 $\frac{1}{16}$  P. in center of SE  $\frac{1}{4}$ . Tam 10 N 40 W 23  
 Do. 10 S 67 E 6  $\frac{1}{2}$

Corrected Lines South + West to  $\frac{1}{8}$  Posts =  
 I made a mistake of 100 ch in setting  $\frac{1}{8}$  Post South of  
 center, corrected same. and re corrected line in SW  $\frac{1}{4}$   
 also  $\frac{1}{16}$  Post in SW  $\frac{1}{4}$ . I had a line both E + W from  
 this  $\frac{1}{8}$  P before correcting it. Run another Line East

SEC 22 43-5 E SEPT. 16 1907

Went to W  $\frac{1}{4}$  P. found both BTs. the Sugar is  
 ALL right for course and distance the Birch is  
 N 88  $\frac{1}{2}$  W 15. Gout notes say it is S 44 W 13

Run East var 3  $\frac{1}{2}$  E

58 offset N 2 Links to miss Y. Birch 30 in dia  
 7300 Pappoose Railroad

8000 set Line stakes. as  $\frac{1}{4}$  P. could not be found  
 it is in an old Wind fall and is all burned  
 OVER nothing left

Came back to SW  $\frac{1}{4}$  P. and run N var 3  $\frac{1}{2}$  E

= SEPT 1907 =

3937 fell. 10 Links West of cor. found the Birch OK.  
 Hem. is gone. made new bearing  
 Hem = 10 S 50 E 30

Went South + set  $\frac{1}{8}$  Post at 1968  $\frac{1}{2}$  + 5 E of Rand  
 see bottom of page 147 Hem 30 N 87 E 27 Hem 14 S 88 E 39  
 made + H 18 S 28 W 31 = 115 72 W 25

East from NW cor. var 3  $\frac{1}{2}$  East

4000 made diligent search but did not find  $\frac{1}{4}$  P.  
 7678 fell 68  $\frac{1}{2}$  N of cor. found NE BT OK but  
 dead west BT gone. made new bearings

Birch N  $\frac{1}{2}$  E 26

Hem N 54 W 35

Went West and set  $\frac{1}{8}$  P. at 5758 + 51  $\frac{1}{2}$  S of randBirch 8 N 47  $\frac{1}{2}$  E 33  $\frac{1}{2}$ " 20 22  $\frac{1}{2}$  W 35

Corrected Line West + set  $\frac{1}{4}$  P. at 3839 and 34  $\frac{1}{4}$   
 South of rand Birch 14 N cedar 8 N 55 W 16 7 7

Hem 22 E 8 N 42 E 7 see page

South from NE cor. var 40 E. 146. for West  $\frac{1}{8}$  Post  
 1948 intersect Pond 100 wide bears E + W  
 4000 no  $\frac{1}{4}$  P. limbs du down and burned up  
 5600 Enter Swamp

7000 LEAVE

8020 fell 160 ch East of cor. which I set from  
 the Hem. stump of the or. BT as shown  
 me Bussell's. walking Boss. Cedar has  
 been grubbed out Post sets in center of RR.  
 made new bearings Hem stump 20 N 10 W 47  $\frac{1}{2}$

(over)

Birch " 9 S 63 W 18

S&C 22-43-5-E SEPT  
ATTY 9" 1907 CONT"

Went north and set  $\frac{1}{4}$ P at 4010 +  $8\frac{1}{2}$ W of Rand,  
Sugar stub. 20 N10W  $47\frac{1}{2}$   
No other timber standing.

Went north and set  $\frac{1}{8}$  Post at 2005 and  $20\frac{3}{4}$ W of Rand  
Set N.E. as  $\frac{1}{8}$ P is in Pond Spruce 6 N  $37\frac{1}{2}$ E  $25\frac{1}{2}$   
SWest from S.E. Cor. " 6 N  $52\frac{1}{2}$ W  $27\frac{1}{2}$   
Var.  $3\frac{1}{2}$ E

1800 Leave Swamp found ~~w~~f was running on  $7\frac{1}{2}$ E  
caused by having started on R.R. track.

3950 crossed R.R. track runs W + S

4000 offset N 120 ch to old line changed course  
145 am now running on  $5\frac{1}{2}$ E which is the  
course of old line for 4000 ch NO  $\frac{1}{4}$ P.  
= SEPT 10" 1907 =

7629 fell 20  $\frac{1}{2}$  South of corner, found Birch ok  
Cedar is down, stump is under large Hem.  
Windfall made new bearing. Birch 16 S  $33\frac{1}{2}$ E 50

Looked 3 hours for this corner, there is no line to it  
except from the north. found a cor. made by us  
surveyor and obliterated, found their old camp and  
one of their old camp pails, found where their names  
were carved, and pictures carved. 45 years ago +  
Went East and set  $\frac{1}{8}$  Post at 572  $\frac{3}{4}$  and 150  $\frac{3}{4}$  North  
of Rand

Hem 16 N  $51\frac{3}{4}$ E 23

Birch 12 S  $64\frac{1}{2}$ W 7

Corrected line East and set  $\frac{1}{4}$  Post at 3814  $\frac{1}{2}$  and  
100  $\frac{3}{4}$  N of random. Birch 24 S  $88\frac{1}{2}$ W 8

Hem 18 N  $84\frac{1}{4}$ E  $8\frac{1}{2}$

Corrected line East and set  $\frac{1}{8}$  Post at 1907  $\frac{1}{2}$  and  
50  $\frac{1}{4}$  North of random. Hem 18 S  $29$ E  $18\frac{1}{2}$

No other timber standing

Went to Talley 1919 and East of NW Cor. and set  $\frac{1}{8}$  Post  
17  $\frac{1}{4}$  North of random. Birch 4 N  $4$ E  $40\frac{1}{2}$

Hem 5 S  $5$ W 41

Went to E  $\frac{1}{4}$  Post and picked up E + W  $\frac{1}{4}$  Line and  
at 7624 fell 145  $\frac{1}{2}$  North of  $\frac{1}{4}$  Post. DEC 1892

Change course 105  
forward

SEP 22 43-5E Continued SEPT 11" 1907

Went to N  $\frac{1}{4}$  Post and run south var  $3^{\circ}$ E

3100 Enter Swamp

3700 Leave "

3850 Enter "

4800 Leave "

8107 fell  $54\frac{1}{2}$  West of  $\frac{1}{4}$  Post

Went North + set center Spruce 10 S  $3\frac{1}{2}$ W  $34$

" " 6 N 11 E  $15\frac{1}{2}$

Distance to N  $\frac{1}{4}$  Post 3963

" " S " " 4144

" " E " " 3839

" " W " " 3831

1981  $\frac{1}{2}$  N of center set  $\frac{1}{8}$  Post Sugar 14 N  $26$ E  $20\frac{1}{2}$

Birch 48 S  $52$ W  $30\frac{1}{2}$

1916  $\frac{1}{2}$  E " " "  $\frac{1}{8}$  " Hem 20 N  $48$ W  $9\frac{1}{2}$

Sugar 8 N  $79\frac{1}{2}$ E  $15\frac{1}{2}$

1915  $\frac{1}{2}$  W " " "  $\frac{1}{8}$  " Hem 12 N  $11$ E  $25\frac{1}{4}$

" " 16 S  $40$ E  $21\frac{1}{2}$

South from  $\frac{1}{8}$  Post East of center Var.  $3^{\circ}$ E

4080 fell 14 W of  $\frac{1}{8}$  Post.

Corrected line North to  $\frac{1}{8}$  Post

North from  $\frac{1}{8}$  E of center Var  $3^{\circ}$  S

3973 fell 3 Links East of  $\frac{1}{8}$  Post. AS N  $\frac{1}{8}$ P. one line

is in Lake, which lies NW + SE of corrected line

South + set  $\frac{1}{16}$  Post Sugar 12 N  $34$ W  $6\frac{1}{4}$

Birch 18 S  $82$ E  $16$

Run west from  $\frac{1}{16}$  Post in center of NE  $\frac{1}{4}$  Var  $2^{\circ}$  45' E

1918 fell 11 Links N of  $\frac{1}{8}$ P. corrected line East to  $\frac{1}{16}$ P.

and north from  $\frac{1}{8}$ P. north of center.

North from  $\frac{1}{8}$ P. West of center Var  $3^{\circ}$  15' E

3952 fell 10  $\frac{1}{2}$  E of  $\frac{1}{8}$  Post

East from  $\frac{1}{16}$  Post on West line  $2^{\circ}$  50' E

3822 fell 178  $\frac{1}{2}$  N of  $\frac{1}{8}$ P. Something wrong. Went west to  
 $\frac{1}{8}$ P. and found  $\frac{1}{8}$  Post had been set from line stake, instead  
of Talley 2000 obliterated same + set  $\frac{1}{8}$ P. 1968  $\frac{1}{2}$  found the  
distance between posts to be exactly 178  $\frac{1}{2}$ . Corrected line E and  
set  $\frac{1}{16}$ P. and corrected line S to  $\frac{1}{8}$ P. Tam 6 S  $75$ W  $56$   
finished SEPT 13" 1907 " " 6 S  $9$ W  $70\frac{1}{2}$



S E C = 30 " 43.5. E SEPT 19 " 1907

Began at N.E. cor<sup>n</sup> which I set in JULY 1907  
 And run South var  $3\frac{1}{2}^{\circ}$  East  
 800 Enter Swamp (WET)  
 4057 FELL 133 East of  $\frac{1}{4}$  Post. Set Post from both  
 Org<sup>n</sup> B.T. Course is correct to both, but the  
 distance to Tam<sup>n</sup> is 21 instead of 13.  
 corrected Line North + set  $\frac{1}{8}$  Post at 2028  $\frac{1}{2}$   
 and  $8\frac{1}{2}$  W of Random <sup>Cedar 8 N 23 W 22</sup>  
 = SEPT 20 " 1907 = <sup>Tam 14 S 10  $\frac{1}{2}$  E 1  $\frac{1}{2}$  ..</sup>  
 South from East  $\frac{1}{4}$  P. var  $2^{\circ}$  E. Still in very wet swamp  
 10.00 Leave Swamp NEEDLE SAYS  $1\frac{1}{2}^{\circ}$  E  
 1300 Enter " " " " " "  
 2900 Leave " " " " " "  
 4112 FELL 137  $\frac{1}{2}$  WEST of cor<sup>n</sup> set Post from both  
 Org<sup>n</sup> B.T. Pine ok. cedar nearly gone, made  
 one. new bearing <sup>Cedar 7 N 62 W 13  $\frac{1}{4}$</sup>   
 corrected Line North + set  $\frac{1}{8}$  Post at 2056  
 +  $68\frac{3}{4}$  West of Rand <sup>Cedar 7 N 89 E 36</sup>  
<sup>Birch 6 S 84 W 40  $\frac{3}{4}$  ..</sup>

West from SE. cor<sup>n</sup> var  $3\frac{1}{2}^{\circ}$  E

1000 Leave Swamp  
 2700 Enter " and creek bottom, water all over  
 3000 center of creek 20 Links wide runs SW  
 4000 could not find Org<sup>n</sup>  $\frac{1}{4}$  Post. found where  
 some surveyor had hunted for it. and I  
 made a new one at 4025 + 50 South of Random  
 = SEPT 21 " 1907 =  
 7737 FELL 218 ch South of corner. set Post from  
 3 Org B.T. one down and rotten  
 corrected Line East and set  $\frac{1}{8}$  Post by proportional  
 measurement at 6030 West of SE cor<sup>n</sup> and 1707  
 East of SW corner <sup>Tam 14 N 11 E 21  $\frac{1}{2}$</sup>   
<sup>Cedar 8 S 36 E 33</sup>  
 Went East and set  $\frac{1}{4}$  Post at 4020 West of SE  
 corner + 108  $\frac{1}{2}$  North of Rand <sup>Tam 18 N 29 E 44  $\frac{1}{2}$</sup>   
<sup>" 14 S 26 W 41  $\frac{1}{2}$</sup>   
 Went E corrected Line East and set  $\frac{1}{8}$  Post at  
 2010 and  $54\frac{1}{4}$  North of Rand <sup>Hem 16 N 55 W 15  $\frac{1}{2}$</sup>   
 corrected Line East to corner <sup>DO 14 S 32 E 10</sup>

Section 30. 43-5 SEPT 23 1907 cont

Went to N.W. Cor which I set SEPT 14 1907  
 Run South var  $3\frac{1}{2}^{\circ}$  E  
 3988 FELL 30 WEST of  $\frac{1}{4}$  Post, SE Post from both  
 Org<sup>n</sup> B.T. OK. Went north and set  $\frac{1}{8}$  Post at 1994  
 and 15 East of random cedar 8 N 67 E 19  
<sup>Tam 14 N 51 W 23</sup>  
 South from West  $\frac{1}{4}$  Post var  $3\frac{1}{2}^{\circ}$  East  
 3995 FELL 35 East of corner (var  $4^{\circ}$  East, ~~West~~)  
 corrected north + set  $\frac{1}{8}$  Post at 1997  $\frac{1}{2}$  and  
 17  $\frac{1}{2}$  West of random <sup>Tam 9 S E 3</sup>  
 = SEPT 25 " 1907 = <sup>DO 14 S W 36</sup>  
 South from N.  $\frac{1}{4}$  Post var  $1\frac{1}{2}^{\circ}$  E  
 2100 Leave Swamp  
 5300 Enter " "  
 6200 Leave " "  
 7800 Enter " "  
 8088 FELL 21 Links East  $\frac{1}{4}$  Post. corrected Line N 400 ch  
<sup>DEC 26. change course</sup>  
 Went to West  $\frac{1}{4}$  Post and run East var  $3\frac{1}{2}^{\circ}$  East  
 800 Enter Swamp  
 1800 Leave " NEEDLE SAYS 240 E  
 8451 cross N+S corrected Line  
 4700 Enter Swamp  
 7747 = SEPT 26. 1907 =  
 7747 FELL 50 north of  $\frac{1}{4}$  Post set a week ago (org B.T.)  
 corrected Line West and set  $\frac{1}{8}$  Post at 5804 +  
 1948 East of center. corrected West and set center  
<sup>Birch 15 N 39 E 21</sup>  
<sup>Spruce 17 S 14 W 27</sup>  
 DISTANCE TO N  $\frac{1}{4}$  Post 4029  
 " " S  $\frac{1}{4}$  " 4059  
 " " E  $\frac{1}{4}$  " 3886  
 " " W  $\frac{1}{4}$  " 3851  
 2085 West of center set  $\frac{1}{8}$  Post by proportional measurement  
 and 1766 East of West  $\frac{1}{4}$  " <sup>Tam 12 N 57 W 27</sup>  
<sup>DO 12 S 25 W 18  $\frac{1}{2}$</sup>   
 2029  $\frac{1}{2}$  South of center set  $\frac{1}{8}$  Post  
<sup>Cedar 10 N 45 W 23</sup>  
<sup>DO 15 S 47 E 22  $\frac{3}{4}$</sup>



152 SEC 20. 36-6E OCT 18" 1907 cont"

Went to South 1/4 Post which I SET, Sept 1903  
SET flag on E + W 1/4 Line (rand) at 4092 and  
lined on to same. and run north  
7901 fell 40 West of 1/4 P. I SET in SEPT 1903

Went South and SET CENTER of SECTION

Pine Stump 18 N 58 1/2 W 124

do do 12 S 54 W 79

Distance to N 1/4 Post 3954

" " S " " 3947 = 7901

" " E " " 3933 = 4044

" " W " " 4111

on Paga  
county  
Record

Went East and SET 1/8 Post at 196 1/2 + 156 1/4 N of  
Random

B. Pine 10 N 19 E 31

do 7 S 31 1/2 W 34

copied  
5  
m

corrected line East to 1/4 Post

Went to center and corrected line W to 1/4 Post

SET 1/8 Post South of center at 1973 1/2 and 10 Links  
East of random

B Pine 7 N 69 1/2 E 118

Fence Post 8 S 41 E 33

finished at 4:30 P.M. and came home

SEC 20. 40-7 OCT 21" 1907

I wanted me bet 20 + 21 but it is gone  
found where org. line came to Lake and  
SET me. Chained north on org line 377 to  
1/4 Post which is gone, found sufficient evidence  
and SET 1/4 Post

Birch 7 N 40 W 27 1/2

W Pine 10 S 75 E 13

Run west var = 1 1/2 East. which is course of the  
north line 4'

4000 SET post for center and prolonged line  
West to Lake

ALSO run South from center to Lake  
DO NOT quarry this nor except 1/4 P and  
me. finished Oct 22 1907

Work done for G Komke

SEC 28. 40-7. Oct 22" 1907 3 p 153

AS SW COR: is in Lake and me gone  
I found where org. line came to Lake  
and SET me. ASPEN 4 N 63 E 18  
W Pine 10 S 48 W 47

Run N. var = 3 1/2 E.

1298 1/2 - 100 South of ~~SW~~ marsh + Stream

2074 1/2 - over = Oct 23 = "

5030 center of G.M. + St. P. RR.

7257 from me + 7694 from COR: fell  
63 East of me. which is in Lake. as  
the Lake is about 8 feet above its  
normal height found N.S. BT. "a stump"  
made new bearing; Hem 10 N 87 E 57  
no other

found a shortage of 196 ch divided same and  
went South + SET N 1/8 P at 5853 N of COR: in Lake  
and 5416 N of me. Sugar 8 N 88 E 62 3/4  
do S 3 1/2 E 28 1/4 22 1/2

went South + SET 1/4 Post at 3902 N of corner  
and 3465 N of me. ASPEN 4 N 44 W 23 1/4  
no trees near

Corrected line South to marsh + Stream

= Oct 24, 1907 =

Went to a point on Lake where East line  
should leave Lake but could not find me  
Went north and found org line run by us.  
Depto surveyor A. Anderson, SET instrument  
at this point and run South to Lake 10.03  
ch. and SET Temp = me. and Chained  
north to the point where I found old line

Var 3 1/2 E Prolonged line north  
2681 am 100 South of bay of Lake  
3553 over bay of Lake to high bank no timber  
6000 offset East 357 to old line "timber"  
7635 fell 31 West of corner in old burning  
found the Hem = down, marks ok

" " Birch Stump "no marks" found  
Point of old Post; SET new and made new  
Bearing; W Pine Stump 40 N 51 1/2 W 21



154 SEC. 28" 40-7 Oct 24 1907

Went back and moved Temp. mc West 56 1/2 which places it in line between NE corner and the point where I found org. line 1003 N of mc. found distance to mc. same as Temp. mc. set cedar post and made bearing

W. Pine Stump 20 N 79 E 44  
no others near

Went North + set 1/4 Post on line bet. NE cor. and mc and 36 17/2 N of mc. or 40 17/2 N of SE cor. and piled rock around it as there is no timber for bearings.

Went N and set 1/8 P at 56 26 N of mc. or 60 26 N of cor. in Lake

W. Pine Stump 36 N 3 W 8  
no others near

In figuring correction I used the point where I found old line 1003 N of mc

West from N 1/8 Post on east line  
Var. 3 1/2 E

9.50 Enter swamp or creek bottom  
12.50 Spring Creek 20. runs SW  
21.50 Leave Swamp + creek bottom  
43 24 1/2 am 50 Links East of Lake  
55 49 OVER LAKE + SWAMP  
75 50 Center of C.M. + St Paul R.R.

= OCT 26" 1907 =

7792 fell 94 N of 1/8 Post

Went East and set 1/16 Post at 1956 or at 5844 and 70 1/2 S of rand. W. Pine Stump 26 N 31 E 12 1/2  
no others near.

Went E and set 1/8 P. N. of center at 3896 and 47 S of Random

Went East and set 1/16 P at 1956 and 23 1/2 S of Random

SEC. 28. 40-7. E Oct 26" 1907<sup>155</sup>

East from W 1/4 Post var 3.40' East  
4897 in intersect Lake

7407 over

7637 fell 23 1/2 N of random

Went west and set center at 3818 1/2 and 113/4 S of rand. Birch 16 N 76 E 55 1/2

W. Pine Stump 24 S 25 W 34

Went west and set 1/8 Post at 1909 1/4 + 5 3/4 South of Random

W. Pine Stump 20 N 67 1/2 W 54  
no others near

North from 1/8 P West of center var 3 1/2 E  
1969 fell 18 1/2 West of 1/16 Post

Went South to 1/8 Post and Prolonged corrected Line South

2866 intersect Lake and set mc

Oak 12 N 43 W 8

W. Pine Stump 14 S 53 1/2 W 12

16 N 43 E 12

~~Aspen 8 N 49 E 11 1/2~~

Went to center and run north var 2° E

1984 fell 12 East of 1/16 Post. went back to center and run South on corrected line var 2 1/2 S

384 intersect Lake + set mc. W. Pine Stump 14 S 53 1/2 W 12  
Aspen 8 N 49 E 11 1/2

Went 1/16 Post in center of NE 1/4 and run South on an intermediate course bet. E line + N + S 1/4 line 7.48 E. 1507 to Lake + set mc.

W. Pine Stump 14 S 74 E 37 3/4

no others near

This is all in 28. finished Oct 27 1907 at 1:15 PM

156 SEC. 26-43-5 NOV. 1st 1907

Went to NE cor. found Birch ok but marks nearly gone found stump of aspen SET NE Post and made new bearing. HEM 8 N 44 E 10 1/2  
no other

Runsouth Var 3/2 E needle Says 3° E  
2400 Stream 25 wide runs WEST needle Says 3° E

2600 Railroad

7914 FELL 6 1/2 W. of corner

Went north + SET 1/4 P. Sugar 12 N 37 1/2 E 22  
HEM 18 S 73 1/2 W 41 1/4

Corrected Line N. to corner

West from E 1/4 Post Var 3 1/2 E

950 to Railroad

2430 .. Stream 25 wide runs South

4500 .. Railroad

7871 FELL 108 north of 1/4 Post SET Post from the Linden and stump of hemlock + made new bearings. Birch 12 N 24 W 64  
Do. 12 S 5 1/2 W 43 1/2

Went to NE cor. again + run WEST Var 4° E  
1425 Enter Swamp

1450 Stream 10 runs South

3966 FELL 1/4 Links S of 1/4 P. SET Post from NW B.T. + stump of SE B.T. corrected East and SET 1/8 Post

South from N 1/4 P. Var 3.45 E

275 to Railroad

1100 " " "

3600 " " " and Enter Swamp

4500 Leave

8072 FELL 69 Links W of 1/4 P. SET Post from NW B.T. now a stump, and the stump of SW B.T. made NE bearing. HEM 8 S 2 E 10  
no other

Corrected Line north + SET center of section

Cedar 8 N 20 1/2 W 2 1/2  
" 8 S 74 1/2 W 6

157

SEC. 26-43-5 cont. NOV 4 1907

Dist. to North 1/4 P 3996 } 7871

" " South " " 4076 }

" " East " " 3964 } 8072

" " West " " 3907 }

SET 1/8 Post East of center at 1982 on corrected Line  
HEM 12 East 15  
W Pine 18 S LE 20

East from South 1/4 Post on old Line var 2 1/2 E  
3943 FELL 240 South of Post

Went WEST + SET 1/8 Post. Birch 11 S 74 E 4 1/2  
ELM 14 S 74 W 30 1/2

South from 1/8 P. E of center Var 4° E  
4019 FELL 24 3/4 W of 1/8 Post corrected north to 1/8 Post

North from 1/8 Post East of center Var 4 1/2 E

750 Stream 20 runs SW

3300 to Railroad

3976 FELL 12 East of 1/8 Post

Corrected South to E 1/8 Post and from 1/8 P. E of center to E 1/4 Post

This is ALL in 26 except to correct the Line from center East to 1/8 Post and from South 1/4 Post East to 1/8 Post NOV 5 1907

SEC 23-43-5 NOV 6 1907

Went to SE. cor. set last Friday and  
run north var 40° E

450 Railroad

4030 FELL 37 W. of 1/4 P. Set post from E B.T.

W one gone made new bearing

Birch 11 N 40 W 42

No other

Corrected Line South to corner

North from E 1/4 P var 3 1/2° E

2900 Enter Swamp

3992 FELL 20 3/4 W of 1/4 P. Set Post from

East B.T. ok. found stamp of Spruce

made new bearing Spt 4 N 57 W 30

+++ see page 159 for N 1/8 P No other

West from NE cor. var 40° E

560 Leave Swamp and enter Windfall

= NOV. 7. 1907 =

4000 COULD NOT FIND 1/4 POST

7000 LEAVE WINDFALL

7802 FELL 70 Links N. of COR. SET IN SEPT 1907

Went East and set 1/4 P. at 3901 &amp; 3888.

of random Dead Birch 26 N 26 1/2 E 39

No other

Went East and set 1/8 P at 2000 1/2 + 17 1/2 S

of random Sugar 7 S 86 E 49

Do. S. S. 13 E 58 1/2

West from East 1/4 Post var 7 1/2° E

1167 Intersect Lake

1847 Over Lake + Enter Windfall

4800 Railroad

5600

7800 FELL 25 South of 1/4 P Which I SET in  
SEPT 1907.

North from South 1/4 P in small Wet Swamp

Set Post from NW B.T. var 320° E

7973 FELL 36 1/2 W 1/4 Post - Went South and

Set Center of Sec. Hem 9 S 4 E 42 1/2

cedar 6 S 78 1/2 W 13

SEC 23. 43-5-E NOV 8-1907 Cont.

Distance to N 1/4 Post 3980 = 7973

" " S " " 3953

" " E " " 3957 = 7810

" " W " " 3863

Corrected Line South to 1/4 Post

" " East from Center and Set

1/8 Post at 1978 Dead W Pine 26 S 24 E 47

Birch " " 8 N 56 W 27 1/2

= NOV. 9. 1907 =

North from 1/8 P East of Center var 30° E

3981 FELL 45 W of 1/8 Post. Corrected Line S. to 1/8 P.

Corrected Lines around SE 1/4 and E 1/2 of

N 1/4 this is all in SEC. 23.

SECTION 24-43-5-E NOV 9. 1907

Went to NE cor. which I set 3 days ago

Run East var. 40° E.

4011 FELL 53 North of 1/4 P. Set new Post

from NE B.T. the SE one is gone, made

new bearing Cedar 12 S 72 E 6

No other

Went West + Set 1/8 Post. Cedar 8 N 27 1/2 E 8 1/2

Do 8 S 40 E 12 1/2

+++ N 1/8 P. on E Line of SEC 23. Cedar 8 N 76 W 30 1/2

Birch 12 N 63 E 17

Run East from N 1/8 Post on W Line. 24 var 340° E

2005 1/2 Set Temp 116 P. Run N. var 320° E

1951 Hit the Post. Went South Temp 116 Post at

1996 South of 1/8 Post on N Line and Corrected

Line West to 1/8 P. on on West Line

finished NOV 10 at moon

Snowed 4 inches last night and is  
snowing now



SEC 24-35-11. NOV 15 1907

Went to West 1/4 P. which I set from both Org. B.T. in JULY 1901. Run south var 3 1/2 E which the course of this line north of W 1/4 P 1700 to Grandon road where road runs E and another road runs South  
4056 fELL 115 East of Cor. which I identified by the stump of West Org. B.T. made new bearings Sugar 10 N 77 E 79 1/2  
SUGAR 12 N 69 1/2 W 104

Corrected Line North to 1/4 Post  
Coped on Page 355

East from SW Cor var T° West  
4199 fELL 252 South of 1/4 Post both Org B.T. OK. went west and set 1/8 Post at 2099 1/2 and 126 N of road

North from South 1/4 Post var 5° East  
1250 Grandon road  
= NOV 16 1907 =

7830 fELL 183 East of 1/4 Post which I set in 1901

Went to West 1/4 Post again + run East var 00  
7801 fELL 174 1/2 north of 1/4 Post. Set from both Org. B.T.  
Went West and set center crooked Sugar 12 N 34 W 37  
B. Ash 16 S 34 E 36 1/2

Distance to North 1/4 Post	40.40
" " South " "	37.90
" " East " "	37.64
" " West " "	40.37

Went West + set 1/8 Post : Lind 8 N 5 W 53/4  
Do. 12 S 7 E 53/4

South from 1/8 Post west of center var 3° East  
14.40 Enter field

16.50 Leave " 1915 center of road  
3970 fELL 47 Links W of 1/8 Post Corrected Lines Around the W 1/2 of SW 1/4. and finished Sunday Nov. 17 1907 I am 65 YEARS OLD today August 19 - 1911 see Book of this date Page 30  
County record

SEC 25-35-19 &amp; NOV 16 1907

Went to SW Cor. found Post set by Dorr and NE B.T. OK. Sugar is gone  
Run East var 40 E  
3952 fELL 91 Links N. of 1/4 P. set Post from both Org B.T. corrected Line West to Cor

Went to East 1/4 P. found Dorr's Post and both Org B.T. found corrected line N from this. took course of this, which is 4.45' East and run South var 4.45 E  
1990 Pratt Railroad  
3965 fELL 225 1/2 West of Cor. found Post OK. B.T. all gone. the Slump of NE B.T. with marks OK. made new bearing

Tran 14 N 11 W 37  
No others near

Went West + set 1/4 Post; TEL POLE 10 N 83 W 102  
" " " " 10 S 84 E 175

Corrected var to 1/4 P. is 8° E and 4.45 from 1/4 P. to me. average course of whole line is 6° E. Course of the West side line is 5.45. hence N 45 1/2 line should run on 558 6°  
NOV 19 1907

Went to SW 1/4 P and run N var 6 E  
1942 1/2 set 1/8 Post; ~~center~~

Went S 1/8 P. on East Line and run West var 3 E  
2625 fELL 2 1/2 Links South of Temp 1/8 P  
Still West on same Line same var 3 E

SEC 25-35-10.E. NOV 18 1907

WENT to S.W. COR. found Post set by Dorr from NE BT. both Post and tree O.K.

Run East var  $4^{\circ}E$

3952 FELL 9 Links N of  $1/4$ P. Set Post from both org BTs corrected line W to cor.   
 *corrected on Page 306*

WENT to East  $1/4$ P. found Dorrs Post and both org BT. found Dorrs corrected line north from this Post set instrument at Post took course of Dorrs Line (which is  $44^{\circ}0'E$ ) and Prolonged it South

3965 FELL 225 W of corne. found Stump of NE BT. marks plain the other BT. have been grubbed out. found old Post ok. made new bearing:  $Tam 14 N 11 W 37$

*no other*

found course of this from  $1/4$ P. South to cor to be  $8.10E$  and AVERAGE course from MC South to sec cor is  $6.45$

WENT N + SEC  $1/8$ P. TEL. POLE  $10 N 83 W 102$   
 $10 S 84 E 175 1/2$

this Post is in the right of way of the Pratt branch of the C + NW R.R. and 20 Links N of track

WENT to S.W. COR again + followed old line to Lake found Dorrs mc. made new bearing. used His Post. Cedar Stump  $14 N 75 W 7 1/2$   
*no other*

Run South var  $3 1/2 E$

2194 FELL 7 Links W of cor. found a shortage of 6 Links. Proportioned same and set  $1/8$  Post at  $19 1/2$  N. of ~~MC~~ HEM  $7 N 47 1/2 E 19 1/2$   
 $5 1/4$ P. line i. fir  $10 S 76 1/2 W 25$

WENT to ~~Post~~ and run WEST var  $3^{\circ}E$ . this is same course as AS South line from SW cor as  $1/4$ P.  
 8504 FELL 13 South of  $1/8$  Post

*country record*

WENT to  $5/4$ P. and run N var  $5^{\circ}07$

2009 Intersect correct  $1/8$  Line this shows that  $5/4$  Post is  $2 1/2$  Links South of true line sec -

SEC 25-35-10.E cont NOV 19 + 20 1907

SW + SE corners. so I set  $1/8$  Post at  $19 1/2$  N of  $5/4$ P and on intermediate course bet East + West Sec Lines.

Cedar  $18 S 48 W 17$

"  $14 S 45 E 11$

W corrected line East and set  $1/16$ P. E. when an intermediate course would be coming from E  $1/8$ P. on S line. which is at  $22 3/4$  W of E  $1/4$ P.

Birch  $14 N 58 E 12 1/4$

*no other*

Run North on intermediate course bet N + S  $1/4$  line and E sec line

1982 1/2 SEC  $1/8$ P.  $12 N 41 W 19 1/2$

$12 N 89 E 15 1/2$

*corrected on Page 306*

Run East from this  $1/8$  Post var  $3^{\circ}E$

1937 FELL 6 Link N of  $1/4$ P. corrected line West to  $1/8$ P.

SEC  $1/16$ P. in center of SW  $1/4$  1956 East of  $1/8$ P. on W line

Distance from  $1/8$ P. N of South  $1/4$ P to  $1/8$ P on West line is  $38 1/2$  and to E  $1/8$ P. on E line is  $45 1/2$  showing that it is over 5<sup>th</sup> corner from  $5/4$ P. to SE cor

*country record*

2194  
 199 1/2  
 202 1/2

SEC 34 39-6. E NOV 26 1907

Went to N.E. Cor found NW BT marks nearly gone. Someone had made new bearing  
 J. Pine 8 N 71 E 21 1/2

Run W ... other Post is in road

Run West Var 40°

2000 Center of road 30 Links East South

4000 " " " 50 " North

found post but no bearings Post has been moved. Was on brush pile  
 needle shows 6 1/2° E Var

7000

7676 fell 19 1/2 South of cor. found Stumps of both org BT and an angle iron for Post. Went East end SEC 1/4 P. at 3838 + 97 1/2 N of random

Post sets in W. Pine 9 N 23 E 18 3/4

School House yard " " 9 S 42 W 22

Corrected line East and set 1/8 P at

19.19 and 48-62 links N of random

copied on Page 73

county record

W. Pine Stump 30 S 42 W 104 1/2

no other

South from N 1/4 Post Var 40°

1500 needle shows a Var of 50°

3000 " " " 3 1/2 E

7807 fell 397 W of 1/4 Post, iron pipe for Post these BT a sugar is OK

NOV 28 1907

South from N.E. Cor Var 5.45 East

700 minocqua + Hazelhurst Road SW + NE

3880 fell 2 inches W. of 1/4 P. found Stump of NW

BT. East one is gone. ALSO .. Point of Post

SEE Sec by WILLIAM ALLEN went N and

Page 165 " 1/8 Post W. Pine 14 S 9 E 179

no other

South from E 1/4 P. on same course from N.E. Cor but needle shows 5.15

3889 fell 123 East of cor. found Stumps of

both org BT. ashens are gone. Corrected

N and set 1/8 P W. Pine Stump 15 N 28 E 15

" " " 9 S 44 W 11

SEC 34 39-6 cont nov 28. 1907

from page 164. made new bearings

W. Pine Stump 18 S 10 1/2 W 35

R. Oak 12 S 27 1/2 E 84

West from East 1/4 P. Var 2 1/2 E

2000 needle shows 3 1/4 E

2150 minocqua + Hazelhurst road

5650 CM + 1st P. RR.

7916 fell 25 1/2 South of 1/4 P. found Stump

of NW BT and the hole where East BT

was burned out. set new Post and

made new bearing J. Pine 26 S 27 W 151

no other

Went East and set center of SEC

copied on W. Pine Stump 30 S 42 1/2 E 65

Page 73 no other

Distance to N 1/4 P 3858 7807

" " S " " 3949 County

" " E " " 3970 7916

" " W 3946 record

Set 1/8 P. N. of center J. Pine 8 N 34 W 69 1/2

" " 8 S 42 3/4 W 77 1/2

Set 1/8 P S. of " W. Pine Stump 18 S 80 E 25 1/2

" " Stump 28 N 80 W 43 1/2

Set 1/8 P E of " W. Pine Stump 18 S 68 E 13

" " Stump 28 S 19 3/4 W 63

north from 1/8 P. E of center Var 5 1/2 E

3876 fell 39 E of 1/8 Post corrected line to 1/8 P

East from 1/8 P. N. of center Var 2 1/2 E

2000 needle shows 7 1/2 W Var

3000 minocqua road NE + SW

3911 fell 242 South of 1/8 P. corrected

Went W + set 1/8 P W. Pine Stump 16 N 3 W 41

no other

Went to S 1/8 P. on E line + run W Var 2 1/4 E

NOV 30 1907

3615 minocqua Road

3968 fell 63 P. North of 1/8 Post

corrected line East to 1/8 P

over



166 SEC. 24. 39-6.E. cont. nov 30 1907

Went to m.c. on East Side of Lake on  
Town Line, found stump of Pine BT OK.  
Oak is gone SET Post and run E var 4° E  
3254 fELL 58 South of SE corner  
corrected Line West and set 1/8 P.

Birch 8 N 52 1/4 W 11

Birch 8 N 89. E 27

found an overrun of 21 Links. Proportion  
-ed same to set this 1/8 P and run N. var 4 1/2

3928 fELL 113 East of 1/8 P. went South and  
set 1/16 Post

Aspen 7 N 68 E 18 3/4

Birch 2 S 40 W 5 1/4

corrected ALL Lines in SE 1/4 except the  
Lines around SW SE on South & West Sides.

Corrected ALL Lines in NE 1/4

found Local Attraction <sup>on</sup> ALL Lines  
except Town Line, more particular near  
center of section

finished nov 30 1907 =

will have to correct some Lines tomorrow  
= see 1<sup>st</sup> 1908 =

corrected Lines

Copied on page 73 county record

SEC. 13. 39-5.E. DEC 2 1907<sup>167</sup>

Went to NW. COR. found SE. B.T. OK.  
Set Post and made new bearing

OAK 10 N 5 E 31

no other

Run East var 4° E

3400 enter Swamp

4000 fELL 55 1/2 N. of 1/4 P. which I set from  
both org. B.T.s. went West and set 1/8 P.  
at 2000 and 27 3/4 South of random

1/2 Pine 16 N 58 1/2 W 68 1/2

1. " 16 S 33 W 168

Run South from this 1/8 P. var 4° E

1095 intersect Lake and set m.c.

1/2 Pine 14 N 61 1/2 E 42

W. " 15 N 31 W 39

I then proceeded to Survey 2 acres of Land  
described as follows to wici:

A piece or parcel of Land in Lot 3 SEC 13. 39-5 E

and more particularly described as follow to wici:

Beginning at a Post which stands on shore of Lake  
~~the~~ 439 ch West of a Post

where the line between Lots 2 and 3 intersects

MEER LAKE Thence N. 4° W var 4 E 900 ch


" W at right angles 225 ch

" S South at right angle 842 ch

" Easterly along shore of Lake

225 ch to Place of beginning

copied on page 13. county record



## Survey of an island in Mercer Lake

in SEC 13. 39.5E DEC 3<sup>rd</sup> 1907

I Proceed as follows

SET NE COR. of 13. from SE B.T. and run South  
Var 40°E680 ~~8~~ 20 Links from m.c. which I set from PineThe oak is gone found course of Line from  
COR. to m.c. to be 5 1/2 E Var. AmI then placed instrument at m.c. and on  
Line to cor. set flag on West Point of island  
which bears S 10° E instrument adjusted on  
5.30° E Var. chained across Lake to flag

175 INTERSECT LAKE

2296 to flag. in Place of flag set Tam post

Aspen 10 N 20 E 21

" " 8 S 31 1/2 E 15 1/2

I then began the meander of island from  
m.c. thence S 39 1/2 E 500 thick brush, stopping  
Shore. " N 16 1/2 E 500 " " "

" " " N 54 W 350 " " "

" " " S 82 W 100 " " "

" " " S 15 W 225 " " "

" " " to come and place of beginning

copied on page 12  
county Record

## SEC = 24 37. 10. East DEC. 11 1907

Went to NE COR. found 3 org. B.T. NW BT 15  
down. set new Post and run West Var 1/2° E  
9356 fell 8.20 South of COR. set Post from both  
Org. B.T. Oak is down. Baked an

Went East and set 1/4 Post at 4678 and 4.10

North of random W line 20 N 53 1/2 W 42 1/2

Page 331

" " 26 S 77 1/2 E 44 3/4

Went East + set 1/8 Post at 2339 and 2.05 North  
of Rand Birch 8 N 53 3/4 W 29

" " 8 S 25 1/4 E 21 1/2

South and 2.05 No from N 1/4 Post Var 45° W  
= DEC 13 1907 =

38.00 INTERSECT LAKE bears NE + SW

46.50 OVER LAKE camp record " "

80.00 COULD not find 1/4 P. Think the Govt  
SURVEYORS did not run any E + W Line  
in the East Tier of SEC. in this town.

I have run the lines bet 25 + 26 - 24 + 25

13 + 24 and 12 + 13 and found no 1/4 Posts

Went to SW COR. and run East Var 2 1/2 W

4000 LOOK ~~dig~~ diligentlY for 1/4 P.  
but could not find it

48673 fell 58. South of m.c. bet 24 and 25

which I set as follows. found B.T. for  
m.c. bet 25 + 30. and set Post measured

north across LAKE. found dist bet

m.corners 21.21, gov't dist 25.21 a shortage

of 4.00 ch. proportioned shortage and set

COR. to 24.25. 15 and 30 on ie 49 Links North of

m.c. corrected my rand bet 24 and 25 on

to this cor. and corrected Line west to Shore

of LAKE 51 Links and set m.c. bet SEC 24 + 25

SEE bottom of Page 131 Tam 6 N 82 3/4 W 125

For 1/4 P

" " 5 S 70 1/2 W 95

Went West and set 1/4 Post at 48.41 East of SW COR.

and 32 1/3 Links N of rand. I found a shortage on

this an OVERrun of 15.05 bet SW cor. and m.c.

Proportioned surplus. to set 1/4 P. distance given

by U.S. Surveyors 7168 my measure 715

8673. HE did not run this Line, no Line marked

170 SEC. 24. 37. 10. E cont. DEC. 15. 1907

and nothing to show line had been run.  
See bottom of Page 171 for S. 14 P

Picked up my N + S 1/4 Line (random) and at 76.49 fell 54 2/3 W of 1/4 Post. DEC 7, 117 corrected var 3 1/5 E a change in course of 4°

Went to East 1/4 Post. found Post & set and bearings & made in 1907. The bearings are  
Maple 12 N 44 E 35  
Birch 12 S 22 W 23.

Run West Var. 5° W

35.00 intersect Lake county

47.00 OVER

90.20 fell 80 North of 1/4 Post which I set from stumps of org B.T.'s marks on Tam arg on c pine ok. made new bearing W Pine 20 S 5 1/2 E 33  
Went East and set center of sec. on ice

W Pine 20 N 1 W 32 1/2  
" " 24 N 5 1/2 E 31 1/2

Distance to East 1/4 Post 42 33 1/2

" " " West " " 51 22 1/2 47.86 1/2  
" " " North " " 39 39  
" " " South " " 37 10

Dist. from center to South Shore of Lake on true line 450

" " " North " " " " " " 300

Corrected Line North from center and set 1/8 Post at 1969 1/2

W Pine 12 N 38 E 9  
Birch 10 S 44 W 8

East from 1/8 Post North of center var 4.30 W  
1900 intersect Lake

3100 OVER

4470 fell 16 Links N. of 1/8 Post which I set in 1907  
The bearings are Maple 10 North 1 Link  
W Pine 16 S 18 E 39 1/2

North from 1/8 Post East of center var 5° East  
1150 intersect Lake Read

2400 LEAVE

3930 fell 185 W of 1/8 Post. went S, and set center corrected lines around the SW. NE  
Camp is on SW NE near S line and not far from sec cor  
W Pine 20 N 15 3/4 W 40 3  
" " 8 N 74 1/2 W 26 1/2

SEC. 24. 37. 10. E cont. DEC 16. 1907 171

Set 1/8 Post East of center at 2116 3/4 and 18 3/4 South of rand. W Pine 10 N 45 E 9

Copied on Page 10 S. 8 E 20  
331 W Pine 10 inches in dia. for Post

finished DEC. 16 1907 and scaled trespass on SW. NE 24. there is 2670 feet new cut logs on Skids. and 5450 feet (28 trees) used in building Camps. 4 years ago. County road

SEC. 1. 36. 10. E. DEC. 17. 1907

went to South 1/8 Post on West Line set by B. F. Dorr. Run East var. 4° E.

3708 fell 88 Links north of 1/8 Post East of center, which I set as follows, as I had run both 1/4 Lines & set center. I found the distance from center to the South 1/4 Post 3961 So I set 1/8 Post at 1980 1/2 and 9 1/3 East of my random. See Page 107 and 112. Birch 8 N 75 E 31 1/2  
fir 10 S 71 W 27

Corrected Line West to 1/8 Post

S 1/4 Post W Pine 17 N 25 E 37

" " 13 S 61 3/4 E 22

See 1 Copied on Page 308  
County road



SEC- 12-36-10-E DEC- 18" 1907

Went to North  $\frac{1}{4}$  Post which I set last winter. Run south var  $2\frac{1}{2}^{\circ}$  East  
3800 Enter Haymarsh

5120 Stream 30 Links wide run SW

5300 LEAVE Hay marsh

7942 fell 199 East of  $\frac{1}{4}$  Post, I set in 1897

Went north and corrected line at center

20.00ch to  $\frac{1}{4}$  Post  
" " " " " from  
" " " " " 18.17 $\frac{1}{2}$

Set West  $\frac{1}{8}$  Post on north line at ~~35.35~~ + 2618  
North of Random See Page 107.

Copied on Page 312 Cedar 6 N 55 W 3 $\frac{1}{2}$

" " 10 S 54 E 2 $\frac{1}{2}$

DEC- 19" 1907

Went to West  $\frac{1}{4}$  Post which I set in 1897 and  
run east on an old random var  $2^{\circ}$  W  
2500 Enter Swamp

3564 crossed N+S corrected  $\frac{1}{4}$  Line

4100 Enter Hay marsh

4400 Stream 20 runs S.W.

4750 LEAVE SW Hay marsh

7175 fell 214 $\frac{3}{4}$  south of  $\frac{1}{4}$  Post found  
Stumps of both org BT's OK found Post  
Set by Dorr. went west and set center

fir 5 N 28 E 20

Spruce Pine 10 S 60 $\frac{1}{2}$  W 10

Dist to N  $\frac{1}{4}$  Post 3902

" " S " " 3840 county record

" " E " " 3611

" " W " " 3564

Set  $\frac{1}{8}$  Post W of center at 1782 and W of rand

fir 8 N 83 E 43

Sugar 10 S 71 $\frac{1}{2}$  W 27

Set  $\frac{1}{8}$  P. E of center at 1805 $\frac{1}{2}$  + W of random

17 Pine stump 16 N 46 W 36

" " " " 16 S 74 S 44 $\frac{1}{4}$

Set  $\frac{1}{8}$  P. N of center at 1951 + W of random

OSPerr 10 N 41 W 2

fir 11 S 66 $\frac{1}{2}$  E 21

SEC 12-36-10 E cont- DEC- 20 1907

South from W  $\frac{1}{8}$  P. on N Line  $\frac{1}{2}^{\circ}$  E  
3807 fell 69 W of  $\frac{1}{8}$  Post

Copied on Page 312

West from  $\frac{1}{8}$  Post N of center var  $\frac{1}{2}^{\circ}$  E

3585 fell 44 $\frac{1}{2}$  N. of  $\frac{1}{8}$  Post set by Dorr

Took his bearing Tam 15 S 42 $\frac{3}{4}$  E 24 $\frac{1}{4}$

made new one Cedar 6 N 6 E 23 $\frac{1}{2}$

Went East and set  $\frac{1}{16}$  Post Tam 8 27 $\frac{1}{2}$  W 24

" " 12 29 $\frac{1}{2}$  W 26

Corrected Lines around NE.NW.

= Dec 21" 1907 =

South from  $\frac{1}{8}$  Post East of center var  $1\frac{1}{2}^{\circ}$  E

300 Stream 20 Links wide run west

3921 fell 24 $\frac{1}{2}$  East of  $\frac{1}{8}$  Post, which I set

45 follows. went to South  $\frac{1}{4}$  Post and

run east on my old random which

is 29 Links south of rand.

3593 fell 58 North of cor- found stub of SW

org- BT and stump of NW BT both had

marks. Set new Post, and made new

bearing Tam 15 N 11 W 21 $\frac{1}{2}$

no other

Went west and set  $\frac{1}{8}$  Post

Pine 20 N 11 $\frac{1}{2}$  E 23 $\frac{1}{2}$

" " 10 S 88 $\frac{1}{2}$  W 30

Corrected line north to  $\frac{1}{8}$  Post East of center

" " from center West to  $\frac{1}{8}$  Post

East "  $\frac{1}{8}$  "

South from  $\frac{1}{8}$  Post west of center

Var  $1\frac{1}{2}^{\circ}$  East

2200 Enter creek bottom

2800 Leave " + "

3738 fell 34 East of  $\frac{1}{8}$  Post which I set

in 1897 corrected line north to  $\frac{1}{8}$  Post

found trespass on SE of SW

" my tape is 6 inches to long at bet-

99 + 100 Links I have used two months

finished at noon, sealed trespass in

PM county record

SEC # 8 36-10 DEC 26 1907

found the tamarac B.T. for me. on north side of fish Lake. cedargone. set new Post and made new bearing: B. Ash 6 N 60 W 110

Run north var  $3\frac{1}{2}$  E copied on 6381 fell 534 West of corner.

found a shortage of 4.12 Proportioned the over run and set  $\frac{1}{4}$  Post at 2105

north of me and 4276 South of NE cor<sup>n</sup> and 176 East of random. Tam 12 N 36 E  $8\frac{1}{2}$

Page 310

W. Pine 18 S 20 E 15.

corrected Line South to me.

chained South from me. on course of corrected Line 10.67 to South shore of Lake me. gone, but as the shore line is exactly East and West for several rods the distance would be the same found an overplus of 4.09 Proportioned overplus and set  $\frac{1}{8}$  Post on ice 33 Links South of me. County Record

Run a P.C. Line West from  $\frac{1}{4}$  Post 21.25 ch

" " " " " "  $\frac{1}{8}$  " 21.25 "

" " " " " " not north + south on the West side of Lot 2

finished Dec 27 1907

SEC 17 38-10 DEC 30 1907

Went to center set by Dorr and run East var 45' East

150 road to 3. Lakes SE + NW

4160 fell 22 Links north of  $\frac{1}{8}$  Post

Came West + set  $\frac{1}{8}$  P. Hem 12 N 58 E 37

Birch 8 S  $40\frac{1}{2}$  W 11  $\frac{1}{2}$

Corrected Line West to center

copied on Page 343

South from  $\frac{1}{8}$  Post East of center var 2.10 E

1961 fell 15 Links East of  $\frac{1}{16}$  Post

3922 "  $26\frac{1}{2}$  East of  $\frac{1}{8}$  Post which I set 6 years ago.

corrected Line north to  $\frac{1}{8}$  Post found trespass on NE. SE. scaled it. found there had been 14850 feet. 58 trees cut by Brown Bros. about 3 years ago.

finished Dec 31 1907

for work done in this SEC by me see Page 129 county record

## INDEX.

Page.

1  
2  
3  
3  
6  
5  
7  
9  
10  
10  
18  
114  
14  
18  
20  
19  
21  
23  
25  
26  
30  
32  
34  
36  
38  
40  
41  
41  
42  
43  
44  
45  
47  
48  
47  
50  
51



# INDEX.

# INDEX.

Section	TOWNSHIP.		RANGE.		CITY OR VILLAGE.	ADDITION.
	N.	S.	E.	W.		
27	39		6		Road for town	
21	37		9		" " "	
23	36		8			
36			10			
14	39		6			
20-21-28	36		6		Use line for 19-20	
39			6			
18	36		8			
1	38		6			
36	39		6			
26	36		10			
25	"		"			
36	"		"			
20	37		8			
23	36		7			
23	36		6			
14			"			
18	43		8			
7	"		"			
35	36		9			
34	36		10			
7	"		11			
2	35		8			
23	42		7			
12	37		13			
10	42		5			
34	36		6			
5	38		10			
32	39		10			
33	"		"			
9	38		10			
12	42		7			
4	37		8			
384	38		8			
29	38		8			
35	38		8			
32	42		8			
30	"		"			

FOR WHOM SURVEYED.	DATE SURVEYED.	WHEN			Page.
		Day.	Month.	Year.	
of Minocqua		19	July	1905	1
" Pine Lake		24	"	1905	2
Rhineland Power co		26	"	1905	3
Menasha wooden w co		31	"	"	3
W H Clauson		14	Aug	"	6
Town of Cassian		5	"	"	5
Christ and Emery Nelson	Aug 14	"	"	"	7
Levi J Bielings	Sept 2	Sept	"	"	9
"	3	"	"	"	10
Menasha w w co	20	"	"	"	10
"	28	"	"	"	13
"	Oct 2	Oct	"	"	14
Brooks + Ross Lbr co	" 3	"	"	"	14
Town of Woodboro	13	"	"	"	18
" " Cassian	18	"	"	"	20
"	21	"	"	"	19
Menasha w w co	3	NOV	"	"	21
"	5	"	"	"	23
Town of Pelican	13	"	"	"	25
Menasha wooden w co	16	"	"	"	26
"	3	DEC	"	"	30
G.S. Coon et al.	6	"	"	"	32
Brooks + Ross	9	"	"	"	34
Brown Bros Lbr co	14	"	"	"	36
Brooks + Ross	20	"	"	"	38
John Garbu	22	"	"	"	40
Robbins Lumber co	27	"	"	"	41
"	28	"	"	"	41
"	30	"	"	"	42
"	2	January	1906	"	43
Yaukey Bissell Lbr co	11	"	"	"	44
Brown Bros Lbr co	16	"	"	"	45
"	20	"	"	"	47
Antone - - - Ski	21	"	"	"	48
Brown Bros Lbr co	23	"	"	"	47
Yaukey Bissell Lbr co	9	February	"	"	50
"	11	"	"	"	51

Section	TOWNSHIP.		RANGE.		CITY OF VILLAGE.	ADDITION.
	N.	S.	E.	W.		
31	42		8			
34	37		8			
28	38		8			
27	27		26		Sturgeon Bay Door CO.	
5W 74	38		8			
10 12	36		9			
5 12 8	36		10			
27	37		6			
Survey of Road for						
Town line between Towns 36 & 37 Rang						
and bet SEC 2 & 35 and 3 & 34						
Survey of Roads						
14-12	36		6			
16+17	"		"			
21	"		"			
29	37		9			
26	38		9			
19	42		4			
32	41		8			
10	40		8			
28	41		8			
22	36		7			
4	42		5			
23	42		5			
14	36		6			
10	36		6			
21	37		9			
29	37		9			
2.3-4-5	36		8			
23	42		7			
36	37		9			
3	36		10			
29	37		11			
30	37		11			
33	39		9			
30	37		9			

Survey of Road for

Town line between Towns 36 & 37 Rang and bet SEC 2 & 35 and 3 & 34

Survey of Roads

SEC-30-37-9. August 8 1906  
Went to SEC 2 or 3 found pipe for corner & Run west 1/4 or 1/2 by BT

found set an iron pipe for corner & Run west 1/4 or 1/2 by BT  
630 in Denstet Lake  
712 do do  
820 do do  
1050 do do  
1310 do do  
1813 over  
1925 do  
2365 over  
3692 To Brown Lake flowage

Intersects Lake flowage 6 d 200 East of M.C. in Lakon  
Set M.C. !! Dead HEMLOCK 3" W 20' E connected line to corner  
SEE PAGE 184

FOR WHOM SURVEYED.	WHEN SURVEYED.			Page.
	Day.	Month.	Year.	
Yawkey Bissell H. Co	14	Feb	1906	53
Rhineland Iron Co	13	March	"	54
to Bogenski + Bro	4	May	"	55
John Somerson et al.	10	"	"	57
Town of new bald	24	"	"	58
" " Pelican	4	June	"	60
" " "	9	"	"	61
" " carman	"	"	"	62
" " "	"	"	"	62
" " "	"	"	"	63
" " "	14	"	"	"
" " "	15	"	"	"
" " "	16	"	"	"
" " "	"	"	"	64
" " "	"	"	"	"
" " "	17	"	"	65
Carl Johnson	23	"	"	66
Davis Kirk	24	"	"	67
Stat of Wisconsin	25	"	"	68
Olof Rosen	26	"	"	69
Chicago Parties	27	"	"	"
FN Cockwell	29	"	"	"
Town of Woodboro	July 5	July	"	70
Calvin Doris Buck	" 3	"	"	73
Jay Payne	31	"	"	76
James P. Somerson	August 2	August	"	"
Marsh	" 3	"	"	"
Town of Pine Lake	" 15	"	"	77
to O'Rourke	" 14	"	"	77
Olof Rosen	" 19	"	"	77
Menasha seed co	" 24	"	"	78
Blue grass Land co	" 29	"	"	79
Menasha wooden ware co et al	Sept 3	September	"	80
TOWN OF MONICO	24	"	"	84
" " "	26	"	"	85
" " "	28	"	"	85
Tender Seed	3	Oct	"	86
to Rhineland Paper Co	8	August	1906	79

Section	TOWNSHIP.		RANGE.		CITY OF VILLAGE.	MONY FOR CITY ADDITION.
	N.	S.	E.	W.		
32	36		9			
7	36		11			
6	"		"			
13	"		8		SCHOOL Ground	
3	42		5			
36	37		10			
21	41		6			
29	35		11			
22	36		10			
7	36		7			
5	36		11			
8	36		11			
4	"		"			
9	42		5			
1	36		10			
10	38		9			
3	34		11			
7	38		8			
2	38		9			
3	"		11			
1	36		8			
21	40		8			
1	36		10			
13	40		6			
15	"		8			
14	"		8			
29	41		8		LEVELS of creek in Lot 1	
14	40		8		in Lot 1	Lot 450 + 332 + 239
2	34		11			
33	37		9			
21	38		8			
28	38		8			
15	37		8		Road Town of newbold	
14	"		"			
4	38		8			
15 + 16	37		8		Road for town of newbold	
14 15	37		8			

SEC 30-37-9 Cont  
 Set flag at SE cor. and at east 1/4 post  
 lined instrument bet. flags and  
 marked line on hard land between  
 SE cor. and 1/4 P  
 Then measured the hard land  
 in SE 1/4 ranied to page 185

LEVELS of creek in Lot 1  
 in Lot 1 Lot 450 + 332 + 239

FOR WHOM SURVEYED.	DATE SURVEYED.	WHEN			Page.
		Day.	Month.	Year.	
a Mattson		12	oct	1906	88
menasha wooden ware co		17	"	"	31
"		20	"	"	89
Town of crescent		3	NOV	"	91
William Levia		8	"	"	92
menasha wooden ware co		10	"	"	93
frank weachter		15	"	"	94
William Rier		31	"	"	95
Brown Bros Lumber co		29	"	"	96
Smith and White		5	DEC	"	99
menasha wooden ware		19	"	"	103
"		2	jan	1907	"
HALE and others		4	"	"	"
H. E. fot		17	"	"	106
menasha wooden ware co		20	february	"	107
steve kaz morick		9	march	"	108
T. B. Irvin		22	"	"	108
town of newbold		11	april	"	109
albert snyder		30	"	"	110
Lewis Friday		2	may	"	111
Rhineland Power co		4	"	"	111
OF OF ROSEN		14	"	"	112
menasha wooden ware		26	march	"	112
U.S. Government		28	"	"	113
Blue grass Land co		17	may	"	114
OLOF ROSEN		18	"	"	114
26-7. DW Sayer		19	"	"	114
Henry friend		21	"	"	115
Tom Irwin		27	"	"	116
Porter Johnson + Zander		31	"	"	118
TOWN NEWBOLD		4	June	"	119
"		8	"	"	120
"					122
HETMAN FETKE		12	"	"	122
"		13	"	"	123
CEYZEIR		17-18	"	"	120
newbold					123



Section	TOWNSHIP.		RANGE.		CITY OF VILLAGE.	ADDITION.	FOR WHOM SURVEYED.	DATE SURVEYED.	WHEN RECORDED			Page.
	N.	S.	E.	W.					Day.	Month.	Year.	
28	41		7				ca goodyear	25	June	1907	126	
33	"		"				"	27	"	"	124	
1	36		10	✓			menasha Wooden ware et	6	JULY	"	127	
2	36		10	✓			"	7	"	"	128	
14	36		9				STILWELL	8	"	"	128	
17	38		10	✓			School board of Sugar Camp	11	"	"	129	
20	43		5				flambeau Lbr co	16	"	"	130	
29	"		"				"	24	"	"	133	
6	37		8				Gillispiiz	5	aug	"	137	
35	36		9		SEE PAGE 25 and 138		William Hardell	8	"	"	138	
36	"		"				"	9	"	"	139	
5	43		5				Turtle Lake Lbr co	18	"	"	140	
6	43		5				"	21	"	"	141	
19	"		"				" + flambeau Lbr co	5	SEPT	"	143	
22	"		"				"	6	"	"	145	
2	39		6		woodruff org - Plat. replatted; Part of Blocks B + E		Cf. Brodock	30	aug	"	142	
30	43		5				Turtle Lake + flambeau Lbr co	19	SEPT	"	148	
28	43		5				"	6	OCT	"	136	
20	36		6				Cal Taylor	17	"	"	151	
20	40		7				Carl Komke	21	"	"	152	
28	40		7				Gf. REEDAL	22	"	"	152	
26	43		5				flambeau Lbr co	1	NOV	"	156	
23	43		5				"	6	"	"	158	
24	43		5				"	10	"	"	159	
24	35		11				John Wojcaski	15	"	"	160	
25	35		10	✓			Moran HES ET AL	18	"	"	162	
34	38		6				George Ratbrodt	26	"	"	164	
13	39		5				Mrs Johnson	2	DEC.	"	168	
"	"		"		Survey of Island		William Arthur Bishton	3	"	"	168	
24	37		10				M W W Co + Brown Bros	11	"	"	169	
1	36		10		SEE Pages 107, 112, 172		"	17	"	"	171	
12	"		"				"	18	"	"	172	
8	"		"				WILLIAM HARDELL	26	"	"	174	
17	38		10				Robbins Lbr co	30	"	"	175	

# INDEX.

Section	TOWNSHIP.		RANGE.		CITY OR VILLAGE.	ADDITION.
	N.	S.	E.	W.		
Thence	49	E	382		Continued	
Thence	N	49	E	382		
"	"	49	W	68	copied on Page 230	
"	S	84	"	263		
"	N	22	"	263		
"	"	15	E	100		
"	S	77	W	421		
"	N	34	"	80	to SE Line 2402 West	
	from SE corner					
"	N	34	W	157		
"	N	18	E	147		
"	N	11	W	63	county record	
"	N	25	W	282	of field notes	
"	S	56	W	400		
"	N	66	W	355		
"	N	5	W	163		
"	N	25	W	323		
"	S	82 1/4	W	400	to N+S 1/4 Line	
	South on 1/4 line					
	533 to Shore of Boom Lake					
ISLAND NO. 4						
Commencing on south line of SEC 30						
800 ch west of SSE corner. flowage is 100 E & 25 W						
Thence	N	23	E	443		
at	400	on this course flowage is 86 E and 52 W				
"	300	"	"	"	13	47
"	200	"	"	"	00	62
"	100	"	"	"	23	20
*Commencing again at same Point +						
Thence	S	66	W	260		
at	100	on this course flowage is 25 S and 10 N				
"	200	"	"	"	Lake	50
Thence	N	59	W	208		
at	100	on this course		"	103	33 N
"	208	"	"	"	185	75

# INDEX.

FOR WHOM SURVEYED.	WHEN			Page.
	Day.	Month.	Year.	
Thence N 36 W 273 to LAKE				
at 100 on this course flowage is 143 S and 103 N				
" 200 " " " " " 98 " " 113 "				
ISLAND no 5				
Commencing at a Point 1850 ch of SE corner				
and on SE line between 30 & 31				
flowage at this Point is 200 W and 125 E				
Thence S 7 W 82 to Lake				
Beginning again at same Point				
Thence N 7 E 475 to flowage				
at 200 on this course flowage is 250 W and 150 E				
" 400 " " " " 150 " " 75 E				
copied on Page 230				
county record of field notes				