

36-11

181

181

PAGES 1-64

BLANK

SEC: 16-36-11 April 5th 1919 65

S/4 P set by B.F. Dorr from org B.T.
 " Run. N. U. as 3rd
 6246 FELL 682 E OF N/4 P. SET NEW Post
 FROM DORR'S NEW B.T. SW. Pine 12 S 77 E 40
 came South and at TALLEY 41 corrected
 and found CENT. OF SEC. 1/2 Links E of my
 corrected line South to TALLEY 32 asch
 found line passes through cook
 camp about 6 feet from N.E. corner

PAGES 66-144

BLANK

SECTION 36-35-11-JULY 19-1925

NW CORNER found ~~for~~ D H Vaughan
S.E. BT. a W Pine 10 S 41 E 86. has been cut
Low a.W. cut in Top

South from NW cor var $3\frac{1}{2}$ E
8126 $\frac{1}{2}$ fell 221 E of of SW corner found
Stump of orig" oak B.T. Spruce is
now a stub + stands S. 113 $\frac{1}{4}$ E 179

Daw's Tam: stub stands S N 88 W 49 $\frac{1}{2}$
change course 130' set S 18 Post on
West line at 6095 + 165 $\frac{3}{4}$ W of random

nothing for bearings Set
W $\frac{1}{4}$ Post at 4063 $\frac{1}{4}$ ~~west~~ of and 110 $\frac{1}{2}$
West of random Balsam 10 S 86 E 75 $\frac{1}{2}$

" " S N 67 $\frac{1}{2}$ W 60 $\frac{1}{2}$
N $\frac{1}{8}$ Post on West line $\frac{3}{4}$ S N 12 S 68 $\frac{1}{4}$ E 30
S.W. Cor. E. U. var $\frac{1}{2}$ E

4085 fell 238 N of South $\frac{1}{4}$ Post

SW B.T. OK NE B.T. is in center of road
and cut very low made new
bearings { W Pine S E 30 S 72 E 50

West $\frac{1}{8}$ Post on South line { W Pine S E 14 S 75 $\frac{1}{2}$ E 9 $\frac{1}{2}$
maple S N 25 E 46 $\frac{1}{4}$

East from NW cor " U. var T. 30' E

4033 fell on the N $\frac{1}{4}$ Post both orig" trees

They are nearly gone made NEW

{ maple stub 10 13 W 23 $\frac{1}{2}$

" " 14 26 W 55

W $\frac{1}{8}$ P. on N line { Birch 10 S 23 $\frac{1}{2}$ W 49 $\frac{3}{4}$

" " 10 S 31 $\frac{3}{4}$ E 49

N $\frac{1}{4}$ P. E U. var 1° W

2052 $\frac{3}{4}$ fell fell 86 $\frac{3}{4}$ N of $\frac{1}{8}$ P by D H Vaughan

2054 are 5 $\frac{1}{2}$ South of NE Corner all four
orig trees are cherry, and a dozen
SW. Birch stump on the spruce is a stub
SE Birch OK

NE Cor Run South var 2° 30' E

4003 fell 29 W of E $\frac{1}{4}$ P found NW Birch
nearly gone { cedar S N 71 E 20 $\frac{1}{2}$

" " S S 64 E 23

{ Birch 12 S 76 W 34

ell

N¹/₈ on E Line { Birch 12 N 8 E ³/₄

30 S 76 W 26

W¹/₄ P Run East Var 2° W8004 full 35 S south of W¹/₄ P. change course 15'N¹/₄ Post Run south var 2.5° E8053 full 65 E of S¹/₄ PostCenter of Section { Birch 14 N 38 W 27 ¹/₂ } 8053

{ " 14 S 85 E 43 }

Distance to N¹/₄ Post 4122

" " S " " 3931

" " E " " 4141 } 8204

" " W " " 4063

1/8 P N of center { Birch 12 S 86 W 31 ¹/₂{ Elm " 14 S 32 E 13 ¹/₂1/8 P S. of center { Pine 10 S 13 E 28 ¹/₄{ Birch 12 N 1 ¹/₂ W 54 ¹/₄

1/8 P E of center { Birch 18 S 84 W 23

{ W Pine 10 S 54 ¹/₂ E 35

North from 1/8 P East of center Var 2.25° E

4060 full 8 ¹/₂ E of 1/8 Post

East from 1/8 P N of center Var 2.25° W

4124 full 3 Lks South of 1/8 Post

1/16 P in NE ¹/₄ { Hem 14 N 50 W 14{ Birch 12 S 70 E 31 ¹/₂

West from 1/8 P N of center Var 1.20° W

4048 full 22 ¹/₂ S of 1/8 P.South from W¹/₈ P on N Line var 2° E2044 full 1 ¹/₂ Lks of 16 Post1/16 Post in NW ¹/₄ { Maple 10 N 85 W 14{ Iron wood 8 S 27 E 21 ³/₄

PAGES 147-176

BLANK

