

D.H. VAUGHAN #9

9

Book No 9

D H Saughan
opened August 20 - 1920

Book 9

9

288
288
288
288
288

ngents,
rule is
the line
ed from,
A), and
m a suf-
ius, and
ite side
of inter-
Secants
od. Set
in line,
nce α to
we find
her less
ir lines
line of
C. Let
33° 20'
e same
find the
the two
for the
be .186.
h is the
a small
e from
ns. In
minute
nber of

I.

SEC. 35-4 Aug. 4-1920

1

W. 1/8 P on N Line on iron bolt
R South on 3 1/2 E on offset of 5.74 links

500 offset W 74 Lks

1039 Some River

1473 Over "

2486 File 108 W of Lynns 1/8 P on iron pipe

Connected line N from Big Some River

N. from N 1/8 P in road

2628 to corner in road

Set a Post 1703 N of 1/8 Post and
turned off a right angle East
50 to E Line of Road. Then 355 to the
East line of a 6 acre tract belonging
H H S. and set an iron pipe

Then east 191 to Spring creek and
set another iron pipe

" on iron pipe on N 1/8 line 405 E of
N 1/8 Post on West line on bank of

Big Some

35-8 Aug 21-1920

1/4 P between 2+11 are trees but as
they are to be removed to build road
I made new bearings to wit:

{ Birch 10 N 34 W 61 1/2

{ Sugar 16 S 1/2 W 37 1/2 and chose an
iron pipe for Post 1 1/2 + 4 1/2 inches

Cont. to 1-2-11, 12, 35-8

at E. corner had to be made new on
account of road also, I made new
Bearings

{ Birch 18 N 22 E 115

{ Hemm 12 S 52 E 59 1/2

2 SEC 6. 37. 10 E August 14 - 1920

SW cor found Post and B.T.'s DORR'S

Run E Var 4° E over level ground

42.22 Dams 1/4 Post is gone, as his bearings
were sprec. and this is the only low
ground there is near, and this only 75 LKS
wide I must be very close to it.

5753 Enter Swamp

6650 Stream 10: course South

8000 did not find corner will try
again later on to locate it.

SEC " 17-36-8 OCT 12-1920

SW Corner found Stps of org tree

" " " " " " " " " " " "

NEW Pine 12 N 51 1/2 E 37 1/4
" " " " " " " " " " " "

Run E Var 3 1/2 E

1507 fell 46 1/2 S. of MC found stump
of org tree set post + prolonge line
to Lake. whole dist 1507

connected line west to corner

SW cor North Var 4° E

1197 to mc set post from org stp

NE 1/4 Pine stp 12 S 40 E 17

Prolonged Line N 100 to Lake

connected line S to corner

copied on Page 25 Book 37-10

SEC 24. 37-7 OCT 13 - 1920 3

Began at M.C. on south shore
of Lake Mildred found StP of
W. Pine marks OK, also StP of Bench near Post
Run N Var 3 1/2 E

1047 over Lake Seadia Post 1020
6346 fell 88 E of NW corner

found SW tree down marks OK
made NEW W. Pine StP 16 S 28 W 42 1/2
" " " " " " " " " " " "

found an overrun of
Proportioned Sams + set 1/8 P at 433 8
north of MC on N Show of Lake
" " " " " " " " " " " "

W Pine StP 12 N 75 1/2 E 15 3/4

" " " " " " " " " " " "

connected line south from NE corner
to 1/4 P which is set 233' N of ~~st~~ on
S. Show of Lake MC on South Show of Lake

W Pine StP 20 S 43 E 47

" " " " " " " " " " " "

Set mc on N Show of Lake 1047 N
of mc on South Show " "

W Pine StP 12 S 34 1/2 E

" " " " " " " " " " " "

sealed trespass on E 1/2 of NE 1/4

copied on Page 97- Book 37-7

Sec 27-39-6

W^m Krupp Took me to corner
26-27-34-35 and located
BT made by D.H.V. cut off with
saw at top of ground
Y PINE 8 N 71 E 21 1/2 - IN CENTER
ROAD HAS SMALL IRON DRIVEN
ON SW SIDE

NEW { OAK 12 S 40 E 11 1/2
W PINE STP 36 N 46 1/2 W 120

NORTH FROM THIS CORNER
Between 27-26 VAR 4° E
33.88 FELL 85% EAST OF ORIGINAL MC
SHORTAGE 62 LINKS
1964 SET 1/8 POST
NEW { W PINE STP 30 N 34 E 36
30 N 83 W 31
copied in Book 39-6 Page 109

Sec 23-37-9

WENT TO 1/4 Post BET. 23+26
FOUND POST AND BT MADE IN 1903
NEW { W. PINE STP 12 N 31 1/2 W 19

WEST FROM S 1/4 Post VAR 350' E
41.92 FELL 305 1/2 SOUTH
20.96 SET 1/8 Post
W 1/8 N Line { CEDAR 3 N 70 W 12 1/2

WENT TO DORR'S 1/8 W OF CENTER
POST AND BT OK
RUN EAST VAR 1° E
2096 DORR'S CENTER FOUND
POST AND BTs
NEW { BIRCH 14 58 1/2 W 18
MAPLE 6 62 E 13 1/4

EAST FROM CENTER VAR 1° E
4395 FELL 7 links NORTH
2197 SET 1/8 POST
NEW { W PINE 10 S 60 1/2 W 21
1/8 E OF CENTER { W BIRCH 12 N 56 1/2 W 10 1/2
copied on Page 93 Book 37-9

6 SEC 29-37-10

SE COR. WEST VAR 230' W
2993 FELL 24 S. OF MC
SHORTAGE 3.21 SET 1/8 AT
18.06 AND 14 1/2 N OF RAN.
E 1/8 S LINE } NO BT

EAST FROM CENTER SET BY PHV
41.76 HIT POST VAR 7° E
2088 SET 1/8
1/8 E OF CENTER } JAM STUB 10 S 50 1/4 W 203
 } q. PINE 6 S 21 E 170 1/2
 } NO SCRIBING IRON

EAST FROM NW COR VAR 330° E
8377 FELL 287 NORTH
~~E 1/8 N LINE~~ } NPINE ST 12 N 40 W 54 1/2
 } J PINE TREE 12 S 81 E 126

N 1/4 ↗

NORTH FROM E 1/8 S. LINE VAR 330° E
3756 FELL 11 E

SOUTH FROM E 1/4 VAR 3° E
4063 FELL 62 E
2031 1/2 SET 1/8
S 1/8 E LINE } W PINE ST 10 N 11 E 37
 } NO SCRIB IRON
Copied on Page 117-Book 37-10

SEC 36-35-11 7-19-28

N.W. COR Found J.H.O. SE BT
which HAS BEEN ^{LOW} W, HAS A
W cut in top. W PINE 10 S 41 E 86

SOUTH FROM N.W. COR. VAR 3° 30'
8126 1/2 FELL 221 EAST
FOUND STP OF ORIG. OAK
ORIG. SPRUCE NOW STUB STANDS
S 113 1/4 E 179. DORR'S TAM STUB
N 88 W 49 1/2. CHANGE COURSE 1° 30'
6095 AND 165 3/4 WEST SET S 1/8
S 1/8 W. LINE } NO BTs

4063 1/4 and 110 1/4 W. 1/4 S
W 1/4 } BAL 10 S 86 E 75 1/2
 } " 8 N 67 1/2 W 60 1/2
2031 1/2 AND 55 1/4 SET N 1/8
N 1/8 W LINE } POP 12 S 68 1/4 E 30

EAST FROM SW COR VAR. 330°
4085 FELL 238 NORTH
SW BT OK - NE BT IN
CENTER OF OLD ROAD CUT VERY
LOW

S 1/4 POST } NEW W. PINE ST 30 S 72 E 50
2042 SET W 1/8 S. LINE
W 1/8 S LINE } W PINE ST 14 S 78 1/2 E 9 1/2
 } MAPLE 8 N 25 E 46 1/4
CHANGE COURSE 330

collected in Book 36-11 from 145-6
EAST FROM NW COR VAR 130°
4023 at POST showed low run
BOTH ORIG NERLY GONE
N 1/4 } MAPLE ST 10 1/3 W 23 1/2
 } " 14 26 W 55
2011 1/2 W 1/8 N LINE Book 35-11
W 1/8 N LINE } BIRCH 10 S 23 1/2 W 49 3/4
 } " 10 S 31 3/4 E 49

EAST FROM $\frac{1}{4}$ POST VAR 1° W
 2054 $\frac{3}{4}$ FELL 86 $\frac{3}{4}$ N OF $\frac{1}{8}$ SET, BY DHV
 CHANGED COURSE $2^{\circ}40' = 3^{\circ}40' W$
 2055 FELL 5 $\frac{1}{2}$ SOUTH OF NE COR.
 ALL FOUR ORIG RTs CHERRY
 DOWN SW BIREH STP - Spruce IS
 A STUB. SE BIREH OK

SOUTH FROM NE COR VAR $2^{\circ}30'$
 4003 FELL 29 W
 FOUND NW BIREH NEARLY GONE

E $\frac{1}{4}$ { CEDAR 8 N 71 E 20 $\frac{1}{2}$
 " 8 S 64 E 23
 BIREH 12 S 76 W 34
 2001 $\frac{1}{2}$ SET N $\frac{1}{8}$ E LINE
 N $\frac{1}{8}$ E LINE { BIREH 12 N 8 E 31
 " 30 S 76 W 26

EAST FROM W $\frac{1}{4}$ VAR 2° W
 8204 FELL 35 SOUTH
 CHANGE COURSE $15'$

SOUTH FROM N $\frac{1}{4}$ VAR $2^{\circ}30' E$
 8053 FELL 65 EAST

CENTER: { BIREH 14 N 38 W 27 $\frac{1}{2}$
 OF SEC { " 14 S 85 E 43

DISTANCE TO N $\frac{1}{4}$ POST 4122 } 8053
 " " S " " 3931 }
 " " W " " 4063 } 8204
 " " E " " 4141 }

$\frac{1}{8}$ N OF CENTER AT 2061
 { BIREH STP 12 S 86 W 31 $\frac{1}{2}$
 { ELM " 14 S 32 E 13 $\frac{1}{2}$
 copied in Book 36-11

Pages 145-6 should be in
 Book 35-11

$\frac{1}{8}$ S OF CENTER AT 6087
 { WPINE 10 S 13 E 28 $\frac{1}{4}$
 { BIRCH 12 N 12 W 54 $\frac{1}{4}$

$\frac{1}{8}$ E OF CENTER 6133 $\frac{1}{2}$
 { BIREH 18 S 84 W 23
 { WPINE 10 S 54 $\frac{1}{2}$ E 35

NORTH FROM $\frac{1}{8}$ EAST OF CENTER
 VAR $2^{\circ}25'$
 4060 FELL 8 $\frac{1}{2}$ EAST

EAST FROM $\frac{1}{8}$ N OF CENT VAR $2^{\circ}25' W$
 4124 FELL .03 SOUTH

$\frac{1}{16}$ NE { Hem 14 N 50 W 14
 { BIRCH 12 S 70 E 31 $\frac{1}{2}$

WEST FROM $\frac{1}{8}$ N OF CENT. VAR $12^{\circ}0' W$
 4048 FELL 22 $\frac{1}{2}$ SOUTH

$\frac{1}{16}$ NW { MAPLE STP 10 N 85 W 14
 { IRONWOOD 8 S 27 E 21 $\frac{3}{4}$

SOUTH FROM W $\frac{1}{8}$ N LINE VAR $2^{\circ} E$
 2044 FELL 1 $\frac{1}{2}$ LINKS WEST
 covered on Pages 145-6
 Book 36-11 should have been
 in Book 35-11

8-2-20

WENT TO N $\frac{1}{4}$ WHICH IS IRON PIPE
AND PH VS Y PINE BT WHICH STANDS
N $\frac{1}{2}$ W INSTEAD OF 10 $\frac{1}{2}$ W

WEST FROM N $\frac{1}{4}$ VAR 170' WEST
4067 $\frac{1}{2}$ FELL 13 SOUTH

SW-BT STANDING - A STUB
2033 $\frac{3}{4}$ SET W $\frac{1}{8}$ N LINE
W $\frac{1}{8}$ N LINE { Y PINE 12 N 30 W 12 $\frac{1}{2}$
 { W BIRCH 10 S 56 E 37 $\frac{1}{4}$

SOUTH FROM NW COR VAR 2° E
400 WOLF RIVER

1218 OVER
3700 " SWAMP

4150 FELL 2 $\frac{1}{2}$ WEST

FOUND SW ORIG. BT. IT WAS
DOWN AND HAS CUT OFF 8 FEET
LONG. PROPEL IT UP

W $\frac{1}{4}$ NEW { NEM STP 24 N 1 E 25 $\frac{3}{4}$

EAST FROM W $\frac{1}{4}$ VAR 2° EAST
678 WOLF RIVER

1222 OVER
8138 $\frac{1}{2}$ FELL 366 $\frac{1}{2}$ NORTH
CHANGE COURSE 2° 34

SOUTH FROM N $\frac{1}{4}$ VAR 2° EAST
8184 FELL 199 $\frac{1}{2}$ EAST

FOUND STP OF ASPIN - SPRUCE
OK BUT DEAD - CHOPPED IN AND FOUND
MARKS

S $\frac{1}{4}$ NEW { Y PINE 16 N 46 $\frac{1}{2}$ W 56 $\frac{1}{2}$
 { " 16 N 68 E 58 $\frac{1}{4}$
CHANGE COURSE 1° 24

CENTER { W PINE 48 N 1 E 65 $\frac{1}{2}$
OF SEC { Y " 16 S 10 $\frac{3}{4}$ W 37
 { colored on Pages 141-142

DISTANCE TO N $\frac{1}{4}$ POST 4100 } 8184
" " S " " 4084 }
" " W " " 4036 } 8138 $\frac{1}{2}$
" " E " " 4102 $\frac{1}{2}$

EAST FROM S $\frac{1}{4}$ VAR. 30° E
4145 FELL 10 NORTH
2072 $\frac{1}{2}$ SET E $\frac{1}{8}$ S LINE
E $\frac{1}{8}$ S LINE { SPRUCE 8 N 81 $\frac{1}{2}$ W 9 $\frac{1}{2}$
 { " 10 S 85 $\frac{1}{2}$ E 28 $\frac{1}{2}$

$\frac{1}{8}$ N OF CENT AT 2050

$\frac{1}{8}$ N OF CENT { Y PINE 18 N 78 $\frac{1}{2}$ W 32 $\frac{1}{2}$

$\frac{1}{8}$ S OF CENT AT 6142

{ SPRUCE 8 S 39 E 18
 { " 8 S 88 $\frac{1}{2}$ W 11

$\frac{1}{8}$ W OF CENT AT 2018

{ IRON PIPE

$\frac{1}{8}$ E OF CENT AT 6087

{ SPRUCE STP 14 N 62 $\frac{1}{4}$ W 19

NORTH FROM $\frac{1}{8}$ E OF CENT VAR 1° 34 E

4084 FELL 7 $\frac{1}{2}$ WEST
2042 SET $\frac{1}{16}$ POST

$\frac{1}{16}$ NE { NOT TREES NEAR

SOUTH FROM $\frac{1}{8}$ E OF CENT. VAR 1° 20'

4073 FELL 03 EAST
2036 $\frac{1}{2}$ SET $\frac{1}{16}$ POST

$\frac{1}{16}$ SE { NOT TREES NEAR

SOUTH FROM W $\frac{1}{8}$ N LINE VAR 1° 24 E
4114 FELL 40 WEST PROLONG LINE TO LAKE
2057 SET $\frac{1}{16}$ POST

$\frac{1}{16}$ NW { Iron Pipe

Book 35 - 4

Sec 20-39-10 8-17-20

EAST $\frac{1}{4}$ - CEDAR OK POST COMES
ON EAST EDGE OF CREEK
WEST FROM E $\frac{1}{4}$ VAR 3° E
8223 Fell 750 NORTH OF W $\frac{1}{4}$
WHICH I LOCATED THE BEST I
COULD FROM SEVERAL THINGS. POST
AND ONE ORIG BT THROWN OUT TO
SIDE OF ROAD AND OTHER INDEICATIONS
POST IS ON EAST EDGE OF ROAD AND
NEAR SOUTH END OF CUT
GRAY BOLDER 4 FEET IN DIAMETER
S $54\frac{1}{2}$ E 18 TO NEAREST POINT
A LARGE BOLDER ON WEST SIDE
OF ROAD WITH WHITE STREAKS
N $82\frac{1}{4}$ W 62 TO N END OF BOLDER

WEST FROM NE COR VAR 3° E
7943 Fell 682 $\frac{1}{2}$ NORTH
3971ⁱⁿ and 341 $\frac{1}{4}$ SOUTH SET N $\frac{1}{4}$ NOBT:
1980 $\frac{3}{4}$ " 170ⁱⁿ " " E $\frac{1}{8}$ " "

SOUTH FROM NORTH $\frac{1}{4}$ VAR 3° E
8387 Fell 362 $\frac{1}{2}$ EAST OF S $\frac{1}{4}$
FOUND OLD POST AND USED IT
S $\frac{1}{4}$ { BIRCH 20 N 6 E 82ⁱⁿ
{ ROUND STONE 2 $\frac{1}{2}$ FEET
THROUGH S 82 W 13 TO CENTER

CENTER { BIRCH 20 N 68 E 27 $\frac{1}{2}$
OF SECTION MAPLE 10 S 6 W 7 $\frac{1}{2}$

| | | |
|---------------------------------------|---|------|
| DISTANCE TO N $\frac{1}{4}$ POST 4104 | } | 8387 |
| " " S " " 4283 | | |
| " " E " " 4078 | | |
| " " W " " 4145 | | |

~~Copied on Page 141-142~~
Copied on Page 81

Sec 20-39-10

$\frac{1}{8}$ EAST OF CENTER AT 2039
{ NOTHING FOR BTs

$\frac{1}{8}$ WEST OF CENTER AT 6150
{ New 10 N 8 W 16 $\frac{1}{2}$

$\frac{1}{8}$ NORTH OF CENTER AT 2052
{ BIRCH STP 20 N 35 E 24 $\frac{3}{4}$

$\frac{1}{8}$ SOUTH OF CENTER AT 6243 $\frac{1}{2}$
{ New 10 N 88 W 9
{ Bal 10 N 24 $\frac{1}{2}$ E 14

NORTH FROM $\frac{1}{8}$ E OF CENTER VAR 10° E
4102 Fell 82 EAST
2051 PUT IN $\frac{1}{16}$ POST

SOUTH FROM WEST $\frac{1}{4}$ VAR 2° E
3896 Fell 44 $\frac{3}{4}$ WEST
1948 SET S $\frac{1}{8}$ W LINE
S $\frac{1}{8}$ W LINE { BIRCH 12 N 38 E 23

SW CORNER FOUND OLD POST AND
USED IT
SW COR { New 12 N 35 E 10 $\frac{1}{2}$
{ POCKET COMPASS

EAST FROM S $\frac{1}{8}$ W LINE VAR 5° 30' E
4067 Fell 28 SOUTH
2033 $\frac{1}{2}$ - 1116

of Book ~~35~~ H
of Book 3910

sec 16-39-6

N 1/4 is DORR'S POST AND BT ALSO
MC EAST OF N 1/4 POST
WEST FROM N 1/4 VAR 43°
2061 FALL 16" SOUTH OF DORR'S 1/8 POST
W 1/4 N LINE DORR'S } Y PINE STP 20 N 67 1/2 E 44 1/2
NEW } " TREE 8 S - E 31

NW COR FOUND NE ORIGINAL
ORIGINAL { Y PINE STP 20 N 50 E 44
DORR'S { W " " 10 N 63 1/2 W 17
NEW { Y " TREE 10 S 86 1/4 E 48 1/4

SOUTH FROM NW COR VAR 2° 45' E
2500 POND
3500 OVER
3812 FALL 34 1/2 EAST
FOUND NW ORIG. BT NOW STP
W 1/4 NEW Y PINE 14 N 25 E 77

SOUTH FROM W 1/4 N LINE VAR 2° 15' E
3812 AND EAST FROM W 1/4 VAR 4° E
2061 PREW LINE TOGETHER AND
SET 1/8 W OF CENTER
{ Y PINE 6 S 36 W 8

PROLONG LINE EAST TO LAKE 9.20 Chain
AND SET MC

{ W BIRCH 5 S 31 W 15
{ ASPIN 8 N 8 W 7 1/2

1/16 NW { Y PINE 10 S 11 E 28
copied on page, 65. Book 39-6

SEC= 1-39-6 ^N NOV 29, 1920 15

N 1/4 P. found ^{Stub} NW ^{org} tree NEW

{ PINE 14 S 5 W 13

" " 10 N 70 E 19

Run South Var 3 1/2 E
1200 St Paul RR track

2850 C & NW RR

4346 fell 13 W of S 1/4 P drove an iron
bolt. for post on N line of E+W road
and in center of N+S road
{ Y PINE 16 S 59 W 135
{ FENCE POST 8 S 89 1/2 E 38

S 1/4 P. run E Var 3 1/2 E

3969 HIT found South org tree
down marks ok drove an iron for post
in center of E+W road and made new
bearing { Y PINE 11 N 70 1/2 E 137
" " 5 N 11 W 48

North from SE Cor Var 3 1/2 E

1742 C & NW RR.

4394 fell 65 W of NE Cor found NE + NW
org trees the NE one is broken off 4 feet
above surface. NW one is a stub
6 feet high NEW { B. PINE 12 N 68 E 62
" " 12 S 22 W 40

found an oven rim of 9 LKS Proportional
oven run + Set E 1/4 P at 400' and 59 1/3
E at random The W org SEP is there
and checks with Govt notes. No marks

Pasted in book
39-6
county record

West from E 1/4 P Var 3 1/2 E

7984 fell 46 S. of 1/4 P on the ice
Found the E + West meander corners
on town line and Set NW Cor on ice
Then Set 1/4 P 23 links nearer town
line than E 1/4 P as I found the
town line is bearing N 23 links to
the unit as we go west

16 SEC 139-6E cont SEC 1. 1920

Set center of SEC $\frac{1}{2}$ B. P. 10 N 21 W 65
" " " 12 S $9\frac{1}{2}$ E 26 $\frac{1}{2}$

Dist to N $\frac{1}{4}$ P. 365 $\frac{1}{2}$ Dist. to E $\frac{1}{4}$ Post 3996
" " S " " 3980 $\frac{1}{2}$ " " W " " 3988

West from N $\frac{1}{4}$ Post var 3 $\frac{1}{2}$ E
3487 full 1 LK N of MC. found a shortage
of 13 LKS. Proportioned same & set

W $\frac{1}{8}$ P on N line at 1992 W of N $\frac{1}{4}$ P.

an iron pipe for Post. nothing for bearing.
S $\frac{1}{8}$ on E line $\frac{3}{4}$ W. P. line SEP 18 N 68 E 99 $\frac{1}{2}$
and an iron rod with ring on top
for Post.

Center of SE $\frac{1}{4}$ iron pipe with stake in top

S $\frac{1}{8}$ on west line an iron pipe at fence Post

$\frac{1}{8}$ P E of center an iron pipe

$\frac{1}{8}$ P W " "

center of SW $\frac{1}{4}$ an iron pipe

all these iron pipes are 1 $\frac{1}{2}$ feet

above surface.

East from S $\frac{1}{8}$ P on W line var 3 $\frac{1}{2}$ E

3554 St PRR copied in book 39-6

3682 C & NW RR County record

3997 to $\frac{1}{8}$ P. center of NW at 1968 $\frac{1}{2}$

from S $\frac{1}{8}$ on W line N 946 to C & NW RR

" " $\frac{1}{16}$ P in SW cor

SEC 5 7+8 +36 +7. 38/2 DEC 21. 1920 17

con to 7-8-17. 18

Found SEP of org Birch

Run N. var 4 $^{\circ}$ E

6724 Full 194 E of con to 5.6. 7+8

found NW tree OK SET tree down

Went South and found SEP of NE tree

Set Post $\frac{1}{4}$ P. 4884 N of con &

2540 South of con to 5.6-7+8

Set Spruce 6 S 37 W 68

" " 6 N 26 W 85

N from $\frac{1}{4}$ P between 7+8 var 6 $^{\circ}$ E

2540 full 50 W of corner

Set N $\frac{1}{8}$ P between 7+8 at

1270 N of $\frac{1}{4}$ P Post

W P. 10 N 5 W 03

" " 8 South $\frac{1}{2}$

West from con to 5.6. 7. 8 var 4 $^{\circ}$ E

4132 Full 46 South of $\frac{1}{4}$ Post

Found Birch OK. aspen a stub 10 feet high

Set E $\frac{1}{8}$ P bet 6+7 cedar 16 S 13 E 19

DEC 1. 11

18 SEC 7+8 38 12 DEC 22 1920

Car to 7+8-17+18 found the org LREC
Run N U on 4° E

6724 Full 1.94 E of Car to 5-6-7-8 OK
Went S and found 1/4 Post bet 7+8
and made NEW bearings

{ Spruce 6 S 37 1/2 W 68
{ " 6 N 26 1/2 W 85

Run N from this 1/4 P between 7+8 var 6° E
2540. Full 50 West of Corner.

Connected line South & set 1/8 Post
at 1270 & Equidistant bet 1/4 P & corner
{ WP line 10 N 45 W 3
{ " " S South 1 1/2

SEC 27.38-11 JAN 1921
N from S 1/4 P set by D H Vaughans

Var 2 3/4 E
8335 Full 21 W of N 1/4 P on non pipe
W 1/4 P on Stamp of hemlock
Var 2° 50' E

6225 to Big Lake
8162 Full 258 South of 1/4 P on ice which
& set by proportional measurement
bet meanders

N 1/4 Post ok Run West var 2 50' E
Could not find me it has been
washed away by flooding Lake
so I run west from NE corner to N 1/4 P
and prolonged W same as bear had
done. 4295 to corner in lake
SE corner ok Run N var 0 to W 1/4 P
and prolonged line N

9294 Full 238 E of corner on ice
East from 1/8 P S of center var 2° E

4295
4150
1/45

ISSUE 11
SEC 27-38-11 JAN 24 1921 19

N from S 1/4 P set by D H U var 2 1/2 E
8335 full 31 west of N 1/4 P by dam

North from SE corner var 0
8294 full 238 E of corner on ice which
& set as follows Began at NE corner
and run West corner to N 1/4 P and
prolonged line West to Lake, no me.
Prolonged line on ice & set temp
Run N from SW corner to W 1/4 P and
prolonged line N to intersection
of N line & set NW corner

East from W 1/4 P. OK var 2° 50'
6225 to Big Lake set line stakes and
went to SE corner and run West N
106 to Big Lake full 238 E of NE corner
8294 full 238 E of NE corner, as were
both meander corners original. set
1/4 Post 4227 Picked up E & W
1/4 line and at 8162 full 258 S of E 1/4 P

West from N 1/4 P Down Run this line
& his notes read 4150 me. 4295 to
corner in Lake. Did the long
thing on west line and it checked
up very close and set corner by
skinning the lines together
East from 1/8 P South of center var 2° E
4086 full 112 South of 1/8 P on ice
copied in county record

N from SW corner var
4170 full 88 east of W 1/4 P OK.
Set South 1/8 P on West line on non pipe
Center of See; nothing for bearings
Dist to N 1/4 P 4220 } on page 108
" " S " " 4115 } Post sets in an
" " E " " 4031 } Open Swamp
" " W " " 4031

20 See 27-38-11 east

East from $\frac{1}{8}$ P N of center var $1\frac{1}{2}$ E

3972 full 219 N of $\frac{1}{8}$ P

$\frac{1}{16}$ P in NE $\frac{1}{4}$ $\frac{1}{8}$ P N 76 E 141 $\frac{1}{2}$

north from $\frac{1}{16}$ P var 2^o

1815 full 17 W of $\frac{1}{8}$ P

N from $\frac{1}{8}$ Post west of center 35^o

3563 full 39 E

East from N $\frac{1}{8}$ P on west line

5767 full 13 N $\frac{1}{16}$ P in NE $\frac{1}{4}$

Posted on Page 133 Book 35-10

SEC 19-39-11 Feb 21-1921

W $\frac{1}{4}$ P is center of E+W + N+S Roads

Run N in road

3995 HIT IT. Set N $\frac{1}{8}$ P on W line

E from NW corner in Road
5900 to N $\frac{1}{4}$ P. Foundation corner of 1082
Proportioned corner and Set

W $\frac{1}{8}$ P on N line at 34.51 E of NW corner

East from N $\frac{1}{4}$ Post

3984 to NE corner. Set E $\frac{1}{8}$ P on N line

South ^{From} NE corner var 4^o E

2156 full 78 E of MC OK BY DHV

Set N $\frac{1}{8}$ P on E line W in 10 N 67 $\frac{1}{2}$ 31

6 S 63 E 27

East from $\frac{1}{8}$ P N of center by DHV var 1200 E

3972 full 219 N of $\frac{1}{8}$ P

Set $\frac{1}{16}$ P in NW $\frac{1}{4}$ $\frac{1}{8}$ P in N 76 E 141 $\frac{1}{2}$

north from $\frac{1}{16}$ Post var 2^o E

1812 full 17 W of $\frac{1}{8}$ P

E from N $\frac{1}{8}$ P on west line

5767 full 13 N of $\frac{1}{8}$ P W of center

Copied in County records

in Book-39-11 on Page 77

SEC 14-35-10 April 1, 1921 ²¹

Began at E $\frac{1}{4}$ Post

and run ~~North~~ var $3\frac{1}{2}$ E

3940 full 57 E of corner OK

Set N $\frac{1}{8}$ P on E line at 1970

Spruce 7 S 76 E 17

West from this $\frac{1}{8}$ Post var $3\frac{1}{2}$ E

Same course as N. sec. line

1500 to Lake

Then Run N from $\frac{1}{8}$ P on two lines

420 and Set Post. Then West to Lake

1075 and Set Post. This line cuts

off 5 acres from the South Part of

lot 4. leaving about 18

acres in north part of lot which

is at this date the property of a

Mr. Roder of Manito

Wauwatosa ^{Part}

Posted Page 57 Book-35-10

SEC 12-35-10 April 2 1920

Page 133

SEE book #2 for former work

Set $\frac{1}{8}$ Post S of center from my

Random. See Book 8 Page 133

Birch 10 S 82 E 28

10 N 24 E 10

Run E from this $\frac{1}{8}$ P var 00

2144 to $\frac{1}{16}$ P in SE $\frac{1}{4}$

Set on top Pipe $\frac{1}{4}$ x 30 inches

at $\frac{1}{8}$ P S of center and at center

March 26-21

SEC 12-35-10 April

Set $\frac{1}{8}$ Post south of center

Birch 10 S 82 E 28

10 N 24 E 10

Posted in Book 35-10 Page 57

22 SEC 29.36-8E Apr 7- 1921

Went to center of section in road marks are gone from StP of Dams BT changed E from W 1/4 P (OK) to 1/8 Post west of center which I set nearly 20 years ago and then E to center and found Dams BT. StP. Set Post and Ames 15 to Place an iron for Post Run N from center var 2° E
3945 fell 129 E of Dams 1/4 Post. OK
Post Set 1/8 P. N of center Nothing for bearing. Ames is to Put on iron monument for Post Run W from 1/8 Post var 3 1/2 E
750 Enter wet marsh
1600 over PAGE 157. Book 36-8
2000 Set Temp 1/16 Post

SEC 33-38-8 Apr 4. 1921

NE cor Cedar Post and StP & Stub org
Run South var 3 1/2 E

1600 leave Swamp Parted on Page 133

4000 1/4 P gone

7911 fell 93 E of SE. Corner which

I set from orig BT 15 years ago found Post rotted & broken

Set E 1/4 P at 3955 1/2. Made NEW Bearings W.P. StP 16 S 64 E 29
16 S 29 W 41 1/2

West from E 1/4 Post var 3 1/2 E

8072 fell 169 South of W 1/4 P my Road

found StP of org. tree but marks are gone. but I set this Post several years ago. and saw them make a fence from it west and my line of stakes

Dec: for correction 1.23 50
change Course 2.10' Book 38-8

8172

SEC 33-38-8 cont

23

N 1/4 P found it down relocated it as near as possible and made new BT

W Pin 8 S W 65 W 53.

South from N 1/4 Post var 3 1/2 E

650. Lake 1036 over lake by Studio

7856 fell 227 E of 1/4 Post I set 15 years ago by running from SW to SE corner

DECIMAL for correction 2.90 N 1/4 W 52

center of Sec. W Pin StP 26.8 B W 52

dist to N 1/4 Post 3864. To E 1/4 Post 522 4044

S " " 3986 W " " 4128

1/8 P E of center W Pin of P 16 S 85 W 45

N. from 1/8 P east of center var 2° E

3992 fell 13 W of E 1/8 P on N line in road

made NEW BT. W.P. StP 12 N 12.37 1/2

1/8 P N of center Tam 6 N 15 W 32 W.

6 S 32 1/2 E 22

N 1/8 P on E line gray bolder 3 1/2 x 5 1/2 with

small hole out S 42 1/2 W 59

East from 1/8 P. S. of center

4068 fell 27 N of 1/8 P Parted on 133

W 1/8 P on N line found StP of Heron

BT that I made 18 years ago

Set Post in center of road Book 38-8

Run South var 2° E

(Apr 20 - 1921

See 8 - 36 - 7.

Down Road for Town of Woodboro.

Come at a point on Sec line bet 5-8

10.75 East of N 1/4 cor of Sec S 4 Pin Pole 80-E-82.

Thence N. 87. E. 320.

S 50 E 985.

S 63 E 205

S 55 E 300 to center of creek

Posted
05
03
03
06-7

Sec 8-36-7- Apr 20-1921

Went to N. 1/4 cor. and run East bar 3° E
2242 Lake West and set 1/8 post at
20.00 W.Pine St 16.890 E 45 1/2.

Surveyed a piece of land as followed

Beginning at a Point 3.50 ch South of
E 1/8 P on N Line

Thence South on Temp. 1/8 line 4.00

Thence East right angles. 500

" N Parallel with 1/8 line 4.00

Thence West to Place of beginning 500

Post on Page 33
Book 367

SEC 18 36 8 SEPT 26 1921

8 SET 1/16 Post in S.E. 1/4 in 1905
Darr + Monell had set the center
of section + the 1/8 P N of center.

and East of center and South of center
I had run the South line from me
East to 1/4 P and from 1/4 Post E to
S.E. cor + set E 1/8 P on South

line and as the S 1/8 Post on E line
and the South 1/8 Post on West line
are both in lake I set 1/16 P in S.E. 1/4
Equidistant bet 1/8 P S of center and
E 1/8 P on South and surveyed a line for
road from 1/16 P West to 1/8 P South of
center. This was done in 1905

The road is now in use
To day I set Flag at 1/16 Post and
instrument at 1/8 P South of center and run
line West to Lake and set one corner on
W Pine Stump 16 N 6 E 12 links

Post on Page 36-7
Book 367

Parted on Page 13 Book 36-7
Survey of road for

for Town of Woodboro
April 28 1921

commencing at NE cor. of sec
3-7.36-NR-7E

Thence S. on section line bet
2+3

900 interest the woodboro road
on old R.R. grade

3100 to Lake
4030 full 1.04 E of 1/4 Post ok

Corrected line from woodboro
road N to corner for road for the
Town of Woodboro

SEC 3. 38-7 April 29-1921

Began at NE corner and run South
on E line

1389 to bar 1/8 P. iron pin + Bm
3362 set 1/4 Post line. Two poles S.W. 72

6362 found bar S 1/8 P. BT ok
found an angle in line of 1/4 P.

Set new Post and corrected line
N. to 1/4 Post

May 2, 1921. SEC 10 38-7
Went to SW corner found fence

Post, for Post + SEPs of org BTS they
are rotten + nearly gone but they
are ok. AT Wood Smith at my

request, perpetuated this corner and
to Ld my H placed the line Post where

The original corner stood I had set a
new Plat M 1899 From org tree

when I surveyed the Tomahawk Lake
and Hazelhurst road

Run E on 345 1° E.

4089 Full 75 N of Iron Pipe bar
to be the 1/4 Post think it is ok

East from South 1/4 Post var 1° E

3956 full 125 S. of SE corner

4030 3936 ok

26 SEC 3-38-7E cont. May 2-1921

f found Post down but rock
Placed around where it stood found
Stp 2 of orig trees

Dam Sit this Post in NOU 1893
and placed rock around it
SEC. 250

SEE E 1/8 P on South line B. oak 10 S 2 E 38
~~E 1/8 P on South line~~

W 1/8 P on S. line & Ashen 8 N 4 E 28
Part of 13 Book 38-7

N from SW corner var 2 1/2 E
1910 full 38 West of Dams 1/4 Post 1/8 P
found Dams bearing a
& W. Pin Stp 30 N 55 E 44

connected onto this 1/4 and Reel
Prolonged connected line N.

300 to flowage. Sent flag to
To N Side of flowage and cut out
the line To Top of hill. did no chain it

SEC 10 38-7 May 3 1921

W 1/8 P on N line. S. var var 3 1/2 E
39.87 full 72 E of 1/8 W of center
& had placed flag at W 1/4 P.
and center of see set by Dams

(I had run this line 3 years ago
for a road for Town of Tom's Lake)
Placed instrument on line bet flags
and chained from W 1/4 P. to center
distance 4039. Set 1/8 P at 20 19 12
{ W Pin STP. 30 S. 33 E 49 1/2 38 7
Parcel Pay 44 Book

Set 1/6 Post in NW 1/4 Ashen 7 N 44 E 31
1/6 P in NW 1/4 E var 1 1/2 " 8 N 50 W 49
2030 full 64 S. of Dams 1/4 P N of center
1/8 P N of center E var 3 1/2 E.
1987 full 12 N of a Point where
this should be. It may not be exactly

Copied on Page 41. Book 38-7
SEC 10 38-7 cont apr 3 1921

27

Run N from Temp: 18 P var 4° E

~~2030 full to 1945 full 155 W of 1/8 P~~
Corrected all lines run in N 1/2 of
See 10-38-7

SEC 6-39-12 May 9-1921
Began at W 1/4 P found St P of
Pink org brick marks ok thick
Run N var 4° E very
under growth and rough ground
200 Enter Swamp 2300 Less Swamp
3787 full 37 1/2 E of corner. found
Old Post. NE org. two ok & green
SE org brick is down marks ok
Other trees gone just rotten St P?
Went S & set S 1/8 P Post on line
found a shortage of 19 LKS.
Set 1/8 P at 19 90
W. Pin stub 24 S 20° E 42

NW cor in center of E+W & N+S Roads
org: bearings gone
Chained South in road to SW
corner also in road but had marks
on stump 278 South and bound it
7610 between corners set 1/4 P at
3809 TL Pole N 34 1/2 E 53 3/4 at SW cor
3805 N Pin St P 12 N 48 W 43 1/2
S 1/8 W line TL Pole 10 S 86 E 29
W Pin St P - N 80 W 31
Placed iron rods at SW cor. W 1/8 P
and 1/8 S 1/8 P on W line
East from W 1/4 Post var 3 1/2 E
7492 full 86 S of Dams 1/4 P OK
S 1/4 P found Dams Post + BTE
Run N var 3 1/2 E

200 Tolake
2700 Oak Lake
7881 Full 505 West of Dams 1/4 Post
Found long St P Post & placed
an iron pipe 1/2 inch x 36 in for Post
center of SEC: Iron Pipe 1 1/2 in by 36 No BT
Dist: to N 1/4 P 3860 } 1 1/8 P
" " S " " 4021 } N of center
" " E " " 3688 } W P St P 14 N 7 E 44
" " W " " 3804 } 12 S 5 E 11
Placed iron man. at S 1/4 P
center of line N 1/4 + 1/8 P No center
Copied on Page 45 Book 37-9

Began at Dams 1/8 P on South line
found his bearing, made 30 years ago
Set new Post and made new bearing
W.P. Pin St P 28 S 67 1/2 E 10
Run north var 10.45 E
810 center of 500 RR
8323 Full 37 5 1/2 W of Dams E 1/8 P N line
Found both of his bearings, set
NEW Post and made new bearing
Sugar 16 S 75 E 42
D.L. 453 change course 2-36'
connected line S. to R.R.
S 1/4 P OK Run N var 10 1/4 E
8329 Full 105 W of Dams 1/4 P Found
both of his B.T. No Stump, remarked that
connected line S to 1/4 Post.

N 1/4 P East var 445
2472 1/2 Full 55 1/2 N of Dams 1/8 P
connected line W to 1/4 P
Oct 18 - 1920
East from E 1/8 Post on N line var 4 1/2 E
2472 full 8 LK South of corner
Found SETREE down + rotten
marks OK found Point of 09 Post
Set NE POST + made NEW
bearings. W.P. 24 S 37 E 75
Sugar 8 N 85 W 18
center of SEC: W.P. 30 N 23 E 27
1/8 P N - center W. Pin St P 10 N 5 W 25
1/8 S of center " " 24 S 42 1/2 E 18
copied on Page 29 Book 36-8

copied on Page 79 Book 36-8

May 12 - 1921.

Commencing on the line
between ~~between~~ Sections 25 & 26 in
Township 37 N R 8 East and 31 chains
N of corner to 25-26-35 & 36 237"
Thence N 21° E 110 4° E 575"
" " 50 " " " " 310"
" " 34 " " " " 370"
" " 64 " " " " "

Wild Wood Road May 14 1921

Commencing at a Point on Secⁿ
line between Sec^s 23 & 26. 170 E of 1/4 P
Thence N 31° E 110 4° E 545 chains

| | | | |
|---|-------------|----------|------------|
| " | North | 450 | " |
| " | 80 E | 200 | " |
| " | North 1/2 W | 800 | " |
| " | 38 W | 280 | " |
| " | 18 " | 175 | " |
| " | 52 " | 170 | " |
| " | | 445 | " |
| " | N 31° E | 110 4° E | 545 chains |
| " | 80 E | " " " | 450 " |
| " | 80 E | " " " | 200 " |
| " | 80 E | " " " | 300 " |
| " | 38 W | " " " | 280 " |
| " | 18 " | " " " | 145 " |
| " | 5 " | " " " | 170 " |
| " | 32 " | " " " | 445 " |

May 14 1921

Copied on Page 50

BOOK 37-8

All copied
on Page 50
Book 37-8

Commencing at a Stake which
stands on Southeast corner of State
Highway and - Charns meadow
from the north line of Secⁿ lot 7
Thence South westerly along and
Southeasterly line of said Highway

As The Section corners and
1/4 Posts are said to be obliterated
by fire and time, I began at the
corner of § 15-16. 21-22 which is
OK. and run N Var 4.25' E

3968 found orig. 1/4 Post on line

4900 Enter Swamp 5600

5600 intersect Lake Post on Page 37

6100 over Lake BOOK 39-9

7936 found what I believe to be the

orig. and corner to 9-10-15. 16 set

Part and made new RT 27 Pin 8 N 52 1/2 E 24

16 S 27 1/2 W 11

Run West Var 9° E. 70 LKS to Swamp

4000 did not find 1/4 Post

8000 " " " Corner to 8. 9. 16. 17

10800 To outlet of Dam Lake

111.11 over outlet. Runned had to quit

Do not know when I will begin again.

Found corner of Sec 8-9-16-17 and

Dave's post. new B.T. { Humlok 18 N 54 E. 34.

East and set 1/4 cor. { W Pine 15 N 60 E. 24

" " " " { " " 8 S 51 W 41

North from SW cor Var 3 1/2 East

7992 fell 12 W of cor Org B.T. Jam down

new B.T. { Spruce 9 S 37 E 11.

West 1/4 cor. { W Pine St. 20 N 79 E 26

" " " " { I think this is good B.T.

SE Cor n. Var 3 1/2 E.

7992 fell 31 West of Cor set by L.V.

from old B.T. rotten and almost gone

new Post Iron Post and BT { W Pine 10 S 60 W 64

" " " " { W Pine St. 16 S 17 1/2 E 26

NW Cor East Var 6.55 East

7941 fell 4 S of Sec cor. set by L.V.

West and set 1/4 cor Iron Pipe

West 1/8 on S Line { W Birch 3 N 31 W 5

2 in Pipe { W Birch 6 N 40 E 18 1/2

E 1/4 cor { W Pine 10 S 55 W 40

Center of Sec { Tur 14 S 62 W 88

" " " " { W Pine St. 6 S 26 E 54

" " " " { Oak

1/8 N of Center W Birch 8 S 10 E 25

S 1/8 on E Line { Aspen 10 N 56 W 24

" " " " { " " 6 S 22 E 12

East 1/2 on S Line { Aspen 10 N 89 E 20

" " " " { W Birch 6 S 65 W 26

Sout fr m supposed MC on E line

Var 4.15 E

2270 fELL 2.65 E of The org Line
on a 12 inch J. Pine

Run South from This tree Var $3\frac{1}{2}$ E
at 7550 South of MC intersect Swamp
" 3445 " " " leaw Swamp

6770 found Evidence of org corner
also had found old line in
Several places. ansure it is

The original line

went back to 2270 and set 1/4 Post in
Swamp 4030 N. of SE Corner on Iron
Pipe 66 feet long. and prolonged
line from 2270 N to Shore of
Crawling Stone Lak 6870 N of SE
corner. on iron pipe set in cement
set a post on iron pipe in cement
275 South of MC and run west at
right angles to E line
2000 set on iron pipe in cement
and run N 9.93 to crawling stone
" set an iron pipe in cement
Prolonged line South from
The iron pipe which is 9.93 South
of mc. 2645 and set post on
iron pipe in cement at SW corner
of Lot 5. and run \perp E at right angles
1999 $\frac{1}{2}$ to E 1/4 P of Lot 5

115

Org. corner found

Notes

by H.C. Hall

SEC: 2436-7 JUNE 6-1921

S 1/8 P on E Line found my NW BT and Post set in June 1914.

SEE County record (Dorrs Book) Page 49. Chained west in road 20 on South 1/8 line 2078 and set Temp 1116 Post in SE 1/4

Went to S 1/8 Post on west line. found stumps of both of my B.T.s Chained South in road on west line 2027 to Loc at SW corner an iron Pin East from SW corner Var 1° E. Same corner as South 1/8 line. Rained came home at 12 M.

June 8"

150 Enter Swamp

350 Leave Swamp

6500 Swamp on stream runs South

9247 full 143 N of SE corner. found Post & set 14 1/2 years ago. only BT's still ok but badly burned some as stumps Set E 1/8 Post on S Line W Pin set P 1/4 S 14 E 22 North from E 1/8 Post 1 " " 15 N 9 E 21 1/2 on South line var 4° E.

2012 full 26 W of Temp 1/16 Pin SE 1/4

Corrected onto 1/16 P and prolonged Lin N 1202 to Lake

Set Stak 308 E of 1/16 Post and run N 96° to Lake Parallel with 1/8 line already in this strip is 3.27. Had to get 10 acres altogether. Set a Stak 333 E of 1/16 P and run South Parallel with 1/8 line to South 333 E of 1/8 Post

Copied on Page 24 Book 367
County recordRoad for TOW of Lynn BETWEEN³⁷

1313 2.29 + 30364 June 19 21 22
Set Post from St of Birch org two
Run N bet 29 + 30 Var 4° E
15756 full 29 E of Carb 16.17.19-20 found
Step of Sugar org two did not
correct this line as it is nearly all
Swamp had new bearing to
corner 29-30-31.32
1/2 Birch 15 S 72 1/2 W 71

Copied on
Page 19
Book 367
County record

SEC: 19 + 30 35-5 JUNE 23-1921

Began at corner to 24-25.19-130

Township 35 N Range 4 + 5 E

Run E Var 4° E

4286 full 46 1/2 S. of 1/4 P. found ST P of Hemlock org L & C Corrected line here for road for Town of Somers

SURELY of Road for town
of Lynn bet. Secs 26 + 35-36.4
East from corner to 26.27-34-35 Var 4° E
7646 full 106 N of Car found 2 of trees
Set a large cedar Post.
Set 1/4 Post bet 26 + 35 NO BT'S
Road overseer agreed to place
iron monuments for 1/4 P and set
iron mon: 50 LKS N + 50 LKS S of Post
& set these points by small stakes

North from 1/4 Post bet 26 + 35
8084 full 369 W of 1/4 P found the
Sugar down but marks ok
either gone, corrected line South for
Road.

12-36-1
Section 35

38 SURVEY of Road for Town of

NEWbold May 27. 1921
commencing at the corner to
15-16. 21 + 22 - T. 37 N R 8 E

Thence north on section line
2975 chains copied on Page 151 Book 37-8

Thence N 45 1/2 W Var 4° E 5.55 chains
" " 48 " " " 1005 "
to an old road + set stake and
made bearing } Pine S 31 1/4 S 5 E 83

SEC 2+3-35-4 + SEC 34+35 in

36-4 Chained E from corner to
33 + 34. 36-4 to corner to corner to
35 + 36 - 36-4 and set corner to
34 + 35 - 36-4 in edge of Stream.
nothing for bearings

SEC 26 + 35 - 36 4

Began at corner to 26. 27. 34 - 35
on iron monument Run E Var 4° E
4000 Could not find 1/4 Post but am
on the original line

7636 F W 106 Not corner OK set a large
Cedar Post for corner

Went West and set 1/4 Post between 26 + 35
and on original line. Set a small Post for
1/4 P and a small Post 50 links N + 50 Lk. S S
The chairman said he would have iron
monuments placed at The 3 Points
mentioned at 1/4 Post

North from 1/4 Post between 26 + 35
Var 4° E
8084 feet S 69 W of 1/4 P found the Sugar
down but marks OK

Posted on Rays 77 Book 36 1/2

SEC 11. 39-6 June 4 1921

39

SURVEYed a Piece of Land in
lot 4 as follows
Commencing at a cedar Post
which stands N 47° W and 1300 feet
from the South 1/8 Post between
said section 10 + 11. N 47 W 75 ft
Thence N 43° W 60 ft. then S 43°
E 60 ft + 187 = 247 to a stake
which stands on shore of Lake
Thence Southeasterly on shore of
Lake 75 ft. Thence N 43° West
198 feet to Place of beginning

WILLOW LAKE ROAD

Town of Lynn June 13 1921
Began at corner to 27 + 28 - 33 + 34
and placed iron monuments
at all the corners North to and
including town line bet Towns
34 + 35 Range 4. Post at an angle 146. Town of 36-4

SEC 20-39-5 JUNE 29-1921

Went to NE cor. found both orig trees
down marks OK Run South Var 4° E
39.26 FELL 156 1/2 E of 1/4 Post. found
an old Post marked 1/4 S also
found stump of orig tree. set
Post and made NEW bearing
W Pine 11 S 44 W 54

corrected Random on to this 1/4 P
and run south on corrected line

300 west bend of Squirrel River
1963 set Temporary 78 Post marks
West from E 1/4 Post var 3 1/2 E
100 Enter swamp copied on Page 81
2979 L G Ave Swamp Book 39-5
5000 Enter open marsh
over

6159 Over Swamp

7924 full 478 S. of 1/4 P. 2. org trees ok
SE & NE Pos. DEC: 6.032

SE 1/8 P W of center at 5943. NOBT
North from 1/8 P W of center via 3 1/2 E
which is parallel with West Line
The course of E + W 1/4 Line is 0004
to be continued SE Edge
- as per on Page 81 Book 39-5 -

SEC 29-39-11 JULY 5 1921

Survey of road for 3 Lakes

commencing at a point on the
South line of Section 25. T. 39. R. 11

3.00 West of South 1/4 Post

| | | | |
|----------|--------|---|-----|
| thence N | 32 | E | 321 |
| " | 35 | " | 374 |
| " | 33 | W | 554 |
| " | 44 | " | 248 |
| " | 12 1/2 | " | 410 |
| " | 22 | " | 285 |
| " | 24 | " | 518 |
| " | 64 1/2 | " | 293 |
| " | 41 1/2 | " | 357 |
| " | 60 | " | 665 |
| " | 68 | " | 136 |

To Donnellys E + W 1/4 line in 29
courses and distances given as the
center and line of road
magnetic courses only given and
var. 3 1/2° E

M. C. on E shore of Lake on S. Line
did not find it. but found an old
fence that several told me was
gone before me. was gone. Ran East
on line of fence

200 of fence bears N of Line
2500 Enters swamp
7362 full 259 N of SE CO OK have
USED THIS COR SEVERAL TIMES
STPS of org trees ok but marks gone
Found an over run of 28 LKS
Proportioned same and set S. 1/4 P.
at 4015 1/2 and 3347 E of M.C.

July 19

Set S 5 N 64 1/2 W
Tam 5 S 15 E 5 1/2

Set W 1/4 P on line 1340 W of line an iron
bolt 36 x 3/4 inches a dark gray boulder
2 1/2 x 2 1/2 feet. 1 1/2 feet above the surface
bears a white vein near center on top
of boulder, bears 18 W 54 LKS distant.
NE COR found stp of cedar, Tam: down and
rotten, also found old Post
Run south var 3° E as per on page 77-78
7.00 Leave swamp, hard cutting
9.00 Enter " " Thick timber
2400 leave timber enter open swamp

JULY 20

8133 FELL 332 W of SE Cor
DEC: for connection 4.100
Set S 1/8 on E Line 2033 N of SE Cor
nothing bearings all open swamp
SE 1/4 E 1/4 Post at 4066 Nothing for BT's
" N 1/8 P on E Line Birch 8819 W 1/2
35-11 mark. & N. 42 E 12

NE COR NEW Birch 10 N 61 E 24 1/2
Cedar 10 S 56 1/2 W 16
Run W on 1/8 W var 4° E.
and at Right angle with East Line
over

SEC 19.35-11-E Cont. July 21-1921
~~SEC 20.39-5 cont. July 21-21~~

20.00 am on orig line and have been
 ALL THE WAY FROM NE COR.
 at 888 NE COR of cemetery
 off sec 12 lks to MISS TREES
 300 C & NW RR
 3400 State Highway
 3665 S of 17c 25 lks E of water line
 on E shore of PELICAN LAKE

BOOK 10 N 4 1/2 W 20 1/2
 14 S 31 E 36 3/4

E 1/4 P. Rim West on an intermediate
 course bet N + S Sec. line angle 90.10
 1600 LEAVE SWAMP and climb Hogs back
 1950 over hogs back & enter SWAMP
 3907 center of C & NW RR
 4125 State Highway
 4687 S of ME 50 lks E of water line of N.C.
 PELICAN LAKE

This is the line bet lots 2 + 3

9 fmd in running the N + 1/4 line
 is the E line of lot 5 and it must
 extend north until it intersects S. LAKE
 and find the E-W 1/4 line intersects
 the E line of lot 5 40.66 N of S. 1/4 P

F 1/4 Post. W. Cont. on Pages 77 & 78 Book 35-11
 1600 LEAVE SWAMP to Hogs back
 1950 over " "
 3900 C & NW RR
 4015 full 3 1/2 S. of a point where 1/4 lines
 intersect. 317

N from S 1/4 P.

1650 LEAVE SWAMP to Hogs back
 2100 over Hogs back & enter SWAMP
 4066 full 4.11 E of center of section
 which is on W Side of S of State Highway
 30 LKS

Continued July 25 1921

S of 1/8 Post. S. of center No B.T. near
 Rim E From 1/8 P South of center Va 208
 550 LEAVE SWAMP to Hogs back

700 over hogs back to SWAMP

4015 full 179 1/2 N of 1/8 Post

Corrected line W to 1/8 Post and
 Prolonged corrected West 1233
 to Lake marked a W Bch 16 inch
 in diameter for the Post.

Total Length of South 1/8 line is 5248

S of E 1/8 Post on South line 2007 1/2

West of SE corner

Corrected E-W 1/4 line prolonged it
 West from center 672 and marked a
 W. Bch 8 in in dia for the Post

Total length of E 1/4 line 4687

the course of S 1/8 line is Var 15'E
 and is Parallel with S Line

N 1/8 P on E line run West on an
 intermediate course bet E + W 1/4 line
 and N. Sec line

840 to Hogs back 100 wide

3250 C & NW RR

3310 State Highway

3735 LAKE + set an iron bolt 36 x 3/4 in
 Set iron monuments at all meander cor
 S 1/4 1/4 + 1/8 P S. of center

Finished July 26-1921

Copied on Pages 77 & 78 Book 35-11

N $\frac{1}{4}$ P is in River. found Me. 5.50 E

Run S. and W. 550. am opposite of
N $\frac{1}{4}$ P and 587 S. of it and running
South var 3 $\frac{1}{2}$ E

4700 to State Highway

7994 fell 276 E of S $\frac{1}{4}$ Post by C. D. Vaughan

Dec. for conction 3.452.

change course 1.59'

E $\frac{1}{4}$ P. found Str. of org: Pine mad.

NE W. 1/2 Pine 12 N 29 $\frac{3}{4}$

Run N var 3.30. E

2490 Stram 30. Run W

4407 fell 82 W of cor: in center road

Post sets on N side of road 30 links
from center of road of
found a shortage of 146

Set N $\frac{1}{8}$ P at 1935 $\frac{1}{2}$ + 36. E. of Rand

E $\frac{1}{4}$ P. Run W 5° W as 8 was told it was
NECESSARY SO TO DO

7005 of 6 set N to miss barn

8000 set line stakes and went to SW cor

set by C. D. Vaughan by m direction

found his cor: 347 W of his Random

and his S $\frac{1}{8}$ P on W line 244 W of "

chained N. on his random 2979 $\frac{3}{4}$

and set W $\frac{1}{4}$ P. 1.41 W of his Random

$\frac{1}{2}$ W Pine 10 S 35 $\frac{1}{2}$ E 72 $\frac{1}{2}$

Picked my Random from S. 14 Post

and at 8120 fell 277 N. of W $\frac{1}{4}$ P

DEC 2672. Set center. Nothing

For bearings. dist to N $\frac{1}{4}$ P 3804

" " S " " 2176

" " E " " 3963

" " W " " 4316

Set $\frac{1}{8}$ P. N. of cent. nothing for B.T.s

E. from $\frac{1}{8}$ P N of cent var 3 $\frac{1}{2}$ E

4022 fell 460 N of $\frac{1}{8}$ P in fence

No bearings

School Ground at Star Lak

To arrive at Place of beginning.
Began at N $\frac{1}{8}$ Post between sections
14 + 15 Township 41 N Range 8 E.
Thence South on section line
847. Thence E var 4 $\frac{1}{2}$ E 20.26 to a
stake which stands 37 $\frac{1}{2}$ N of center
of State highway, or town road. and
is the Place of beginning.
Then West Parallel with town road
3.16 $\frac{1}{4}$ Chains. Thence at right angles
3.16 $\frac{1}{4}$ " " E. " " "
3.16 $\frac{1}{4}$ " " S " " "
3.16 $\frac{1}{4}$ " To Place of beginning
Containing one acre

SEC 3-35-8 Aug 1st 1921

Went to MC on Left bank of River
 which is 550 E of $1/4$ P in river
 and run S.W. by RT. angles UNTILL
 I was 587 S. of and 550 W of MC
 Run South Var $3\frac{1}{2}$ E
 $4113 + 587 = 4700$ Set at Highway
 7994 Fell 276 E of $1/4$ P set by C.D.U
 Dec. 3, 452. change course 1.59"

E $1/4$ P. found stump of org Pine. Set
 NE Post in new BT Pine 12 N 21 W $39\frac{3}{4}$
 Run North Var 40 E

2420 Strain 30 course west
 4404 fell 82 W of Cor in center of Road
 The Post is moved 30 Lks. N.
 Found a Shorbag E of 36 Lks
 Set N $1/8$ P on E Line at 1935 $1/2$
 and 36 E of R Nothing for BT.

E $1/4$ P West Var 5 W.
 5705 off set N 100 To miss Barn
 8000 Set Line Stakes, and went to
 S $1/8$ P on W Line set by C.D.U
 I had his NOTES. found He had
 set S.W. Cor 347 W of Random
 and had set his $1/8$ P at 2179
 N. of corner and 244 W of Road
 Chain N on his Rand: 2179 and
 set W $1/4$ P at 141 W of Rand

1V Pine 10 S $35\frac{1}{2}$ E $72\frac{1}{2}$
 Picked up my Random at
 8120 fell 327 N of $1/4$ P. including off Sec
 Dec 2672 Set Center Nothing for BT
 Dist: to N $1/4$ P 3804
 E " " 3963

found a Shorbag bet. Center & N $1/4$ P
 of 888 Set N $1/8$ P North of Center
 at 2176 S of N $1/4$ P in River.
 E from $1/8$ P Not Cent Var on
 3665 4022 F 70 Lks N of $1/8$ P
 corrected line west to $1/8$ P

Aug 8-1921

SURVEY of Road for Town of NEWbold

Began at $1/8$ P N. of center of Sec 27-38-8
 Run N Var $3\frac{1}{2}$ E
 1936 fell $35\frac{1}{2}$ W of $1/4$ P bet 16 + 21 38-8
 found this $1/4$ P was set by Dorr
 from org BTs NEW WP inc stp 16 N 33 E 61
 $16532E61$

WP inc stp 16 S 50 W 56
 corrected Line South to $1/8$ P for road
 SEC 16 38-8 August 8-1921
 S $1/4$ P NEW WP Pine stp 16 N 33 E 61
 Cahell on Page 178

RUN N Var 20 30 E
 3760 fell 105 $1/2$ E of center by Dorr
 Found his BT WP Pine stp 26 N 83 E 23
 Set $1/8$ P. South of center at 18.80 and 67
 $52\frac{1}{2}$ West of Rand Book 38-8

corrected on to dorrs $1/4$ P and
 Pro Longline N Var 4 10' E
 166 To Swamp and W End of Lake
 598 over Swamp & Lake
 3975 FELL 24 E of N $1/4$ P. found Dorrs
 BT J. Pine stp 16 N 45 W 38 found his post
 down + rotten. Set $1/8$ P. Post N of
 Center Nothing for bearings
 corrected line from center S to S $1/4$ P
 for Road for NEWbold

SURVEY of Road for TOWN of NEWbold
 commencing at a Stake which stands
 on N + S $1/4$ Line in SEC. 16 Township
 30 N. R. 8 E 30.62 chains N. of South $1/4$ Post
 Then west Var $3\frac{1}{2}$ E 7.30 chain
 " N 12 15' W 2.97 "
 " " 37 " 4.98 "
 " " 11 E 1.99 "
 " " 15 " 3.60 "
 " " 70 " 4.59 "

SURVEY of ROAD FOR NEWBOLD Cont^d

These N80 E 160
 174 " "51" 190 Post 38-8
 " "82" 266 TO N+S 1/4 Line
 1189 S of ~~1/4~~ of 1/8 P N of Center
 Corrected Road line on N+S 1/4 line
 Completed Aug 10 1920

also commencing at the 1/8 Post
 north of the center of Section of
 Section 21. Township 38. N. R. Aug. 8
 East. Thence north on 1/4 line
 line 193600 chain to the 1/4 Post
 between Sections 16. & 21. 38-8
 (shown on Page 178 Book 38-8)

SEC 33-39-7 AUG 26-27 1921

1/8 P E of center by Don Rm N

Var 3 1/2 E ~~7 1/2~~ E of the 1/16 P

1992 f.w. 7 1/2 E E of 1/16 P in NE 1/4

Corrected line south to 1/8 P

W From 1/8 P E of center Var 4 1/4 E

2104 f.w. 217/100 Lks S of center

Corrected line E to 1/8 Post

SEC 9-39-9

SURVEY of ISLAND in BALLARD LAKE⁴⁹

August 15. 1921

Began at northernly end and run
 southerly near center as follows

S. 63° W 200

" 74 " 115

" 85 1/2 W 177 to S.W. E d

Distance at this point to main land
 on last course 545

Set stake 100 c. Part to main land
 and measured each way to deep water
 as shown on map

As this island is in Sec 4-4-8

and worked to locate it. I went to

the m.c. on S. shore of lake on west

line. found original B.T. but dead.

B.F. Dork had perpetuated it by new

Post and bearing trees. I have this notes

Rm S. Var 3 1/2 E

300 heavy swamp

1013 f.w. 123/4 E of Dorss 1/8 P. found

his Post and B.T.'s

2674 f.w. 40 E of S.W. corner found

stumps of original trees

Set NE Post and remarked steps

Run E from corner to 4-5-8-9 Var 3 1/4

5248 m.e. sec of lake

5379 f.w. 139 N of m.c. found the

6 m. down + dead mark oak

The birch is under a large pine

wind fall. Set an iron p.p. for

m.c. Then meandered the

south shore of lake to section line

SEC. 3. 39-7 AUGUST 26 1921

Began at $\frac{1}{8}$ P. E. of center iron
Pipe and RT. ok. Run N Var $3\frac{1}{2}$ E
1992 Fell $7\frac{1}{2}$ E of $\frac{1}{16}$ Post
W $\frac{1}{8}$ From $\frac{1}{8}$ P. E. of Center Var 4° E
21.04 FLL $2\frac{1}{4}$ S of Center

Record

SEC 35. 35-13. AUG. 30 1921

SW COR. OK. Run E Var $3\frac{1}{2}$ E
7974 fELL $7\frac{1}{2}$ N of SE COR. OK
Dec 29.6. Change course 33'
found SEP of $\frac{1}{4}$ P. Sugar 12530 E 44
NEW 1 12577 W $1\frac{1}{4}$

N from SE COR Var 3° E

7100. S Line of State Highway
8094 fELL $37\frac{1}{2}$ E. of NE COR. Sugar RT. OK
NE COR. W Var 3° E. Dec 46
7909 fELL 25 S of NW COR. OK
NW COR. NEW Hem 10 N 85 E $7\frac{1}{2}$

" N $\frac{1}{4}$ Post Maple 10 N 79 W 14N $\frac{1}{4}$ P. South Var 3° E8101 fELL 29 W of S. $\frac{1}{4}$ P. Dec 358W $\frac{1}{4}$ P. OK Run E Var 3° E7913 fELL 25 N of E $\frac{1}{4}$ P. See it in

Swamp No BT

Center of SEC No BT Piled rock around it

Dist to N $\frac{1}{4}$ P 3919

" " S " " 4182

" " E " " 3968

" " W " " 3945

Set $\frac{1}{8}$ P. E. of center + Piled rock around it
It is $29\frac{1}{2}$ E of Center

South from $\frac{1}{8}$ P. E. of center 3504033 fELL 19 W of $\frac{1}{8}$ P.S $\frac{1}{8}$ P. E. Line. Rock around itE from $\frac{1}{16}$ Post in SE $\frac{1}{4}$ Var 2451985 fELL 11 N OF $\frac{1}{8}$ P. Hem to 544 W 33

" 540 E 39

N $\frac{1}{8}$ P. E. Line. Sugar 9538 E 1442

Run W Var 250 E 3956 fELL

SEC 35-36-11 Aug 1921

SEC 1-39-5 E SEPT 5 1921 (SEC Sec 1)

S $\frac{1}{4}$ P. W Var $3\frac{1}{2}$ E

4046 fELL 280 N of corner. found MC
first and then chamed E and found cor
and found 3 had FELL

SEC 1-39-5 SEPT 5 1921

WEST from S $\frac{1}{4}$ P. Var $3\frac{1}{2}$ E

Found M.S. and set new Post. Then

" air NW cor NEW AS Hens 75 $\frac{1}{2}$ W 42Run W Var $3\frac{1}{2}$ E Run N Var $3\frac{1}{2}$ E

573 to Lake Set ME NO BT.

Cancelled Line E from NW cor to $\frac{1}{4}$ P.

SEC 139-5 Sept 12 1921

E $\frac{1}{8}$ P. on S. Line Run West on Random

2740 to E Side of Flosshams Road

2763 " W " " " " " " " " "

Set stake on "connected line"

3 staves 10 S 70 E 200

SEC 9 35-12 Sep 14 1921

SW COR. OK Run N Var $2\frac{1}{2}$ E $\frac{1}{8}$ P.

2010 fELL 84 West of Somones corner

Dec 4.16 Change course

north from $\frac{1}{8}$ P. set by Somones var

7979 fELL 264 South of corner to 4.5-8.9

Set N $\frac{1}{8}$ P. bet 8+9W Var from N $\frac{1}{8}$ P. bet 8+9 Var 245 E

2500 open water or Lake

2072 Center of RR track

2329 wet Swamp and set Post

Set $\frac{1}{16}$ Post at 20 and Piled rock "and"Set $\frac{1}{4}$ P. bet 8+9 at 3989 Rock around itWest from $\frac{1}{4}$ P. bet 8+9 Var 245 E

1914 center of RR track 25 N of E. Current

2000 Set $\frac{1}{8}$ P. Rock around it

3300 open water

2876 enter wet swamp continued Page 52

SEC 8+9 Cont 35-12

West from S 1/4 P bet 8+9

4185 to Lake 1st me

E from W 1/4 Post of Sec 9 on 245

7883 full 3072 S of E 1/4 P. of 9 on 245

West from S 1/8 P bet 8+9

4185 to Lake 1st Post

SEC 15-36-12 line in Run N 88 3/4 W

N Line of 15 on Run S 88 3/4 W

Bet 24+ 2536 12

Staked from an Iron Pipe Run E 13 1/2 E

700 Enter Swamp

1700 Leave "

2700 Enter "

5600 Leave "

6784 full 667 N of corner

SEC 32-39 11 E

A piece of Land in an island in

Lot 4 described as follows

Commencing at a stake which stands

on westerly shore of an island 80 m. or by

West Swamp and Lake, and in S. 88.20 W

W. of 1/4 P between Sections 29+32 and

1080 from said 1/4 P.

Thence S 45 E 538

" N 73 1/2 E 760

" N 22 1/2 W 1140

" N 22 W

Copied into
Book

SEC 32-39-11 SEPT

A piece of Land in lot 4

described as follows

Commencing at a stake which

stands stands S 85 W from 1/4 Post

29+32 T. 39 N. R. 11 E and 10.80 dist

Thence S 45 E 538

" N 73 1/2 W 760 ✓

" N 22 1/2 W 114

" N 22 W 468-463

" S 83 W 511

" S 57 W 117

" S 12 1/2 W 53

" N 26 W 14 to Place of

beginning

This piece of Land is

really an island surrounded by

Wet boggy marsh and Lake

SEC 11.12 13 + 14 SEPT 21. 1921

37-10

Run south from this corner 1/4 P

did not find 1/4 Post

corner to sections

sections

23-24-25-26

12000 did not find 1/4 Post

16000 " connects to 25.26.35.36

This line is for a road for stakes as

setting stakes but no corner

except at starting Point

Have set all the corners on this line

years ago but the stakes as has destroyed

them in clearing this lands

Copied
into
Book
37-11

54 sec 9-38-7 Oct 3 1921

Found Darius E 1/8 Post on South line
 Set new Post and run West Var Var 30° E
 1932 Fall 95 1/2 N of ~~corner~~ corner to
 9-10-15-16 OK
 S E cor. Run W Var 3 1/2 E
 1983 Fall 100 N. of 1/8 P by D H Vaughan
 corrected on to 1/8 P and prolong of line W
 Found Var of corrected line to 1.50 E
 1980 Fall 11 N of 1/4 Post corrected Var 1/2° E
 West from S 1/4 Post Var 30° E
 1242 m.c. found Post & stump of org tree
 Set New Post made NEW BT. 1/3 Pin 12 N 35° E 40
 #544 P. Run north var
 N from S E corner var 3 1/2 E
 4008 fall 98 W of 1/4 P in new road
 went south & set S 1/8 P on E line
 { ashen 6 N 26 E 5 1/2
 connected line from E 1/4 P west to Lake
 and the south line from S E corner to Lake

SEC 1139-6 Oct 8 1921

a piece of land in Lot 4 described
 as follows To wit:
 commencing at a cedar Post which
 stands N 49° W. and 1350 Feet from the
 S 1/8 Post between Sections 1 and 11.
 Thence N 43° west 60 feet
 " " 47 west 75 "
 " " 43 East 60 + 162 Feet = 222 Feet
 to a stake which stands on shore of Lake
 Thence South easterly 75 feet measured
 at right angles to an iron pipe on
 shore of Lake Thence N 43° west
 298 Feet to place of beginning

copy
 in Book
 38-7

SECTIONS 19-20-30 39-7 Oct 18, 1921 55

SURVEY of road for the Town
 of Woodruff
 commencing at a Stake which
 stands N 81° E and 5.16 chains
 from the S E cor of the S W S W of N
 SEC 20. 39-7

| | | | |
|--------|----|--------|------|
| Thence | S | 24 E | 506 |
| " | " | 12 E | 750 |
| " | S | 24 W | 183 |
| " | " | 25 W | 185 |
| " | " | 2 E | 363 |
| " | 25 | 25 E | 312 |
| " | S | 6 W | 383 |
| " | " | 18 W | 493 |
| " | " | 12 W | 423 |
| " | " | 21 W | 700 |
| " | " | 8 W | 1090 |
| " | " | 59 W | 433 |
| " | " | 61 " | 473 |
| " | " | 72 " | 296 |
| " | " | 71 " | 208 |
| " | N | 77 " | 292 |
| " | " | N 51 " | 308 |
| " | " | 47 " | 209 |
| " | " | 62 " | 300 |
| " | " | 45 " | 300 |
| " | " | 32 " | 200 |
| " | " | 27 " | 600 |
| " | " | 42 " | 200 |
| " | " | 62 " | 200 |
| " | " | 78 " | 300 |
| " | " | 86 " | 200 |
| " | " | 74 " | 200 |
| " | " | 60 " | 200 |
| " | " | 44 " | 300 |
| " | " | 41 " | 500 |
| " | " | 47 " | 201 |
| " | " | 57 " | 1300 |
| " | " | 62 " | 300 |
| " | " | 44 " | 200 |

The East line of Lot 1
 800
 300
 W
 71
 88
 S
 S

finished and survey rendered
 Oct 18-1921 Total 15560
 Consistent distances above given on center of line of

56 SEC 30-38-7 Oct 24-1921

NW cor found a post set by Ira Smith 25 feet E of true corner which in center of road. St at highway No 10 chained in center of road 3300 Road bears W. Prolonged line and at 4020 found org. 1/4 Post. Bearings gone but found where Post stood and measured one. Nothing for Bearings

Run E along fence, on
1847 found Ira Smith's 1/8 P No bearings
Began again at NW cor and run E
1845 found Smith's W 1/8 P on N line

Run West from this 1/8 Post var 50°
4214 full 80 W of 1/4 Post on NW 1/4
connected line N of 1/8 Post west of center
connected line N. and set 1/16 P in NW 1/4
and then cut off from south side of the
NW NW. a strip of land 500 wide and set
Post at each end and a line of stakes between

SEC 1 39-5. Oct 26 1921

S 1/4 P. Set in July 1920

Run N var 3 1/2° E Same course as E 1/4 N
E option line

1621 To Lake & set me

W 1/8 P. on S. Line Set from my
Talley stakes on Random Run

Sept 1921 this 1/8 P is at 2023 W of 1/4 P

Run N var 3 1/2° E

Sept 5 1921

West from S 1/4 P 522 seed of 1919

var 372 E

4046 full 142 N of cor on trees nearly
gone NE. 1/8 P 125 7 1/2 W 42

SW cor. Run N var 3 1/2° E

573 To Lake and set me No B.T.

Oct 15
~~SEC 35-36-7~~ Survey of Road

57

for Town of Woodruff, get
commencing at a stake which
SW. Nord stands N. 81° E and 5.16 from SEC corner
of SEC 20. 39-7. E. Then

There S 24 E 50.6

" " 12 W 75.0

" " 25 " 88.5

" " 2 E 36.3

" " 25 E 31.2

" " 6 W 38.3

" " 18 W 49.3

" " 12 " 42.3

" " 21 " 70.0

" " 8 " 109.0

" " 59 " 43.3

" " 61 " 47.3

" " 72 " 29.6

" " 71 " 20.8

" N 77 " 29.2

" " 51 " 30.8

" " 47 " 20.9

" " 62 " 30.3

" " 45 " 30.0

" " 32 " 20.0

" " 27 " 60.0

" " 42 " 20.0

" " 62 " 20.0

" " 78 " 30.0

" S 86 " 20.0

" " 74 " 20.0

" " 60 " 20.0

" " 44 " 30.0

" " 41 " 50.0

" " 47 " 20.1

" " 57 " 13.00

" " 62 " 13.00

" " 44 " 20.0

" " 71 " 50.0

88 " 300 To the E line of SEC 30 39-7-39-7

Copied into the census and dig houses
 above given as center
 and line of Road
 34 FOLIOS
 Record Book 39-7
 Page 147

NW cor in center of State highway
 a Post set by 1ra South stand 25 feet
 East of corner.

Chained Southern center of Highway
 2800 Highway

Sept 5th 1921

SEC 139-5. Oct 26

WEST from S $\frac{1}{4}$ P which about 2 year
 ago from one arg. tract

4046 feet 140 $\frac{1}{2}$ N of SW cor found
 Stub of arg. tree NEW when 12575 $\frac{1}{2}$ W 42
 also found mc West of corner

Run N from corner var 3 $\frac{1}{2}$ E

573 to Lake and set mc No BTs

connected line East to $\frac{1}{4}$ Post

Oct 27-1921

SE $\frac{1}{8}$ Post on South line no BT

Run N var 3 $\frac{1}{2}$ E

2050 to Lake and set mc at 1400. an

this line cross Hansen's road at 1400

mc SW $\frac{1}{4}$ P 88.5 W copied

7 75.5 E

N from S $\frac{1}{4}$ P var 3 $\frac{1}{2}$ E

355 to road

6621 To Lake set mc No BT, new

Run N 66 W var 3 $\frac{1}{2}$ E Set Stake

every 300

1581 $\frac{1}{4}$ found & was 27 links from Lake

connected line back mc



N 150 magon an Lake

angle at NE COR 15. 117 $\frac{1}{2}$
 or N 66. W.

E line of 117 $\frac{1}{2}$ or N 66 W 1581 $\frac{1}{4}$ to
 Lake and set mc SW $\frac{1}{4}$ P in 14561 E 35 $\frac{1}{4}$
 found just 3 acres of land N of Base line
 and South of Lake. Deducted 3 acres
 from South end of 25 acre tract. to
 have been up what lies N of base line
 The average width of land N of base is
 227 So the lines on E & W side of 25 acre
 Prep 227 short of the lines on the
 N & S side.

found a tree squared up and
 is said to be done by Lamonts the
 farmer owner and was supposed to
 represent the SW & S.E. corner of the
 land sold to HATCH by Lamonts
 This tree 200 South + 260 E
 of my S.E. corner

The E end of dwelling house is
 3.50 W of E line 500 South of
 Lake. T Barn is about .150 S.W
 of dwelling copied

Nov 1 1921
Road for TOWN of STELLA

Commencing at the corner
 Copied into county record
 to 8-9-16-17-3710. November 2 1921
 found my bearings made 3 years
 ago. Set new Post and run W. Var 1¹/₂
 2881 full 90 S. of 1/4 P. between 8 & 17;
 found Stumps of orig bearings and
 Post set 22 years ago. Post was down
 made new one. and corrected line
 East to 1/4 Post = = =

SEC 22. 37-8 Nov 3-1921

The center of this Section is on Lake
 and as I have previously Run the
 E. and West and N & S Section
 lines. and the South line from S.E.
 corner to 1/4 Post. I lean at S.E. corner
 where I found the steps of my BT's
 (SEE Sections 22 & 23 37-8 County
 Records) Var 4° E

4266 found 1/4 P on line
 8948 full 8.16 N of corner found
 Post set 20 years ago. SW orig
 tree OK Set new Post and went
 East and set W 1/8 P. on South line

W Pine 12 N 25 1/2 E 5 58
 E 1/4 P. an iron bolt 1 1/2 x 1 6 inches
 SW corner of log house N 12 W 49 1/2
 Run west from E 1/4 P var 30° E
 3544 Intersect Lake
 4406 over

8658 full 3 link N of 1/4 P. Post gone
 and a large fence Post in its place
 as I had previously Run. all the
 Section lines and as the center comes
 in lake I set 1/8 Post W of center as
 follows. I ran N from S 1/4 Post on
 on an intermediate course. The same
 distance bet Wren E 20 lines and
 set 1/8 P west of center at 2164 no 137 near

SEC 22 37-8 cont: Nov 4th 1921 61

South from 1/8 P West of center
 var 6 1/2 E
 4078 full 126 E of 1/8 Post
 connected line North to 1/8 Post.
 S E 1/8 P South of center 2266 Post
 West of S 1/8 P on E line. and 2072
 N of S 1/4 P (SEE 23-37-8
 East of 1/8 P South of center var 40°
 1053 to Lake copied to County record
 1720 over Lake Book - 38-7
 4055 full 408 S of 1/8 P in Highway
 NEEDLE shows a change of
 course of 5° at 1/8 Post
 connected line west to 1/8 Post

SECTION 28-35-10

Dec 8 1921

N 1/4 Post found Dorrs Boulder
 with X on top 8 x 10 x 24
 Thence E on 1/4 line 800
 Thence South parallel
 with N + S 1/4 line 400
 Thence West parallel with
 E + W 1/4 line 800 Thence
 North on N + S 1/4 line to
 Place of beginning

62 SEC 13-35-10 DEC 5, 1921

Survey of road for
P.E. Kable for street in his Plat
on Reesum Lake
commencing at Platted lot 31432
Then N 3- E 143 feet ✓

" " 42 1/2 " 167 ✓

" " 50 1/2 " 123 ✓

" " 56 " 314 ✓

" " 54 " 104 ✓

" " 29 " 241 ✓

" " 32 " 202 ✓

" " 25 " 176 ✓

" " 30 " 134 ✓

" " 32 1/2 " 128 ✓

" " 43 " 137 ✓

" " 19 1/2 " 124 ✓

" " 15 " 106 ✓

" " 11 " 106 ✓ To center of

East & west on E & W 1/4 line
measured west on 1/4 902 to Lake

SEC 2-3310 DEC 9 19-1921

E 1/4 Post. Stone with + on Top. Set
by B & Dorr. OK

Run East Var 9° E. S. to Rock in road
2150 Shore of Summit Lake

54650m

6591 FOLL 314 W of E 1/4 org BT's

SEC 2-33-10-E DEC 19-1921

E 1/4 Post. Stone with + on Top. Set by
B & Dorr. OK

Run West Var 9° EE

2150 to Summit Lake dim in road
54650m

6591 FOLL 314 S. of West 1/4 Post OK.

N 1/4 Post. Boulder with + on top set by
B & Dorr. Run South Var 100° E

400 to Summit Lake

5430 crossed E & W 1/4 line as connected
full 2. links E of 1/4 Post in

Road on iron pipe 2 x 20 inches
Set 1/8 P. west of center

Took levels of Lake at cemetery
found Lake is 1 foot 2 10ths below
what it was 30 years ago

Took levels again where E & W line
intersects Lake 2150 W of E 1/4 Post

and found Lake 1 foot below what it
was 30 years ago

Gave evidence in court at
Ontario as to Survey & E

64 By Lynn V. ...
 SEC 30-37-7 ~~Sec~~ 9" 1922

W 1/4 P. Org. Erecs. Post Set by DHU in 1904
 Run E Var 3 1/4 E
 8398 Fell 24 Lks South of E 1/4 P by DHU
 S 1/4 P. Org. Erecs. (nearly) same but ok
 Run N Var 3 1/2 E
 8145 Fell 406 E of 1/4 P ok corner Var 5 1/2
 center of sec

T E L. P. 6 L. S 5 4 N 6 5
 N 4 2 E 6 4 1/2

| | | |
|------------------|------|-------------------------|
| DIST TO N 1/4 P. | 4018 | W Pin 8 N 4 2 E 6 4 1/2 |
| " " S " " | 4127 | |
| " " E " " | 4219 | |
| " " W " " | 4179 | |

SEC 1/8 P W of center Nothing for B.T.s
 " " " E " " " " " "
 " " " N " " " " " "

Parties have Promised to Place non
 monuments at all corners.
 finished Jan
 Copied in Book 37-7. Page 121

LOT 5 SEC 25 39-6 Jan 31 1922⁶⁵

W 1/4 Post found Post Set by Darn
 Run N on line run by Carlson
 1939 fell 116 W of Darn 18 P
 which is The NW corner of Lot 5
 connected line South and set
 Posts 400 and 800 N of W 1/4 Post
 which is SW corner of lot 5. in flowage
 East from NW corner of lot 5
 Var 7 1/2 E
 1600 to Lake. from the Blump of
 Norway. marked by Post
 E 8 4 Lks N of me.
 Run South on ice Var 4 1/2 E
 538. it is 50 to E shore of Lake
 and 77 N of Wolf's S N E cor
 10.00 it is 61 Lks West to Shore of
 Lake
 1300 to a point of Land attending
 S E. from from main Land
 This Point attends about 300 SE
 and is one wide.
 1400 over Point of Land
 1939. it is 500 West Shore of Lake
 Set a Stake 400 N of 1939 Stake
 and another 800 N
 Run West from stake 1939 Var 7 1/2 E
 1545 fell 2 1/2 N of West 1/4 Post
 connected line East to Shore of
 Lake at 1052 E of 1/4 Post
 West from the Stake which is 400
 N of 1939. Var 7 1/2 E Var 7 1/2 E
 50 it is 50 to Shore of Lake
 1544 - 50 to Shore of Lake
 129 to Woodards W line
 1564 to West line Flee 33 N of Post
 800 N. of W 1/4 Post.
 Set a Post where line crosses
 Woodards West line.

Record new return

West from Sta a stake 400 N of
1939 on from SE cor of lot 5
to show of lake
1530 to a stake on west line which
is 400 N of SW corner of lot 5

Then surveyed a lot known as
~~the~~ ~~a~~ WOLFS Lot described as
follows commencing at a stake
which stands on the East shore of lake
and 565 from SE corner of lot 5
and measured along lake shore
Thence N 65° W 1/2 mi 3 1/2 E 1.13 LKS
" S 23° W " " 1 81 1/2 LKS
" S 69° E " " 200 to

Shore of Lake Thence " northeasterly
along shore of Lake to place
beginning containing 521/100 acres

Decided to woodard
commencing at SW corner of land
decid to wood

Thence S 15° E 320 ~~ft~~^{chng}
Thence S 12° E 7.07 to Shore of
Tanahtuk Lake Thence north
and easterly to where op amt
Extends 3 south easterly about 600'
Thence Thence north westerly along
Shore of lake to the S.E. corner
of land decid to wood
Thence S 69° W to Place of
beginning

copied into county recd

SW COR ORG Bearings

Run E var 3 1/2 E
7472 full 184 N of corner OK but dim
DEC 2.46 found an overrun of
~~324~~ 126 Set E 1/8 P on N line at 2034
West of NE cor: { Pine ST P 20 N 2 W - 8 LKS
7538 1/2 W 45 1/2

Posted in book 38-6

SW COR - found set of 0" LK
Set NE Post and Run E var 2 1/2 E
7450 did not find SE cor but
found old N+S Line and the
distance N to Lake is about right
Set E 1/8 on South line same
distance from SE cor as E 1/8 P
on N line then run a line
from 1/8 P to 1/8 and set 1 1/16
Post in center of NE corner
Set 1/8 P E of center at
3826 set center of section
nothing for BT's

Bearings for 1/8 P E of center is
{ Pine ST P 10 S 87. E 34

SEC 9, 38-6.

Surveyed a piece of land as
follows commencing at a
stake which stands on line
between Sections 9 & 10. 468 N of
M.C. Thence N 45° E 220 to Lake
Thence S 45° E along shore of
Lake 100 feet Thence N 45° W
to see line, Thence N on sec
line to place of beginning 100 feet

Posted in Book 38-6 Page 36

A piece of land in lot 3 section commencing at a cedar Post which stands South 34° West of the South $1/8$ Post between Sections 10 and 11 Township and Range above given. Thence

A piece of land in lot 3 Township 39 North Range 6 East and more particularly described as follows

To wit: Commencing at a cedar Post which stands South 34° West and 900 feet from the South $1/8$ Post between Sections 10 + 11. Township and Range above given. Thence North 56° West 60 feet. South 34° West 150 feet.

Thence South 56° E 240 feet to Shore of Lake. Thence northeasterly on Shore of Lake to a stake which stands S. 56° East and 460 feet from the Place of beginning.

Thence N 56° W 460 to the Place of beginning.

A course was run and a map copied into County record

Began at SE corner found 33 Ham or BT. OK See Book 8 Page Run N 41° 3/4 W

3200 over Stone Lake

6500 to River

7600 over

8171 full 41° 3/4 E of corner

See book 7 Page 391 - See cor 330

West from NE cor: 41° 3/4 E

25.25 full 34° N of M.C.

Set E $1/8$ P on N Line. No BT

31/4 P OK Chained N on my Rand

41° 1/2 E

1100 wagon road

1600 to Lak

2147 found my M.C. on West

Shore of lake and and 590 E of $1/8$ Post on 10

connected on to $1/8$ P and run N 4295 to center of section on 10

6100 to $1/8$ P N of center on 10

9095 - N $1/4$ P on 10

1687 N of center to 18 Land and set

M.C. 7 Pine 6 N 85 E 6 1/4

and began meander of island

S. 50 E 357

N 20 E 480

N 17 W 525

N 30 E 694

N 58 W 970

N 78 W 555

S 30 E 570

S 5 W 465

S 26 E 970

S 68 E 632

Total 6138

South from $1/8$ Post S

E from $1/8$ Post South of center

Var 45° E

1918 Set $1/16$ P in

SE $1/4$ an Iron

No BT

copied into County record

70 SEC 15 36-9 April 19, 1922

NE Cor. found my BTs. Feb 17, 1902
Run S. Var 15° E
1894 f W 15 E of my 1/8 Post 20 y ears ago
East from NE corner Var 4° E
about 1400 to Lake did not chain

SEC 4-37-8. E April 25, 1922 ^{POSTED}
SE. cor Run N. Var 13 1/2 E
1912 full - W of Dorrs 1/8 Post
connected onto his 1/8 Post Run N

125 to flowage
1381 over flowage
3824 SE 1/4 Post
E 1/4 Post Run west var 3.45 E
117 to Lake

1805 over Lake There N. on 1/8 line
600 to original share of Lake

SEC 25-39-6 April 26 1922 ^{Range}
Began at 1/8 P. bet 25 & 36 and Run N

SEC 1638-8 April 28
M.C. on E side of Lake on Line ok
Run E Var 3 1/2 E

2374 to corners to SECs 9-10-15-16 ok
Set Posts made new bearings
W Pine St P 20 NE 22
18 SW 15

Run South Var 3 1/2 E
300. It is 700 W to Lake
500 " " 600 " " "
800 " " 500 " " "
1000 " " 400 " " "
1200 " " 300 " " "
1500 " " 300 " " "
1846 To Lake and set me

Rested

* In switch back
fully admits he did
not find Sec. Cor.
9-10-15-16

see 19-38-6 June 6 1922 71

NE Cor. SEE ~~SW~~ SW Cor of 17
Run South Var 2° E
550 Enter open swamp
1750 Over
7500 Looked The prolonged line S
8000 Set line Stakes. did not find cor

N 1/4 Post ok var 2° E
Run ~~NE~~ East

3343 full 47 S of NW corner found
The remains of the 4 org trees
found a shortage of 87 Lks
Proportioned Shortage + Set W 1/8 P
on N Line W Pine stub 10 N 21 W 60
" " " 12 S 19 E 85

NE Cor NEW { Y. Pine 10 N 78 E 98

" " Runs Var 3 1/2 E Gout notes say 7 1/2 E

4880 full 107 E of me found E Tree ok
W E C down marks ok Set new Post
N 1/4 P Run South Var

W 1/4 P Set it at 4007 as I found an
over run of 10 Lks

W 1/4 P { W Pine 10 N 27 1/2 W 21
" " 12 S 30 W 43

N 1/4 Post ok Run South var 2 1/2

8000 Set Line Stakes. and went to
South shore of Lake did not
find SW corner. but Set me 101
E of where cor should be
The shore of Lake has been
flooded and corner is washed
away + is now in Lake

Run E than New Bearings for M.C.
are Y Pine St P 16 S 29 E 23

" " stub 10 S N 89 E 21

Run E from me which is 101 E
of corner in Lake chained from corner
Continued on page 76

72 SEC 12-37-8

W 1/8 P on N Line set it from Dares notes
{ W Pin st E P 18 N 8 1/2 W 39 1/2
{ and run N on Dares line 20.00
thence west to Dares 1/8 Post

SEC 2238-11 MAY 21-1922

Began at center of Section set years ago. Do not know as it is correct but Roads and fences are made on this old survey & used it
Run W. Var 5° E. as line previously run and marked

3714 offset N + R.T. A 225 Then W of R.T.A.

File 2125 to wagon Road
3711 to Lake & set line.

Then surveyed a piece of land as follows commencing at me an from Pk then E on 1/4 line 5.47 ch

thence N parallel with shore of Lake 5.47 ch: Thence west parallel 1/4 line 5.47 ch Thence south along shore of lake 5.47 to me and the place of beginning containing 3. acres then platted lots N to sec line

See 4-35-4 May 22 1922

South from NE cor var 3 1/2 E
8471 full 4.10 1/2 W of SE cor OK
Dee For connection 1016

SEE 1/4 Post at 42.25 There is an over run
N 1/8 P on E Line { Pin st P 18 S 4 W 46 1/2

The ~~N~~ N + S 1/4 line is run and center set and roads are made for many years ago and I used it but do think it right. But run one is satisfied
West from E 1/4 P. var 4 1/2 E

3977 full 33 S. of center an iron Mon
4010 full 53 S of center

The 1/8 P N of center has been established
E from 1/8 P N of center var 3 1/2 E
Set 1/8 P E of center and Run N var 4° E
1100 same line

4420 full 33 W of 1/8 Pin Highway
Set 1/16 P in NE 1/4

{ W Pin st P 30 N 74 E 63
" " " 30 N 50 E 47

SEC 32, 36-7 May 17-1922

N 1/4 P OK Run South var 4° E
6159 to Lake

7135 over " bid not find S 1/4 P and went to corner SW cor. OK and set
an E var 4° E

4003 full 10 N of 1/4 P in fee

Set S 1/8 P on W Line
Platted Lots for John Head

74 See 17-38-6 May 24 1922

NE Cor found stub of N 1/4 P
Set Post and made new bearings

Run West } Var 3 1/2 E
1913 to Lak and set one
{ W Pine St 20 N 28 W 69
{ Y Pine St 18 N 56 E 29
{ " " " 10 S 10 W 12

~~2228 to S. Point of island~~
From me to Point of island 1385

~~2785 over Lake & set one~~
3158 to whor { Y Pine 10 N 20 E 43

7974 Found evidence enough to set #
NW cor { Y Pine 16 N 42 E 22 1/2
" " " S 20 W 51 3/4

NW cor Run South Var 3 1/2
3249 to Lak

4714 over Lake
8000 No corner

Went West and found 1/4 P. bit ¹⁸⁺¹⁹ 19220
and run E Var 3 1/2 E

8063 FLL 245 Not S 1/4 P
Stile E on corrected line

3973 + 8063 = 12036 and set
S.E. cor { W. Pine 24 N 63 W 22
{ Y " " 16 S 64 W 60 1/2

Went West and set S.W. cor at
4031 1/2 Equidistant bet 1/4 Posts

E 1/8 P on south line { Asher 12 S 89 E 33
Set W 1/8 P on S line oak 12 N 8 W 48
Set W 1/8 P South line 36 W 50

Set corner to 17-18-19-20
{ Y. Pine 10 S 36 E 151
{ W " " 12 N 35 W 121

Picked up my west line and at 8155
fll 229 E of cor.
corrected var 2 1/2 E

M.C. on N shore of lake W Pine 10 East 5 Lks
S. " " " " No B.T.

S 1/8 P on E line sets on E side of swamp
nothing for bearings

Continued

Set E 1/4 Post at 3885
{ W Pine St 24 S 69 W 9

Set N 1/8 P. at 1942 1/2 nothing for B.T.s
~~S 1/8~~ found a shortage on N line
between m.c. + NW cor of 110 Proportional
Shortage + set W 1/8 Post at 4001 E of
NW corner { oak 12 S 75 E 67
{ ash 16 S 76 W 76

Went 1/8 on N line { W Pine 12 N 16 W 23
South from W 1/8 Post on N line var 2 1/2
2224 to Lak & set one
{ Y Pine St 24 N 20 W 19

See 19-38-6 June 6 1922

NE cor Y Pine 12 S 36 E 151
" " W " 12 N 35 W 121 } NEW
" " " " 10 Var 2 1/2 E

NE cor. Runs } SEE SW cor of 17 P ^{Picked}
550 Enter open swamp
1756 over
7500 did not find corner set line stakes
Went to N 1/4 Post. St 6 of org B.T. ok

N 1/4 P Run West Var 2 1/2 E
3343 fll 47 S. of NW cor found all
of the rig trees but nearly gone

NEW Pine 10 N 78 E 98
Set W 1/8 P on N line { W P St 16 N 21 W 60 1/2
" " " 12 S 19 E 85

found an a shortage of 87 Lks Proportional
Shortage to set this 1/8 Post at
South from NW cor var 3 1/2 E
= June 1922 =

488 FLL 107 E of M.C. ok. found an over run
106 Proportional Same + set W 1/4 P. at 4088
W. Pine 10 N 7 1/2 W 21 }
Y. " " 12 S 30 W 43 }
Set m.c. at W End of S line on S. Shore of
Lak. and on line from NW corner ^{5 Lks}

July 6, 27 for m.c.

76 SEC 19-38-6. continued from Page 71

7542 full 44 S. of S & E corner. found
NE B.T. ok and original Post
Set new Post

found a shortage of 19 LKS and
Proportioned Same and set S 1/4 P
at 4010 W of S & E corner

{ oak 10 N 30 E 12
{ Birch W Pin 12 S 21 E 28

Set E 1/8 P on South line at 2005 W of S & E cor

E 1/8 P { oak 10 N 31 E 8
{ Birch 18 N 44 W 21 18 N 43 W 20

Set S 1/4 P

Picked up E line and at 7988

full 55 W of S & E corner
N 1/4 P. run South Near 20 E

8000 full 83 W of S 1/4 Post
DEC for correction - 0104

Set E 1/4 P at 3994 and 27 1/2 E of Rand

{ Maple 12 N 10 1/2 E 4 1/2
{ " 12 S 89 1/2 W 67 1/2

S 1/8 P on E Line { W Pin Stb 16 N 54 1/2 W 43 1/2
" " " " 14 N 72 1/2 E 54

W 1/4 P. Run E Van 430 E

1565 Road corner NE + SW

7378 full 277 1/2 N of S 1/4 P

Set center of section

{ W Pin Stb 24 N 53 E 25

14 N 29 1/2 W 66

Dist to N 1/4 P 4024

" " S " " 3976

" " E " " 4009

" " W " " 3371

Set 1/8 P ~~N~~ of center South of center

{ W Pin 14 N 68 E 26 1/2

" " 10 S 11 W 16

1/8 P N of center { B Pin 3 N 5 E 13

19-38-6 cont June 24 1927

77

1/8 PE of center is about 5 LKS in lake
on west shore

1/8 P W of center { Birch 3 N 13 1/2 W 39

East from 1/8 P. S. of center Van 2.45 E

400 Road

2200 Enter Swamp

3200 Over

4008 full 17 N of S 1/8 P on E Line

Went west and set 1/16 Post

in SE 1/4 { Maple 10 N 38 W 32

10 S 62 1/2 E 33 1/2

1/8 PE of center Run N Van 2 1/2 E

4008 hit E 1/8 P on N Line

Set center of NE 1/4

{ W Pin Stb 16 N 34 E

MC on S. shore of lake on South

line of

{ W Pin Stb 16 S 29 E 23

" " Stb 10 N 89 E 21

East from MC on S line Van 3 1/2

7542 full 44 S of S & E corner

copied

copied

copied

in book 1386

78 SEC 32-36-7 May 17-1922

N 1/4 Post ok. Run South Var 44° E
6159 intersect Lak Manson
7135 over
7850 full 200 E of 1/4 Post in fence
To find this I went to the S.W. Cor
and run E Var 4° E COR. VAR = 2°-33' E
4003 full 8 S. of 1/4 P. in fence
Set Temp 18 P.S. of center at
~~5850~~ 5850 No BT

1/8 Post

SEC 1938-6. JUNE 6. 1922

Purled Purled
SEC 07 Pine 10836 E 151
W 12 N 85 W 121 This had
NE cor. S. Var 2° E. been posted
550 Enter Swamp on Page 75
1750 over

SEC 7 36 8 JUNE 26-1922

1/8 Post N of center ok by Dam
Run E Var Var 4 1/4 E
2437 full 118 N of 1/16 Post in road
corrected on to 1/16 P. and prolonged
line East 2437 and Set N 1/8 P on
E line No BT

POSTED

this is also

SEC 3-36-8 June 27. 1922

79

N 1/4 P in Center of State Road
Run S Var 4 1/2 E
2449 full 25 E of Dams 1/8 Post ok
connected on to this 1/8 Post and
run S on corrected line
4074 Found Dams center on line
Found Dams bearing ok
E from center Var 4 1/2 E 1/8 P.S. of center
4004 full 40 1/2 N of Dams 1/16 Post
Found Dams bearing + Iron Pipe
Went West to center and corrected
my Random out to center and
Prolonged corrected line West
Var 3. 45° E
3950. (Dams distance to W 1/4 P but did
not find W 1/4 P. all based out
W 1/4 P. South Var
center of Section Run S on corrected
line from N 1/4 Post
1958 The distance given by Dams to
1/8 Post S. of center and Set Post
{ W P in STP 1/6 N 55 E 18
W 1/4 Post No BT Run S. Var 3° 45' E
4993 full 60 E of SW cor ok
S E S. 1/8 P. on W line at
2496 1/2 N of SE cor W P in STP 20 N 41 W 19 1/2
WEST from S 1/8 P on W line Var 7° E
3981 full 227 S of Post
corrected line West 1/8 P. E of center
and S 1/8 P. on W line to W 1/4 Post

Posted
to here

80 Survey of Road for the

Town of Sugar Camp
commencing at the 1/4 Post
between Sections 31 & 32 in
Township 39 N. R. 10 East

Thence East 950 Chans.

| | | | | |
|---|------|----------|------|---------------------|
| " | S | 23 E | 1250 | v |
| " | " | 84 " | 1250 | v |
| " | N | 75 " | 500 | v |
| " | " | 60 " | 325 | land less old grade |
| " | S | 88 " | 500 | v |
| " | N | 87 " | 300 | v |
| " | S | 65 " | 140 | v |
| " | " | 70 " | 271 | v |
| " | " | 59 " | 284 | v |
| " | " | 71 " | 510 | v |
| " | " | 27 " | 150 | v |
| " | " | 54 " | 190 | v |
| " | N | 74 " | 272 | v |
| " | " | 70 " | 215 | v |
| " | " | 61 " | 176 | v |
| " | East | | 523 | v |
| " | N | 88 " | 292 | v |
| " | " | 76 " | 433 | v |
| " | " | 62 " | 400 | v |
| " | " | 42 " | 406 | v |
| " | " | 67 " | 205 | v |
| " | " | 59 " | 235 | v |
| " | " | 55 1/2 " | 435 | v |
| " | " | 72 " | 375 | v |
| " | " | 88 " | 220 | v |
| " | " | 57 " | 182 | v |
| " | " | 85 " | 334 | v |
| " | " | 72 " | 165 | v |
| " | S | 86 " | 252 | v |
| " | " | 87 " | 254 | v |
| " | " | 59 " | 533 | v |
| " | " | 76 " | 397 | v |
| " | " | 86 1/2 " | 420 | v |
| " | N | 82 " | 207 | v |

| | | | | |
|--------|---|--------|---|-----|
| Thence | N | 87 1/2 | E | 215 |
| " | S | 73 1/2 | " | 305 |
| " | " | 62 | " | 305 |
| " | N | 84 | " | 215 |
| " | S | 73 | " | 123 |
| " | " | 70 | " | 377 |
| " | N | 48 | " | 177 |
| " | " | 48 | " | 117 |
| " | " | 5 1/2 | W | 286 |
| " | S | 46 | " | 266 |
| " | N | 9 | " | 318 |
| " | " | 4 | E | 277 |
| " | " | 13 | " | 185 |
| " | " | 10 | " | 339 |
| " | " | 14 | " | 352 |
| " | " | 10 | " | 262 |
| " | " | 35 | " | 200 |
| " | " | 46 1/2 | " | 222 |
| " | " | 39 | " | 187 |
| " | " | 48 | " | 207 |
| " | " | 60 | " | 256 |
| " | " | 37 | " | 222 |
| " | " | 61 | " | 136 |
| " | " | 5 | " | 310 |

the course and distance
above given are the centers
and line of road

This 15th day of July 1922
Posted

NE Cor found NE tree OK green

Run W Var 3 1/2 E

8200 to flowage & outnotes say it is 5020. Looked for NW Cor ~~at~~ for 1 1/2 days and found it on W Edge of flowage. Two Pines & stump some marks left. The notes say it is on SE Post and Run S 9.50 over flowage to a point of hard land. found the West Line is all in flowage & the way to Stone Lake corrected. N. Line E and set W 1/8 Post at 21.37 1/2 E of NW cor SEEN 1/4 Pal

W from NE Cor Var 3 1/2 E

8200 to flowage
8538 fell 27 1/2 S. of NE corner found stp of W Pine some marks of scribbling iron ok The J. Pine is down but ok

copied

This corner is on W bank of flowage and 30 LK's N of flowage. Cout notes say it is 2450 farther west

Set Post and made new Bearings

B Pine 5 N 60 W 9 1/2

Birch 5 S 89 1/2 E 23

" 8 N 47 1/2 W 8 3/4

" 6 S 58 W 21

Dec 322

corrected line E to NE corner set W 1/8 Post on N Line at 2113 E of NW corner ~~Birch 5 S 58 W 21~~ W " 14 S 5 E 85

N 1/4 Post

W 1/8 Post { Birch 5 S 58 W 21
" 8 N 47 1/2 W 8 3/4

N 1/4 P Pine 12 N 46 W 18
W " 12 S 55 E 21

E 1/8 Post N Line

W me on N Line found both old trees dead. South one is down both dead marks ok Set new Post and made new B P Pine 11 East 28 1/2 Run E Var 3 1/2 E

SEC 32-39-9 Aug 14 1922
NE Cor found old Pine OK

west on 3 1/2 E

8100 Top of hill East side of Stream
8550 over Stream
8538 found stump of W. Pine BT also found the Y pine down The V Pine is only 3 feet from water on S. side Set new Post and made NEW bearings { B Pine 5 N 60 W 9 1/2
Birch 5 S 89 1/2 E 23

picked up my random line and at 8438 fell 27 N of Post Dec 322.

W 1/8 Post on N Line { Birch 8 N 47 1/2 W 8 3/4
" 6 S 8 W 21
N 1/4 P Pine 12 N 46 W 18
W Pine 12 S 55 E 85 ✓

E 1/8 Post N Line { aspen 6 N 16 W 28
" 4 N 33 E 14 1/2
corrected N Line all the way

N 1/4 Post S. on Var 3 1/2 E
over

NW cor. Run S

33. intersect flowage & stream

This line is in stream &

the whole length last it

me on line, on S. Lone Lake

found both original trees

both dead. S. one is down. OK

set new Post and made

NEW Bearing. W. Pin 11 East $28\frac{1}{2}$ Run E from me var $3\frac{1}{2}$ E

2183 to flowage at W. End of Old dam

2983 over "

dam

3238 over flowage at E. End of dam

5017 did not find SE corner

still East on same course

but began to chain new.

2269 Felt on a line full 1015

2269. or 5237 E of MC full 121 N

of $1\frac{1}{8}$ Post set in Oct 1906

had also set a post on bank

of stream 1645 N of SE cor

Began at this Post and

Run S and 1645. and

on this course 2048 W of

 $1\frac{1}{8}$ Post set at SE. corner{ Dead W Pin 2486 W $75\frac{1}{2}$

Picked my Random from

M.C. and at 5220 E of MC

Full 126 N of SE corner

Found an overrun of

of 203 between MC and

SE. cor. Proportioned same

and set ~~at~~ S. $1\frac{1}{4}$ Post at

4168 W of SE corner and 1058 E

of M.C.

N. $1\frac{1}{4}$ P. S. with var $3\frac{1}{2}$ E8097 full 86 $\frac{1}{2}$ W of S. $1\frac{1}{4}$ PostSE corner N var $3\frac{1}{2}$ E

1645 full 12 W of Post on S. bank of

stream found stump of FBT

& marked in 1906

3456 full 9 lks west of MC.

found stump & marked in 1906

{ W. Pin set 16583 W $25\frac{1}{2}$ { " " 12 N $87\frac{1}{2}$ E 36

corrected line to SE corner

as there is NO E or W $1\frac{1}{4}$ Posts

both are lake or flowage

& divided the ~~dist~~ distanceon N & S $1\frac{1}{4}$ line into 4 equalParts N $1\frac{1}{8}$ Post on $1\frac{1}{4}$ lineS. $1\frac{1}{4}$ P. { Y. Pin 12 N 66 W $12\frac{1}{2}$ on $1\frac{1}{4}$ line { " " 8 S $59\frac{1}{2}$ W $20\frac{1}{2}$ Center of SEC { Y. Pin 8 N $25\frac{1}{2}$ W 29

" " 8 S 84 W 21

 $1\frac{1}{8}$ P N of center { Y. Pin 12 N 54 W 34" " 12 N $43\frac{1}{2}$ E 43corrected $1\frac{1}{4}$ line fromN. $1\frac{1}{4}$ to S. $1\frac{1}{4}$ P.E from $1\frac{1}{8}$ P N of centervar 3° E E

834 E N E E SW dam

2235 over

4208 full 825 of MC which is

N. $1\frac{1}{4}$ P on E line

corrected line west to

 $1\frac{1}{8}$ P N of center and Prolongline west from $1\frac{1}{8}$ Post andset $1\frac{1}{16}$ Post in NW $1\frac{1}{4}$ 2100

{ ASPE 10 S 45 E 15

{ " " 8 N 10 W 16

2686 to flowage and set me

noting for Bearings over

see 32-39-9 cont aug 26"

West from Center Var $3\frac{1}{2}$ E
 3/15 to Flowage } 9 P.M. 10 S 10 E 20 $\frac{1}{2}$
 } Ashen 8 N 80 W 2 LKS

East from Center Var $3\frac{1}{2}$ E
 29 41 to Lake & set me
 } Tam stub 12 N 70 W 28
 } W.P.M. SEP. 14 N 5 W 13.

Finished Aug 26 1922 5 P.M.
 Rained a little all day

SEC 26-3510 Aug 30 1922

Found Darius West $\frac{1}{4}$ P M Road
 OK NO bearings But Post OK on
 a witness Pos 100 N. Var 5° E

W $\frac{1}{4}$ P North
 2760 to Lake am sure I found the
 original STPs of ME & ELL 75 W
 W $\frac{1}{4}$ P. E. Var $5\frac{1}{2}$ E

at 2060 Set $\frac{1}{8}$ P same distance as
 Darius ~~Set~~ $\frac{1}{8}$ claims it was on S. Line

{ Birch 16 S 1 E 12 $\frac{1}{2}$

{ Hem 14 N 8 W 46. Iron for Post

near N Side of Road

2120 Set Center of Section in road
 an Iron belt drawn an Iron Belt 37

S of center in edge of cut
 North from $\frac{1}{8}$ P E of W $\frac{1}{4}$ P. Parallel
 with west line. did not chain it

But set me on shore of Lake The
 distance is about 2500

me. Hem 8 S 35 E 9 $\frac{1}{2}$

Birch

11 S 18 W 12

POSTED

see 27-39-11 Aug 30 1922

found Darius N $\frac{1}{4}$ P OK and all his
 monuments just as his notes
 called for. found the distance
 from N $\frac{1}{4}$ P to center of SEC 1900
 His 16 Post in NW $\frac{1}{4}$ is a little over
 \$ 450. found The Thunder Lake
 Lbrco's Surveyors had made a
 mistake and TOOK E+W $\frac{1}{4}$ line
 for the N $\frac{1}{8}$ line

SEC 14 39-6. Sept 14 1922

Began at E $\frac{1}{8}$ P on South Line.
 which I set a few years ago
 Run E Var $3\frac{1}{4}$ E full 2 LKS of car
 OK did not chain this as I had chained
 it before and have my notes with me.
 Began again at $\frac{1}{8}$ Post and prolonged
 corrected Line W and set $\frac{1}{4}$ Post at 2000

{ Oak 9 N 8 E 45 $\frac{1}{2}$

{ " 8 N 85 E 38.

Prolonged corrected line west end
 at 839 State Highway

2254 intersect Tam and set M.C.

J. Pine 16 North 4 LKS

W " 24 S 85 E 16.

Then Platted Lake shore for me

C. Lawson: 7 P.M. 16 North 4 links

W " 24 S 85 E 16

POSTED

COPIED

SURVEY of Road for Pine Lake

in Sec 17. 39-9 Oct 6" 1922
 commencing at $\frac{1}{4}$ Post
 between Sections 17 and 20-3
 set new Post and made new
 Bearings $\frac{1}{4}$ Pine 12 N 5 W 24 $\frac{1}{2}$
 Thence S on $\frac{1}{4}$ line Var 1 $\frac{1}{2}$ E
 26.40. Thence S. 53 E. 13 88
 " " S. 73 0 E 17 0 4
 " " S 49 E 69 6 and
 intersect highway at a stake
 which stands 43 links north of
 Bridge on Pine Lake Road
 Whole length of Road
 surveyed 57 2 8

POSTED

SEC 30.38-6 Oct 9. 1922

commenced at the m.c. on the
 South Shore of Bear Lake. Between
 Sections 25-30. made new Bearings
 $\frac{1}{4}$ Pine 14 N 62 $\frac{1}{2}$ E 19.
 Run South from this m.c. Var 3 $\frac{1}{2}$ E
 3095 feet 152 W of m.c. on north
 shore of Lake, found on org. tree
 This 500 N 63 W 14 and WALL 6 N S B T
 Tam 4 N 32 E 15 Lks. set new Post

and corrected line N to m.c.
 South from N $\frac{1}{4}$ P by DHU, Var 3° E
 255 to Lak and set m.c. $\frac{1}{4}$ Pine 9 62 E 8
 3265 over Lake 4002 feet 16 N of $\frac{1}{4}$ P
 4002. Found old line and part of the
 N Birch org. tree

Set new Post $\frac{1}{4}$ Pine S P 34 S. 17 W 5 8
 NE corner set by DHU who surveyed
 Sec 19 Run South Var 3 $\frac{1}{2}$ E
 4002 feet 16 E of $\frac{1}{4}$ P.
 East from $\frac{1}{16}$ Post in NE $\frac{1}{4}$ Var 2° E
 1515 leave Lak and set Post

SEC 30-38-6 cont

Run on $\frac{1}{4}$ line Var 2° E
 688 m.c. set Post for m.c. $\frac{1}{4}$ Pine 12 N 76 E 48
 " " 12 S 11 $\frac{1}{2}$ W 70
 Center of Sec. $\frac{1}{4}$ Pine $\frac{1}{4}$ Pine S P 36 S 42 W 49
 Dist to N $\frac{1}{4}$ P 4081
 " " S " " 4069
 " " E " " 4069

Copied in Book
3-6

copied

mean on N shore of Lak 742

BOOK 9 pasted to here

SEC 1-35-8 Town of
Harrison meal m.c.

S $\frac{1}{4}$ P. OK RUN N Var 3° E
 7722 feet 528 E of N $\frac{1}{4}$ P OK

NW COR OK RUN E Var 3° E
 7955 feet 49 S. of Town corner
 E $\frac{1}{8}$ P on N Line $\frac{1}{4}$ Hem 28 S 36 E 19
 $\frac{1}{4}$ Maple 7 S. 3 $\frac{1}{2}$

W $\frac{1}{8}$ P on N Line $\frac{1}{4}$ W Birch 7 S 15 W 1 Link
 cedar

S E N $\frac{1}{4}$ P at 3977 $\frac{1}{4}$ W PINE 12 S 13 E 30 $\frac{1}{2}$
 East from N $\frac{1}{4}$ Post
 3893 m.c. set N + S 174 Lks + set center
 on iron $\frac{1}{16}$ P E 37 11 To W $\frac{1}{4}$ P 3893
 DIST: E $\frac{1}{4}$ P 4005. SET $\frac{1}{8}$ P. S. o center of
 " S $\frac{1}{4}$ P 20 12 $\frac{1}{2}$

SET $\frac{1}{8}$ P N of center at 5738.
 S $\frac{1}{8}$ P on W Line East 3985 feet 44 S. of
 $\frac{1}{16}$ Post set at 1922 $\frac{1}{2}$

90 SEC 33-39-7 Oct 25 1922 ^{Book 53} 133

Began at the $\frac{1}{8}$ Post E of center
Set by barn

Run LE via 7th

340 intersect Lake Mc Gon. Restored
609 over "

2002 full 146 N of E $\frac{1}{4}$ Post found
my bearing found a large fence Post
Set where $\frac{1}{4}$ P. stood.

went west and set me on E shore of
Lake & W Pin set p 28 N 89 E 82.

Set me on W shore of Lake 340
E. of $\frac{1}{8}$ P. oak 5 N 63 W 18

Set at E highway is 100 N of E me
" 160 E " " "

North from west me corner

300. to PK Wright Road. Set at Highway
15 240 East.

500. it is 300 E to State (road) highway

1210 State highway.

from $\frac{1}{8}$ Post E of center it is

315 S. on $\frac{1}{8}$ line to lake & me.

copied

SEC 536-7 Oct 22 1922

91

SURVEY of Road for the
TOWN of Woodboro
commencing at a stake
which stands 575. East of ~~lake~~ lake
between and on line ^{between}
Sections 5 & 8 Town 36-8

Thence S. 51 E. 403

N 88 E 270

70 " 197

copied " S 82 " 330 post

" N 30 " 275 copied

" " 30 " 30

" " 76 " 315

" " 40 " 970 and intersect

N & S Town Road in said Sec 5

The courses and distances above
given as the center and line of
Road.

92 SEC 32-38-8 NOV 11 1922

Center of SEC. Run West on Line of
fence going East
918 small stumps
1985 Wisconsin River. Highbanks
2000 to River Set Stake at 1985

SEC 35-37-7 NOV 21-1922
NW COR OK SET 12 years ago

" " E Var 3° E
8061 fell 99 N of NE COR OK org
corrected Var 2° 18'
S 1/4 P org bearings Run N Var 3° E
8048 fell 14 W of N 1/4 Post made
NEW BTS W Pine stp 16 S 72 E 24 1/2
S 1/8 P on W Line Set b DHU 12 years ago OK
" " " East Var 365 E
8052 fell 100 W of S 1/8 P on E Line
Set by DHU 12 years ago. from
Point of his Post Rock around it
also stump of his BT
Set 1/16 post in SE 1/4 at 6036
E of S 1/8 P on W Line
Set 1/8 P South of center at 2040
N. of S. 1/4 P
and 4022 E of S 1/8 P on W Line
1/16 Post in SE 1/4 N 15°
4017 fell 70 W of E 1/8 Post on N Line
E 1/8 Post on N Line W Pine stp 15 N 26 W 163
" " " 14 East 44
finished Nov 21 1922
Posted into County record of 37-7

#48 1/4 P between
Sections 3+4-35-4

DEC 20 1922
This 1/4 P was Lost and
restored by the evidence of
6 men who swore to its original
Position. and show an iron
monument 1 inch in diameter
and 22 inches in ~~the ground~~
in Length. Leaning it 6
inches above the surface
and made new bearings
cedar stump P 18.5 27 1/2 W 7 1/2
STEP 16 N 54 W - 83

SURVEY OF ROAD FOR TOWN
SUGAR C CMB on Jun 8, 1923
commencing at the
corner of sections 28+29.
32+33 TOWNSHIP 39 N. R. 9 East
thence East 42.42 chains to
west line of county highway
The course and distance
above given are the
center and line of Road
ALSO beginning at same
see Page 98

94 Survey of road for Town of

Woodboro. Oct 24-1922

Commencing at a Stake which stands 575 chains East of Lake on the section between Secs 5 & 8 in Township 36 N Range 7 East

Thence South 51° E 4.03 chains

| | | | |
|---|------|-------|-------|
| " | N 88 | W 270 | " |
| " | " 70 | " 197 | " |
| " | S 82 | " 330 | " |
| " | N 30 | E 275 | " |
| " | " " | " 30 | " |
| " | " 76 | " 513 | " |
| " | " 40 | " 970 | " and |

intersect the Nelson road in Section 5. Whole length of road is 25.90/100 chains

The courses and distances above given are center and line of road

SEC 19. 35-8 JAN 2-1923

E 1/4 Post Found on old Post Birch gone

Tam down & rotten 8° E

Run W. Van

69 full W of 1/4 P marks gone

Post is ok

N 1/4 Post orig bearings ok

Run S South Van 8° E

full south of S 1/4 P ok

Finished by LJM

Section 1 37-9 E

MAY 2nd 1923

SW COR IRON PIPE IN CENTER OF E+W ROAD SEE SEC 139-6 RUN N. ON WEST LINE. FOUND 1/4 P AND NW CORNER S.E. CORNER

SEC 12-368 MAY 14-1923

SURVEYED A PIECE OF LAND AS FOLLOWS TO WIT

Commencing at an iron pipe W stands on westerly line of State Highway and 500 feet northerly from a point where said Highway intersects the line between lots 5 & 6 in said section 12. Thence N at right angles with State Highway 500 feet to a stake. Thence northerly at right angles and parallel with said Highway 100 feet to a stake. Thence easterly at right angles 500 feet to an iron pipe which stands on westerly line of said Highway. Thence southerly on westerly line of said 100 feet to an iron pipe and place of beginning

W 1/4 Post in E+W Road end
bearing SE um bok
Run N Var 3 1/2 E on em offset
0.5 Lks East to miss flnc
4020 fell 25 Lks E. of NW corner
one offset: BT. Large fence post
for corner

my Random is 25 E of cor
but this includes the offset
see N 1/8 Post on west line
and corrected South to 1/4 P

Survey of Road for
the Town of Sugar Camp
continued June 8-1923

Thence west on line
between sections 29 + 32
64.02 to the west 1/8 Post
on the north line of
section ~~30~~ 32.

the course and distance
above given are the center
and line of Road
COPIED into -39-9

NE COR is in cent of N+S Road
2.75 North of angle in Road
Run South Var ~~2 1/2~~ E 9° W
76.58 fell 3.00 East of S E corner
Correct Var 11° 13' West

NE COR RUN W. VAR 3 1/2 E
800 fud and swamp
1000 enters Swamp over field + Swamp
3600 enters Swamp
39° 02' fell 247 N of Dorr's 1/4 Post of
correct line East and Set
1/8 Post Nothing for bearings
Corrected Var 7.07' E

SW COR NEW TEL Pole 9 S 44 E 35
Run E Var ~~2 1/2~~ E 13° E
3475 fell 35 North of Dorr's 1/4 P
Corrected Var 12° 24'

S 1/4 Post NEW { W. Birch 4569 W 11
no other
S 1/4 Post on corrected line
Var 12
3475 SEE SE corner
Tam 6 N 60 E 45

SW cor N. Var 4° W on Road
4118 Burnstein Supported 1/4 P
8170 fell 62 W of NW corner ok

N 1/8 on W Line 6127 1/2 & 46 E
E of Random { Boulder 1111 and
7 feet high with
hole near bottom Facing
a crease down N 80 W 25

W 1/4 P. Iron pin Set at 4085.
and 31 E of Random

Copied into 39-9

SEC 15-37-9 cont

S 1/8 P on Westline Tel Pole
7. S 40 W 38 on Iron Pine Road

E 1/4 at 3844.150 W of Random
{ Spruce 6 N 6 W 7 1/2

{ " " 5 S 47 W 4 Iron Pine
S 1/8 on E Line { W. Pine 20 S 23 W 74 Run

center sec. Tam 8 S 7 E 9 man

Dist to N 1/4 P. 3954

" " E " " 3992

" " " " 3682

" " W " " 3640

1/8 P S. of center (J. Pine) N 42 W 62 1/2

1/8 P S of center West

1300 center of highway

3552. Full 3. 26 S of 1/8 P

corrected. corrected east and

Set 1/16 in S W 1/4 is a bed of boulders
on Iron Pine crevice (ashen) S 10 W 16

when 8 S 76 E 27

W 1/8 P S line { Y Pine 20 S 34 E 40

N on 5 1/2 E

1982 fire 71 W corrected line South

1/8 P E of center (J. Pine) 10 N 26 W 38 1/2

B. Pine N 86 E 41 1/2

1/8 P E of center N on 9 W

1270 center of highway

3848 full 11 W of 1/8 P.

corrected line South & set 1/16 Pine

N 1/4. { Spruce 6 N 28 W 8 1/2

tanable 5 S 19 W 11

N 1/8 P on E line Spruce 6 N 28 E 35

2 1/8 D N of center Spruce 6 North 12

" " 6535 W 15 1/2

copied in to county records

in Book 37-9 Pages 61-2

51-2

SEC 7-36-8 JULY 25 1923 99

NE cor OK Run South Var 11 E
2183 my Temp. 1/8 P on line
7270 to Crescent Lake No MC
8586 over Lak. full 430 E of
MC. on South Shore of Lake OK
DEC 505 change course

corrected Var 2'
Change Course 2.45'

as MC is gone on N + W
Shore of Lake caused by plugging
and the Lake is now at its
original stage & set N + W MC
on shore of Lake

Set 1/8 Post on E Line at 6000
S of NE corner Iron Pine
for 1/8 Post and both MC corners
corrected line N to Right way
of 500 R

Found Dorr had South
Line and set E 1/8 P on S. line
distance from S 1/4 P to ~~an~~

To 1/8 P is MC is 1023. Chain
Dorr says it 3659 from S 1/4 P
to org. MC is 3659 and the
1/8 Post is 2323 E of S 1/4 Post

copied into book 36-8

100 Survey of Road for the

Town of Sugar Camp

August 28-1923

commencing at an iron
E monument which stands
in the center of County Trunk
Highway, 1400 chains north of
the South 1/4 Part of Section 16
T^h township 38. N. R. 10 east

There, north 49 degrees east
2378 ch

| | | | |
|----------|-----|---|------|
| Thence N | 49° | E | 300 |
| " | 85 | " | 350 |
| " | 60 | " | 300 |
| " | 85 | " | 200. |
| " | 60 | " | 2200 |
| " | 35 | " | 127 |
| " | 85 | " | 241 |
| South | 50 | " | 336 |

To East line of lot 2 in said

Block B⁶th whole distance 4472

at 1/2 mile and 19 rods

copied in Book 38-10

copied in Book 38-10

SEC 18-39-9 Aug 23 1923 101

NE cor W Va -

7700 Full 488 S of NW cor ok

change course 3.87 = 388 W Va
see for correction 0634

NW cor } Pin Stake 10 S 12 E 45

Set a W on N Line at 573 1/2 36 N of Road

W 1/4 N Line } B Pin 4 S 54 W 18 1/2
" " 4 S 1/2 W 28 1/2

Set N 1/4 P at 38 21 + 24 1/2 N of Road

Pin Stake N 1/4 N 4 W 26

J. 24 S 1 W 60

E 1/4 P N Line } as per 6 N 78 E 48 1/4
Oak 4 N 8 1/2 W 7 1/2

NE cor } Pin Stake 16 N 77 W 34

N mc on W Line org. lines down and
burned but marks ok and new one
} Pin 10 N 75 E 48

N mc on West line Run N Va 2.45 E
6943 full 180 W of NW cor

Set N 18 P on W Line at 4945 N of mc

} Pin 8 S 51 W 90

Oak 3 S 21 E 4 3/4

Set W 1/4 Post by professional measurement
at 2947 N of mc

} Pin 16 N 47 E 64 1/2

" " 10 S 41 E 70

S 1/4 P on W Line at 949 N of mc by
Proportion } Pin 8 N 51 E 22

change course 1° 28" = 117 E

SEC 18 is in center of ^{NEW} Road

SE cor. W Pine Str

16 N 42 W 38 1/2
 12 S 2 W 58 1/2

E SE cor. Run W Van 1 W

3999 Full 440 S of S 1/4 Post
 E 1/8 P on S line } oak 4 N 49 W 11

S 1/4 P West Van 6 21 E

2863 Full 51 N of MC. } W Pine stub 12 S 22 W 25

E 1/8 Post on South line by Proportions at 1993

E 1/8 on S line } oak 4 N 49 W 11
 W Pine stub 10 S 6 E 15 1/2
 Aspen S 6 E 15

West from S 1/4 P Van 6 21

2863 Full 51 N of MC. } W Pine 12 S 22 W 35

E 1/8 P on N line ^{North} Van 130 E

2028 Set 1/16 P in NE 1/4

~~5185~~ 118 to Lake set MC Not by bar BTS

N 1/4 P South Van 1.15 E

2014 Set 1/8 P N of center

2137 Lake and set in center Then 50 Lk. to Lake

South from W 1/8 P on N line Van 1.15 E

7946 1/2 Full 37 1/2 E of W 1/8 P on S line

4008 Set 1/8 P west of center

2004 Set 1/16 P in NW 1/4

5977 Set 1/16 P in SW 1/4

W 1/4 Post East than and Set 1/8 Post
 West of center at 1900 and 20 W of Road

SURVEY of Road for the
Town of Sugar Camp.

commencing at an iron
 monument which stands 111 centers
 of County Trunk Highway and 1400
 North of the North 1/4 Post of
 Section 16. in Township 38 N. R. 10 E
 Thence N. 49 E. 2378 chains

| | | | | |
|--------------------------|--------|----|-----|--------------------|
| " | " | 18 | 606 | " |
| " | " | 42 | 100 | " At its on |
| This course enters Lot 2 | | | | |
| Thence | N 60 E | | 300 | SEE Page |
| " | " | 18 | 300 | |
| " | " | 60 | 350 | 100 |
| " | " | 85 | 300 | |
| " | " | 60 | 220 | |
| " | " | 80 | 147 | |
| " | " | 60 | 241 | |
| " | " | 50 | 366 | To E Line of Lot 2 |

Whole distance 3942 chains
 4 Rods Less than 1/2 mile
 The courses and distances above given
 are the center and line of Road

104 SEC 34-36-4 Sept CDV

NWC corner found iron pins
Set by D H Vaughan bearings gone

E Iron is in center of road goes
West and East & South

Run S. Var 2.45' E

7901 Hat corner between 3 & 34

3950 1/2 SE 1/4 Post bet 3 & 34

which stands in center of Road
going N & S and West

{ W Pin Set 16 N 82 E 43 1/4

S 1/8 W. Line at 1926
16 S 34 W 35

N 1/8 on W line { Elm 4 S 82 1/2 W 44 1/2
at 1975 (Iron)

{ W Pin Set 16 S 49 E 65 1/4
IT is N 6 1/2 W 121 to South end of
concrete Culvert

East from NW corner 6.45 E

8060 Hit NW corner. Could not find
iron P.P.E set corner from

D HURT Birch 3 N 76 E 54 Iron
for corner

N 1/4 P at 4030. W Pin Set 16 S 51 W 64
iron for Post

E 1/8 P. on N line at 6045 on line
iron for Post

SEE 34-36-4

105

Set W 1/8 P on Line at 2615 on
line iron for corner

{ W Pin Set 24 S 27 E 42 3/4

E from NW corner var 6.45' E

8060 Hit NE corner could not
find pins. Set corner from Birch
marked by D H V. NEW IRON

Set N 1/4 P at 4030 on Line Iron

{ W Pin Set 16 S 51 W 63 3/4

" Hem St P 18 S 50 E 51

W 1/8 P on N Line at 2015 2615

Iron for Post. W Pin Set 24 S 27 E 42 3/4

Set E 1/4 P at 4084 Iron

Located SE corner W Pin Set by D H V

{ W Pin Set 30 N 26 W 143 3/4

{ Elm 14 S 42 E 177 1/2 Iron

N from SE corner var 2 1/2 E

8168 Hit NE corner at ~~6126~~

S 1/8 on E Line 6126

{ Hem Set Pin 89 E 66 1/2

S 1/8 on E line at 3042

{ Hem St P 18 S 38 W 59

maple 8 N 59 E 39 1/2

Iron monuments for all corners

19
 sec 11-38-11 Oct 24, 1923

aprec of land in govt lot 4
 sec 11-38-11 described as follows
 To wit: To arrive at the place
 of beginning. commence at
 a stake which stands on shore of
 Virgin Lake where the N + S $\frac{1}{4}$
 line intersects said lake and is
 269 feet north of the south line
 of said lot 4. Thence northeasterly
 along shore of lake 460 feet and
 place of beginning.
 Thence east 86 feet to a stake which
 stands the westerly line of said highway
 Thence south 10° E along said line
 of highway 349 feet to a stake.
 Thence south 38° West
 59.5 feet along private road to
 a stake Thence North 52° West
 272 feet to a stake and the
 place of beginning
 from monuments placed at all
 stakes sit. and also at shore of Lake
 where the N + S $\frac{1}{4}$ line intersects
 lake.
 copied in to book 38-11 on
 Page 45.

see 2438-10

NOV 9, 1923

went to the center of sec 1
 found my first post
 found at the corner in the
 in the SW of 38 $\frac{1}{4}$ and set
 new post B, ok.
 The 178 P 3 of center the maple
 as dow for land mark
 The 378 on E line post and
 beams ok
 my Farm Survey Survey
 was made see 1909
 see Book 6 Page 118

SECTION 16.39-6

SEC 17-39-9 Oct 3rd 1923

SW Corner ok. 1 from pike in center of Road
 Run N 1/4 3 1/2 E
 3754 f ell 72 West of M.C. SEE NEW
 Post. Corrected line South to corner
 at 2098 found Someones' 18P
 on corrected line did not know it
 (Copied into Book 39-9)

--- MARCH 27 1924 ---

SEC 16-39-6 March 27/1924

W 1/4 Post. found step of original
 marks ok

Run S. Var 1.30 E
 40.06 f ell 67 West of corner

which f set from orig B.Ts 20

years ago. SEE S 1/8 Post on

WEST line at S E S 1/8 P on W line
 at 2003. and 33 1/2

Y Pms 8 S 1 E 9 1/2
 " " 7 N 36 W 10 1/4

Post ed in Book 396

PAGE 65

SEC 16-39-6 Sept: 1920

N 1/4 P. set by Dorr found meander eas
 East of N 1/4 P. by Vaughan
 N 1/4 Post W Var 4 1/2 E
 2061 f ell 16 S of Dorr's 1/8 Post
 W 1/8 P on N Line NEW Pms 8 S + E 31
 NW Corner found the east orig line also
 Dorr's B.T. } Pms 10 N 63 1/2 W 19
 " " 10 10 OK 10 S 86 1/4 E 48 7/4

NW Corner S Var 2.45 E

2500 Pond

3500
 3812 f ell 34 1/2 E of 1/4 Post. found at P of orig

W 1/4 P NEW. } Pms 14 N 25 E 77

South from W 1/8 P on N Line var 2 1/4 E at
 3812 and E from W 1/4 Post var 4 1/2 E

2061. drew lines together and set 1/8 Post

West of center. Run 6 S 6 W. 8. and
 Prolonged line E to Lake and set me

Branch 5 S 31 W 8

2061 8 N 8 W 7 1/2 set 1/16 Post in NW 1/4

Y Pms 10 S 11. E 28

March 27-1924

W 1/4 P. OK am S Var 1 1/2 E

40.06 f ell 67 W of corner which I set
 from orig trees about 20 years ago

SEE S 1/8 P on W line at 2003 and 33 1/2 E

of Random } Pms 8 S 1 E 9 1/2

" " 7 N 36 W 10 1/4

Apr. 30, 1924

119

Section 23 - 36 - 9

N.W. cor. found org. cor. identified from bearings made by myself several years ago. As these bearings about to be destroyed Made new bearings Iron Mon.

{ N. 64 E. 145 1/2
S.W. Cor. of School House bears
N. 45 1/2 E. 203

Ran E. 2186 found bearings for 1/8 P. Which I set several years ago. Placed an iron mon. 50 lbs. S. and one 50 lbs. N. of 1/8 P. At 42.92 found 1/4 P. and placed iron mon. same as at 1/8 P. At 64.38 found E. 1/8 P. on N line. Placed iron mon. same as at 1/4 P.

At 87.85 found my bearings for N.E. cor. and made new bearings

{ Y Pine 6 N 37 1/2 W 48
Remarked my org. B.T.

Ran S. from N.E. cor. Var. 3 1/2 E.

NE corner P.M. 6 N 37 1/2 W 48
Y Pine 8 S 35 W 50 1/4

NE COY NEW Pine 14 N 61 W 131

" 141

Placed iron mon same as at 1/8 P.

SEC 23 Cont

MAY 3, 1924

South from NW cor 2 1/2 E
206 f. w. 29 E of 1/8 Post. found my B.T.s and Pos and drove an iron monument 41 22 on cornered line found my org 1/4 Post.

South from W 1/4 P on cornered line 4074 fell 80 1/4 E of SW corner. found my Post ~~at~~ which I set in 1910 from org B.T.s took bearings made by monster

{ Tam 7 N 58 1/2 W 52

{ Pine 10 S 39 1/2 E 75

Went N and at 2032 found my 1/8 P set in 1910 { Tam 12 N 74 1/2 E 66 1/4

{ S. Van 3 1/2 E

NE. cor

112 SURVEY of Road for the

Town of Crescent in sections
20 and 21. 36-8. JULY 14 1924

commencing at the $1/8$ Post
east of the center in section

20. Thence east on $1/4$ line

to the $1/4$ Post between section

20 and 21. Thence east on the

$1/4$ line in section 21 to the
 $1/8$ Post west of the center of 21

All in Township 36 N Range

8 East E.

Posted in BOOK 36-8

PAGES 113-174

BLANK

SEC 25-39-6

North from W $\frac{1}{4}$ POK U $\frac{1}{2}$ E

1939 fell 116 W of barn $\frac{1}{8}$ P

East from This $\frac{1}{8}$ Post U $\frac{1}{2}$ E

1600 feet 8. South of barn m $\frac{1}{2}$ E.

South from barn m $\frac{1}{2}$ E U $\frac{1}{2}$ E

5.00 1E, 1577 W to Shore of Lake

1000 "

61 " To a Point of Land which extends

S. E from shore of lake. It is 100

wide and extends S. E. 400 ~~feet~~ ^{feet} ch

1939 Set Stake on ice and went to W

$\frac{1}{4}$ Post and run East U $\frac{1}{2}$ E

and Parallel WIL 18 line

1545 line 2 $\frac{1}{2}$ N of Stake on ice

Went from a stake on ice which ^{is} 800 North

of SE cor of Lot 5 U $\frac{1}{2}$ E

50. Shore of lake

129 to Woodards line

1524 fell 33 N of a stake on W line and 800

ft of West $\frac{1}{4}$ Post

INDEX

INDEX

| Section | TOWNSHIP | | RANGE | | CITY OR VILLAGE | ADDITION |
|--------------|----------|----|-------|----|-----------------------|----------|
| | N. | S. | E. | W. | | |
| 4 | 3 | 5 | 4 | | | |
| 1.2.11-12-35 | | | 8 | | | |
| 7 | 3 | 6 | 8 | | | |
| 35 | 3 | 5 | 11 | | | |
| 36 | 3 | 5 | 11 | | | |
| 20 | 3 | 9 | 10 | | | |
| 17 | 3 | 6 | 8 | | | |
| 24 | 3 | 7 | 7 | | | |
| 7 | 3 | 6 | 8 | | | |
| 27 | 3 | 9 | 6 | | | |
| 23 | 3 | 7 | 10 | | | |
| 29 | 3 | 7 | 10 | | | |
| 16 | 3 | 9 | 6 | | | |
| 1 | 3 | 9 | 6 | | | |
| 5-6-18 | 3 | 8 | 12 | | | |
| 748 | | | | | | |
| 27 | 3 | 8 | 11 | | | |
| 19 | 3 | 9 | 11 | | | |
| 14 | 3 | 5 | 10 | | | |
| 12 | 3 | 5 | 10 | | | |
| 33 | 3 | 8 | 8 | | | |
| 29 | 3 | 6 | 8 | | | |
| 14 | 3 | 5 | 10 | | | |
| 18 | 3 | 6 | 8 | | | |
| 243 | | | | | | |
| 3 | 3 | 8 | 7 | | | |
| 10 | 3 | 8 | 7 | | | |
| 6 | 3 | 9 | 12 | | | |
| 11 | 3 | 7 | 9 | | | |
| 25 | 3 | 7 | 8 | | | |
| 23 | | | | | | |
| 30 | 3 | 7 | | | | |

Town of Woodruff

under See 5963 R.S. 1919

Set 1/8 P South of center
Birely

Road for new bald

INDEX

| FOR WHOM SURVEYED | WHEN | | | Page |
|------------------------------------|-----------------|-------|------|-------|
| | Day | Month | Year | |
| Bissell & Co | 4 | Aug | 1920 | 1 |
| Town of Harrison | 21 | " | " | 1 |
| F E Parker | 1 28 | Sept | 1920 | 29 |
| Town of Schaefer | 2 | AUG | " | 10 |
| " | 19 | JULY | " | 7 |
| " " Sugar Camp | 17 | AUG | " | 12 |
| Liberty Land & Investment Co | 12 | Oct | " | 3 |
| High Land SHEEP Co | 13 | " | " | 3 |
| Liberty Land & Investment Co | 18 | " | " | 29 |
| | 20 | July | 1919 | 4 |
| LARSON | 25 | OCT | 1920 | 5 |
| MILLER MERDITH | 20 | JULY | " | 6 |
| WASSERBURGER | 10 | Oct | " | 14 |
| Surveyed under Section 5963 | 2 | DEC | " | 15 |
| Thunder Lake Lbr Co | 21 | " | " | 17 |
| Town of 3 Lakes See 5963 R.S. 1919 | | | " | 21 |
| John F. Pope et al | 21 | Feb. | " | 20 |
| Loais Pope et al | 21 | Feb | 1921 | 20 |
| Joseph Roder | 1 | april | 1921 | 21 |
| Banta | | | " | 21 |
| See Banta | 2 | " | " | 22 |
| See 5963 R.S. of 1919 | 11 | " | " | |
| Roder | 10 | " | " | 21 |
| Town of Woodboro | 20 | Apr. | 1921 | 23-24 |
| - Larson | 26 | " | " | 24 |
| Road for town of Woodboro | 28 | " | " | 25 |
| Mr Ebert | 2 | May | " | 25 |
| " | 2 | " | " | 26 |
| Laughan of Woodruff | 9 | " | " | 27 |
| See 5963 R.S. w/ls 1919 | | " | " | 28 |
| Town of NEWBOLD | 12 | " | " | 30 |
| " | 14 | " | " | 30 |
| See 4963 R.S. | 9 | Jan | 1921 | 64 |

INDEX

| Section | TOWNSHIP | | RANGE | | CITY | ADDITION |
|---------|----------|----|-------|----|--------------------------------------|----------|
| | N. | S. | E. | W. | VILLAGE | |
| 9 | 39 | | 9 | | Sec. 5963 R.S. 1919 | |
| 29 | 40 | | 5 | | no good E 1/4 McELINE | |
| 11 | 39 | | 6 | | | |
| 24 | 36 | | 7 | | | |
| 29.30 | 36 | | 4 | | Road for town of Lynn | |
| 26+35 | 36 | | 4 | | Willow Lak Road in "36-4" | |
| 20 | 39 | | 5 | | | |
| 29 | 39 | | 11 | | Road for Town of Three Lakes | |
| 19 | 35 | | 11 | | under Sec 5963 RS | |
| 3 | " | | 8 | | | |
| 16+23 | 38 | | 8 | | Road for NEWbold | |
| 33 | 39 | | 7 | | Aug 26 - 1921 | |
| | | | | | Began at 1/8 P. E. of center by barn | |
| | | | | | Run N on 3/4 E | |
| 33 | 39 | | 7 | | Aug 27 - 1921 | |
| 33 | 35 | | 8 | | School ground at SE of Lake | |
| 33 | 39 | | 7 | | | |
| 35 | 35 | | 13 | | | |
| 7 | 39 | | 5 | | | |
| 9 | 35 | | 12 | | | |
| 32 | 39 | | 11 | | | |
| 23.24 | 37 | | 10 | | Road for Starks co | |
| 9 | 38 | | 7 | | | |
| 11 | 39 | | 6 | | a piece of land in lot 4 | |
| 1920 | " | | 7 | | Road for Town of Woodruff | |
| 30 | 38 | | 7 | | | |
| | | | | | Road for Town of Woodruff | |
| 1 | 39 | | 5 | | 25 acres in lot 4 | |
| 8+17 | 37 | 10 | | | Road for the town | |
| 22 | 37 | 8 | | | | |
| 28 | 35 | 10 | | | School ground | |
| 13 | 35 | 10 | | | Road for Kable and his | |
| 2 | 33 | 10 | | | | |
| 25 | 39 | 6 | | | | |

| FOR WHOM SURVEYED | WHEN | | | Page |
|---------------------------|------|-------|------|------|
| | Day | Month | Year | |
| Frank Creek ET. AL | 23 | May | 1921 | 38 |
| frd Henning | 31 | " | " | 35 |
| AJ Bolger | 4 | June | " | 39 |
| ANNABELLA Heckerling | 6 | " | " | 36 |
| Road for Town of LYnn | 15 | " | " | 38 |
| " " " " " | 16 | " | " | 38 |
| Set iron monuments | 13 | " | " | 39 |
| Mr NELSON | 28 | " | " | 39 |
| Road for Town of 3 Lakes | 5 | JULY | " | 40 |
| Town of Schoepke | 18 | " | " | 41 |
| Leonard Chas Stunt | 8 | Aug | " | 47 |
| NEWbold | | | | 47 |
| Callins & Bunge | 26 | April | 1921 | 48 |
| Leonard S & Farm | 1 | Aug | 1928 | 46 |
| Town of School board | 8 | " | " | 47 |
| Bunge and Collins | 26 | " | 1921 | 50 |
| Keith and Hills | 30 | " | " | 51 |
| B. O. Larson | 1 | Sept | " | 51 |
| Keith & Hills | 14 | " | " | 51 |
| Frank Weiss | 18 | " | " | 53 |
| Starks & wife | 23 | " | " | 53 |
| State Turbocals asyllum | 3 | oct | " | 54 |
| AJ Bolger | 8 | " | " | 54 |
| Ma Lotski | 18 | " | " | 55 |
| Mat OLSki | 24 | " | " | 56 |
| in Sec | 15 | " | " | 57 |
| V. H. Arch | 27 | " | " | 58 |
| of Steels | 2 | Nov | " | 60 |
| Polock | 5 | " | " | 60 |
| Town of Enderben | 8 | Dec | " | 61 |
| Platted lots etc | 5 | " | " | 62 |
| Truman Rice | 19 | " | 1921 | 63 |
| Chicago Party A. O. Dorem | 31 | Jan | 1922 | 66 |

INDEX

| Section | TOWNSHIP | | RANGE | | CITY OR VILLAGE | ADDITION |
|---------|----------|----|-------|----|--|-------------|
| | N. | S. | E. | W. | | |
| 39-20 | 39 | | 7 | | Road the | township of |
| 10 | 39 | | 6 | | | |
| 4 | 38 | | 11 | | | |
| 30 | 37 | | 7 | | | |
| 15 | 36 | | 9 | | | |
| 4 | 37 | | 8 | | | |
| 25 | 39 | | 6 | | | |
| 16 | 38 | | 8 | | | |
| 12 | 37 | | 8 | | | |
| 22 | 38 | | 11 | | | |
| 4 | 35 | | 4 | | | |
| 32 | 36 | | 7 | | | |
| 19 | 36 | | 6 | | | |
| 7 | 36 | | 8 | | | |
| 3 | 36 | | 7 | | | |
| 17 | 38 | | 6 | | | |
| 9 | 38 | | 6 | | | |
| 32 | 39 | | 9 | | | |
| 26 | 35 | | 10 | | | |
| 27 | 39 | | 11 | | | |
| 32 | 39 | | 9 | | | |
| 14 | 39 | | 6 | | | |
| 2017 | 37 | | 9 | | | |
| 30 | 38 | | 8 | | | |
| 13 | 35 | | 8 | | | |
| 33 | 39 | | 7 | | Road for woodboro | |
| 5 | 36 | | 7 | | | |
| 32 | 38 | | 8 | | | |
| 35 | 37 | | 7 | | | |
| 344 | 35 | | 4 | | Town of Somers | |
| 19 | 35 | | 8 | | | |
| 1 | 39 | | 7 | | woodruff | |
| 12 | | | | | | |
| 15 | 37-9 | | | | under the provision of section 5963 | |

INDEX

| FOR WHOM SURVEYED | WHEN | | | Page |
|------------------------------|------|-------|------|------|
| | Day | Month | Year | |
| woodruff | 15 | oct | 1921 | 57 |
| AJ Bolger | 9 | feb | 1922 | 68 |
| FALLON & BONOWSKI | 15 | " | 1922 | 69 |
| SEC 5963 RS | 19 | apr | " | 70 |
| | 25 | " | " | 70 |
| | | " | " | 70 |
| OA Durum | 20 | " | " | 70 |
| Shurtz | 26 | " | " | 70 |
| Larson | 1 | may | " | " |
| Klose Resat | 2 | " | " | 72 |
| NORLON | 22 | " | " | 73 |
| John Hess | 17 | " | " | 73 |
| Town of Hasehurst | 6 | June | " | 75 |
| Liberty Land & Investment Co | | " | 27 | 78 |
| | | may | 2 | 79 |
| Town of Hazelhurst | 24 | may | 1922 | 74 |
| Bennet | 21 | may | 1922 | 67 |
| Charles Conro | 14 | aug | " | 82 |
| Fans Evans | 28 | " | " | 86 |
| Praehers association | 30 | " | " | 87 |
| EVA CLAWSON | 14 | SEPT | " | 87 |
| Town of Pine Lake | 6 | oct | " | 88 |
| John Swartz | 9 | " | " | 88 |
| Town of Harrison | 19 | " | " | 89 |
| T. W. Bubmann | 25 | " | " | 90 |
| | | oct | " | 95 |
| Town of woodboro | 24 | " | " | 92 |
| | 11 | Nov | " | 92 |
| | 21 | " | " | 93 |
| Brown of Waupesa | 20 | DEC | 1923 | 93 |
| Town of Somers | | | | |
| Hulbert & Tillman | | | | |
| application for survey | 3 | May | 1923 | 95 |
| OA Hilgermann | 14 | " | may | 95 |
| Town of Pine Lake | 15 | June | 1923 | 97 |

INDEX

INDEX

| Section | TOWNSHIP | | RANGE | | CITY | ADDITION | FOR WHOM | WHEN | | | Page |
|---|----------|----|-------|----|---------|-------------------------|-----------------------|------|-------|------|------|
| | N. | S. | E. | W. | VILLAGE | | SURVEYED | Day | Month | Year | |
| 16 | 38 | | 10 | E | | Road Sugar Camp | Town of Sugar Camp | 28 | aug | 1923 | 100 |
| 34 | 36 | 4 | | | | Town of Lynn | Town of Lynn | 29 | Sept | 1923 | 104 |
| 11 | 38 | # | 11 | E | | | Henry Sary | 24 | oct | " | 106 |
| 17 | 39 | | 11 | E | | 39-9 | cheaps man | | | | |
| | | | | | | | Copied into Book 39-9 | | | | |
| 16 | 39 | | 6 | E | | to ascertain and others | Ray Madden | 27 | SEPT | 1922 | 65 |
| <p>N 1/4 P OK. also found East of N 1/4 Post. OK. West from N 1/4 P of Houghton. Van 4 1/2 E 2061 fell 16 S of DOYR'S 1/8 Post NW COR. found the E of BT about doors W 1/8 P on N Line NEW 1/8 P on S + E 31</p> <p>Bearings for NW COR: W Pine 10 N 63 1/2 W 10 } Oak 10 S 86 3/4 E 48</p> <p>NW C OY S Van 245 2500 Pond 3500 " " 34 1/2 E of 1/4 Post. found 38 12</p> <p>Stump of original BT. at 2061 drew lines together and set 1/8 P. West of center then prolonged line East to Lak 9.20 } Bire 5 S 31 W 8 and set m.c. } then 8 N 8 W 7 1/2 Set 1/16 Post in NW 1/4 } Pine 10 S 11 E 28</p> <p>march 27 1924</p> <p>W 1/4 P OK. Run S Van 4 1/2 E D H U 4006 fell 67 W of S W corner which S set 207 Carriage from OY 1/8 E 663 Set S 1/8 Post on weather of 2003 and 33 1/2 E of Random } Y Pine 8 S 189 1/2 " " 7 N 36 W 10 1/4</p> | | | | | | | | | | | |