•				<b>23023</b>
	LAND CORNER	PRESERVATION	ON RECORD	
	this record to preserve the local or inaccessible due to road co			nument that may be
County:	City, Village, Town:	Section:	Town:	Range:
Oneida	Little Rice	1	T. 36 N.	R. 5 E.
Describe what was found, its location and origin. If known, describe if the monument found is a 1/16 corner or other subdivisional corner; a monument called for in a deed; a monument shown on a survey map or plat etc and in what GL or ½ - ½ section or subdivision the monument is located.				Approximate location within Section 1, T36N, R5E
B-3024 lying flat	recovered the railroad spike under the first layer of per Papers 1" diam. iron pipe w	avement. I found	and marked	
	4		•	
			·	

Plan view map of landmark monument location with bearing and distance ties to a minimum of four described witness or reference monuments of concrete, natural stone, metal, live bearing trees or equivalent material or indicate datum & coordinates if tied out using GPS. Indicate what was reset.

**NORTH** 

MAP # L3023
DATE FILED 9-14-15
BY MS
DESCRIPTION FILED
ONEIDA CO. SURVEYOR'S OFFICE

## Seal:



## PROFESSIONAL LAND SURVEYOR CERTIFICATE:

This land corner was referenced out in advance of road construction or other activity as an act of preserving survey evidence or monuments. This corner has not been tested for its accuracy during the course of this preservation. It is recommended that those using the corner position evaluate and verify it prior to use in a survey or other use.

I hereby certify that I am a duly licensed Professional Land Surveyor in the State of Wisconsin; that the location of this Survey or Land Corner was referenced by me, or under my direct supervision and control and that the information shown on this record is true and correct to the best of my knowledge and belief.

Signature

3605011000