


① SE cor. Sec 20 Cedar post & brass up
 iron pipe (Kawalhe 12/56) Orig. cor. (Bennett 11/57)



② E 1/4 SE 1/4 would be at 18.80 (Bennett 11/12/57)

RECEIVED & FILED # 1,794
 Oneida County Surveyor's Office
 Date APR 22 1988
 BY S. J.
 OCS Area #

③ E 1/4 Sec 20 Tam. 13" - N32°W - 16; 8" - S11°E - 6 (Don 12/12/92)
 at 37.60 each way set W.C.D. pipe Tam. 7" - N73°W - 0.410 ch.;
 SB 4" - N46°E - 0.315 ch.; SB 5" - S42°W - 1.60 ch. (Bennett 11/12/57)

④ E¹/₄ NE¹/₄ at 18.800 each way set 3/4" IP for 1/8
PW 4" - S15°E - 0.530 ch. (Bennett 11/12/57)


⑤ NE Cor. Sec 20 Set w.c.d. pipe by double proportion. PW 3" -
S62°W - 0.470 ch.; PN 7" - N75°E - 0.339 1/2 (Bennett 11/12/57)

⑥ N¹/₄ NE¹/₄

⑦ N¹/₄ Sec 20

① W¹/₄ Sec 20 at 37.25 each way set brass cap iron
Pipe. for new ¹/₄ cor. Black ash 12" - S 33° W - 0.606 ch.; Black
ash 16" - S 82° W - 0.674 ch. (Howells 12/56)

② W¹/₄ SW¹/₄ at 18.625 set cedar post for ¹/₈ cor. PN 10" - N 48° W -
0.550 ch.; PN 12" - N 22° E - 0.539 ch.; PW 8" - S 66° E - 0.050 ch.
(Howells 12/56)



③ SW Cor. Sec 20 set brass cap iron pipe. PW 18" - N 49° W - 0.197 ch.;
PW 22" - S 8° E - 0.500 ch.; Cedar 8" - N 88° W - 0.288 ch. (Howells 12/56)

④ S¹/₄ SW¹/₄ at 21.02 set cedar post. PW 12" - N 65° W - 0.415
ch.; PW 15" - N 60° E - 0.210 ch. (Howells 12/56)

⑧ N¹/₄ NW¹/₄ at 21.266 east of NW cor
a marked post wcd. (Kowalke 12/56)

Sec 20 - 28 - 7

⑨ NW cor. sec 20 set a Brass cap iron post. Birch 6" — N 14° W — 0.395
ch.; Birch 6" — S 87° E — 0.390 ch. (Kowalke 12/56)

⑩ W¹/₄ NW¹/₄ at 18.625 set cedar post. Tom. 4" — N 57° E — ~~0.415~~
ch.; Tom. 3" — S 48° W — 0.115 ch. (Kowalke 12/56)

Sec 20-38-9

⑮ S¹/₄ Sec 20 at 42.04 each way set Brass cap iron post. ~~found~~
N 24° W - 0.312¹/₂ ch. (Kavelle 12/56)

⑯ S¹/₄ SE¹/₄ at 21.02 set cedar post. Stem 4" - N 45° W - 0.461 ch.
aspens 9" - S 75° E - 0.370 ch. (Kavelle 12/56)