

CHAINS	H.C. LAWRENCE / JULY 20 1954 S.P. MARMES	CHAINS	H.C. LAWRENCE / JULY 21 1954 S.P. MARMES
<u>SOUTH 1/2</u>	LINE BET. SEC. 8 AND 9. AT CORNER OF SEC. 8-9-16 & 17 THERE IS STAMP OF ORIGINAL GOVT. W. PINE 16" MARKS O.K. 525W 20 IKS FROM MY NEW CEDAR POST. ALSO STAMP OF VANPHAN'S JUNE 21-1916 B.T. VIA W. PINE VIA W. PINE 18 N 58° W 6 1/2 IKS. MADE N.B.T.S. (Y. BIRCH 18" S 56 1/2 E 26) (Maple 8" S 41 W 37) FROM THIS CORNER I RAN NORTH MAG. (Var 0°)	<u>EAST 1/2</u>	LINE BET SEC. 5 AND 8 FROM TEMPORARY CORNER OF 4-5-8 AND 9 I RAN 580° W MAG.
2 28	Old Thompson to Storkley Road E & W at gate in old fence.	1 00	Slough Hole of Stagnated water.
2 80	Line crosses to East Side of Fence Line	2 19	Over a narrow Slough Hole.
4 00	Fence is now 6 Iks. West of Line.	2 30	Ascend into Aspen
10 00	" " " 38 " " "	7 00	a woods road E-W & S.
10 77	Descend very abruptly to Swamp.	10 80	" " " " " "
11 75	Enter a narrow swamp wet bottom.	14 50	enter Swamp.
12 56	Cross an E & W Fence 49 Iks EAST of Corner Fence Post where N & S fence ends.	19 00	a foot trail E-W & S.
13 00	Leave narrow Swamp. B. N.B. & S.W.ly	45 00	Leffe heap.
15 00	in low wet part hole.	47 97	Intersect N & S Random 1/4 Line 1.36 chs South of old Burned 1/4 Post. No B.T.s in evidence.
22 43	enter Cutover Panhandle Swamp.	48 22	Intersect N & S corrected 1/4 Line. There is an Iron Pipe also at 1/4 Cor. I set new 4" dry Cedar Post alongside old Post and Iron Pipe nothing new for B.T.s.
25 00	enter good Spruce & Cedar standing timber.		
39 34	AT WHICH POINT THE ORIGINAL GOVT 1/4 POST IS 15 R.R. due West. Original Spruce down, marks O.K. IT bears S 62 1/2 W 8 Iks. I found print of Original Post and print of another old post. I set new 5" Cedar Post in old post position and made N.B.T.S. (Cedar 12" S 48 W 49) and a (Cedar 14" S 75 E 36)	E 1/16	I set 4" Cedar Post for Temporary E 1/16 Cor 68 Iks North at Right Angle from 24 11 chs intermediate.
5 1/16	I SET a 5" CEDAR POST FOR S 1/16 COR. 7 1/2 IKS WEST OF 19.67 chs intermediate. (No enduring Trees for N.B.T.S.)		
<u>NORTH 1/2</u>	LINE BETWEEN SEC. 8 AND 9 NORTH OF 1/4 COR. CONTINUED RANDOM LINE STRAIGHT FROM CLOSING PICKET 15 IKS EAST OF 1/4 COR. DID NOT CHANGE BEARING AT 1/4 COR. FOR A NEW RANDOM.		
3 00	Leave Timbered Swamp for Open Swamp.		
9 95	a Swamp drain to Run East.		
10 50	Ascend into Aspen type area.		
15 25	E of New Consolidated Road called Wolf River Road.		
15 93	Foot of Hill and South end of a grassy wet slough		
20 37	Over slough to foot of High land.		
28 25	Enter East Border of Open grassy Marsh		
30 75	Leave above grassy Marsh. It is nearly round.		
34 30	E of an old Road to Davis Homestead clearing.		
39 34	No evidence of corner of Sec. 4-5-8 and 9 in this marsh. Going to Farm clearing. I set Temporary 4" Cedar Post 30 Iks West of 39.34 chs. (assuming this corner to be on a straight line with 1/4 Cor. and corner South of it.)		
N 1/16	Set 4" Cedar Post for Temporary N 1/16 Cor. 22 1/2 Iks West of 19.67 chs intermediate North of 1/4 Cor. No B.T.s made. This 1/16 Cor. is easily seen from Consolidated Road on Ground Ridge as it lies in West border of grassy slough (no timber)		