
NO SURVE ARGONNE, HANSEN PHILIP . S-498



O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION

Index No. Y- 19

History of original corner establishment:

SS

Corner established by Goddard and crew, Ripco surveyors, in 1960. Ran random line south from previously established C 1/4 corner to S 1/4 corner bearing S 4° 32' E, distance 58.33-3/4 chains. Set SC 1/16 at 29.17 chains intermediate.

Marked NBT's -Maple 7" S44°E Maple 5" S80°W 14-3/4 links 24 links

Description of corner evidence found

Monument projects 24" above ground. Recovered Ripco's 3/4" iron pipe with 2" diameter alloy cap in good condition. Cap stamped:

Recovered Lawrence's 6" squared cedar post, scribed SC 1/16 S35, SC 1/16 S35, which bears S 35° E 15.0 links. Will use Ripco's monument as this was established with

Recovered OBT's Maple 7" S44°E (S61°E) 24.0 links (23.7 links) scribed CS 1/16 BT.
Maple 5" S80°W (S83°W) 14 links, now dead and down.

S 1/16

Description of monument and accessories I established to perpetuate the original location of this corner.

Marked NBT's -Monument left in place as recovered.

Maple 6" S25°W Marle 5" N17°W both scribed 1/16 BT. 16.2 links 18.7 links

Dated at Rhinelander

, Wis., this 10th

day of July

..., 19..79....

.. Registration No... S-498

Killi Kennen Title Registered Land Surveyor (County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of ...

Signature.

instrument was filed in this office for record on the....

o'clock

Horseby certify that the within the day of Lee Jack To 1979

...Deputy

(Register of Deeds

Ву.....