SS.

certify that on the 7th day of January 1975, I found evidence of the EC-1/16 evidence of the EC-1/ corner of Section 14 location of this corner. as described hereon to perpetuate the original as described hereon; and that from this evidence I established a new monument and accessories Township 36 Philip T. Hansen Fourth Principal Meridian, North, Range, do hereby

Resident witnesses: V. 43. S 498

T36N, R11E

 $\frac{s}{14}$ 22.01 $\frac{22.01}{\text{EC-1/16}}$

O = Corner monument restored.

Ву....

.....Deputy

CERTIFIED LAND CORNER RESTORATION

Index No. 1-20

History of original corner establishment:

No record of bearing trees. corner equidistant between C-1/4 and E-1/4 at 22.01 chains. Corner established by H.C. Lawrence during his retracement survey of 1955. Set EC-1/16 No record of corner established by other surveyors.

Description of corner evidence found:

No trace of BT's. Area has been clear-cut and scarified. Recovered 4" cedar post, squared and scribed S14 EC-1/16 in fair condition.

Description of monument and accessories I established to perpetuate the original location of this corner. Set 1" x 5' galvanized iron pipe with 2" brass cap stamped -

No trees available for BT's.

EC-1/16 S14 CPI-1975

T36N, R11E

Jours Turage Juda (Register of Deeds)	Office of Register of Deeds, County of	Signature Julio J. Sannam. Title Registered Land Surveyo (County Surveyor, Registered Land Surveyor, or other duly authorized official)	Dated at Rhinelander , W
	Oneida on the //	Title Registered Land Surveyor	vis., this 16th
i	day of \mathcal{O}	1 Land Surveyor nly authorized official)	, Wis., this
	day of October 1975	Registration N. S-498	, 1975