

CERTIFIED LAND CORNER RESTORATION


Index No. 0-11

State of Wisconsin }  
County of Oneida } ss.

History of original corner establishment:

I, Philip T. Hansen, do hereby certify that on the 7th day of May, 1975, I found ~~no evidence of the~~ established NC-1/16 corner of Section 21, Township 36 North, Range 11 East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.


Resident witnesses:



Description of monument and accessories I established to perpetuate the original location of this corner.  
From established N-1/4 corner between Sections 16 and 21 and the established C-1/4 corner, the NC-1/16 corner was set equidistant at 20.52 chains North 30 West of the C-1/4 corner. Set a 1-1/2" O.D. x 5' iron pipe with brass cap stamped -

NBT - White spruce 7" S230E 152 links scribed 1/16 BT S498  
White spruce 9" S510E 167.5 links scribed 1/16 BT T36N R11E

NC-1/16 S 21  
CPL-1975



○ = Corner monument restored.

Description of corner evidence found:  
No evidence of previously established corner.

Dated at Rhinelander, Wis. this 7th day of May, 1975.

Signature *Philip T. Hansen* Title Registered Land Surveyor Registration No. S-498  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of Oneida  
Instrument was filed in this office for record on the 1st day of October, 1975  
at 3:00 o'clock P.M.

*Donna Vernege Kuehn*  
(Register of Deeds)

By: Deputy

3611213020