

CERTIFIED LAND CORNER RESTORATION

Index No. F-21

State of Wisconsin

County of Oneida } ss.

History of original corner establishment:
Original Corner established by D.H. Vaughan, County Surveyor. N. Loftus, Ripco surveyor, recovered Vaughan's corner and red pine BT in 1957. Established NBTs - Jack Pine 7" S71°W, 18 links, and black spruce 3" S46°E, 17 links. Set iron pipe with brass cap.


I Phillip T. Hansen do hereby certify that on the 28th day of April, 1977, I found evidence of the N 1/16 corner of Section 11 & 12 Township 37, North, Range 8 East, Fourth Principal Meridian.

I established a new monument and accessories as described hereon; and that from this evidence as described hereon to perpetuate the original location of this corner.

Resident witnesses:

Jim Clafin

Herb Wagoner




Description of corner evidence found:

Recovered 1" iron pipe with 2" square brass cap in excellent condition and securely in ground. Monument projects 20" above ground.
Recovered OBTs - Jack Pine 7" (8") S71°W, 18.0 links (18.5 links), scribed 1/16 S11 BT.
Black Spruce 3" (5") S46°E, 17.0 links (17.3 links), scribed 1/16 BT.

Cap stamped:

T37N R8E
N 1/16
S11 + S12

Description of monument and accessories I established to perpetuate the original location Ripco corner. **As monument was recovered in good condition and securely in ground, it was left as recovered.**



○ = Corner monument restored.

Dated at Rhineland Wis., this 4th day of May, 1977.

Signature Phillip T. Hansen Title Registered Land Surveyor Registration No. S-498
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of Oneida. I hereby certify that the within instrument was filed in this office for record on the 6th day of May, 1977 at 1:00 o'clock P. M.

Terri Terage Kuhn
(Register of Deeds)

By: _____ Deputy