
rertify that on the 28th day of October 19.75, I found evidence of the N-1/16 corner of Sections 14 and 15
Township 37 North, Range 11 East Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:
Glen Barker

Jim Claflin

T37N R11E

N-1/16



O = Corner monument restored

Ву.....

.....Deputy

## CERTIFIED LAND CORNER RESTORATION

Index No. **K-17** 

History of original corner establishment:

marked NBT's: Spruce 4" West Original corner established by J.J. Melendy, Gagen Lumber Company surveyor. recovered by H.C. Lawrence, Registered Land Surveyor. Set new tamarack post and Spruce 7" N25°E 23 links. 3 links and Corner

Description of corner evidence found:

Recovered OBT's: Spruce 4" Recovered 6" tamarack post, squared and scribed 1/8S S14, 1/8S S15 in poor condition. Spruce 7" N23°E West 23 links - now decayed stump. 3 links - now decayed stump,

Description of monument and accessories I established to perpetuate the original location of this corner. Pipe and BT's painted blue. NBT's: Replaced 6" tamarack post with 1" iron pipe with 2" brass cap stamped -Projects 18" above ground. Black spruce 5" S53°E Black spruce 7" N77°E 18.8 links - scribed 1/16 BT, 41.5 links - scribed 1/16 BT. 18.8 links - scribed 1/16 N-1/16 S15 S14 CPI-1975 T37N R11E

Dorus (Register of Doeds)	Office of Register of Deeds, County of	Signature Hille Schemen. Title Registered Land Surveyo (County Surveyor, Registered Land Surveyor, or other duly authorized official)	Dated at Rhinelander , Wis., this
	9	Title Registered Land Surveyor	s 7th
	A	ered Land er duly auth	:
	day of	Surveyo	day of November
	19 Mereby certify that the withing that the withing 19 76	r Ru	rember
	certify than	istration NoS-498	
	t the within	5-498	19.75