SURVEY LANDMARK PRESERVATION RECORD					
It is the primary purpose of this record to preserve the location of any survey landmark subject to disturbance, removal or to be rendered inaccessible, as provided by Section 59.74(2), Perpetuation of Landmarks, Wisconsin Revised Statutes.					
County:	City, Village , Tow		Section:	Town:	Range:
Oneida	Piehl		30	37 North	11 East
Describe survey landmark found or reset and origin if known, such as being a 1/16 corner, called for in a deed or shown on a record land survey map or plat; also note location by Govt Lot, 1/2/4 section or other PLSS subdivisional tract. At the request of Oneida County Surveyor Michael Romportl, I inspected the location of this corner on May 18, 2004, due to pending roadway maintenance, as reestablished by					Show approximate location of survey landmark on this Section diagram:
Professional Land Surveyor Glen Barker, RLS 1682 per his U.S. Public Land Survey Monument Record dated December 20, 1989 and filed in Oneida County records.					
The corner monument and references noted by Barker were recovered as noted below.					
The corner monume	nt and references	MAP # DATE FILE BY NY	2064 0CT 29	2004	30
		DESCRIPTION	N FILED		
Plan view map of survey landmark location with bearing and distance ties to a minimum of four (4) described witness or reference monuments of concrete, natural stone, metal, live bearing trees or equivalent material and/or by described GPS method and precision. **N **Scale:**_N/A The uncapped top of an undisturbed 1" dia. iron pipe monument was found about 6" below the existing graveled roadway surface and at approximately 3 feet East of its traveled centerline. The #1 2.5" dia. iron pipe reference monument was found undisturbed with stamped cap about 24" above surface of vegetated and water-filled drainage ditch and with a standard white poly 'T' marker post nearby. The #2 1" dia. iron pipe reference monument was found undisturbed with uncapped top 8" above grade, which I tied with blaze orange flagging tape as well as a tall wood stick inserted in its top. The #3 7" Twin Tamarack BT was found alive with a 7" SE trunk and a 10" NW trunk which has a plain upper face blaze nearly shut and a plain open lower face blaze; I painted both with blaze orange marking paint. The #4 6" Black Spruce BT was found alive as a 9" Black Spruce with both upper and lower face blazes open; I painted both with blaze orange marking paint. I did not check record bearings and distances to the reference monuments as they were all found undisturbed in my judgment.					
Seal:		PROFESSIONAL LAND SURVEYOR CERTIFICATE:			
This survey landmark is being referenced for the express purpose of location preservation and is not intended as an attestment of the legal significance and/or positional accuracy thereof. Therefore, this survey landmark location should be further evaluated and verified for any future land surveying or related usage purposes. I, William C. Rohde, hereby certify that I am duly licensed as a Professional Land Surveyor in the State of Wisconsin; that the location of this survey landmark was referenced by me or under my direct supervision and/or control; and that the information shown is true and correct to the best of my knowledge and belief.					
Signed: Lielian Folle Date: May 25, 2004					
37//300000					