					nonument that may be		
	CA AI IIIGAAAAN	It is the purpose of this record to preserve the location of a survey or land corner monument that may be disturbed, removed or inaccessible due to road construction or other activity.					
Oneida	City, Village, To		Section: 24	Town: 38N	Range: 5E		
1/16 corner or othe a survey map or pla June 7, 2006: A Forest and alse end of South F perpetuated th	r subdivisional corner; at etc and in what GLo As shown below, o survey map OCS ork Road at the	d origin. If known, description and a monument called for 1/4 - 1/4 section or subsection of subsection and the section and th	rin a deed; a m division the mo ments of the nument are dear Lake bo	onument shown on nument is located.  Plat of Lost located at the at landing. I			
					r described witness or referentiatum & coordinates if tied ou		
using GPS. Indicat		ictal, live bealing trees	or equivalent ii	iateriai di ilidicate t	NORTH		
⊕ = 1" dia ⊗ = 2-1/4	diam. iron pipe fd. m. iron pipe fd. I" diam. iron pipe fd. m. iron pipe set		SOUTH FORK ROAD		KOKIII		
L2288	X = 467 Y = 499 (safe loc	9.19 O & ———	31.12 98.94 X = 500.0 Y = 500.0		4.77 10.14 (sate location)		
TION FILED		I		/	<b>\</b>		
SPASURVEYOR'S	ONSIAMINATION ON STIN 1998 ICOUA, M	activity as an act of not been tested for recommended that use in a survey or I hereby certify the State of Wiscons referenced by the	as referenced of preserving s r its accuracy t those using t other use.  nat I am a duly in; that the lo e, or under my on on this rec	out in advance of urvey evidence of during the course he corner position y licensed Profes cation of this Su y direct supervise	IFICATE:  f road construction or other monuments. This corner of this preservation. It is nevaluate and verify it pricessional Land Surveyor is pricessional Corner was ion and control and that correct to the best of my		