SURVEY LANDMARK PRESERVATION RECORD

It is the primary purpose of this record to preserve the location of any survey landmark subject to disturbance, removal or to be rendered inaccessible, as provided by Section 59.74(2), Perpetuation of Landmarks, Wisconsin Revised Statutes.

County: Section: City, Village, Town: Town: Range:

Oneida 37 North Newbold 19

Describe survey landmark found or reset and origin if known, such as being a 1/16 corner, called for in a deed or shown on record land survey map or plat, also note location by Gov't. Lot, 1/4-1/4 section or other PLSS subdivisional tract.

May 5th, 2007, I recovered a 1.6" dia. iron pipe 6 inches below grade in the north track of Clear Lake Road, and made witness ties as shown in plan below.

Show approximate location of survey landmark on this Section diagram:

8 East


60

00

€ÿ,

(A)

N 1/16 Corner




Reference materials: Plat of Tooly Tail Acres 3⁷⁰⁸¹⁹³000 3707243

0.75" dia. iron rod (NOO:17'31'W 78.80') N 1/16 Corner (S83[·]36[·]15^{*}E 51.59[·]) 1.6" dia. iron pipe S83*36'15'E 51.56 existing ○ 0.75" dia. iron rod 46.16' 50'12'22"E existing roadbed

0.5" dia. iron rod

Bearings assumed, as shown hereon.



Pre-Construction

Seal:



Alum. capped

1.0" dia. iron pipe

PROFESSIONAL LAND SURVEYOR CERTIFICATE:

This survey landmark is being referenced for the express purpose of location preservation and is not intended as an attestment of the legal significance and/or positional accuracy thereof.

Therefore, this survey landmark location should be further evaluated and verified for any future land surveying or related usage purposes.

l, Michael L. Oestreich, hereby certify that I am duly licensed as a Professional Land Surveyor in the State of Wisconsin; that the location of this survey landmark was referenced by me or under my direct supervision and/or control; and that the information shown is true and correct to the best of my knowledge and belief.

signed: Muluely Obstail Date 4/72/08

60

68 00 S) €®