## SURVEY LANDMARK PRESERVATION RECORD

It is the primary purpose of this record to preserve the location of any survey landmark subject to disturbance, removal or to be rendered inaccessible, as provided by Section 59.74(2), Perpetuation of Landmarks, Wisconsin Revised Statutes.

County:

City, Village, Town:

iron pipe as shown in the plan below.

Section:

Town:

Range:

Oneida

Pine Lake

37 North


9 East

Describe survey landmark found or reset and origin if known, such as being a 1/16 corner, called for in a deed or shown on record land survey map or plat, also note location by Gov't. Lot, 1/4-1/4 section or other PLSS subdivisional tract.

May 25th, 2006, recovered brass capped iron pipe and iron pipe 22.85' feet to the north. Also recovered remains of decaying +/- 10" dia. stump with blaze bearing S53W 40.4'. I witnessed the recovered brass capped

Show approximate location of survey landmark on this Section diagram:


CS 1/16 Corner



Reference materials: Survey Map No. C1205, filed 1/08/96

3709271020

Scale: 1" = 40'



DESCRIPTION

Distances to aluminum nails & the sides of all bearing trees.

**Pre-Construction** 

Seal:



## PROFESSIONAL LAND SURVEYOR CERTIFICATE:

This survey landmark is being referenced for the express purpose of locationpreservation and is not intended as an attestment of the legal significance and/or positional accuracy thereof.

Therefore, this survey landmark location should be further evaluated and verified for any future land surveying or related usage purposes.

I, Michael L. Oestreich, hereby certify that I am duly licensed as a Professional Land Surveyor in the State of Wisconsin; that the location of this survey landmark was referenced by me or under my direct supervision and/or control; and that the information shown is true and correct to the best of my knowledge and belief.

signed: Michiel Date2-14-08