SURVEY LANDMARK PRESERVATION RECORD

It is the primary purpose of this record to preserve the location of any survey landmark subject to disturbance, removal or to be rendered inaccessible, as provided by Section 59.74(2), Perpetuation of Landmarks, Wisconsin Revised Statutes.

County:

City, Village, Town:

Section:

Town:

Range:

Oneida

Cassian

12


37

6

Describe what was found, its location and origin. If known, describe if the monument found is a 1/16 corner or other subdivisional corner; a monument called for in a deed; a monument shown on a survey map or plat ect. and in what Gov't Lot, 1/4-1/4 Section or other PLSS subdivisional tract.

> May 7, 2008 - Prior to road construction we searched for the Northwest corner of the Southeast 1/4 of the Southwest 1/4 and found a 3/4" iron pipe 1-1/2' tall. This corner was shown as a found iron pipe in place on the Plat of Survey by John Fisher dated October 1961 - Oneida County Land Information Office Map Number C-1607. He also shows 2 bearing trees which are gone.

Show approximate location of survey landmark on this Section diagram:



Scale: $1 = 20^{\circ}$

Balsan

Tree blazed and

a 60 Ranait set

in side of tree

3706121030

Plan view map of survey landmark location with bearing and distance ties to a minimum of four(4) described witness or reference monuments of concrete, natural stone, metal, live bearing trees or equivalent material and/or described GPS method and precision.

Note

All bearing were taken with a hand compass and distances measured with a tape measure.

Little Bearskin

Creek Road

14" Red Oak

Iron rebar set at South edge of tree

Legend

Set 3/4" x 24" Iron Rebar Weighing 1.50 lbs/lin ft.

HINELANDER

O SUR

Found 3/4" Iron Pipe

8" Birch Also a Owens- Illinois plaque was found on the face of the tree. in side of tree

Tree blazed and a 60 P nail set

Seal

PROFESSIONAL LAND SURVEYOR CERTIFICATE:

This survey landmark is being referenced for the express purpose of location preservation and is not intended as an attestment of the legal significance and/or positional accuracy thereof.

N77E

22.99

Therefore, this survey landmark location should be further evaluated and verified for any future land surveying or related usage purposes

I, Jonathan W. Dulin, hereby certify that I am duly licensed as a Professional Land Surveyor in the State of Wisconsin; that the location of this survey landmark was referenced by me under my direct supervision and/or control; and that the information shown is true and correct to the best of my knowledge and belief.

Signed:

(A) SI SI

) RS M