


2529

2529




DWG. # 441-A  
 BIXBY LAND SURVEYING INC.  
 P.O. BOX 1532  
 RHINELANDER, WI. 54501  
 715-362-5263

EXISTING SITE CONDITION SURVEY FOR  
**JOHN CIRILLI**  
 RHINELANDER, WI.

DATE: 06/17/08 SCALE: 1" = 100' DWN. BY. K.B.

MAP # **2529**  
 DATE FILED **JUL 30 2008**  
 BY **JAB**  
 DESCRIPTION FILED  
 ONEIDA CO. SURVEYOR'S OFFICE



2529

2529