

,	LAND CORNER	<b>PRESERVA</b>	TION RE	CORD		
It is the purpose of this record to preserve the location of a survey or land corner monument that may be disturbed, removed or inaccessible due to road construction or other activity.				ROAD CONSTRUCTION		
County:	City, Village, Town:	Section:	Town:	Range		
ONEIDA	TOWN OF SCHOEPKE	33	35 N	11 E		
Describe what was found, its location and origin. If known, describe if the monument found is a 1/16 comer or other subdivisional corner; a monument called for in a deed; a monument shown on a survey map or plat etc and in what GL or ¼ - ¼ section or subdivision the monument is located.				Approximate Location within Section. 33		
		\$ 				
09/11/1978 - PHILLIP HANSEN SET, 1 1/2" IRON PIPE WITH BRASS CAP AS NOTED ON CERTIFIED LAND CORNER RESTORATION FORM 3511333010.						
07/09/2009 - I FOUND A 1 1/2" DIA. IRON PIPE WITH ALUMINUM CAP AND ONE OF HANSENS BEARING TREES AND REMAINS OF ANOTHER, AND SET NEW WITNESSES AS SHOWN BELOW.						
NOTE: THIS IS A NEWER MONUMENT THAN HANSEN'S 1978 MONUMENT.						
		est.				
				35//333	351/333010	


Plan view map of landmark monument location with bearing and distance ties to a minimum of four described witness or reference monuments of concrete, natural stone, metal, live bearing trees or equivalent material or indicate datum & coordinates if tied out using GPS. Indicate what was reset.



NOTE: PRESENT DAY STAMPING DIFFERENT FROM EXISITING RESTORATION FORM. PIPE PROJECTS £12" ABOVE GROUND AND BENT NORTHEASTERLY.



## 



## PROFESSIONAL LAND SURVEYOR CERTIFICATE:

This land corner was referenced out in advance of road construction or other activity as an act of preserving survey evidence or monuments. This corner has not been tested for its accuracy during the course of this preservation. It is recommended that those using the corner position evaluate and verify it prior to use in a survey or other use.

I hereby certify that I am a duly licensed Professional Land Surveyor in the State of Wisconsin; that the location of this Survey or Land Corner was referenced by me or under my direct supervision and control and that the information shown on this record is true and correct to the best of my knowledge and ballet.

Signature W

08/12/2009