LAND CORNER PRESERVATION RECORD It is the purpose of this record to preserve the location of a survey or land corner monument that may be disturbed, removed or inaccessible due to road construction or other activity. City, Village, Town County: Range: Section: 9E 15 37N ONEIDA PINE LAKE Describe what was found, its location and origin. If known, describe if the monument found is a 1/16 Approximate location within corner or other subdivisional corner, a monument called for in a deed; a monument shown on a Section NE /16 survey map or plat etc and in what GL or 1/4 - 1/4 section or subdivision the monument is located. A RAILROAD SPIKE WAS FOUND AT THE NORTHEAST SIXTEENTH CORNER OF SECTION 15. LOCATION AS SHOWN ON C.S.M. #03016 AND MAP# B6768. MULTIPLE GPS OBSERVATIONS CHECKED WITH AN AVERAGE OF: N: 187,400 21 E: 280, 119.28 SITE VISITED ON ONEIDA CO. GRID IN NAD 83(2011) 6-25-2015 Plan view map of landmark monument location with bearing and distance ties to a minimum of four described witness or reference monuments of concrete, natural stone, metal, live bearing trees or equivalent material or indicate datum & coordinates if tied out using GPS. Indicate what was reset. NORTH **L30**31 MAP # DATE FILED 10-16-15 DESCRIPTION FIRED ONEIDA CO. SURVEYOR'S OFFICE Seal: PROFESSIONAL LAND SURVEYOR CERTIFICATE:



This land corner was referenced out in advance of road construction or other activity as an act of preserving survey evidence or monuments. This corner has not been tested for its accuracy during the course of this preservation. It is recommended that those using the corner position evaluate and verify it prior to use in a survey or other use.

I hereby certify that I am a duly licensed Professional Land Surveyor in the State of Wisconsin; that the location of this Survey or Land Corner was referenced by me or under my direct supervision and control and that the Information shown on this record is true and correct to the best of my knowledge and belief.

Smily K Kerce

9-30-2015

Date